

AHERA THREE-YEAR RE-INSPECTION

John Adams Middle School
2425 16th Street
Santa Monica, California 90405

Prepared for:

Santa Monica Malibu Unified School District
1651 16th Street
Santa Monica, California 90405

Project No.: 110-0006

Date: July 14, 2010

July 14, 2010

Santa Monica Malibu Unified School District
1651 16th Street
Santa Monica, California 90405

Attention: Mr. Terry Kamabayashi

Ref: Three-year Re-inspection
John Adams Middle School, 2425 16th Street, Santa Monica, California 90405

Coffey Environments Project No. 110-0006

Dear Mr. Terry Kamabayashi:

Coffey Environments is pleased to present its report for the AHERA three-year re-inspection of Santa Monica High School, located at 2425 16th Street, Santa Monica, California 90405.

Please do not hesitate to contact the undersigned if you wish to discuss any aspect of the report.

Respectfully submitted by:

Reviewed by:

Coffey Environments

Coffey Environments

Fabian Ruvalcaba
Certified Site Surveillance Technician
Cal/OSHA Cert. #06-4088

Cesar Ruvalcaba
Certified Asbestos Consultant
Cal/OSHA Cert. #95-1799

EXECUTIVE SUMMARY

Coffey Environments conducted an AHERA three-year re-inspection of John Adams Middle School, located at 2425 16th Street , Santa Monica, California 90405. Coffey Environments' Certified Site Surveillance Technician/Certified Asbestos Consultant conducted the following activities to document the project:

- Visual inspection of known asbestos-containing materials (ACM), both friable and non-friable, and suspect ACM not previously identified or sampled;
- Identification of friable and non-friable ACM including ACM not previously identified or sampled; and
- Assessment of friable and damaged non-friable ACM, including ACM not previously identified or sampled.

CONTENTS

1	PROJECT SUMMARY	1
2	FIELD AND ANALYTICAL METHODOLOGY	1
3	RESULTS	1
4	RECOMMENDATIONS	1
5	ASSUMPTIONS AND LIMITATIONS	2
6	SIGNATORY	2

Appendices

Appendix A: AHERA 3-Year Re-Inspection Material Inventories

Appendix B: Previous Inspection Report

Appendix C: Response Action Ratings

Appendix D: Field Sheets

Appendix E: Assessments

Appendix F: Site Map

Appendix G: Coffey Environments Employee Certifications

REPORTED: July 14, 2010

PROJECT NO.: 110-0006

CLIENT: Santa Monica Malibu Unified School District
1651 16th Street
Santa Monica, California 90405

ATTENTION: Mr. Terry Kamabayashi

REF: AHERA Three-year Re-inspection
John Adams Middle School
2425 16th Street
Santa Monica, California 90405

1 PROJECT SUMMARY

Coffey Environments conducted an AHERA three-year re-inspection of John Adams Middle School, located at 2425 16th Street , Santa Monica, California 90405. Fabian Ruvalcaba, a Cal/OSHA Certified Site Surveillance Technician and EPA-accredited Building Inspector employed by Coffey Environments, conducted the inspection on March 9, 2010.

2 FIELD AND ANALYTICAL METHODOLOGY

The inspection was conducted in accordance with protocol set forth in the Asbestos Hazard Emergency Response Act (AHERA) *40 CFR 763 Subpart E*. Information in this report is based on the original AHERA inspection conducted in fulfillment of the requirements of *40 CFR 763 Subpart E*.

The re-inspection activities included the following elements:

- Visual inspection of known asbestos-containing materials (ACM), both friable and non-friable, and suspect ACM not previously identified or sampled;
- Identification of friable and non-friable ACM including ACM not previously identified or sampled; and
- Assessment of friable and damaged non-friable ACM, including ACM not previously identified or sampled.

3 RESULTS

Please refer to the AHERA three-year re-inspection material inventory located in Appendix A.

4 RECOMMENDATIONS

ACM should be monitored and maintained as part of the John Adams Middle School operations and maintenance program until renovation or demolition activities require removal or until material becomes

significantly damaged or the hazard potential changes. Remove or repair these items when practical and cost-effective in conjunction with an EPA-accredited Project Designer.

5 ASSUMPTIONS AND LIMITATIONS

This report was prepared exclusively for use by the Santa Monica Malibu Unified School District, and may not be relied upon by any other person or entity without Coffey Environments' express written permission. The information, conclusions and recommendations described in this report apply to conditions existing at certain locations when services were performed and are intended only for the specific purposes, locations, time frames and project parameters indicated. Coffey Environments cannot be responsible for the impact of any changes in environmental standards, practices or regulations after performance of services.

In performing our professional services, we have applied present engineering and scientific judgment and used a level of effort consistent with the current standard of practice for similar types of studies.

As applicable, Coffey Environments has relied in good faith upon representations and information furnished by individuals with respect to operations and existing property conditions, to the extent that they have not been contradicted by data obtained from other sources. Accordingly, Coffey Environments accepts no responsibility for any deficiencies, omissions, misrepresentations, or fraudulent acts of persons interviewed.

Coffey Environments will not accept any liability for loss, injury claim, or damage arising directly or indirectly from any use or reliance on this report. Coffey Environments makes no warranty, expressed or implied

This report is issued with the understanding that the client, the property owner, or its representative is responsible for ensuring that the information, conclusions, and recommendations contained herein are brought to the attention of the appropriate regulatory agencies, as required.

If you have any questions, please do not hesitate to contact the undersigned at (310) 530-5006. We appreciate the opportunity to be of service to the Santa Monica Malibu Unified School District.

6 SIGNATORY

Respectfully submitted by:

Reviewed by:

Coffey Environments

Coffey Environments



Fabian Ruvalcaba
Certified Site Surveillance Technician
Cal/OSHA Cert. #06-4088

Cesar Ruvalcaba
Certified Asbestos Consultant
Cal/OSHA Cert. #95-1799

CR:cdm

Appendix A

AHERA 3-Year Re-Inspection Material Inventories

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building V (Rooms 22-24)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Stucco	Exterior walls	ND	No	2,000 sq. ft	None Detected	N/A
S	Sand textured plaster	Room 22, 24, storage room, restroom	ND	No	2,200 sq. ft	None Detected	N/A
M	Drywall with joint compound	Room 22, 24, storage room	ND	No	300 sq. ft	None Detected	N/A
M	Duct sealant	Room 22, 24, heater closet on HVAC unit ducts	ND	No	5 sq. ft	None Detected	N/A
M	Chalkboards	Room 22, 24	ND	No	40 sq. ft	Assumed 1	8
S	Acoustical plaster (ceiling)	Room 22, 24	ND	No	1,800 sq. ft	Pos	8
M	12" grey speckled floor tile with adhesive	Room 22, 24, storage room	ND	No	1,800 sq. ft	Assumed 1	8
M	4" grey cove base with adhesive	Room 22, 24, storage room	ND	No	60 sq. ft	Assumed 1	8
M	Blue carpet glue	Room 24	ND	No	500 sq. ft	Assumed 1	8
M	12" fissured ceiling tile	Room 24	ND	Yes	500 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building U (Rooms 10-13)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Stucco	Exterior walls	ND	No	3,000 sq. ft	None Detected	N/A
S	Sand textured plaster	Rooms 10, 11, 12, 13	ND	No	4,500 sq. ft	None Detected	N/A
M	Drywall with joint compound	Rooms 10, 11, 12, 13	ND	No	900 sq. ft	None Detected	N/A
M	White sink insulation	Rooms 10, 11, 12, 13	ND	No	10 sq. ft	None Detected	N/A
M	Acoustical plaster ceiling	Rooms 10, 11, 12, 13	ND	No	3,600 sq. ft	Pos	8
M	2'x4' fissured ceiling panel	Rooms 10, 11, 12, 13	ND	Yes	3,600 sq. ft	None Detected	N/A
M	Chalkboards	Rooms 10, 11, 12, 13	ND	No	100 sq. ft	Assumed 1	8
M	12"grey floor tile with adhesive	Rooms 10, 11, 12, 13	ND	No	600 sq. ft	Assumed 1	8
M	4" grey covebase with adhesive	Rooms 10, 11, 12, 13	ND	No	480 sq. ft	Assumed 1	8
M	Adhesive for blue carpet	Rooms 10, 11, 12, 13	ND	No	300 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum board with joint compound	Community liaison, assistant principal's office 2	ND	No	300 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	4,500 sq. ft	None Detected	N/A
M	Joint compound with drywall	Rooms 21, 23, 30, 31, storage 1 & 2, room 9, nurse's office, attendance office, staff lounge	ND	No	6,000 sq. ft	None Detected	N/A
M	Sand textured plaster	Room 23, storage 1 & 2, 21, 9, nurse's office, attendance office, community liaison, room 20	ND	No	3,500 sq. ft	None Detected	N/A
M	12" random pinhole ceiling tile	Community liaison, attendance office	ND	Yes	300 sq. ft	None Detected	N/A
M	2'x4' fissured ceiling panel	Rooms 30-31, 9, nurse's office, attendance office, community liaison	ND	Yes	2,000 sq. ft	None Detected	N/A
M	Floor tile with mastic (sub flooring)	Staff lounge, room 21-23, attendance office, nurse's office (under floor tile & carpet)	ND	No	3,200 sq. ft	None Detected	N/A
M	9"x9" brown floor tile with mastic	Room 31A center (patch)	ND	No	8 sq. ft	None Detected	N/A
M	Green sheet vinyl flooring	Room 31A	ND	No	50 sq. ft	None Detected	N/A
M	White sink insulation	Room 9	ND	No	2 sq. ft	None Detected	N/A
M	Black sink insulation	Rooms 30-31	ND	No	4 sq. ft	None Detected	N/A
M	Grey duct sealant	Room 31A	ND	No	10 sq. ft	None Detected	N/A

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Acoustical plaster ceiling	Rooms 21, 23, 30, 31, attendance office, assistant principal's office, 1, 2, community liaison	ND	No	7,000 sq. ft	Pos	8
M	Chalkboards	Rooms 21, 23, 30, 31	ND	No	100 sq. ft	Assumed 1	8
M	12" grey speckled floor tile with mastic	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	ND	No	4,000 sq. ft	Assumed 1	8
M	6" grey covebase with adhesive	Community liaison	ND	No	10 in. ft	Assumed 1	8
M	4" Grey covebase with adhesive	Rooms 21, 23, 30, 31, attendance office, storage 1&2, room 9, nurse's office, staff lounge	ND	No	300 in. ft	Assumed 1	8
M	Adhesive for blue carpet	Community Liaison, staff lounge and rooms 21 & 23	ND	No	2,000 sq. ft	Assumed 1	8
M	12" fissured ceiling tile	Room 21	ND	No	900 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building S (Rooms 50-53)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Rough plaster	Room 52, 53	ND	No	2,300 sq. ft	None Detected	N/A
S	Acoustical plaster (ceiling)	Rooms 50-53, 52 A&B	ND	No	3,600 sq. ft	Pos	8
S	Stucco	Exterior wall	ND	No	3,000 sq. ft	None Detected	N/A
M	Drywall with joint compound	Rooms 50-53, 52 A&B, women's restroom	ND	No	2,600 sq. ft	None Detected	N/A
S	Smooth plaster	Room 50B, vestibule, 52B	ND	No	500 sq. ft	None Detected	N/A
M	Black sink insulation	Room 52	ND	No	2 sq. ft	None Detected	N/A
M	Grey duct sealant	Room 52B	ND	No	5 sq. ft	None Detected	N/A
M	Window putty	Room 52A, exterior window	ND	No	5 in. ft	None Detected	N/A
M	White sink insulation	Room 50, 52A	ND	No	4 sq. ft	None Detected	N/A
M	2'x4' fissured ceiling panels	Room 52A	ND	Yes	100 sq. ft	None Detected	N/A
M	Adhesive for blue carpet	Rooms 50-53, 52A	ND	No	500 sq. ft	Assumed1	8
M	12" grey speckled floor tile with adhesive	Rooms 50-53	ND	No	3,500 sq. ft	Assumed 1	8
M	4" grey covebase with adhesive	Rooms 50-53, 52A	ND	No	500 in. ft	Assumed 1	8
M	12" fissured ceiling tile	Rooms 50-53	ND	Yes	3,500 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building R (Rooms 16-18)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum board with joint compound	Rooms 16, 17, 18	ND	No	4,000 sq. ft	Pos	8
M	1'x1' rardon pego hole ceiling tile with mastic	Rooms 16, 17, 18	ND	Yes	2,000 sq. ft	None Detected	N/A
M	Stucco	Exterior walls	ND	No	2,200 sq. ft	None Detected	N/A
M	12" grey speckled floor tile with adhesive	Rooms 16, 17, 18	ND	No	2,700 sq. ft	Assumed 1	8
M	4" black cove base with adhesive	Rooms 16, 17, 18	ND	No	360 ln. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;
 ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building Q (Rooms 14-15, 32-34)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Rough plaster	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	ND	No	11,000 sq. ft	None Detected	N/A
S	Acoustical plaster (ceiling)	Room 32-34, waiting room counselor's A, B, C, hallway A, administration office, lobby room, 34A& 34B, principal's office, 14, 15	ND	No	7,500 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	6,000 sq. ft	None Detected	8
M	2'x4' Random pinhole/fissured ceiling tile	Rooms 33-34, 34A, 34B, waiting room, counselor's A, B, C,	ND	Yes	3,600 sq. ft	None Detected	N/A
M	1'x1' random pinhole/ceiling tile with mastic	Room 32, mechanical room 2	ND	No	1,200 sq. ft	None Detected	N/A
M	Drywall with joint compound	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	ND	No	4,500 sq. ft	None Detected	N/A
M	Floor tile with mastic (under 12"grey tile)	Counselor B, hallway A, administration office, copy room, principal's office	ND	No	800 in. ft	None Detected	N/A
M	White sink insulation	Copy room, room 34 A&B	ND	No	6 sq. ft	None Detected	N/A

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building Q (Rooms 14-15, 32-34)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Grey duct sealant	Mechanical room 1 & 2	ND	No	10 sq. ft	None Detected	N/A
M	Blue carpet glue	Room 32-34, waiting room, counselor A, B, C, principal's office	ND	No	3,500 sq. ft	Assumed 1	8
M	12" fissured ceiling tile	Counselor B, hallway A, administration office, copy room, principal's office	ND	Yes	900 sq. ft	Assumed 1	8
M	12"x12" grey speckled floor tile with adhesive	Room 32-34, hallway A, administration office, copy room, 14, 15	ND	No	5,500 sq. ft	Assumed 1	8
M	4" grey cove base with adhesive	Room 32-34, waiting room, counselor A, B, C, hallway A, administration office, copy room, principal's office, 15A, 14, 15	ND	No	500 in. ft	Assumed 1	8
M	2" grey cove base with adhesive	Room 15	ND	No	50 in. ft	Assumed 1	8
M	Transite chalkboards	Rooms 32-34, 14-15	ND	No	100 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building N (Library)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Acoustical plaster ceiling	Library	ND	No	2,200 sq. ft	Pos	8
M	1'x1' peghole row ceiling tile with mastic	Library	ND	Yes	2,200 sq. ft	None Detected	N/A
M	Stucco	Exterior walls	ND	No	3,000 sq. ft	None Detected	N/A
M	Drywall with joint compound	Library, east section, also in room 43, teacher's lounge	ND	No	2,000 sq. ft	Assumed 2	8
M	Brown flooring composite under carpet	Library under carpet	ND	No	1,200 sq. ft	None Detected	N/A
M	White sink insulation	Teacher's lounge, under sink	ND	Yes	4 sq. ft	None Detected	N/A
M	Beige marble pattern linoleum with mastic	Library under carpet	ND	No	1,200 sq. ft	None Detected	N/A
M	12" fissured ceiling tile with mastic	Library, teacher's lounge (under carpet)	ND	Yes	1,200 sq. ft	Assumed 1	8
M	12" light grey floor tile with mastic	Library, northeast, teacher's lounge	ND	No	1,200 sq. ft	Assumed 1	8
M	4" grey cove base with adhesive	Teacher's lounge room 43	ND	No	60 in. ft	Assumed 1	N/A

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building P (Rooms 44-47 & 54-57)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Rough plaster	Room 54-57, 45, 46B	ND	No	4,500 sq. ft	None Detected	N/A
M	Acoustical plaster (ceiling)	Room 54-57, 47, 47A, 45	ND	No	5,000 sq. ft	Pos	8
M	Stucco	Exterior walls	ND	No	9,000 sq. ft	Pos (trace)	8
M	Drywall with joint compound	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45, 50	ND	No	2,750 sq. ft	None Detected	N/A
M	Smooth plaster	Storage 1, room 48, 47, 47A, 48	ND	No	2,000 sq. ft	None Detected	N/A
M	2'x4' fissured ceiling panel	Room 44, 45	ND	Yes	1,500 sq. ft	None Detected	N/A
M	1'x1' random peghole ceiling tile with glue	Room 47B, 44	ND	Yes	900 sq. ft	None Detected	N/A
M	Brown sheet flooring composite	Room 47B,	ND	No	50 sq. ft	None Detected	N/A
M	Duct sealant	Room 47B	ND	No	10 sq. ft	None Detected	N/A
M	Window putty	Exterior windows	ND	No	50 in. ft	None Detected	N/A
M	12" grey speckled floor tile with adhesive	Room 54-57, room 47, room 47A, 45, 46B, 44	ND	No	3,500 sq. ft	Assumed 1	8
M	2" grey cove base with adhesive	Room 45	ND	No	30 in. ft	Assumed 1	8
M	4" grey cove base with adhesive	Room 54-57, 46B, 44	ND	No	200 in. ft	Assumed 1	8
M	6" grey cove base with adhesive	Room 47	ND	No	60 in. ft	Assumed 1	8
M	Chalk boards	Room 54-57, 47, 47A, 45	ND	No	120 sq. ft	Assumed 1	8
M	Blue carpet adhesive	Rooms 54-57	ND	No	2,500 sq. ft	Assumed 1	8
M	12" fissured ceiling tile	Rooms 54-57, 47, 47A	ND	Yes	4,000 sq. ft	Assumed 1	8

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building P (Rooms 44-47 & 54-57)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2'x4' fissured ceiling panel	Room 44	ND	Yes	700 sq. ft	Assumed 1	8
M	12" straight peghole ceiling tile	Room 44A	ND	Yes	100 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;
 ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building L (Room 70-73)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window putty	Exterior windows	ND	No	100 sq. ft	Pos	8
M	Duct tape on HVAC	Rooms 70B and 72B	ND	No	20 sq. ft	None Detected	N/A
M	Drywall with joint compound	Rooms 70-73, 70B, 72B	ND	No	7,000 sq. ft	None Detected	N/A
S	Stucco	Exterior walls	ND	No	3,000 sq. ft	Pos (trace)	8
M	Barrier paper	Exterior walls	ND	No	3,000 sq. ft	None Detected	N/A
M	2'x4' fissured ceiling panel	Room 70, 71, 72, 73	ND	Yes	3,600 sq. ft	None Detected	N/A
M	12" grey with streaks floor tile with adhesive with black residual mastic	Room 70, 71, 72, 73	ND	No	3,600 sq. ft	None Detected	N/A
M	White duct sealant	Room 70B, 72B	ND	No	20 sq. ft	None Detected	N/A
M	Black counter top	Room 70-73 counter tops	ND	No	200 sq. ft	None Detected	N/A
M	2" gray cove base with adhesive	Room 70-73	ND	No	250 in. ft	Assumed 1	8
M	6" gray cove with adhesive	Room 70-73	ND	No	250 in. ft	Assumed 1	8
M	Chalk boards	Room 70-73	ND	No	100 sq. ft	Assumed 1	8
M	Smooth plaster (walls)	Room 72B	ND	No	100 sq. ft	None Detected	N/A
M	1'x1' peghole ceiling tile	Above drop ceiling rooms 73, 72, 71, 70	ND	Yes	3,000 sq. ft	None Detected	N/A
M	Rough textured plaster	Room 74	ND	No	100 sq. ft	Assumed 1	8

NOTE: Room 75 Electrical Room not accessible.

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1-8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building K (Auditorium)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	1'x1' peghole rows ceiling tile with mastic	Room 25	ND	Yes	900 sq. ft	None Detected	N/A
S	Acoustical plaster (wall ceiling)	Room 25, auditorium, auditorium northwest exit, storage east, also in lobby ceiling, auditorium ceiling and hallway ceiling	ND	No	6,000 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	6,500 sq. ft	None Detected	N/A
S	Rough plaster	Hallway, janitor's closet 1, men's restroom, women's restroom, storage, janitor's closet 3, ticket booth, stage east & west, mezzanine, auditorium's exits.	ND	No	3,500 sq. ft	None Detected	N/A
S	Smooth plaster	Room 25, restrooms 1 & 2, auditorium, lobby, men's restroom & women's restroom	ND	No	3,000 sq. ft	None Detected	N/A
M	Drywall with joint compound	Stage area east and west	ND	No	300 sq. ft	None Detected	N/A
M	12" random peghole ceiling tile	Auditorium south wall	ND	Yes	150 sq. ft	None Detected	N/A
M	White vibration reducer (cloth type)	Mezzanine level HVAC units	ND	No	10 sq. ft	None Detected	N/A
M	Window putty	Exterior window frames at stage area, east	ND	No	10 sq. ft	Pos	8
M	12" grey speckled floor tile with adhesive	Room 25, lobby, storage, janitor's closet 3, ticket booth	ND	No	1,000 sq. ft	Assumed 1	8

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building K (Auditorium)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2" grey cove base with adhesive	Auditorium at northeast & northwest	ND	No	50 ln. ft	Assumed 1	8
M	Wood flooring	Stage, hallway, janitor's closet 1, auditorium, mezzanine level	ND	No	2,000 sq. ft	Assumed 1	8
M	Gray carpet glue	Auditorium	ND	No	2,000 sq. ft	Assumed 1	8
M	Blue carpet glue	Room 25	ND	No	90 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;
 ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building J (Room 26-27)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth plaster	Staff restrooms and room 26 A	ND	No	400 sq. ft	Pos	8
M	Gypsum board with joint compound	Room 26; 26B-5; 27 A-C (walls and ceilings)	ND	No	3,200 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	3,000 sq. ft	Pos	8
M	Duct tape on HVAC	HVAC unit ducting	ND	No	20 sq. ft	None Detected	N/A
M	6" grey cove base with adhesive	Room 26, 26D-J, 27, 27B, 27C	ND	No	300 ln. ft	Assumed 1	8
M	12"x12" grey speckled floor tile with adhesive	Room 27, 27B, 27C	ND	No	900 sq. ft	Assumed 1	8
M	Adhesive for blue carpet	Room 26, 26D-26J	ND	No	900 sq. ft	Assumed 1	8
M	1'x1' fissured ceiling tile	Room 26, 27	ND	No	500 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building H (Room 80-81)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum board with joint compound	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	ND	No	5,200 sq. ft	None Detected	N/A
M	12"12" gray speckled floor tile with adhesive with black mastic	C1, C8, C8A, C7, C5, C4, C2, C3A, C3	ND	No	3,000 sq. ft	None Detected	N/A
M	2'x4' fissured ceiling panel	C1, C2, C3A	ND	Yes	800 sq. ft	None Detected	N/A
M	Black sink insulation	C7, C6 (on sink under coating)	ND	No	4 sq. ft	None Detected	N/A
M	Window putty	Exterior windows	ND	No	300 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	3,800 sq. ft	Pos	8
M	6" gray cove base with adhesive	Rooms C1, C8, C8A, C7, C5, C4, C2, C3, C3A	ND	No	300 ln. ft	None Detected	N/A
M	Duct sealant	Room 66	ND	No	20 ln. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building G (Rooms 82-83)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window Putty	Exterior windows	ND	No	300 In. ft	Pos	8
S	Smooth plaster	Room 81	ND	No	300 sq. ft	None Detected	N/A
T.S.I.	Pipe insulation	Room 82 and 83 along east wall	ND	Yes	80 In. ft	Pos	8
T.S.I.	Pipe fitting insulation	Room 82 along east wall	ND	Yes	6 fittings	None Detected	N/A
M	Sink under coating	Room 82 at sinks	ND	No	10 sq. ft	Pos	8
M	Drywall with joint compoung	Room 82, heater closets and at entry ways	ND	No	600 sq. ft	None Detected	N/A
S	Smooth plaster	Room 81	ND	No	300 sq. ft	None Detected	N/A
M	12"x12" straight peghole ceiling tile	Room 82, 83, 83A	ND	Yes	2,500 sq. ft	None Detected	N/A
M	12"x12" gray speckled floor tile with adhesive	Room 82, 83, 83A	ND	No	3,000 sq. ft	None Detected	N/A
M	2" gray cove base with adhesive	Room 82, 83, 83A	ND	No	120 In. ft	None Detected	N/A
M	6" gray cove base with adhesive	Room 82, 83, 83A	ND	No	100 In. ft	None Detected	N/A
M	Asbestos containing cement panel	Room 82 at northwest desk	ND	No	10 sq. ft	Assumed1	8
M	Chalkboards	Room 82, 83	ND	No	40 sq. ft	Assumed1	8
S	Stucco	Exterior walls	ND	No	3,500 sq. ft	Pos	8
M	4" gray cove base with adhesive	Room 82, 83, 83A	ND	No	150 In. ft	Assumed1	8

NOTE: Room 80 not accessible.

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building F (Room 84-86)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth plaster	Restroom walls and ceiling	ND	No	600 sq. ft	None Detected	N/A
S	Stucco	Exterior walls	ND	No	3,500 sq. ft	Pos	8
M	Drywall with joint compound	Room 84, 85, 86, at heater closets and by entry way	ND	No	950 sq. ft	None Detected	N/A
M	12"x12" random peghole ceiling tile	Room 84, 85, 86 walls and ceilings	ND	No	3,200 sq. ft	None Detected	N/A
M	12"x12" gray speckled floor tile with adhesive	Room 84, 85, 86	ND	No	2,700 sq. ft	None Detected	N/A
M	4" gray cove base with adhesive	Room 84, 85, 86	ND	No	150 In. ft	None Detected	N/A
M	6" gray cove base with adhesive	Room 84, 85, 86	ND	No	300 In. ft	None Detected	N/A
M	Chalkboards	Room 84, 85, 86	ND	No	40 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building E (Room 87-89)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window putty	Exterior windows	ND	No	300 In. ft	Pos	8
M	1'x1' peghole rows ceiling tile	Room 87, 88, 89, wall and ceiling	ND	No	3,200 sq. ft	None Detected	N/A
S	Smooth plaster	At restroom walls and ceiling	ND	No	600 sq. ft	None Detected	N/A
M	Drywall with joint compound	Room 87, 88, 89, at heater closet and by entry ways	ND	No	950 sq. ft	None Detected	N/A
M	12"x12" gray speckled floor tile with adhesive	Room 87, 88, 89	ND	No	2,700 sq. ft	None Detected	N/A
M	6" gray cove base with adhesive	Room 87, 88, 89	ND	No	300 In. ft	None Detected	N/A
S	Stucco	Exterior walls	ND	No	3,500 sq. ft	Pos	8
M	4" gray cove base with adhesive	Room 87, 88, 89	ND	No	100 In. ft	None Detected	N/A
M	Chalkboards	Room 87, 88, 89	ND	No	40 sq. ft	Assumed 1	N/A
M	Corkboards	Room 87, 88, 89	ND	No	40 sq. ft	Assumed 1	N/A

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing; ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building D (Room 90-91)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window putty	Exterior windows	ND	No	200 in. ft	Pos	8
M	Smooth plaster	Room 90B, 90A	ND	No	700 sq. ft	None Detected	N/A
M	Drywall with joint compound	Room 90 and 91, at entry way and heater closets	ND	No	500 sq. ft	None Detected	N/A
M	Button board	Room 90A&B under plaster	ND	No	200 sq. ft	None Detected	N/A
M	12 straight peghole ceiling tile (nailed in type)	Room 90 and 91 walls and ceiling	ND	Y	2,200 sq. ft	None Detected	N/A
M	12" gray speckled floor tile with adhesive	Room 90 and 91	ND	No	1,800 sq. ft	None Detected	N/A
M	6" gray cove base with adhesive	Room 90 and 91	ND	No	240 in. ft	None Detected	N/A
S	Stucco	Exterior walls	ND	No	2,000 sq. ft	Pos	8
M	4" gray cove base with adhesive	Room 90 and 91	ND	No	80 in. ft	None Detected	N/A
M	Chalkboards	Room 90 and 91	ND	No	40 sq. ft	Assumed 1	8
M	Chalkboard mastic	Room 90 and 91	ND	No	40 sq. ft	Assumed 1	8

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building C (Gym Building)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth plaster	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	ND	Yes	10,000 sq. ft	None Detected	N/A
M	1'x1' peghole rows ceiling tile with mastic	Not observed as previously stated	ND	Yes	900 sq. ft	None Detected	N/A
S	Rough plaster	Room 114, 113, 111, hallway D, boys locker room, mech room, 118, 101	ND	No	4,000 sq. ft	None Detected	N/A
M	1'x1' grooved ceiling tile with mastic	Room 102, 114, 113	ND	No	500 sq. ft	None Detected	N/A
M	Acoustical plaster ceiling	Room 114	ND	No	600 sq. ft	Pos	8
M	9" tan with brown streaks floor tile with mastic	Room 111 (under tile)	ND	No	220 sq. ft	Pos	8
M	9" brown and dark brown streaks floor tile with mastic	Room 114, 113 (under tile)	ND	No	150 sq. ft	Pos	8
M	9" off white with green streak floor tile with mastic	Room 106, 102, lounge (under tile)	ND	No	650 sq. ft	Pos	8
S	Stucco	Exterior walls	ND	No	12,000 sq. ft	None Detected	N/A
M	Drywall with joint compound	Room 116	ND	No	250 sq. ft	None Detected	N/A

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building C (Gym Building)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	12" gray speckled floor tile with mastic	Room 102, lounge, 114, 113, equipment room, 116	ND	No	500 sq. ft	None Detected	N/A
M	2" gray cove base with adhesive	Room 102, lounge, 114, 113, boys equipment room, 116	ND	No	200 In. ft.	None Detected	N/A
M	4" green cove base with adhesive	Room 106	ND	No	20 In. ft.	None Detected	N/A
M	4" pink cove base with adhesive	Girls equipment room	ND	No	80 In. ft.	None Detected	N/A
M	Window putty	Exterior window frames at north center entry to girls locker area	ND	No	10 In. ft.	None Detected	N/A
M	Cementitious bench panels	Girls locker area, handicap shower bench	ND	No	5 sq. ft	None Detected	N/A
M	Chalkboard mastic	Hallway A	ND	No	10 sq. ft	None Detected	N/A

NOTE: Room 109, 109A, 108 and 103 not accessible.

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building B (Cafeteria)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2'x4' random pinhole and groove ceiling tile	Eating area 1 (ceiling, staff dining room)	ND	Yes	2,000 sq. ft	None Detected	N/A
M	1'x1' random large and small peghole ceiling tile	Serving area, kitchen, eating area 2	ND	Yes	1,200 sq. ft	None Detected	N/A
M	1'x1' random large and small peghole ceiling tile with mastic	Serving area, kitchen, eating area 2	ND	No	1,200 sq. ft	Pos	8
S	Rough plaster ceiling	Men and women's restroom, hallway west	ND	No	500 sq. ft	None Detected	N/A
S	Smooth plaster	Eating area 1, 2, serving area, staff dining, kitchen, storage 2, hallway east and west	ND	No	4,500 sq. ft	None Detected	N/A
S	Stucco	Exterior walls	ND	No	7,200 sq. ft	None Detected	N/A
M	Drywall with joint compound	Eating area 1, kitchen	ND	No	3,500 sq. ft	None Detected	N/A
M	12" gray speckled floor tile with adhesive	Eating area 1, staff dining, hallway west	ND	No	2,800 sq. ft	None Detected	N/A
M	4" gray cove base with adhesive	Eating area 1, staff dining, hallway west	ND	No	200 in. ft.	None Detected	N/A
S	Blue flooring composite	Eating area 2, serving area, kitchen	ND	No	2,000 sq. ft	None Detected	N/A
M	Window putty	Eating area 1, perimeter window frames	ND	No	200 in. ft.	None Detected	N/A
M	Cementitious wall panel	Eating area 1, east wall on drywall	ND	No	150 sq. ft	None Detected	N/A
M	Cement asbestos access panels (2'x4')	Hallway west and east ceiling	ND	No	2 panels	Assumed 1	8

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building B (Cafeteria)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Button board	Under smooth and rough plaster walls, men's and women's restrooms, hallway east and west, eating area 1 and 2, serving area, staff dining room, kitchen, storage 2	ND	No	5,000 sq. ft	Assumed 1	8
M	Freezer insulation (encased in metal)	Freezer	ND	No	200 sq. ft	Assumed 1	8

NOTE: Pantry, freezer, snack bar, office 1 & 2 not accessible.

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;
 ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building A (Room 92-100)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth plaster	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B	ND	No	2,500 sq. ft	None Detected	N/A
S	Rough plaster	Room 93A, janitor's closet, heater closet	ND	No	300 sq. ft	Pos	8
M	Gypsum board with joint compound	Under 12"x12" random peghole ceiling tile : storage 2, room 93, 94, 95, 96, 97, 98, 98A, 99, 100, 94A, 94B, 94C, 93B	ND	No	7,000 sq. ft	Pos	8
M	12" dark brown floor tile with mastic	Room 98, 98A, 98D (under 12"x12" gray speckled floor tile)	ND	No	1,000 sq. ft	None Detected	N/A
M	9" gray with black streaks floor tile with mastic	Room 98C	ND	No	100 sq. ft	Pos	8
T.S.I.	Hard pipe fitting insulation	Room 95	ND	Yes	2 fittings	Pos	8
M	1'x1' random peghole ceiling tile	Walls and ceilings : rooms 93, 94, 95, 96, 97, 98, 98A, 99, 100, 94A, 94B, 94C, 93B	ND	Yes	9,000 sq. ft	None Detected	N/A
T.S.I.	Pipe insulation	Room 95	ND	Yes	5 in. ft.	Pos	8
S	Stucco	Exterior walls	ND	No	5,500 sq. ft	Pos (trace)	8
M	Button board	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B (under smooth wall plaster)	ND	No	2,500 sq. ft	None Detected	N/A
M	Drywall with joint compound	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	ND	No	4,500 sq. ft	None Detected	N/A

Client: Santa Monica-Malibu Unified School District
Project No.: 110-0006
Project Name: AHERA 3-year re-inspection-John Adams Middle School

Building A (Room 92-100)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	12" gray speckled floor tile with adhesive with black residual mastic	Room 92, 93, 94, 95, 96, 96B, 97, 98, 98D, 98A, 94, 100, 100C, 94A, 94B, 94C, 93B, 93C, 93D	ND	No	8,000 sq. ft	Assumed 2	8
M	Blue carpet glue with black residual mastic	Room 92, storage 2, room 100, 100C	ND	No	1,500 sq. ft	Pos	8
M	Gray carpet glue	Room 95	ND	No	1,000 sq. ft	None Detected	N/A
M	2" gray cove base with adhesive	Room 93, 96, 97, 96B, 98, 98A, 99, 93B, 93C, 93D	ND	No	300 in. ft.	None Detected	N/A
M	4" black cove base with adhesive	Room 95	ND	No	120 in. ft.	None Detected	N/A
M	6" gray cove base with adhesive	Room 93, 96, 97, 96B, 98, 98A, 99, 93B, 93C, 93D	ND	No	300 in. ft.	None Detected	N/A
M	Gray duct sealant	At all heater closets on HVAC units	ND	No	20 sq. ft	None Detected	N/A
M	Chalk boards	All classrooms	ND	No	400 sq. ft	Assumed 1	8
M	Window putty	Exterior windows	ND	No	200 in. ft.	Pos	8
M	Wood floor mastic	Room storage 1, work room, all heater closets	ND	No	400 sq. ft	Assumed 1	8

NOTE: New building (Boys & Girls Club) constructed at south end of building encompassing what used to be Room 100.

(1) S: surfacing, TSI: thermal system insulation, M: miscellaneous

(2) ND: not damaged, D: damaged, SD: significantly damaged

(3) POS: previously identified as positive, NEG: previously identified as negative, ASSUMED 1 = new material, not sampled, assumed asbestos-containing;

ASSUMED 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

Appendix B

Previous Inspection Report

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building A (Rooms 92-100)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	JAA-01-01 JAA-01-02	None detected	Previously sampled (Cape Env. 1992)	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B	2,500 sq. ft.	No	No
Smooth plaster	5524	None detected	Room 96B, north wall center	Room 92, storage 1, walk room, 96b, room 98D, 98C, 94B	2,500 sq. ft.	No	No
Smooth plaster	5525	None detected	Room 98C, southwest corner	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B	2,500 sq. ft.	No	No
Smooth plaster	5526	None detected	Room 92, storage 1, east wall center	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B	2,500 sq. ft.	No	No
Rough plaster	JAA-02-01 JAA-02-02	2% Chrysotile	Previously sampled (Cape Env. 1992)	Room 93A, janitor's closet, heater closet	300 sq. ft.	No	No
Gypsum board with joint compound	JAA-03-01 through JAA-03-03	None detected - 3% Chrysotile	Previously sampled (Cape Env. 1992)	Under 12"x12" random peghole ceiling tile : storage 2, room:93, 94, 95, 96, 97, 98, 98A, 99, 100, 94A, 94B, 94C, 93B	8,000 sq. ft.	No	No
9"x9" light green with dark green streaks floor tile with mastic	JAA-04-01	2% Chrysotile (tile) 8% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Room 100A, 100B <i>Removed</i>	200 sq. ft.	No	No
12"x12" dark brown floor tile with mastic	JAA-05-01 through JAA-05-03	None detected (tile and mastic)	Previously sampled (Cape Env. 1992)	Room 98, 98A, 98D (under 12"x12" gray speckled floor tile)	1,000 sq. ft.	No	No
9" gray with black streaks floor tile with mastic	JAA-06-01	5% Chrysotile (tile) None detected (mastic)	Previously sampled (Cape Env. 1992)	Room 98C	100 sq. ft.	No	No
Hard pipe fitting insulation	JAA-07-01 JAA-07-02	20% Chrysotile	Previously sampled (Cape Env. 1992)	Room 95, 100	2 fitting	No	No
1'x1' random peghole ceiling tile	JAA-08-01 A& B	None detected	Previously sampled (Cape Env. 1992)	Walls and ceilings : rooms 93, 94, 95, 96, 97, 98, 98A, 99, 100, 94A, 94B, 94C, 93B	10,000 sq. ft.	No	No
Pipe insulation	JAA-11-01 JAA-11-02	None detected	Previously sampled (Cape Env. 1992)	Room 95, 100	10 ln. ft.	No	No
Stucco	JAA-10-01	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	5,500 sq. ft.	No	No
Stucco	5518	<1% Chrysotile	Exterior, room 92 southwest corner	Exterior walls	5,500 sq. ft.	No	No

Removed from 100

MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Page 2 of 3

Building A (Rooms 92-100)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Stucco	5519	<1% Chrysotile	Exterior, south wall center	Exterior walls	5,500 sq. ft.	No	No
Stucco	5520	<1% Chrysotile	Exterior, room 93 northwest corner	Exterior walls	5,500 sq. ft.	No	No
Stucco	5521	<1% Chrysotile	Exterior, southeast corner	Exterior walls	5,500 sq. ft.	No	No
Stucco	5522	<1% Chrysotile	Exterior, room 99 northwest corner	Exterior walls	5,500 sq. ft.	No	No
Stucco	5523	<1% Chrysotile	Exterior, between room 99 and 100, north center	Exterior walls	5,500 sq. ft.	No	No
Button board	5527	None detected	Room 92, storage 1, east wall center	Room 92, storage 1, work room, 96B, room 98D, 98C, 94B (under smooth wall plaster)	2,500 sq. ft.	No	No
Joint compound	5528	None detected	Room 92, storage 3, northwest corner	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Joint compound	5529	None detected	Room 95, southwest corner	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Joint compound	5530	None detected	Room 99, heater closet, northwest corner	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Joint compound	5531	None detected	Room 97, southeast corner	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Joint compound	5532	None detected	Room 96, southwest corner	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Drywall	5533	None detected	Room 92, storage 3, northwest	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
Composite drywall with joint compound	5534	None detected	Room 98, heater closet, northeast	Heater closet and dividing walls in rooms 92, 93, 94, 95, 96, 97, 98, 99, 100	4,500 sq. ft.	No	No
12"x12" gray speckled floor tile with adhesive with black residual mastic	5535	None detected	Room 97, southeast corner	Room 92, 93, 94, 95, 96, 96B, 97, 98, 98D, 98A, 94, 100, 100C, 94A, 94B, 94C, 93B, 93C, 93D	8,000 sq. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building A (Rooms 92-100)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Blue carpet glue with black residual mastic	5536	3% Chrysotile	Room 97, northeast corner	Room 92, storage 2, room 100 100C	2,500 sq. ft. ³³	No	No
Gray carpet glue	5537	None detected	Room 95, north center	Room 95	1,000 sq. ft.	No	No
2" gray cove base with adhesive	5538	None detected	Room 96, southeast corner	Room 93, 96, 97, 96B, 98, 98A, 99, 93B, 93C, 93D	300 ln. ft.	No	No
4" black cove base with adhesive	5539	None detected	Room 95, southeast corner	Room 95	120 ln. ft.	No	No
6" gray cove base with adhesive	5540	None detected	Room 96, southeast corner	Room 93, 96, 97, 96B, 98, 98A, 99, 93B, 93C, 93D	300 ln. ft.	No	No
Gray duct sealant	5541	None detected	Room 97, heater closet, south center	At all heater closets on HVAC units	20 sq. ft.	No	No
Chalk boards	N/A	Assumed	No sample collected	All classrooms	400 sq. ft.	No	No
Window putty	JAD-01-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	200 ln. ft.	No	No
Carpet and wood flooring, mastic	N/A	Assumed	No sample collected	Room storage 1, work room, all heater closets	400 sq. ft.	No	No

NOTES:

*The materials shall be sampled prior to disturbance during construction.
 Roof was not inspected.

*Rm 100 - 1 record attached to Boys - & Girls club.
 New construction ~~left~~ of ACM Record*

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 107-0008
PROJECT NAME: John Adams Middle School

Building B (Cafeteria)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
2'x4' random pinhole and groove ceiling tile	JAB-02-01 through JAB-02-03	None detected	Previously sampled (Cape Env. 1992)	Eating area 1 (ceiling, staff dining room)	2,000 sq. ft.	No	No
1'x1' random large and small peghole ceiling tile with mastic	JAB-04-01A through JAB-04-01B	None detected (tile) 2% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Serving area, kitchen, eating area 2	1,200 sq. ft.	Yes	No
Rough plaster ceiling	JAB-05-01 through JAB-05-03	None detected	Previously sampled (Cape Env. 1992)	Men and women's restroom, hallway west	500 sq. ft.	No	No
Smooth plaster	JAB-06-01 through JAB-06-02	None detected	Previously sampled (Cape Env. 1992)	Eating area 1, 2, serving area, staff dining, kitchen, storage 2, hallway east and west	4,500 sq. ft.	No	No
Smooth plaster	5548	None detected	Kitchen, north wall center	Eating area 1, 2, serving area, staff dining, kitchen, storage 2, hallway east and west	4,500 sq. ft.	No	No
Smooth plaster	5549	None detected	Hallway, at entry to snack bar	Eating area 1, 2, serving area, staff dining, kitchen, storage 2, hallway east and west	4,500 sq. ft.	No	No
Smooth plaster	5550	None detected	Serving area, north wall center	Eating area 1, 2, serving area, staff dining, kitchen, storage 2, hallway east and west	4,500 sq. ft.	No	No
Stucco	5542	None detected	Exterior, eating area, southeast corner	Exterior walls	7,200 sq. ft.	No	No
Stucco	5543	None detected	Exterior, women's restroom, northwest corner	Exterior walls	7,200 sq. ft.	No	No
Stucco	5544	None detected	Exterior, storage 2 northeast corner	Exterior walls	7,200 sq. ft.	No	No
Stucco	5545	None detected	Exterior, eating area by northeast entry	Exterior walls	7,200 sq. ft.	No	No
Stucco	5546	None detected	Exterior, eating area by northwest entry	Exterior walls	7,200 sq. ft.	No	No
Stucco	5547	None detected	Exterior, kitchen north center wall	Exterior walls	7,200 sq. ft.	No	No
Joint compound	5551	None detected	Eating area, southwest corner	Eating area 1, kitchen	3,500 sq. ft.	No	No
Joint compound	5552	None detected	Eating area, at northwest entry	Eating area 1, kitchen	3,500 sq. ft.	No	No
Joint compound	5553	None detected	Kitchen, northwest corner on column	Eating area 1, kitchen	3,500 sq. ft.	No	No

MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 107-0008
 PROJECT NAME: John Adams Middle School

Page 2 of 3

Building B (Cafeteria)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Joint compound	5554	None detected	Eating area, at southeast entry	Eating area 1, kitchen	3,500 sq. ft.	No	No
Joint compound	5555	None detected	Eating area, northeast corner	Eating area 1, kitchen	3,500 sq. ft.	No	No
Drywall	5556	None detected	Eating area, 15' south of northeast entry	Eating area 1, kitchen	3,500 sq. ft.	No	No
Composite drywall with joint compound	5557	None detected	Eating area, 15' south of northeast entry	Eating area 1, kitchen	3,500 sq. ft.	No	No
12"x12" gray speckled floor tile with adhesive	5558	None detected	Eating area, north center	Eating area 1, staff dining, hallway west	2,800 sq. ft.	No	No
4" gray cove base with adhesive	5559	None detected	Eating area, at southeast entry	Eating area 1, staff dining, hallway west	200 ln. ft.	No	No
Blue flooring composite	5560	None detected	Eating area 2, floor center	Eating area 2, serving area, kitchen	2,000 sq. ft.	No	No
Window putty	5561	None detected	Exterior, eating room northwest corner	Eating area 1, perimeter window frames	200 ln. ft.	No	No
Cementitious wall panel	5562	None detected	Eating area, east wall center	Eating area 1, east wall on drywall	150 sq. ft.	No	No
Cement asbestos access panels (2'x4')*	N/A	Assumed	Not sampled to avoid damage	Hallway west and east ceiling	2 panels	No	No
Button board*	N/A	Assumed	Not sampled to avoid damage	Under smooth and rough plaster walls, men's and women's restrooms, hallway east and west, eating area 1 and 2, serving area, staff dining room, kitchen, storage 2	5,000 sq. ft.	No	No
Freezer insulation *(encased in metal)	N/A	Assumed	Not sampled to avoid damage	Freezer	200 sq. ft.	No	No
9"x9" red floor tile with mastic	JAB-01-01	3% Chrysotile (tile) 2% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
1'x1' large and small peghole ceiling tile with mastic	JAB-03-01A JAB-03-01B	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Hot water tank insulation	JAB-10-01	3% Chrysotile 25% Amosite 20% Crocidolite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Hard pipe insulation	JAB-11-01	20% Chrysotile 30% Amosite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Hard pipe insulation fitting	JAB-12-01	3% Chrysotile 20% Amosite 25% Crocidolite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 107-0008
PROJECT NAME: John Adams Middle School

Building B (Cafeteria)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Duct insulation	JAB-13-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Soft pipe insulation	JAB-14-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Boiler flue insulation	JAB-15-01	60% Chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No
Furnace flue insulation	JAB-16-01	60% Chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	No	No

NOTES:

*The materials should be sampled prior to disturbance during construction
 Roof was not inspected.

*Not Accessible - Laundry - Freezer
 Sank Be above 1, 2*



CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	JAC-01-01 through JAC-01-03	None detected	Previously sampled (Cape Env. 1992)	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	6,500 sq. ft.	No	No
Smooth plaster	5570	None detected	Room 104, northeast corner	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	10,000 sq. ft.	No	No

R-109-109A, 108 - Not Accessible
 103, storage

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	5571	None detected	Room 106, northwest corner	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	10,000 sq. ft.	No	No
Smooth plaster	5572	None detected	Girls locker room, northwest corner	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	10,000 sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	5573	None detected	Boys shower, west wall center	Girls locker room, girls showers and restroom, equipment area, 106, hallway A, women's restroom, 102, lounge, 104, Hallway B, basketball court, hallway C, restroom 2, storage, boys equipment room, boys shower	10,000 sq. ft.	No	No
1'x1' random peghole ceiling tile with mastic	JAC-02-01 A JAC-02-01 B	None detected	Previously sampled (Cape Env. 1992)	Not observed as previously stated	NA sq. ft.	No	No
1'x1' peghole rows ceiling tile with mastic	JAC-03-01 A JAC-03-01 B	None detected	Previously sampled (Cape Env. 1992)	Not observed as previously stated	NA sq. ft.	No	No
Rough plaster	JAC-04-01 through JAC-04-03	None detected	Previously sampled (Cape Env. 1992)	Room 114, 113, 111, hallway D, boys locker room, mech room, 118, 101	4,000 sq. ft.	No	No
Rough plaster	5574	None detected	Room 114, south wall center	Room 114, 113, 111, hallway D, boys locker room, mech room, 118, 101	4,000 sq. ft.	No	No
Rough plaster	5575	None detected	Boys locker, northwest corner	Room 114, 113, 111, hallway D, boys locker room, mech room, 118, 101	4,000 sq. ft.	No	No
1'x1' grooved ceiling tile with mastic	JAC-05-01 A JAC-05-01 B	None detected (tile and mastic)	Previously sampled (Cape Env. 1992)	Room 102, 114, 113	500 sq. ft.	No	No
Acoustical plaster ceiling	JAC-07-01	3% Chrysotile	Previously sampled (Cape Env. 1992)	Room 114	120 sq. ft.	No	No

106

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
9"x9" tan with brown streaks floor tile with mastic	JAC-11-01	5% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Room 111	220 sq. ft.	No	No
9"x9" brown and dark brown streaks floor tile with mastic	JAC-12-01	5% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Room 114, 113 <i>w/d tile</i>	150 sq. ft.	No	No
9"x9" off white with green streak floor tile with mastic	JAC-13-01	2% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Room 106, 102, lounge <i>w/d tile</i>	650 sq. ft.	No	No
Stucco	5563	None detected	Exterior, basketball court, east center	Exterior walls	12,000 sq. ft.	No	No
Stucco	5564	None detected	Exterior, west center by entry to hallway B	Exterior walls	12,000 sq. ft.	No	No
Stucco	5565	None detected	Exterior, girls locker room, north center	Exterior walls	12,000 sq. ft.	No	No
Stucco	5566	None detected	Exterior, boys locker room, southeast corner	Exterior walls	12,000 sq. ft.	No	No
Stucco	5567	None detected	Exterior, room 118, southwest corner	Exterior walls	12,000 sq. ft.	No	No
Stucco	5568	None detected	Exterior, room 106, northwest	Exterior walls	12,000 sq. ft.	No	No
Stucco	5569	None detected	Exterior, by hallway C, west entry	Exterior walls	12,000 sq. ft.	No	No
Texture coating	5576	None detected	Boys locker, north center	Boys locker (on rough plaster walls and ceiling)	1,000 sq. ft.	No	No
Texture coating	5577	None detected	Boys locker, southwest corner	Boys locker (on rough plaster walls and ceiling)	1,000 sq. ft.	No	No
Texture coating	5578	None detected	Boys locker, east wall center	Boys locker (on rough plaster walls and ceiling)	1,000 sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Joint compound	5579	None detected	Room 116, northeast corner	Room 116	250 sq. ft.	No	No
Joint compound	5580	None detected	Room 116, northwest corner	Room 116	250 sq. ft.	No	No
Joint compound	5581	None detected	Room 116, southwest corner	Room 116	250 sq. ft.	No	No
Drywall	5582	None detected	Room 116, west wall center	Room 116	250 sq. ft.	No	No
Composite drywall with joint compound	5583	None detected	Room 116, southwest corner	Room 116	250 sq. ft.	No	No
12" gray speckled floor tile with mastic	5584	None detected	Lounge, northwest corner	Room 102, lounge, 114, 113, equipment room, 116	500 sq. ft.	No	No
2" gray cove base with adhesive	5585	None detected	Room 102, by restroom	Room 102, lounge, 114, 113, boys equipment room, 116	200 ln. ft.	No	No
4" green cove base with adhesive	5586	None detected	Room 106, west wall center	Room 106	20 ln. ft.	No	No
4" pink cove base with adhesive	5587	None detected	Girls locker, equipment area, northeast	Girls equipment room	80 ln. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building C (Gym Building)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Window putty	5588	None detected	Exterior girls locker area, north center entry	Exterior window frames at north center entry to girls locker area	10 ln. ft.	No	No
Cementitious bench panels	5589	None detected	Girls locker area, shower for handicap, bench	Girls locker area, handicap shower bench	5 sq. ft.	No	No
Chalkboard mastic*	N/A	Assumed	Not sampled to avoid damage	Hallway A	10 sq. ft.	No	No
1'x1' random pinhole ceiling tile with mastic	JAC-08-01 A JAC-08-01 B	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Tank insulation	JAC-09-01	20% Chrysotile 30% Amosite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Pipe fitting insulation	JAC-10-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Tank insulation	JAC-14-01	20% Chrysotile 2% Amosite 25% Crocidolite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Tank insulation	JAC-14-02	25% Chrysotile <1% Amosite 25% Crocidolite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Hard pipe insulation	JAC-15-01	35% Chrysotile 15% Crocidolite	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction.
 Roof was not inspected.

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building F (Room 84-86)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	JAD-06-01	None detected	Previously sampled (Cape Env. 1992)	Restroom walls and ceiling	600 sq. ft.	No	No
Smooth plaster	5615	None detected	Restroom, northeast corner	Restroom walls and ceiling	600 sq. ft.	No	No
Smooth plaster	5616	None detected	Restroom, southeast corner	Restroom walls and ceiling	600 sq. ft.	No	No
Stucco	JAD-13-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls, ceiling	3,500 sq. ft.	No	No
Joint compound	5610	None detected	Room 84, southeast by entry	Room 84, 85, 86, at heater closets and by entry way	950 sq. ft.	No	No
Joint compound	5611	None detected	Room 85, heater closet northeast corner	Room 84, 85, 86, at heater closets and by entry way	950 sq. ft.	No	No
Joint compound	5612	None detected	Room 86, heater closet northeast corner	Room 84, 85, 86, at heater closets and by entry way	950 sq. ft.	No	No
Drywall	5613	None detected	Room 84, heater closet east wall center	Room 84, 85, 86, at heater closets and by entry way	950 sq. ft.	No	No
Composite drywall with joint compound	5614	None detected	Room 84, heater closet northeast corner	Room 84, 85, 86, at heater closets and by entry way	950 sq. ft.	No	No
12"x12" random peghole ceiling tile	5617	None detected	Room 86, northeast corner	Room 84, 85, 86 walls and ceilings	3200 sq. ft.	Yes	No
12"x12" gray speckled floor tile with adhesive	5618	None detected	Room 86, northwest corner	Room 84, 85, 86	2,700 sq. ft.	No	No
4" gray cove base with adhesive	5619	None detected	Room 85, southeast corner	Room 84, 85, 86	150 ln. ft.	No	No
6" gray cove base with adhesive	5620	None detected	Room 84, northeast corner	Room 84, 85, 86.	300 ln. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage	Room 84, 85, 86	40 sq. ft.	No	No
9" beige with brown streaks floor tile with mastic	JAD-02-01	5% Chrysotile (tile) None detected (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building G (Rooms 82-83)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Window Putty	JAD-01-03	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	300 ln. ft.	No	No
Smooth plaster	JAD-06-02	None detected	Previously sampled (Cape Env. 1992)	Room 81	300 sq. ft.	No	No
Pipe insulation	JAD-07-01	25% Chrysotile 30% Amosite	Previously sampled (Cape Env. 1992)	Room 82 along east wall	40 ln. ft.	No	No
Pipe fitting insulation	JAD-08-01	None detected	Previously sampled (Cape Env. 1992)	Room 82 along east wall	6 fittings	No	No
Sink under coating	JAD-09-01	20% Chrysotile	Previously sampled (Cape Env. 1992)	Room 82 at sinks	10 sq. ft.	No	No
Joint compound	5621	None detected	Room 82, southeast at entry	Room 82, heater closets and at entry ways	600 sq. ft.	No	No
Joint compound	5622	None detected	Room 82, southeast entry north	Room 82, heater closets and at entry ways	600 sq. ft.	No	No
Joint compound	5623	None detected	Room 83, by southeast center	Room 82, heater closets and at entry ways	600 sq. ft.	No	No
Drywall	5624	None detected	Room 83, southeast by entry	Room 82, heater closets and at entry ways	600 sq. ft.	No	No
Composite drywall with joint compound	5625	None detected	Room 83, southeast by entry	Room 82, heater closets and at entry ways	600 sq. ft.	No	No
Smooth plaster	5626	None detected	Room 81, northeast corner	Room 81	300 sq. ft.	No	No
Smooth plaster	5627	None detected	Room 81, southeast corner	Room 81	300 sq. ft.	No	No
12"x12" straight peghole ceiling tile	5628	None detected	Room 82, northeast corner	Room 82, 83, 83A	2,500 sq. ft.	No	No
12"x12" gray speckled floor tile with adhesive	5629	None detected	Room 83, northeast corner	Room 82, 83, 83A	3,000 sq. ft.	No	No
2" gray cove base with adhesive	5630	None detected	Room 83A, southeast corner	Room 82, 83, 83A	120 ln. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building G (Rooms 82-83)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
6" gray cove base with adhesive	5631	None detected	Room 82, northwest corner	Room 82, 83, 83A	100 ln. ft.	No	No
Asbestos containing cement panel*	N/A	Assumed	N/A	Room 80 at northwest desk 82 S/W	10 sq. ft.	No	No
Chalkboards* Corkboard	N/A	Assumed	Not sampled to avoid damage	Room 82, 83	40 sq. ft.	No	No
Stucco	JAD-13-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls	3,500 sq. ft.	No	No
4" gray cove base with adhesive	Same as #5619	None detected	Building F	Room 82, 83, 83A	150 ln. ft.	No	No
9" beige floor tile with mastic	JAD-04-01	5% Chrysotile (tile) 2% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report 82 walls, 83 and tile, 83A	NA sq. ft.	No	No
12" tan floor tile with mastic	JAD-05-01 through JAD-05-03	2% Chrysotile (tile) 5% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
Boiler flue insulation	JAD-10-01	60% Chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No

NOTES:

Wood walls were predominant in rooms 82 and 83.

Room 83A was not accessible.

*The material shall be sampled prior to disturbance during construction inspected.

R-80 Not Ass -

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building J (Room 26-27)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Smooth plaster	JAJ-01-01 JAJ-01-02	2% Chrysotile	Previously sampled (Cape Env. 1992)	Staff restrooms and room 26 A	400 sq. ft.	No	No
Gypsum board with joint compound	JAJ-02-01 through JAJ-02-03	5% Chrysotile	Previously sampled (Cape Env. 1992)	Room 26; 26B-5; 27 A-C <i>wall & ceiling</i>	3,200 sq. ft.	No	No
12"x12" off white with brown spots floor tile with mastic	JAJ-04-01 through JAJ-04-03	2% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	N/A	N/A
Stucco	JAJ-05-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls	3,000 sq. ft.	No	No
Duct tape on HVAC	JAJ-06-01 through JAJ-04-03	None detected	Previously sampled (Cape Env. 1992)	HVAC unit ducting	20 sq. ft.	No	No
6" grey cove base with adhesive	Same as #5631	None detected	Building G	Room 26, 26D-J, 27, 27B, 27C	300 ln. ft.	No	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Room 27, 27B, 27C	900 sq. ft.	No	No
1'x1' rando pego hole ceiling with mastic	JAJ-03-01 A&B	None detected	Previously sampled (Cape Env. 1992)	Room 26, 26B-5 - 27A-C	1,500 sq. ft.	No	No
1'x1' rando pego hole ceiling with mastic	JAJ-03-01 A&B	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	1,500 sq. ft.	No	No
Blue carpet glue*	N/A	Assumed	Not sampled, material not disturbed	Room 26, 26D-26J	900 sq. ft.	No	No
1'x1' fissured ceiling tile*	N/A	Assumed	Not sampled, material not disturbed	Room 26, 27	500 sq. ft.	No	No

NOTES:

*These materials should be sampled prior to disturbance during construction
Roof was not inspected.

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building K (Auditorium)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	5732	None detected	Stage area-east northeast corner	Hallway, janitor's closet, men's restroom, women's restroom, storage, janitor's closet 3, ticket booth, storage east & west, mezzanine, auditorium's exits.	3,500 ln. ft.	No	No
Smooth plaster	JAK-05-01 JAK-05-02	None detected	Previously sampled (Cape Env. 1993)	Room 25, restrooms 1 & 2, auditorium, lobby, men's restroom & women's restroom	3,000 sq. ft.	N/A	N/A
Smooth plaster	5733	None detected	Room 25, 5' East of Northwest corner	Room 25, restrooms 1 & 2, auditorium, lobby, men's restroom & women's restroom	3,000 sq. ft.	No	No
Smooth plaster	5734	None detected	Auditorium-west wall center	Room 25, restrooms 1 & 2, auditorium, lobby, men's restroom & women's restroom	3,000 sq. ft.	No	No
Smooth plaster	5735	None detected	Auditorium- east wall center	Room 25, restrooms 1 & 2, auditorium, lobby, men's restroom & women's restroom	3,000 sq. ft.	No	No
Joint compound	5736	None detected	Stage area- east wall, north wall west	Stage area east and west	300 sq. ft.	No	No
Joint compound	5737	None detected	Stage area- east, north wall center	Stage area east and west	300 sq. ft.	No	No
Joint compound	5738	None detected	Stage area- east, north wall east	Stage area east and west	300 sq. ft.	No	No
Drywall	5739	None detected	Stage area- east- north wall - center	Stage area east and west	300 sq. ft.	No	No
Composite drywall with joint compound	5740	None detected	Stage area- east-north wall-center	Stage area east and west	300 sq. ft.	No	No
12"x12" randon peghole ceiling tile	5741	None detected	Auditorium- south wall center	Auditorium south wall	150 sq. ft.	No	No
White vibration reducer (cloth type)	5742	None detected	Mezzanine- HVAC unit	Mezzanine level HVAC units	10 sq. ft.	No	No
Window putty	5743	2% Chrysotile	Exterior stage area east, east center window	Exterior window frames at stage area, east	10 sq. ft.	No	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Room 25, lobby, storage, janitor's closet 3, ticket booth	1,000 sq. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building K (Auditorium)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
2" grey cove base with adhesive	5630	None detected	Building G	Auditorium at northeast & northwest	50 ln. ft.	No	No
Grey marble pattern linoleum with mastic	JAK-01-01 through JAK-01-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	N/A	N/A
1'x2' acoustical ceiling tile with mastic	JAK-07-01 A&B	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA	N/A	N/A
Wood flooring*	N/A	Assumed	Not sampled, material not disturbed	Stage, hallway, janitor's closet 1, auditorium, mezzanine level	2,000 sq. ft.	No	No
Gray carpet glue*	N/A	Assumed	Not sampled, material not disturbed	Auditorium	2,000 sq. ft.	No	No
Blue carpet glue*	N/A	Assumed	Not sampled, material not disturbed	Room 25	900 sq. ft.	No	No

NOTES:

*These materials shall be sampled prior to disturbance during construction.

Roof was not inspected.

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building K (Auditorium)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
1'x1' peghole rows ceiling tile with mastic	JAK-03-01 A&B	None detected	Previously sampled (Cape Env. 1992)	Room 25	900 sq. ft.	Yes	No
Acoustical plaster (wall ceiling)	JAK-06-01 through JAK-06-03	2%-7% Chrysotile	Previously sampled (Cape Env. 1992)	Room 25, auditorium, auditorium northwest exit, storage east	2,500 sq. ft. <i>7000</i>	No	No
Stucco	JAK-08-01	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	6,500 sq. ft.	No	No
Stucco	5724	None detected	Exterior- by room 25 southwest corner	Exterior walls	6,500 sq. ft.	No	No
Stucco	5725	None detected	Exterior- auditorium northwest corner	Exterior walls	6,500 sq. ft.	No	No
Stucco	5726	None detected	Exterior- auditorium southwest corner	Exterior walls	6,500 sq. ft.	No	No
Stucco	5727	None detected	Exterior- restroom 2 east wall center	Exterior walls	6,500 sq. ft.	No	No
Stucco	5728	None detected	Exterior- janitor's closet 2-south center	Exterior walls	6,500 sq. ft.	No	No
Stucco	5729	None detected	Exterior- by room 25 northeast corner	Exterior walls	6,500 sq. ft.	No	No
Rough plaster	JAK-04-01 JAK-04-02	None detected	Previously sampled (Cape Env. 1992)	Hallway, janitor's closet 1, men's restroom, women's restroom, storage, janitor's closet 3, ticket booth, stage east & west, mezzanine, auditorium's exits.	3,500 sq. ft.	No	No
Rough plaster	5730	None detected	Hallway north wall center	Hallway, janitor's closet, men's restroom, women's restroom, storage, janitor's closet 3, ticket booth, storage east & west, mezzanine, auditorium's exits.	3,500 sq. ft.	No	No
Rough plaster	5731	None detected	Stage area- west, northwest corner	Hallway, janitor's closet, men's restroom, women's restroom, storage, janitor's closet 3, ticket booth, storage east & west, mezzanine, auditorium's exits.	3,500 sq. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building L (Room 70-73)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Window putty	JAL-07-01	3% chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	100 ¹ / ₂ ln. ft.	No	No
Duct tape on HVAC	JAL-08-01 through JAL-08-03	None detected	Previously sampled (Cape Env. 1992)	Rooms 70B and 72B	20 sq. ft.	No	No
Joint compound	5705	None detected	Room 73 northwest corner	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5706	None detected	Room 70 south wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5707	None detected	Room 70 southwest corner	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5708	None detected	Room 71 south wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5709	None detected	Room 73 south wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5710	None detected	Room 72 south wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Joint compound	5711	None detected	Room 72 south east corner	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Drywall	5712	None detected	Room 70 east wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Composite-drywall with joint compound	5713	None detected	Room 73 south wall center	Rooms 70-73, 70B, 72B	7,000 sq. ft.	No	No
Stucco	JAL-06-01	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	3,000 sq. ft.	N/A	N/A
Stucco	5714	<1% Chrysotile	Exterior by room 72 north	Exterior walls	3,000 sq. ft.	No	No
Stucco	5715	<1% Chrysotile	Exterior northwest corner	Exterior walls	3,000 sq. ft.	No	No
Stucco	5716	<1% Chrysotile	Exterior southeast corner	Exterior walls	3,000 sq. ft.	No	No
Stucco	5717	None detected	Exterior-by room 70B	Exterior walls	3,000 sq. ft.	No	No
Stucco	5718	None detected	Room 75 southwest corner	Exterior walls	3,000 sq. ft.	No	No
Barrier paper	5719	None detected	Room 75 southwest corner	Exterior walls	3,000 sq. ft.	No	No
2'x4' fissured ceiling panel	5720	None detected	Room 70 center	Room 70, 71, 72, 73	3,600 sq. ft.	Yes	No
12"x12" grey with streaks floor tile with adhesive with black residual mastic	5721	None detected	Room 73 northwest corner	Room 70, 71, 72, 73	3,600 sq. ft.	No	No
White duct sealant	5722	None detected	Room 72B, center	Room 70B, 72B	20 sq. ft.	No	No
Black counter top	5723	None detected	Room 70 northwest corner	Room 70-73 counter tops	200 sq. ft.	No	No
2" gray cove base with adhesive	Same as #5630	None detected	Building G	Room 70-73	250 ln. ft.	No	No
6" gray cove with adhesive	Same as #5631	None detected	Building G	Room 70-73	250 ln. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building L (Room 70-73)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Chalk boards*	N/A	Assumed	Not sampled to avoid damage	Room 70-73	100 sq. ft.	No	No
12"x12" tan with white and brown spots floor tile with mastic	JAL-01-01 through JAL-01-03	2% ^{***} Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A sq. ft.	N/A	N/A
Smooth plaster (walls)	JAL-02-01 through JAL-02-02	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report, R-72B	N/A sq. ft.	N/A	N/A
Tectum board	JAL-03-01 through JAL-03-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A sq. ft.	N/A	N/A
Gypsum board (walls and ceiling)	JAL-04-01 through JAL-04-03	3% chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A sq. ft.	N/A	N/A
1'x1' ceiling tile	JAL-05-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A sq. ft.	N/A	N/A

NOTES:

*This material shall be sampled prior to disturbance during construction
 Roof was not inspected.

Rough Textured Plaster - R-74
 R-75 N/A Electrical R. N/A

Perimeter walls

as Metal Pecking
 Address draws
 Com
 R-73, 72

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building N (Library)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Acoustical plaster ceiling	JAN-04-01 JAN-04-02	2% Chrysotile	Previously sampled (Cape Env. 1992)	Library	1,800 sq. ft.	No	No
1'x1' peghole row ceiling tile with mastic	JAN-06-01A JAN-06-01B	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Library	1,800 sq. ft.	Yes	No
Stucco	JAN-12-01	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	300 sq. ft.	No	No
Stucco	5853	None detected	Exterior- northwest center	Exterior walls	3,000 sq. ft.	No	No
Stucco	5854	None detected	Exterior-southwest corner	Exterior walls	3,000 sq. ft.	No	No
Stucco	5855	None detected	Exterior southeast corner	Exterior walls	3,000 sq. ft.	No	No
Stucco	5856	None detected	Exterior- east wall center	Exterior walls	3,000 sq. ft.	No	No
Joint compound	5857	None detected	Library east center	Library, east section	400 sq. ft.	No	No
Joint compound	5858	None detected	Library east, northeast	Library, east section	400 sq. ft.	No	No
Joint compound	5859	None detected	Library, southeast section, northwest corner	Library, east section	400 sq. ft.	No	No
Drywall	5860	None detected	Library, southeast section, northwest corner	Library, east section	400 sq. ft.	No	No
Composite- drywall with joint compound	5861	None detected	Library, southeast section, northwest corner	Library, east section	400 sq. ft.	No	No
Brown flooring composite under carpet	5862	None detected	Library, by northeast entry	Library under carpet	1,200 sq. ft.	No	No
White sink insulation	5863	None detected	Lounge, west wall center sink	Teacher's lounge, under sink	4 sq. ft.	No	No
Smooth plaster	JAN-01-01 JAN-01-02	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	No	No
1'x1' ceiling tile with mastic (random peghole)	JAN-02-01 A&B	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Rough plaster	JAN-03-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	No	No
Gypsum board with joint compound	JAN-05-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
9"x9" grey with streaks floor tile with mastic	JAN-07-01 through JAN-09-01	5% Chrysotile (tile) 3%-10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Pipe fitting insulation	JAN-11-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building N (Library)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
9"x9" green with brown spots floor tile with mastic	JAN-13-01	5% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Beige marble pattern linoleum with mastic	JAN14-01 through JAN-14-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report <i>Library under Cape</i>	N/A N/A	N/A	N/A
12"x12" brown floor tile with mastic	JAN-16-01 through JAN-16-03	2% Chrysotile (tile) 2% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
9"x9" marble pattern floor tile with mastic	JAN-17-01	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A

NOTES:
Roof was not inspected.

*Note: Text Book R Not Acc. labeled
Med R
46 A
46 B*

*12" floor c.f. w/ mastic - library N/A 1
Tec*

*12" floor tile under f. tile w/ mastic - Teacher's Lounge, 43
4" grey teal tile band → 43
Library*

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	JAN-03-05	None detected	Previously sampled (Cape Env. 1992)	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Acoustical plaster (ceiling)	JAN-04-05	2% Chrysotile	Previously sampled (Cape Env. 1992)	Room 32-34, waiting room counselor's A, B, C, hallway A, administration office, lobby room, 34A & 34B, principal's office, 14, 15	7,500 sq. ft	No	No
Stucco	JAN-12-02	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	6,000 sq. ft	No	No
2'x4' Random pinhole/ fissured ceiling tile	JAN-19-01 through JAN-19-03	None detected	Previously sampled (Cape Env. 1992)	Rooms 33-34, 34A, 34B, waiting room, counselor's A, B, C,	3,600 sq. ft	Yes	No
12" brown with white streaks floor tile with mastic	JAN-21-01 through JAN-21-03	2% Chrysotile (tile) None detected (mastic)	Previously sampled (Cape Env. 1992)	Not observed	N/A	N/A	N/A
12" brown with dark brown streaks floor tile with mastic	JAN-22-01 through JAN-22-03	2% Chrysotile (tile) None detected (mastic)	Previously sampled (Cape Env. 1992)	Not observed	N/A	N/A	N/A
1'x1' random pinhole/ ceiling tile with mastic	JAN-20-01 A&B	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Room 32, mechanical room 2	1,200 sq. ft	Yes	No
Stucco	5814	None detected	Exterior- room 14, south center	Exterior walls	6,000 sq. ft	No	No
Stucco	5815	None detected	Exterior- room 15B, southeast corner	Exterior walls	6,000 sq. ft	No	No
Stucco	5816	None detected	Exterior- room 32, south center	Exterior walls	6,000 sq. ft	No	No

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Stucco	5817	None detected	Exterior- administration office, east center	Exterior walls	6,000 sq. ft	No	No
Stucco	5818	None detected	Exterior- room 34, northwest	Exterior walls	6,000 sq. ft	No	No
Stucco	5819	None detected	Exterior- counselor's office, center southwest	Exterior walls	6,000 sq. ft	No	No
Rough plaster	5820	None detected	Room 33 southwest corner	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Rough plaster	5821	None detected	Room 34B, northeast corner	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Rough plaster	5822	None detected	Administration office, southwest corner	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	5823	None detected	Restroom 1, northeast corner	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Rough plaster	5824	None detected	Counselor's office B, southwest corner	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Rough plaster	5825	None detected	Vault, south wall center	Rooms 32-34, staff men's and women's restrooms, waiting room, counselors A,B,C, restrooms 1 & 2, administration office, copy room, mechanical room 2, vault, 34 A & B, principal's office, 14, 15, 15A & 15B	11,000 sq. ft	No	No
Joint compound	5826	None detected	Room 15, southwest corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Joint compound	5827	None detected	Room 33, southeast corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No
Joint compound	5828	None detected	Room 34, northwest corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No
Joint compound	5829	None detected	Counselor's office B, west corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No
Joint compound	5830	None detected	Room 14, southwest corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Drywall	5831	None detected	Mechanical room 1, west wall center	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No
Composite drywall with joint composite	5832	None detected	Mechanical room 1, northwest corner	Mechanical room 1, waiting room, counselor's A, B, C, hallway A, administration office, copy room, mechanical room 2, 34 A&B, principal's office, room 14, 15, 15A	4,500 sq. ft	No	No
Floor tile with mastic (under 12"x12" grey speckled floor tile)	5833	None detected	Counselor B- at southeast entry	Counselor B, hallway A, administration office, copy room, principal's office	800 sq. ft	No	No
White sink insulation	5834	None detected	Room 34B, northwest corner	Copy room, room 34 A&B	6 sq. ft	No	No
Grey duct sealant	5835	None detected	Mechanical room 2, center	Mechanical room 1 & 2	10 sq. ft	No	No
Blue carpet glue*	N/A	Assumed	New material non-destructive sampling	Room 32-34, waiting room, counselor A, B, C, principal's office	3,500 sq. ft	No	No
12" fissured ceiling tile**	N/A	Assumed	New material non-destructive sampling	Counselor B, hallway A, administration office, copy room, principal's office	900 sq. ft	Yes	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Room 32-34, hallway A, administration office, copy room, 14, 15	5,500 sq. ft	No	No

Handwritten mark: a stylized 'A' with a '2' below it.

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building Q (Rooms 14-15, 32-34)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
4" grey covebase with adhesive	Same as #5619	None detected <i>A-2</i>	Building F	Room 32-34, waiting room, counselor A, B, C, hallway A, administration office, copy room, principal's office, 15A, 14, 15	500 ln. ft.	No	No
2" grey covebase with adhesive	Same as #5630	None detected <i>A-2</i>	Building G	Room 15	50 ln. ft.	No	No
Transite chalkboards*	N/A	Assumed	Not sampled, material intact	Rooms 32-34, 14-15	100 sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction

wind puffy



MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building S (Rooms 50-53)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	JAN-03-03	None detected	Previously sampled (Cape Env. 1992)	Room 52, 53	2,300 sq. ft.	No	No
Acoustical plaster (ceiling)	JAN-04-04	2% Chrysotile	Previously sampled (Cape Env. 1992)	Rooms 50-53, 52 A&B	3,600 sq. ft.	No	No
Stucco	5866	None detected	Exterior room 50, north center	Exterior wall	3,000 sq. ft.	No	No
Stucco	5867	None detected	Exterior room 51, south center	Exterior wall	3,000 sq. ft.	No	No
Stucco	5868	None detected	Exterior room 52, northeast	Exterior wall	3,000 sq. ft.	No	No
Stucco	5869	None detected	Exterior room 53, southeast	Exterior wall	3,000 sq. ft.	No	No
Stucco	5870	None detected	Exterior room, 53, northeast	Exterior wall	3,000 sq. ft.	No	No
Joint compound	5871	None detected	Room 52, southwest corner	Rooms 50-53, 52 A&B, women's restroom	2,200 sq. ft.	No	No
Joint compound	5872	None detected	Room 50, southwest corner	Rooms 50-53, 52 A&B, women's restroom	2,600 sq. ft.	No	No
Joint compound	5873	None detected	Room 52, southwest corner	Rooms 50-53, 52 A&B, women's restroom	2,600 sq. ft.	No	No
Joint compound	5874	None detected	Room 53, southwest corner	Rooms 50-53, 52 A&B,	2,600 sq. ft.	No	No
Joint compound	5875	None detected	Room 51, southwest corner	Rooms 50-53, 52 A&B, women's restroom	2,600 sq. ft.	No	No
Drywall	5876	None detected	Room 53, heater closet, northwest corner	Rooms 50-53, 52 A&B, women's restroom	2,600 sq. ft.	No	No
Composite drywall with joint composite	5877	None detected	Room 53, heater closet, northwest corner	Rooms 50-53, 52 A&B, women's restroom	2,600 sq. ft.	No	No
Rough plaster	5878	None detected	Room 52, northeast corner	Room 52, 53	2,300 sq. ft.	No	No
Rough plaster	5879	None detected	Room 53, south wall center	Room 52, 54	2,300 sq. ft.	No	No
Rough plaster	5880	None detected	Room 50, southeast corner	Room 52, 55	2,300 sq. ft.	No	No
Rough plaster	5881	None detected	Room 51, northwest corner	Room 52, 56	2,300 sq. ft.	No	No
Smooth plaster	5882	None detected	Room 50B, northwest	Room 50B, vestibule, 52B	500 sq. ft.	No	No
Smooth plaster	5883	None detected	Vestibule, southeast	Room 50B, vestibule, 52B	500 sq. ft.	No	No
Smooth plaster	5884	None detected	Room 52B, northwest	Room 50B, vestibule, 52B	500 sq. ft.	No	No
Black sink insulation	5885	None detected	Room 52, south center	Room 52	2 sq. ft.	No	No
Grey duct sealant	5886	None detected	Room 52B, center	Room 52B	5 sq. ft.	No	No
Window putty	5887	None detected	Room 52A, south wall center window	Room 52A, exterior window	5 ln. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building S (Rooms 50-53)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
White sink insulation	5888	None detected	Room 50, southeast corner	Room 50, 52A	4 sq. ft.	No	No
2'x4' fissured ceiling panels	5889	None detected	Room 52A, north end corner	Room 52A	100 sq. ft.	No	No
Blue carpet*	N/A	Assumed	New material, non-destructive sampling	Rooms 50-53, 52A	500 sq. ft.	No	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Rooms 50-53	3,500 sq. ft.	No	No
4" grey covebase with adhesive	Same as #5619	None detected	Building F	Rooms 50-53, 52A	500 sq. ft.	No	No
Dark green linoleum with mastic	JAN-18-03	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
Marble pattern linoleum	JAN-23-01 through JAN-23-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
12" fissured ceiling tile*	N/A	Assumed	Not sampled to avoid damage	Rooms 50-53	3,500 sq. ft.	Yes	No

NOTES:

*The material shall be sampled prior to disturbance during construction
Roof was not inspected.



CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building P (Rooms 44-47 & 54-57)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	JAN-03-02	None detected	Previously sampled (Cape Env. 1992)	Room 54-57, 45, 46B	4,500 sq. ft.	No	No
Acoustical plaster (ceiling)	JAN-04-03	2% Chrysotile	Previously sampled (Cape Env. 1992)	Room 54-57, 47, 47A, 45	5,000 sq. ft.	No	No
Stucco	5744	None detected	Exterior- room 54 northwest	Exterior walls	9,000 sq. ft.	No	No
Stucco	5745	None detected	Exterior- room 56 south center	Exterior walls	9,000 sq. ft.	No	No
Stucco	5746	<1% Chrysotile	Exterior- room 57 northeast	Exterior walls	9,000 sq. ft.	No	No
Stucco	5747	<1% Chrysotile	Exterior- 47A northeast	Exterior walls	9,000 sq. ft.	No	No
Stucco	5748	<1% Chrysotile	Exterior- 47B southeast	Exterior walls	9,000 sq. ft.	No	No
Stucco	5749	<1% Chrysotile	Exterior- room 44 west center	Exterior walls	9,000 sq. ft.	No	No
Stucco	5750	<1% Chrysotile	Exterior- room 45 northeast	Exterior walls	9,000 sq. ft.	No	No
Joint compound	5751	None detected	Room 56, southwest corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45, 44, 47A	2,750 sq. ft.	No	No
Joint compound	5752	None detected	Room 57, northwest corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45, 45, 47A	2,750 sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building P (Rooms 44-47 & 54-57)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Joint compound	5753	None detected	Room 47B, northeast corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45. 46 <i>u4</i>	2,750 sq. ft.	No	No
Joint compound	5754	None detected	Room 47, northeast corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45. 47 <i>u4</i>	2,750 sq. ft.	No	No
Joint compound	5755	None detected	Room 45, south wall center	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45. 48 <i>u4</i>	2,750 sq. ft.	No	No
Drywall	5756	None detected	Room 55, heater closet, northwest corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45. 49 <i>u4</i>	2,750 sq. ft.	No	No
Composite drywall with joint composite	5757	None detected	Room 55, northwest corner	Heater closets & A entry ways, rooms 54, 55, 56, 57, men's restroom ceiling, 47B, 47, 47A, 45. 50 <i>u4</i>	2,750 sq. ft.	No	No
Rough plaster	5758	None detected	Room 55, northeast corner	Room 54-57, 45, 46B	4,000 sq. ft.	No	No
Rough plaster	5759	None detected	Room 57 northeast corner	Room 54-57, 45, 46B	4,000 sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building P (Rooms 44-47 & 54-57)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Rough plaster	5760	None detected	Room 46B, southwest corner	Room 54-57, 45, 46B	4,000 sq. ft.	No	No
Rough plaster	5761	None detected	Room 56, southwest corner	Room 54-57, 45, 46B	4,000 sq. ft.	No	No
Smooth plaster	5762	None detected	Room 47A, southwest corner	Storage 1, room 48, 47, 47A, 44	2,000 sq. ft.	No	No
Smooth plaster	5763	None detected	Storage 1, south wall center	Storage 1, room 48, 47, 47A, 45	2,000 sq. ft.	No	No
Smooth plaster	5764	None detected	Room 44, north wall center	Storage 1, room 48, 47, 47A, 46	2,000 sq. ft.	No	No
Smooth plaster	5765	None detected	Room 44, south wall center	Storage 1, room 48, 47, 47A, 47	2,000 sq. ft.	No	No
Smooth plaster	5766	None detected	Room 47, southeast corner	Storage 1, room 48, 47, 47A, 48	2,000 sq. ft.	No	No
2'x4' fissured ceiling panel	5767	None detected	Room 44, southeast corner	Room 44, 45, 47A	1,500 sq. ft.	Yes	No
1'x1' random peghole ceiling tile with glue	5768	None detected	Room 47B, south center	Room 47B, 44	900 sq. ft.	Yes	No
Brown sheet flooring composite	5769	None detected	Room 47B center	Room 47B,	50 sq. ft.	No	No
Duct sealant	5770	None detected	Room 47B center	Room 47B	10 sq. ft.	No	No
Window putty	5771	None detected	Room 47, southeast corner	Exterior windows	50 ln. ft	No	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Room 54-57, room 47, room 47A, 45, 46B, 44	3,500 sq. ft.	No	No
2" grey covebase with adhesive	Same as #5630	None detected	Building G	Room 45	30 ln. ft	No	No
4" grey covebase with adhesive	Same as #5619	None detected	Building F	Room 54-57, 46B, 44	200 ln. ft	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building P (Rooms 44-47 & 54-57)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
6" grey cove base with adhesive	Same as #5631	None detected	Building G	Room 47	60 ln. ft	No	No
Chalk boards*	N/A	Assumed	Not sampled to avoid damage	Room 54-57, 47, 47A, 45	120 sq. ft.	No	No
Dark green linoleum with mastic	JAN-18-01 JAN-18-02	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Blue carpet glue*	N/A	Assumed	Not sampled to avoid damage	Rooms 54-57	2500**sq. ft.	No	No
12" fissured ceiling tile*	N/A	Assumed	Not sampled to avoid damage	Rooms 54-57, 47, 47A	4000 sq. ft.	Yes	No

NOTES:

*The materials shall be sampled prior to disturbance during construction
 Roof was not inspected.

12' x 4' fissured c.r. - Am 44/47A
12" Strong Resolute wall tile w/ Gln - 44/47A

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building R (Rooms 16-18)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Gypsum board with joint compound	JAR-03-01 through JAR-03-03	2% Chrysotile	Previously sampled (Cape Env. 1992)	Rooms 16, 17, 18	4,000 sq. ft.	No	No
1'x1' rardon peghole ceiling tile with mastic	JAR-04-01 A&B	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Rooms 16, 17, 18	2,000 sq. ft.	Yes	No
Stucco	JAR-05-01	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	2,200 sq. ft.	No	No
Stucco	5701	None detected	Exterior- room 16, southeast	Exterior walls	2,200 sq. ft.	No	No
Stucco	5702	None detected	Exterior- room 17, north center	Exterior walls	2,200 sq. ft.	No	No
Stucco	5703	None detected	Exterior- room 17, south center	Exterior walls	2,200 sq. ft.	No	No
Stucco	5704	None detected	Exterior- room 18, northwest	Exterior walls	2,200 sq. ft.	No	No
12" x12" grey speckled floor tile with adhesive	Same as #5629	None detected <i>AS-2</i>	Building G	Rooms 16, 17, 18	2,700 sq. ft.	No	No
9" beige floor tile with mastic	JAR-01-01	5% Chrysotile (tile) 3% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
9" grey floor tile with mastic	JAR-02-01	5% Chrysotile (tile) 5% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
4" black cove base with adhesive*	N/A	Assumed	Not sampled, material intact	Rooms 16, 17, 18	900 ln. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction.
Roof was not inspected.



CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building H (Room 80-81)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Gypsum board with joint compound	JAD-14-01	None detected	Previously sampled (Cape Env. 1992)	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5632	None detected	Room C4, restroom, northeast corner	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5633	None detected	Room C3, northwest corner	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5634	None detected	Room C8, southwest corner	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3, 1, 6	5,200 sq. ft.	No	No
Joint compound	5635	None detected	Room C2, east wall center	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5636	None detected	Room C5, north wall center	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5637	None detected	Room C1, northwest by entry	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
Joint compound	5638	None detected	Room C7, south center	C1, C1 restroom, C8, C8A, C7, C5, C4, C5 restroom, C4 restroom, C2, C3 restroom, C3A, C3	5,200 sq. ft.	No	No
12" 12" gray speckled floor tile with adhesive with black mastic	5639	None detected	Room C3, north center	C1, C8, C8A, C7, C5, C4, C2, C3A, C3	3,000 sq. ft.	No	No

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building H (Room 80-81)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
2'x4' fissured ceiling panel	5640	None detected	Room C1, south center	C1, C2, C3A	800 sq. ft.	No	No
Black sink insulation	5641	None detected	Room C5, southeast at sink	C7, C6 (on sink under coating)	4 sq. ft.	No	No
Window putty	JAD-01-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	300 in. ft.	No	No
Stucco	JAD-13-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls	3,800 sq. ft.	No	No
6" gray cove base with adhesive	Same as #5631	None detected	Building G	Rooms C1, C8, C8A, C7, C5, C4, C2, C3, C3A	300 in. ft.	No	No

Notes:
 Roof was not inspected.

Duct Sealant - C6



MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building E (Room 87-89)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Window putty	JAD-01-02	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	300 ln. ft.	No	No
1'x1' peghole rows ceiling tile	JAD-03-01	None detected	Previously sampled (Cape Env. 1992)	Room 87, 88, 89, wall and ceiling	3200 sq. ft.	No	No
Smooth plaster	JAD-06-03	None detected	Previously sampled (Cape Env. 1992)	At restroom walls and ceiling	600 sq. ft.	No	No
Smooth plaster	5606	None detected	Restroom, southeast corner	Restroom walls and ceilings	600 sq. ft.	No	No
Smooth plaster	5607	None detected	Restroom, southwest corner	Restroom walls and ceilings	600 sq. ft.	No	No
Joint compound	5601	None detected	Room 87, southwest heater closet, northwest	Room 87, 88, 89, at heater closet and by entry ways	950 sq. ft.	No	No
Joint compound	5602	None detected	Room 89, southwest corner	Room 87, 88, 89, at heater closet and by entry ways	950 sq. ft.	No	No
Joint compound	5603	None detected	Room 88, southeast by entry	Room 87, 88, 89, at heater closet and by entry ways	950 sq. ft.	No	No
Drywall	5604	None detected	Room 89, heater closet east center	Room 87, 88, 89, at heater closet and by entry ways	950 sq. ft.	No	No
Composite drywall with joint compound	5605	None detected	Room 87, southwest heater closet, northwest	Room 87, 88, 89, at heater closet and by entry ways	950 sq. ft.	No	No
12"x12" gray speckled floor tile with adhesive	5608	None detected	Room 89, north center	Room 87, 88, 89	2700 sq. ft.	No	No
6" gray cove base with adhesive	5609	None detected	Room 89, west center	Room 87, 88, 89	300 ln. ft.	No	No
Stucco	JAD-13-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls / ceiling	3500 sq. ft.	No	No
4" gray cove base with adhesive	5619	None detected	Building F	Room 87, 88, 89	100 ln. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage	Room 87, 88, 89	40 sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction.
 Roof was not inspected.

Walls & Ceiling Woods

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building F (Room 84-86)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Sink under coating	JAD-09-02 JAD-09-03	10% Chrysotile	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No
12"x12" brown floor tile with mastic	JAD-12-01 through JAD-12-03	2% Chrysotile (tile) 5% Chystotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	NA sq. ft.	No	No

NOTES:

Wood walls were predominant in rooms 84, 85, 86.
 *The material shall be sampled prior to disturbance during construction.
 Roof was not inspected.

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building D (Room 90-91)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Window putty	JAD-01-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior windows	200 ln. ft.	No	No
Smooth plaster	JAD-06-04	None detected	Previously sampled (Cape Env. 1992)	Room 90B <i>90A</i>	200 sq. ft.	No	No
Smooth plaster	5595	None detected	Room 90B, north center	Room 90B <i>90A</i>	200 sq. ft.	No	No
Smooth plaster	5596	None detected	Room 90B, southeast corner	Room 90B <i>2</i>	200 sq. ft.	No	No
Joint compound	5590	None detected	Room 91, southwest heater closet, northeast corner	Room 90 and 91, at entry way and heater closets <i>2-20-11</i>	500 sq. ft.	No	No
Joint compound	5591	None detected	Room 90, at southeast entry	Room 90 and 91, at entry way and heater closets	500 sq. ft.	No	No
Joint compound	5592	None detected	Room 90, southwest corner	Room 90 and 91, at entry way and heater closets	500 sq. ft.	No	No
Drywall	5593	None detected	Room 91, heater closet, north wall center	Room 90 and 91, at entry way and heater closets	500 sq. ft.	No	No
Composite drywall with joint compound	5594	None detected	Room 90, heater closet, northeast corner	Room 90 and 91, at entry way and heater closets	500 sq. ft.	No	No
Button board	5597	None detected	Room 90B, southwest corner	Room 90B, under plaster <i>90B</i>	200 sq. ft.	No	No
12"x12" random peghole ceiling tile	5598	None detected	Room 91, by southeast entry	Room 90 and 91 walls and ceiling	2200 sq. ft.	No	No
12"x12" gray speckled floor tile with adhesive	5599	None detected	Room 91, west center	Room 90 and 91	1800 sq. ft.	No	No
6" gray cove base with adhesive	5600	None detected	Room 90, northwest corner	Room 90 and 91	240 ln. ft.	No	No
Stucco	JAD-13-13-01	2% Chrysotile	Previously sampled (Cape Env. 1992)	Exterior walls <i>1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100</i>	200 sq. ft.	No	No
4" gray cove base with adhesive	Same as #5614	None detected	Building F	Room 90 and 91	80 ln. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage	Room 90 and 91	40 sq. ft.	No	No

NOTES:

Wood walls predominant in room 90 and 91.

Room 90B was not accessible. *90A*

*The material shall be sampled prior to disturbance during construction
 Roof was not inspected.

MATERIAL INVENTORY
ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Gypsum board with joint compound	JAN-05-02 JAN-05-03	2% Chrysotile	Previously sampled (Cape Env. 1992)	Community liaison, assistant principal's office 2	300 sq. ft.	No	No
Stucco	5772	None detected	Exterior, room 19 southwest	Exterior walls	4,500 sq. ft.	No	No
Stucco	5773	None detected	Exterior, room 20 east center	Exterior walls	4,500 sq. ft.	No	No
Stucco	5774	None detected	Exterior, staff lounge, northwest	Exterior walls	4,500 sq. ft.	No	No
Stucco	5775	None detected	Exterior, room 31 northeast	Exterior walls	4,500 sq. ft.	No	No
Stucco	5776	None detected	Exterior, storage 2 north center	Exterior walls	4,500 sq. ft.	No	No
Joint compound	5777	None detected	Room 31, north wall center	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Joint compound	5778	None detected	Room 30, northwest corner	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Joint compound	5779	None detected	Nurse's office, south wall center	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Joint compound	5780	None detected	Storage, east center	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Joint compound	5781	None detected	Room 23, southeast corner	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Joint compound	5782	None detected	Room 21, southwest corner	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Joint compound	5783	None detected	Staff lounge, southeast corner	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Drywall	5784	None detected	Room 31A, west wall center	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Composite drywall/ joint compound	5785	None detected	Room 31A, southeast corner	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	6,000 sq. ft.	No	No
Sand plaster	5786	None detected	Nurse's office, northwest corner	Room 23, storage 1&2, 21, 9, nurse's office, attendance office, community liaison, room 20	3,500 sq. ft.	No	No
Sand plaster	5787	None detected	Storage 1, southeast corner	Room 23, storage 1&2, 21, 9, nurse's office, attendance office, community liaison, room 20	3,500 sq. ft.	No	No
Sand plaster	5788	None detected	Room 23 northeast corner	Room 23, storage 1&2, 21, 9, nurse's office, attendance office, community liaison, room 20	6,000 sq. ft.	No	No
Sand plaster	5789	None detected	Attendance office, southwest corner	Room 23, storage 1&2, 21, 9, nurse's office, attendance office, community liaison, room 20	6,000 sq. ft.	No	No

MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Sand plaster	5790	None detected	Attendance office, northwest corner	Room 23, storage 1&2, 21, 9, nurse's office, attendance office, community liaison, room 20	3,500 sq. ft.	No	No
12"x12" random pinhole ceiling tile	5791	None detected	Community liaison, center	Community liaison, attendance office	300 sq. ft.	No	No
2'x4' fissured ceiling panel	5792	None detected	Room 31, west center	Rooms 30-31, 9, nurse's office, attendance office, community liaison	2,000 sq. ft.	No	No
Floor tile with mastic (sub flooring)	5793	None detected	Staff lounge, southwest corner	Staff lounge, room 21-23, attendance office, nurse's office (under floor tile & carpet)	3,200 sq. ft.	No	No
9"x9" brown floor tile with mastic	5794	None detected	Room 31A center (patch)	Room 31A center (patch)	8 sq. ft.	No	No
Green sheet vinyl flooring	5795	None detected	Room 31A Center	Room 31A	50 sq. ft.	No	No
White sink insulation	5796	None detected	Room 9, northeast	Room 9	2 sq. ft.	No	No
Black sink insulation	5797	None detected	Room 31, west wall center	Rooms 30-31	4 sq. ft.	No	No
Grey duct sealant	5798	None detected	Room 31A, center	Room 31A	10 sq. ft.	No	No
Acoustical plaster ceiling	JAN-04-04	2% Chrysotile	Previously sampled (Cape Env. 1992)	Rooms 21, 23, 30, 31, attendance office, assistant principal's office, 1, 2, community liaison	7,000 sq. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage.	Rooms 21, 23, 30, 31	100 sq. ft.	No	No
12"x12" grey speckled floor tile with mastic	Same as #5629	None detected A-2	Building G	Rooms 21, 23, 30, 31, storage 1&2, room 9, nurse's office, attendance office, staff lounge	4,000 sq. ft.	No	No
6" grey covebase with adhesive	Same as #5631	None detected A-2	Building G	Community liaison	10 ln. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building T (Rooms 21, 23, 30, 31)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
4" Grey covebase with adhesive	Same as #5619	None detected <i>A-2</i>	Building F	Rooms 21, 23, 30, 31, attendance office, storage 1&2, room 9, nurse's office, staff lounge	300 ln. ft.	No	No
Smooth plaster	JAN-01-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Wood pattern linoleum with mastic	JAN-10-01 through JAN-10-03	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Brown linoleum with mastic	JAN-24-01 JAN-24-02	None detected (tile & mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Grey with specks linoleum	JAN-25-01 JAN-25-02	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
2'x4' ceiling tile	JAN-26-01 through JAN-26-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A N/A	N/A	N/A
Blue carpet glue*	N/A	Assumed <i>A-2</i>	No sampled to avoid damage	Community Liaison, staff lounge and rooms 2 & 23	2,000 sq. ft.	No	No
12" fissured ceiling tile*	N/A	Assumed <i>A-2</i>	Not sampled to avoid damage	Room 21	900 sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction.
Roof was not inspected.



MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica Malibu Unified School District
 PROJECT NO: 108-0085
 PROJECT NAME: John Adams Middle School

Building U (Rooms 10-13)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Stucco	5836	None detected	Exterior, room 10, southwest	Exterior walls	3,000 sq. ft.	No	No
Stucco	5837	None detected	Exterior, room 11, northeast	Exterior walls	3,000 sq. ft.	No	No
Stucco	5838	None detected	Exterior room 12, north center	Exterior walls	3,000 sq. ft.	No	No
Stucco	5839	None detected	Exterior, room 13 southwest	Exterior walls	3,000 sq. ft.	No	No
Stucco	5840	None detected	Exterior, room 13 northeast	Exterior walls	3,000 sq. ft.	No	No
Sand plaster	5841	None detected	Room 10, northeast corner	Rooms 10, 11, 12, 13	5,500 sq. ft.	No	No
Sand plaster	5842	None detected	Room 13, south wall center	Rooms 10, 11, 12, 13	5,500 sq. ft.	No	No
Sand plaster	5843	None detected	Room 12, north wall center	Rooms 10, 11, 12, 13	5,500 sq. ft.	No	No
Sand plaster	5844	None detected	Room 11, northwest corner	Rooms 10, 11, 12, 13	5,500 sq. ft.	No	No
Sand plaster	5845	None detected	Room 11, south wall center	Rooms 10, 11, 12, 13	5,500 sq. ft.	No	No
Joint compound	5846	None detected	Room 10, northwest	Rooms 10, 11, 12, 13	900 sq. ft.	No	No
Joint compound	5847	None detected	Room 11, northeast	Rooms 10, 11, 12, 13	900 sq. ft.	No	No
Joint compound	5848	None detected	Room 13, northwest	Rooms 10, 11, 12, 13	900 sq. ft.	No	No
Drywall	5849	None detected	Room 13, northwest	Rooms 10, 11, 12, 13	900 sq. ft.	No	No
Composite drywall with joint compound	5850	None detected	Room 13, northwest	Rooms 10, 11, 12, 13	900 sq. ft.	No	No
White sink insulation	5851	None detected	Room 10, southeast	Rooms 10, 11, 12, 13	10 sq. ft.	No	No
2'x4' fissured ceiling panel	5852	None detected	Room 10, east center	Rooms 10, 11, 12, 13	3,600 sq. ft.	Yes	No
Acoustical plaster ceiling	JAN-04-04	2% Chrysotile	Previously sampled (Cape Env. 1992)	Rooms 10, 11, 12, 13	3,600 sq. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage	Rooms 10, 11, 12, 13	100 sq. ft.	No	No
12"x12" grey floor tile with adhesive	Same as #5629	None detected	Building G	Rooms 10, 11, 12, 13	600 sq. ft.	No	No
4" grey covebase with adhesive	Same as #5619	None detected	Building F	Rooms 10, 11, 12, 13	480 ln. ft.	No	No
Blue carpet glue*	N/A	Assumed	Not sampled to avoid damage	Rooms 10, 11, 12, 13	3,000 sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction
 Roof was not inspected.



**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building V (Rooms 22-24)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Stucco	JAN-12-03	None detected	Previously sampled (Cape Env. 1992)	Exterior walls	2,000 sq. ft.	No	No
Stucco	5799	None detected	Exterior room 22, southwest	Exterior walls	2,000 sq. ft.	No	No
Stucco	5800	None detected	Exterior room 22, southeast	Exterior walls	2,000 sq. ft.	No	No
Stucco	5801	None detected	Exterior room 24, northwest	Exterior walls	2,000 sq. ft.	No	No
Stucco	5802	None detected	Exterior room 24, southeast	Exterior walls	2,000 sq. ft.	No	No
Sand plaster	5803	None detected	Storage room northeast corner	Room 22, 24, storage room, restroom	2,200 sq. ft.	No	No
Sand plaster	5804	None detected	Room 24, east wall center	Room 22, 24, storage room, restroom	2,200 sq. ft.	No	No
Sand plaster	5805	None detected	Room 24, southwest	Room 22, 24, storage room, restroom	2,200 sq. ft.	No	No
Sand plaster	5806	None detected	Room 22, east wall center	Room 22, 24, storage room, restroom	2,200 sq. ft.	No	No
Sand plaster	5807	None detected	Room 22, southwest	Room 22, 24, storage room, restroom	2,200 sq. ft.	No	No
Joint compound	5808	None detected	Room 22, southwest corner	Room 22, 24, storage room	300 sq. ft.	No	No
Joint compound	5809	None detected	Room 24, northeast corner	Room 22, 24, storage room	300 sq. ft.	No	No
Joint compound	5810	None detected	Room 24, southwest corner	Room 22, 24, storage room	300 sq. ft.	No	No
Drywall	5811	None detected	Room 22, southwest	Room 22, 24, storage room	300 sq. ft.	No	No
Composite drywall with joint compound	5812	None detected	Room 24, southwest	Room 22, 24, storage room	300 sq. ft.	No	No
Duct sealant	5813	None detected	Room 24, heater closet center	Room 22, 24, heater closet on HVAC unit ducts	5 sq. ft.	No	No
Chalkboards*	N/A	Assumed	Not sampled to avoid damage	Room 22, 24	40 sq. ft.	No	No

**MATERIAL INVENTORY
ASBESTOS**

CLIENT: Santa Monica Malibu Unified School District
PROJECT NO: 108-0085
PROJECT NAME: John Adams Middle School

Building V (Rooms 22-24)

MATERIAL	SAMPLE NUMBER	ASBESTOS CONTENT	SAMPLE LOCATION	MATERIAL LOCATION	APPROX. QTY.	FRIABLE	DAMAGE
Acoustical plaster (ceiling)	JAN-04-04	2% Chrysotile	Previously sampled (Cape Env. 1992)	Room 22, 24	1,800 sq. ft.	No	No
12"x12" grey speckled floor tile with adhesive	Same as #5629	None detected	Building G	Room 22, 24, storage room	1,800 sq. ft.	No	No
4" grey covebase with adhesive	Same as #5619	None detected	Building F	Room 22, 24, storage room	60 ln. ft.	No	No
2'x4' ceiling tile	JAN-27-01 through JAN-27-03	None detected	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
9" beige floor tile with mastic	JAN-28-01	5% Chrysotile (tile) None detected- 5% Chrysotile (mastic)	Previously sampled (Cape Env. 1992)	Not observed in areas stated in the previous report	N/A	N/A	N/A
Blue carpet glue*	N/A	Assumed \varnothing	Not sampled to avoid damage	Room 24	500 sq. ft.	No	No
12" fissured ceiling tile*	N/A	Assumed \varnothing	Not sampled to avoid damage	Room 24	500 sq. ft.	No	No

NOTES:

*The material shall be sampled prior to disturbance during construction
Roof was not inspected.



Appendix C


Response Action Ratings

**FIGURE 4 - RESPONSE ACTION HIERARCHY
THERMAL SYSTEM INSULATION (TSI- ACM)**

Response Action Priorities

- 1) Isolate area and restrict access. Immediate removal is mandatory; contact an Accredited Project Designer (APD).
- 2) Isolate area and restrict access. Repair or Remove Immediately; contact an APD. If ACBM remains following response action, followup with O&M; restrict access to reduce disturbance potential.
- 3) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or removal on a priority basis; contact an APD. If ACBM remains following response action, followup with O&M; limit access to reduce disturbance potential.
- 4) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or removal when practical and cost effective; contact an APD.
- 5) Continue O&M. Schedule repair or removal when practical and cost effective; contact an APD.
- 6) Same as 5 (lower priority basis).
- 7) Continue O&M. Reduce disturbance potential where practical. Remove when practical and cost effective; contact an APD.
- 8) Continue O&M until major renovation/demolition requires removal under NESHAPs or until hazard potential changes. Remove when practical and cost effective; contact an APD.

FIGURE 1 - DECISION TREE
THERMAL SYSTEM INSULATION
ASBESTOS CONTAINING BUILDING MATERIALS
(TSI-ACMs)




**FIGURE 5 - RESPONSE ACTION HIERARCHY
SURFACING MATERIALS (SURFACING - ACBMs)**

Response Action Priorities

- 1) Isolate area and restrict access. Immediate removal is mandatory; contact an Accredited Project Designer (APD).
- 2) Isolate area and restrict access. Repair or Remove Immediately; contact an APD. If ACBM remains following response action, followup with O&M; restrict access to reduce disturbance potential.
- 3) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or remove on a priority basis; contact an APD. If ACBM remains following response action, followup with O&M; limit access to reduce disturbance potential.
- 4) Continue O&M. Limit access to reduce disturbance potential. Schedule repair or remove when practical and cost effective; contact an APD.
- 5) Continue O&M. Schedule repair or remove when practical and cost effective; contact an APD.
- 6) Same as 5 (lower priority basis).
- 7) Continue O&M. Reduce disturbance potential where practical. Remove when practical and cost effective; contact an APD.
- 8) Continue O&M until major renovation/demolition requires removal under NESHAPs or until hazard potential changes. Remove when practical and cost effective; contact an APD.

FIGURE 2 - DECISION TREE

SURFACING MATERIAL
ASBESTOS CONTAINING BUILDING MATERIALS
(SURFACING-ACBMs)




**FIGURE 6 - RESPONSE ACTION HIERARCHY
MISCELLANEOUS MATERIALS (MISC.- ACBMs)**

Response Action Priorities

- 1) Isolate area and restrict access. Immediate removal is mandatory; contact an Accredited Project Designer (APD).
- 2) Isolate area and restrict access. Repair, Encapsulate, or Remove Immediately; contact an APD. If ACBM remains following response action, followup with O&M; restrict access to reduce disturbance potential.
- 3) Continue O&M. Limit access to reduce disturbance potential. Schedule repair, encapsulate, or remove on a priority basis; contact an APD. If ACBM remains following response action, followup with O&M; limit access to reduce disturbance potential.
- 4) Continue O&M. Limit access to reduce disturbance potential. Schedule repair, encapsulate, or remove when practical and cost effective; contact an APD.
- 5) Continue O&M. Schedule repair, encapsulate, or remove when practical and cost effective; contact an APD.
- 6) Same as 5 (lower priority basis).
- 7) Continue O&M. Reduce disturbance potential where practical. Remove when practical and cost effective; contact an APD.
- 8) Continue O&M until major renovation/demolition requires removal under NESHAPs or until hazard potential changes. Remove when practical and cost effective; contact an APD.

FIGURE 3 - DECISION TREE

MISCELLANEOUS MATERIAL
ASBESTOS CONTAINING BUILDING MATERIALS
(MISC.-ACBMs)



Appendix D

Field Sheets

3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg A (Rm 92-99)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth Plaster	Same As Previous	ND	N	2500 sq ft	Neg	N/A
S	Rough Plaster	↓	ND	N	300 sq ft	Pos	8
M	Gypsum Board w/ Jt. Cap	Same As Previous Except R-100	ND	N	7000 sq ft	Pos	8
M	2x4's 12" DK. Brown F.T. w/ Maste	Same As Previous	ND	N	1000 sq ft	NEG	N/A
M	4" Gray w/ Black Stracks F.T. w/ Maste	↓	ND	N	100 sq ft	Pos	8
T.S.I.	Hard Pipe Fittings Insulation	Rm 95	ND	Y	2 Fittings	Pos	8
M	1'x1' Round Peghole Ceiling tile	Same As Previous except R-100	ND	Y	9000 sq ft.	NEG	N/A
T.S.I.	Pipe Insulation	R-95	ND	Y	5 lin ft.	Pos	8
S	Stucco	Extern walls	ND	N	5500 sq ft	Pos (Trace)	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMus D
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg A (R-92-9100)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Butt-on Board	Same As Previous Except R-100	ND	N	2500 sqft.	NEG	N/A
M	Drywall w/ Jt. Compound		ND	N	4500 sqft.	NEG	N/A
M	12" Gray Speckled F.T. w/ Adhesive/Black	Same As Residual Material	ND	N	8000 sqft.	ASSUMED 2 NEG 2	8
M	Blue Carpet Glue w/ Black Residual Material	R-92 - Storage R-2	ND	N	1500 sqft.	Pos	8
M	Gray Carpet Glue	R-95	ND	N	1000 sqft.	NEG	N/A
M	2" Gray Coveboard w/ Adhesive	Same	ND	N	300 in ft.	NEG	N/A
M	4" Black Coveboard w/ Adhesive	Same		N	120 in ft.	NEG	N/A
M	6" Gray Coveboard w/ Adhesive			N	300 in ft.		N/A
M	Gray Duct Sealant			N	20 sqft.		N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"

3-Year Re-Inspection Material Inventory

Client: S M Murp
Project No: 110-0006
Project Name: John Adams Adams M.S. - Bldg A (Rm 92-100)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	chalk boards	Same As Previous Report	ND	N	400 sq ft.	As-d	8
M	wooden Putty	↓	D	N	200 li. Pl.	Pos	8
M	Wood Floor Mastic	↓	ND	N	Ass'd Ⓟ 400 sq ft.	Ⓟ As-d Sheet 1	8
Note: New Bldg (Boys' Girls Club) Constructed at South End of Bldg what used to be Bldg 100.							Encapsulate

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
Project No: 110-0006
Project Name: John Adams M.S. - Bldg BC Cafeteria

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2'x4' Plaster Patch on - & Gypsum Ceiling tile	Same As Previous	ND	Y	2000 sqft.	NEG	N/A
M	1'x1' Plaster Patch Small Peghole Ceiling tile	↓	ND	Y	1200 sqft	NEG	N/A
M	↓ Blocks		ND	N	1200 sqft.	POS	8
Ⓜ	Rough Plaster Ceiling		ND	N	500 sqft.	NEG	N/A
S	Smooth Plaster		ND	N	4500 sqft	NEG	N/A
S	Stucco		ND	N	1200 sqft	NEG	N/A
M	Jt. C-p w/ Drywall		ND	N	3500 sqft	NEG	N/A
M	12" Gray Speckled F.T. w/ Adhesion		ND	N	2800 sqft.	NEG	N/A
M	4" Gray Concrete w/ Adhesion		ND	N	200 sqft.	NEG	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: S.M. Mueser
 Project No: 110-0006
 Project Name: John ~~Ad~~ Adams M.S. - Bldg B (Caterina)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)	
S	Blue Floursparite	Same as Previous	ND	N	2000 sq ft	NEG	N/A	
M	Window Putty	↓	ND	N	200 in ft	NEG	N/A	
M	Cementitious Wall Panel		ND	N	150 sq ft	NEG	N/A	
M	Asbestos Acoustic Ceiling Access Panels (2x4)		ND	N	2 panels	Assumed	8	
M	Button Board				5000 sq ft.	Assumed	8	
M	Freezer Insulation (Encased in Metal)			↓	↓	200 sq ft	↓	8
	9" Red F.T. w/ Nuts		Not Obs'd					
	1'x1' large & small Perforated Ceiling tiles w/ Nuts							
	Hot water tank							

Note: Pandey; Freezer; Snack Bar office 1 & 2

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMCS D
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg L (Frym Bldg)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth Plaster	Same As Previous	ND	N	10000 sqft	NEG	N/A
M	1'x1' Pebble Rows Ceiling tile w/Mortar	↓	ND	Y	700 sqft.	NEG	N/A
S	Rough Plaster		ND	N	4000 sqft.	NEG	N/A
M	1'x1' Grooved Ceiling tile w/Mortar		ND	N	500 sqft.	NEG	N/A
M	Acoustical Plaster Ceiling		R-114, 106	ND	N	1000 600 sqft	Pos
M	9" tan w/Brown streaks F.T. w/Mortar	R-111 (under tile)	↓	↓	220 sqft.	Pos	8
M	9" Brown w/DK Green streaks F.T. w/Mortar	R-114, 113 (under tile)	↓	↓	150 sqft.	Pos	8
M	9" off white w/Green streaks F.T. w/Mortar	R-106, 102, lounge. (under tile)	↓	↓	650 sqft.	Pos	8
S	Stucco	Exterior walls	ND	N	12000 sqft.	NEG	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg C (Gym Bldg)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	5/8" Comp w/ Drywell	Same as Previous	ND	N	250 sqft.	NEG	N/A
M	12" Gray Speckled F.T. w/ Marble	↓	↓	↓	500 sqft.	↓	↓
M	2" Gray Covelet w/ Adhesin	↓	↓	↓	200 sqft.	↓	↓
M	4" Green Covelet w/ Adhesin	↓	↓	↓	20 sqft.	↓	↓
M	4" Pink Covelet w/ Adhesin	↓ (P)	↓	↓	80 sqft.	↓	↓
M	Window Putty	↓	ND	N	10 sqft.	NEG	N/A
M	Cementitious Back Panels	↓	↓	↓	5 sqft.	↓	N/A
M	Chalkboard Marble	↓	↓	↓	10 sqft.	↓	↓
Note:		R-109, 109A, 108, 103, Not Accessible.					

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMALLWOOD
 Project No: 110-0006
 Project Name: John Adams H.S. - Bldg F (F-84 → 86)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Smooth Plaster	See - As Previous	ND	N	600 sq ft	NEG	N/A
J	Stucco	↓	ND	N	3500 sq ft.	Pos	8
M	Drywall w/ Jt. Cap		ND	N	950 sq ft.	NEG	N/A
M	12" Round Peghole Ceiling tile		ND	N	3200 sq. ft.	NEG	NA
M	12" Gray Speckled F.T. w Adhesive		ND	N	2700 sq ft.	NEG	N/A
M	4" Gray Concrete w Adhes-		I	I	150 in ft.	NEG	I
M	6" Gray Concrete w Adhes		I	I	300 in ft	↓	↓
M	Chalk boards		I	I	40 sq ft	Ass-d	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client:

SMMUSD

Project No:

110-0006

Project Name:

John Adams Adams, M.S. Bldg 6 (R 82-83)

Page 1 of 2

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)	
M	Wet Patch	Same As Previous	ND	N	300 ln. ft.	Pos	8	
S	Smooth Plaster	↓	ND	N	300 sq. ft.	Neg	N/A	
T.S.I.	Pipe Insulation		and 83	ND	Y	80 ln. ft.	Pos sq. ft.	8
T.S.I.	Pipe Fitting Insulation			ND	Y	6 fittings	NEG	N/A
M	Sink under Coating			ND	N	1 sq. ft.	Pos	8
M	Drywall w/ Jt. Comp			ND	N	600 sq. ft.	NEG	N/A
S	Smooth Plaster			ND	N	300 sq. ft.	NEG	N/A
M	12" Straight Recessed Ceiling tile			ND	Y	2500 sq. ft.	NEG	N/A
M	12" Gray Speckled F.T. w/ Adhesives			ND	N	3000 sq. ft.	NEG	N/A

(1) S – surfacing, TSI – thermal system insulation, M – miscellaneous

(2) ND – not damaged, D – damaged, SD – significantly damaged

(3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg 4 (R-82-P85)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2" Gray Covebase w/ Adhesive	Same As Previous	ND	N	120 sq ft	NEG	8 N/A
M	6" Gray Covebase w/ Adhesive	↓	↓	↓	100 sq ft	NEG	N/A
M	Asbestos Containing Cement Panel	R-82 S/W at Desk	↓	↓	10 sq. ft	Assumed 1	8
M	Chalkboards	Same As Previous	↓	↓	40 sq ft	Assumed 1	8
S	Stucco	↓	↓	↓	3500 sq ft	Pos	8
M	4" Gray Covebase w/ Adhesive	↓	↓	↓	150 sq. ft	Assumed 1	8
		R-80 Not Accessible					

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SM MURP
 Project No: 110-0006
 Project Name: Jordan Adams M.S. - Bldg K (Auditorium)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	1'x1' Peghole Rows Ceiling tile w/ Mastix	Same As Previous	ND	Y	900 sq ft.	NEG	N/A
S	Acoustical Plaster Wall and Ceiling	(Also: lobby ceiling, Auditorium ceiling) Hallway	ND	N	6000 sq. ft.	Pos	8
S	Stucco		ND	N	6500 sq ft.	NEG	N/A
S	Rough Plaster		ND	N	3500 sq ft.	NEG	N/A
S	Smooth Plaster		ND	N	3000 sq ft.	NEG	N/A
M	Drywall w/ Jt. Cap		ND	N	300 sq ft.	Neg	N/A
M	12" Round Peghole Ceiling tile		Y	Y	150 sq ft.	NEG	N/A
M	White Vibration Reducer (Clath type)		N	N	10 sq ft.	NEG	N/A
M	Window Putty	N	N	10 sq ft.	Pos	8	

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMAUSD
Project No: 110-0006
Project Name: John Adams M.S. - Bldg K (Auditorium)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	12" Gray Speckled floor tile w/ Adhesive	Same As Previous	ND	N	1000 sqft.	POS Assumed 1	8
M	2" Gray Limestone w/ Adhesive		ND	N	50 sqft	+	8
M	wood flooring				2000 sqft.	Assumed 1	8
M	Gray Carpet Glue				2000 sqft.		8
M	Blue Carpet Glue				400 sqft.		8


- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client:
Project No:
Project Name:

SMMUSP
110-0006
John Adams H.S. - Bldg L (F-70-PTS)



Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window Putty	Same as Previous	ND	N	Pos	100 sq ft	POS
M	Duct Tape on HVAC		ND	N	NEG	20 sq ft	N/A
M	Drywall w/ Jt. L-P		ND	N	NEG	1000 sq ft	N/A
S	Stucco		ND	N	Pos (Trace)	3600 sq ft.	8
M	Barrier Paper		ND	N	NEG	L	N/A
M	2'x4' Fissured Ceiling Panel		ND	Y	NEG	3600 sq ft	N/A
M	12" Gray w/ streaks. Floor tile w/ Adhesive w/ Black Resid. Mustn		ND	N	NEG	3600 sq ft	N/A
M	White Duct Sealant		L	L	NEG	20 sq ft.	N/A
M	Black Countertop		L	L	NEG	200 sq ft.	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
Project No: 110-0006
Project Name: John Adams M.S. - Bldg L (R-76-PTB)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	2" Gray Gougeon w/ Adhesive	Same As Previous	ND	N	250 in ft.	NEG As-d 1	8 8
M	6" Gray Gougeon w/ Adhesive	↓	ND	N	250 in ft.	NEG As-d 1	8
M	Chalkboards	↓	ND	N	100 sq ft.	Ass-d 1	8
M	Smooth Plaster walls	Rm 72 B	ND	N	100 sq ft.	NEG	N/A
M	1'x1' Peghole Ceiling Panels below tile	Above Drop Ceiling Panels 73, 72, 71, 70	ND	Y	3000 sq ft.	NEG	N/A
M	Rough Textured Plaster	R-74	ND	N	100 sq ft.	Ass-d 1	8
	Note -	Rm 75 Not Assessed					
		Electrical Rm					

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client:

SMMUSD

Project No:

110 - 0006

Project Name:

John Adams H.S. - Bldg. N (Library)

Page 1 of 2

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Acoustical Plaster Ceilings	Same As Previous	ND	N	2200 sq ft.	Pos	8
M	1'x1' Peghole (Random) Ceiling tile w/ Mastic	Also Rm 43, Tech Lounge	ND	Y	2200 sq ft.	NEG	N/A
M	Stucco		ND	N	3000 sq ft.	NEG	N/A
M	Drywall w/ St. C-P		ND	N	2000 sq ft.	Ass-d 2	8
M	Brown Plaster C-P		ND	N	1200 sq ft.	NEG	N/A
M	White Sinks Insulate		ND	N	4 sq ft.	NEG	N/A
M	Beige Marble Pattern Panels w/ Mastic	Library Under Carpet	ND	N	1200 sq ft.	NEG	N/A
M	12" Fiss-d Ceiling tile w/ Mastic	Library (N/E), Tech Lounge	ND	Y	~1200 sq ft.	Ass-d 1	8
M	12" Lt. Green F.T. w/ Mastic	Library (N/E) - Tech Lounge	ND	N	1	Ass-d 1	8

(1) S – surfacing, TSI – thermal system insulation, M – miscellaneous

(2) ND – not damaged, D – damaged, SD – significantly damaged

(3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
Project No: 110-0006
Project Name: John Adams H.S. - Bldg N (Library)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	4" Grey Gypsum w/ Adhesive	Teacher Lounge Rm 43	ND	N	60 sq. ft.	Ass'd 1	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams M.S.

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Rough Plaster	Same As Previous	ND	N	11000 sqft	NEG	N/A N/A
S	Accidental Plaster		ND	N	7500 sqft	Pos	8
S	Stucco		ND	N	6000 sqft.	NEG	N/A
M	2'x4' Random Pinkish Fissured Ceiling tile		ND	Y	3600 sqft.	NEG	N/A
M	12" Brown w/white streaks floor tile w/Mastic		ND	N	Not observed		
M	1'x1' Random Pinkish Ceiling tile w/Mastic		ND	Y	1200 sqft.	NEG	N/A
S	Stucco		ND	N	6000 sqft.	NEG	N/A
M	Drywall w/ Jt. LP		ND	N	4500 sqft.	NEG	N/A
M	Floor tile w/Mastic (candy 12" grey tile)		ND	N	800 sqft.	NEG	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMCUSD
 Project No: 110-0006
 Project Name: John Adams - M.S.

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	White Sink insulation	Same as Previous	ND	N	6 sqft.	NEG	N/A
M	Grey duct sealant		ND	N	10 sqft	NEG	N/A
M	Blue C-patch			N	3500 sqft.	Ass-d 1	8
M	12" Fiberglass tile				900 sqft.	↓	8
M	12"x12" grey speckled floor tile w/ Adhesive				5500 sqft.	↓	8
M	4" grey concrete w/ Adhesive			ND	500 in ft	Ass-d 1	8 8
M	2" grey concrete w/ Adhesive				50 in ft.	↓	8
M	Transite chalkboards				100 sqft.	110 sqft.	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-inspection Form

Client: SAMUSD
 Project No.: 110-0006
 Project Name: John Adams M.S. Bldg 5 (R-50-53)

Technician: F. Ruvoldo
 Date: 4/6/10
 Page: 1 of 2

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approx. Qty.	Results (3)	Recommendations/Response Action (4)
S	Rough Plaster	Same As Previous	ND	N	2300 sqft.	NEG	N/A
S	Acoustical Plaster (Le.ing)	↓	ND	N	3600 sqft.	Pos	8
S	Stucco		ND	N	3000 sqft.	NEG	N/A
M	Orig wall w/ st. Corp		ND	N	2600 sqft.	NEG	N/A
S	Smooth Plaster		ND	N	500 sqft.	NEG	N/A
SM	Black snake insulation		ND	N	2 sqft.	↓	N/A
SM	Grey Duct Sealant		ND	N	5 sqft.	↓	N/A
M	Window Putty		ND	N	5 sqft.	↓	N/A
M	white snake insulation		↓	N	4 sqft.	NEG	N/A
M	2'x4' Fissure & Ceiling Panel		↓	Y	100 sqft.	↓	8
M	Adhesive for Blue Carpet		↓	↓	N	500 sqft.	Assumed 1

- (1) S-Surfacing, TSI-thermal system insulation, M-miscellaneous
- (2) ND=no damaged, D-damaged, SD-significantly damaged
- (3) POS=Previously identified as positive, NEG=previously identified as negative, ASSUMED-1=new material, not sampled, assumed asbestos-containing
 ASSUMED-2=not enough samples collected, material is assumed asbestos-containing
- (4) For response actions (1-8) refer to "Response Action Ratings Sheet".

3-Year Re-Inspection Material Inventory

Client: SMMUCD
Project No: 110-0006
Project Name: John Adams M.S. - Bldg 5 (R-50 → 53)

Material Class (1)	Material	Mat la Location	Current Assessment(2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	12" Grey Speckled floor tile w/Adhesive	Same As Previous	ND	N	5500 sqft.	Ass-d ↓	8
M	4" Gray Louchura w/Adhesive	J	J	N	500 sqft.	↓	8
M	42 heavy Dk Green linoleum w/ Mastic	N/A	—				
M	Marble Pattern linoleum	J	—				
M	12" Fissured Ceiling tile	R-50 → 53	ND	Y	3500 sqft.	Ass-d ↓	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSP
 Project No: 110-0006
 Project Name: John Adams MS - Bldg P - (44-047 54-057)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Rough Plaster	same as previous	ND	N	4500 sqft.	4200 NEG Ⓟ sqft.	N/A
M	Acoustical Plaster Ceiling		ND	N	5000 sqft.	1 2000 POS Ⓟ sqft.	8
M	Stucco		ND	N	9000 sqft.	Pos (Trace)	8
M	Drywall w/ Jt. Comp		ND	N	2750 sqft.	NEG	N/A
M	Smooth Plaster		ND	N	2000 sqft.	NEG	N/A
M	2'x4' Fiberglass Ceiling Panel		ND	Y	1500 sqft.	NEG	N/A
M	1'x1' Random Rebar Ceiling tile w/ Gels		ND	Y	900 sqft.	NEG	N/A
M	Brown sheet flooring composite		ND	N	50 sqft.	NEG	N/A
M	Duct Sealant		ND	N	10 sqft.	NEG	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams H.S. - Bldg P- (44-047 54-057)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window Putty	See As Previous Report	ND	N	50 ln.ft.	NEG	N/A
M	12" Gray Speckled Fluorite w/ Adhes.	↓	↓	↓	3500 sq.ft.	As-d 1	8
M	2" Gray Louver w/ Adhesive		↓	↓	36 ln.ft.	↓	8
M	4" Gray Louver w/ Adhesive		↓	↓	200 ln.ft.	↓	8
M	6" Gray Louver w/ Adhesive.		ND	N	60 ln.ft.	As-d 1	8
M	Chalkboard		↓	↓	120 sq.ft.	↓	8
M	Blue Blue (-pet Adhes.)		↓	↓	2500 sq.ft.	↓	8
M	12" fiss-d Ceiling tile		↓	↓	4000 sq.ft.	↓	8
M	2'x4' fiss-d Ceiling tile		R-44	ND	↓	700 sq.ft.	As-d 1
M	12" straight Perhole Ceiling tile	R-44A	ND	Y	100 sq.ft.	As-d 1	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: John Adams M.S. Bldg. R (R-16-018)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum Board w/ Jt. Cap	Same as Previous	ND	N	4000 sqft.	Pos	8
M	1'x1' Random Peghole Ceiling tile w/ Mastic		ND	POS	2000 sqft	NEG	N/A
M	Stucco		ND	N	2200 sqft.	NEG	N/A
M	12" Grey Speckled F.T. w/ Adhesive		ND	N	2700 sqft	Ass-d	8
M	4" Black Louver w/ Adhesive		↓	↓	360 in ft.	↓	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMUSD
 Project No: 110-0006
 Project Name: Jehu Adams M.S. - Bldg H (R-80-881)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum Board w/ Jt. Comp	Same as previous	ND	N	5200 sq.ft.	NEG	N/A
M	1/2" Gray Speckled Floor Tile w/ Adhesive w/ Black Mortar		ND	N	3000 sq.ft.	NEG	N/A
M	2' x 4' Fiss-d Ceiling Panel		Y	800 sq.ft.	NEG		
M	Black sink Insulation		N	4 sq.ft.	NEG		
M	Window Puffy				300	NEG Pos	8
S	Stucco				3800 sq.ft.	Pos	8
M	6" Gray Concrete w/ Adhesive				360 sq.ft.	NEG	N/A
M	Duct Sealant		R-26		20 sq.ft.	Ass-1	N/A

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMMurp
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg E (R-87-89)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window Putty	Same As Previous	ND	N	300 luff.	Pos	8
M	1'x1' Reghole Rows Cells tile		ND	N	3200 sqft.	NEG	N/A
S	Smooth Plaster		ND	N	600 sqft.	NEG	N/A
M	Drywall w/ Joints		ND	N	950 sqft.	NEG	N/A
M	12" x 12" Gray Speckled F.T. w/ Adhesive		ND	N	2700 sqft.	NEG	N/A
M	6" Gray Corbel w/ Adhesive		ND	N	300 luff.	NEG	BYR
S	Stucco		ND	N	3500 sqft.	Pos	8
M	4" Gray Corbel w/ Adhesive		ND	N	100 luff.	NEG	N/A
M	Chalkboards		R-87, 88, 89	ND	N	40 sqft.	NEG
M	Chalkboards		+	+	40 sqft.	(+) 2	+

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: Somerset
 Project No: 110-0006
 Project Name: John Adams M.S. - Side D / Rm 90-91

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Window Putty	Exterior windows	ND	N	200 in ft	Pos	8
M	South Plaster	Rm 90B, 90A	ND	N	700 sq ft.	NEG	8 N/A
M	Drywall w/ Jt. Cap	Same As Previous	ND	N	500 sq ft.	NEG	8 N/A
M	Bedden Board	Rm 90A & B and Plaster	ND	N	200 sq ft.	NEG	N/A
M	12" straight Pepsols Ceiling tile (Nailed in type)	Same As Previous	ND	Y	2200 sq ft.	NEG	N/A
M	12" Gray Speckled floor tile w/ Adhesive			N	1800 sq ft.	NEG	N/A
M	6" Gray Concrete w/ Adhesive				240 in ft.	NEG	8
S	Stucco				2000 sq ft.	Pos	8
M	7" Gray Concrete w/ Adhesive				80 in ft.	NEG	N/A
M	Chalkboards	Rm 90, 91		N	40 sq ft.	Assumed 1	8
M	Chalkboard Mortar	Rm 90, 91			40 sq ft.	1	8

~~Notes: Rm 90B Not Assessed~~

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client:

SMMUSD

Project No:

110-0006

Project Name:

John Adams M.S. - Bldg T (Rm 21, 23, 30, 31)

Page 1 of 2

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
M	Gypsum Band w/ft. Cap.	Same As Previous.	ND	N	300 sqft.	POS	8
S	Stucco		ND	N	4500 sqft.	NEG	N/A
M	ft. Cap w/ Drywall		ND	N	6000 sqft.	NEG	N/A
M/S	Sand Textured Plaster		ND	N	3500 sqft.	NEG	N/A
M	12" Round Perforated Ceiling tile		ND	Y	300 sqft	NEG	N/A
M	2'x4' Fissured Ceiling Panel		ND	Y	2000 sqft.	NEG	N/A
M	Plastic tile w/ Mask (Sub flooring)		ND	N	3200 sqft.	NEG	N/A
M	9" x 9" tile f.t. w/ Mask		ND	N	8 sqft.	NEG	N/A
M	Green sheet Vinyl floor		ND	N	50 sqft.	NEG	N/A

(1) S – surfacing, TSI – thermal system insulation, M – miscellaneous

(2) ND – not damaged, D – damaged, SD – significantly damaged

(3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing

(4) For response actions 1–8 refer to "Response Action Ratings Sheet"

3-Year Re-Inspection Material Inventory

Client: SMMUSP
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg T (Rm 21, 23, 30, 31)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)	
M	White Sink Insulation	Same As Previous	ND	N	2 sq ft.	NEG	N/A	
M	Black Sink insulation	↓	↓	↓	4 sq ft.	NEG	N/A	
M	Grey Duct Sealt				10 sq ft.	NEG	N/A	
S	Acoustical Plaster Ceiling				7000 sq ft.	POS	8	
M	chalkboards				100 sq ft.	As-d	1	8
M	12" Grey Speckled Granite w/Plaster				4000 sq ft.	As-d	1	8
M	6" Grey Coveform w/Adhesion				10 sq ft.	As-d	1	8
M	4" Grey Coveform w/Adhesion				300 sq ft.	As-d	1	8
M	Adhesion for Blue Carpet.				2000 sq ft.	As-d	1	8
M	12" Fissured Ceiling tile				900 sq ft.	ND	N	↓

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMAUSD
 Project No: 110-0006
 Project Name: John Adams M.S. - Bldg 4 (R-10-DTS)

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)
S	Stucco	Same As Previous	ND	N	3000 sqft.	NEG	N/A
S	Sand Textured Plaster	↓	ND	N	4500 sq.ft.	NEG	N/A
M	Drywall w/ Jt. Comp.		ND	N	900 sqft.	NEG	N/A
M	White Snake Insulation		ND	N	10 sqft.	NEG	N/A
M	Acoustical Plaster Ceiling		ND	N	3600 sqft.	Pos	8
M	2'x4' Fiberglass Ceiling Panel		ND	Y	3600 sqft.	NEG	N/A
M	Chalkboards		ND	N	100 sqft.	Ass-d1	8
M	12" Grey F.T. Adhesive		ND	N	600 sqft.	↓	8
M	4" Grey Gypsum Adhesive		↓	↓	480 sqft.	↓	8
M	Adhesive for Blue Gypsum	↓	↓	300 sqft.	↓	8	

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



3-Year Re-Inspection Material Inventory

Client: SMUUCD
 Project No: 110-0006
 Project Name: John Adams M.S. ✓

Material Class (1)	Material	Material Location	Current Assessment (2)	Friable (Y or N)	Approximate Quantity	Results (3) or Sample #	Recommendations/Response Action (4)	
S	Stucco	Same As Previous	ND	N	2000 sqft.	NEG	N/A	
S	Sand Textured Plaster		ND	N	2200 sqft.	NEG	N/A	
M	Drywall w/ JT. Imp.		ND	N	300 sqft.	NEG	N/A	
M	Duct Sealant		ND	N	5 sqft.	NEG	L	
M	Chalkboards		ND	N	40 sq. ft.	Ass-d 1	8	
S	Acoustical Plaster Ceiling		ND	N	1800 sqft.	Pos	8	
M	12" Gray Speckled F.T. w/ Adhesive		ND	N	1800 sqft.	Ass-d 1	8	
M	4" Grey Covebase		ND	N	60 sqft.		POS	
M	Blue Carpet		ND	N	500 sqft		L	8
M	12" Fissured Ceiling Tile		ND	N	500 sqft		L	8

- (1) S – surfacing, TSI – thermal system insulation, M – miscellaneous
- (2) ND – not damaged, D – damaged, SD – significantly damaged
- (3) POS – previously identified as positive, NEG – previously identified as negative, ASSUMED – 1 = new material, not sampled, assumed asbestos-containing; ASSUMED – 2 = not enough samples collected, material is assumed asbestos-containing
- (4) For response actions 1–8 refer to "Response Action Ratings Sheet"



Appendix E

Assessments

ASSESSMENT SHEET

Functional Space Number N/A
 Homogenous Area Letter 2

Sample Number JAA-07-01 : 2
 School Number N/A
 Building Number 1

Functional Space Description Rm 95
 School Name John Adams H.S.
 Building Name Blk A

1. Friable Material: Y

2. Non-friable Material:

3. Damage Rating:
 (A) No Damage: X
 (B) Moderate Damage
 (1) <= 10% Distributed
 (2) <= 25% Localized
 (C) Significant Damage:
 (1) >10% Distributed
 (2) >25% Localized

4. Type of Damage
 (1) Deterioration
 (2) Water Damage
 (3) Air Erosion
 (4) Vandalism
 (5) Other N/A

5. Description of Damage: N/A
 (1) Blisters (4) Crushed Insulation
 (2) Buckling (5) Debris on Floor
 (3) Crumbling (6) Delamination

(7) Dislodged/Missing Pieces (11) Scrape Marks
 (8) Gouges (12) Stains/Discoloration
 (9) Punctures (13) Torn/Dislodged
 (10) Ripped/Missing Jackets (14) Water Damage

6. Disturbance Potential:
 (A) Potential For Contact:
 (1) Very Likely
 (2) Accidental Contact Possible
 (3) Small Disturbance Likely X
 (4) Large Disturbance Likely
 (>3 sq. or linear ft.)

(B) Possible Contact Factors:
 (1) Near Systems Requiring Repair/Maint.
 (2) High Traffic Area
 (3) Within Reach of Students and Teachers
 (4) Other N/A

(C) Occupancy:
 (1) Maint. Workers X
 (2) Students/Teachers X
 (3) Public
 (4) Area Not Normally Entered

 (1) 1/Day Approx. Hours 8hr.
 (2) 1/Wk. Approx. Hours 40hrs
 (3) 1/Mo. Approx. Hours 160hrs

(D) Influence of Vibration:
 (0) None X
 (1) Low
 (2) Moderate
 (3) High

(E) Source of Vibration:
 (1) Athletic Events
 (2) Mechanical Equipment
 (3) Sound Waves
 (4) Other N/A

(F) Potential For Air Erosion:
 (0) None X
 (1) Low
 (2) Moderate
 (3) High

(G) Source of Air Erosion:
 (1) Air Plenum
 (2) Air Shaft
 (3) Elevator Shaft
 (4) Other N/A

(H) Preventative Measures:
 (1) Restrict Access
 (2) Other O.M.

7. Removal of ACM Mandatory (Repair Not Possible):
 (Do not check above without giving reason below.)

Reason For Recommending Removal: _____

(A) Remodeling/Renovation Planned X (B) Demolition Planned X

Comments: _____

F. Ruvalcaba (Print Name) [Signature] (Signature) 4/6/10 (Date)

ASSESSMENT SHEET

Functional Space Number NA
Homogenous Area Letter 2

Sample Number JAA-11-01:2
School Number N/A
Building Number 2

Functional Space Description R-95-
School Name John Adams M.F.
Building Name Bldg A

1. Friable Material: Y

2. Non-friable Material:

3. Damage Rating:
(A) No Damage: X
(B) Moderate Damage
 (1) <= 10% Distributed
 (2) <= 25% Localized
(C) Significant Damage:
 (1) >10% Distributed
 (2) >25% Localized

4. Type of Damage
(1) Deterioration
(2) Water Damage
(3) Air Erosion
(4) Vandalism
(5) Other NA

5. Description of Damage: N/A
(1) Blisters (4) Crushed Insulation
(2) Buckling (5) Debris on Floor
(3) Crumbling (6) Delamination

(7) Dislodged/Missing Pieces (11) Scrape Marks
(8) Gouges (12) Stains/Discoloration
(9) Punctures (13) Torn/Dislodged
(10) Ripped/Missing Jackets (14) Water Damage

6. Disturbance Potential:
(A) Potential For Contact:
(1) Very Likely
(2) Accidental Contact Possible
(3) Small Disturbance Likely X
(4) Large Disturbance Likely
 (>3 sq. or linear ft.)

(B) Possible Contact Factors:
(1) Near Systems Requiring Repair/Maint.
(2) High Traffic Area
(3) Within Reach of Students and Teachers
(4) Other NA

(C) Occupancy:
(1) Maint. Workers X
(2) Students/Teachers X
(3) Public
(4) Area Not Normally Entered

(1) 1/Day Approx. Hours 8
(2) 1/Wk. Approx. Hours 40
(3) 1/Mo. Approx. Hours 160

(D) Influence of Vibration:
(0) None X
(1) Low
(2) Moderate
(3) High

(E) Source of Vibration:
(1) Athletic Events
(2) Mechanical Equipment
(3) Sound Waves
(4) Other X

(F) Potential For Air Erosion:
(0) None X
(1) Low
(2) Moderate
(3) High

(G) Source of Air Erosion:
(1) Air Plenum
(2) Air Shaft
(3) Elevator Shaft
(4) Other X

(H) Preventative Measures:
(1) Restrict Access
(2) Other 0: M

7. Removal of ACM Mandatory (Repair Not Possible):
(Do not check above without giving reason below.)

Reason For Recommending Removal: _____

(A) Remodeling/Renovation Planned X (B) Demolition Planned Y

Comments: _____

F. Pucalab (Print Name) [Signature] (Signature) 4/6/10 (Date)

ASSESSMENT SHEET

Functional Space Number NA
Homogenous Area Letter I

Sample Number JAD-08-01
School Number _____
Building Number _____

Functional Space Description R-82,83
School Name John Adams M.S.
Building Name Bldg G

1. Friable Material: X

2. Non-friable Material: _____

3. Damage Rating:
(A) No Damage: X
(B) Moderate Damage _____
 (1) <= 10% Distributed _____
 (2) <= 25% Localized _____
(C) Significant Damage: _____
 (1) >10% Distributed _____
 (2) >25% Localized _____

4. Type of Damage
(1) Deterioration _____
(2) Water Damage _____
(3) Air Erosion _____
(4) Vandalism _____
(5) Other N/A

5. Description of Damage: N/A
(1) Blisters _____ (4) Crushed Insulation _____
(2) Buckling _____ (5) Debris on Floor _____
(3) Crumbling _____ (6) Delamination _____

(7) Dislodged/Missing Pieces _____ (11) Scrape Marks _____
(8) Gouges _____ (12) Stains/Discoloration _____
(9) Punctures _____ (13) Torn/Dislodged _____
(10) Ripped/Missing Jackets _____ (14) Water Damage _____

6. Disturbance Potential:
(A) Potential For Contact:
(1) Very Likely _____
(2) Accidental Contact Possible _____
(3) Small Disturbance Likely X
(4) Large Disturbance Likely _____
 (>3 sq. or linear ft.) _____

(B) Possible Contact Factors:
(1) Near Systems Requiring Repair/Maint. _____
(2) High Traffic Area _____
(3) Within Reach of Students and Teachers _____
(4) Other N/A

(C) Occupancy:
(1) Maint. Workers X
(2) Students/Teachers X
(3) Public _____
(4) Area Not Normally Entered _____

(1) 1/Day Approx. Hours <1
(2) 1/Wk. Approx. Hours _____
(3) 1/Mo. Approx. Hours _____

(D) Influence of Vibration:
(0) None X
(1) Low _____
(2) Moderate _____
(3) High _____

(E) Source of Vibration:
(1) Athletic Events _____
(2) Mechanical Equipment _____
(3) Sound Waves _____
(4) Other N/A

(F) Potential For Air Erosion:
(0) None X
(1) Low _____
(2) Moderate _____
(3) High _____

(G) Source of Air Erosion:
(1) Air Plenum _____
(2) Air Shaft _____
(3) Elevator Shaft _____
(4) Other N/A

(H) Preventative Measures:
(1) Restrict Access _____
(2) Other O: M

7. Removal of ACM Mandatory (Repair Not Possible): _____
(Do not check above without giving reason below.)

Reason For Recommending Removal: _____

(A) Remodeling/Renovation Planned X (B) Demolition Planned X

Comments: _____

F. Peralta
(Print Name)


[Signature]
(Signature)

4/6/10
(Date)

Appendix F

Site Map

John Adams Teachers



Appendix G

Coffey Environments Employee Certifications

State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Cesar Ruvalcaba



Name

Certification No. 95-1799

Expires on 10/27/10

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

State of California
Division of Occupational Safety and Health
Certified Site Surveillance Technician

Fabian Ruvalcaba

Name

Certification No. 06-4088

Expires on 11/15/10

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.

