



**HAZARDOUS MATERIALS SURVEY REPORT
FOR THE
MODERNIZATION OF BUILDING E
(PACKAGE 1B)
AT
LINCOLN MIDDLE SCHOOL
SANTA MONICA MALIBU UNIFIED SCHOOL DISTRICT
1501 CALIFORNIA AVENUE
SANTA MONICA, CALIFORNIA 90403
PROJECT # DSA#A03-113031/FILE NO. 19-96

ATC PROJECT NO. 52.25526.0009 (Task 4)

DECEMBER 1, 2010**

Prepared by:

ATC Associates Inc.
25 Cupania Circle
Monterey Park, California 91755
Phone: (323) 517-9780
Fax: (323) 517-9781

Prepared for:

Ms. Julia Eiko Hawkinson, AIA, LEED AP
Deputy Program Manager
c/o Parsons/CCM, A Joint Venture
Santa Monica Malibu Unified School District
12100 Wilshire Boulevard
Los Angeles, California 90025

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	3
2.0 ASBESTOS	4
2.1 Sampling Methodology and Analysis	4
2.2 Results	5
2.3 Conclusions and Recommendations	6
3.0 LEAD-CONTAINING MATERIALS	10
4.0 OTHER HAZARDOUS MATERIALS	12
4.1 Devices Containing Mercury	12
4.2 Equipment Containing Polychlorinated Biphenyls	12
4.3 Equipment Containing Chlorofluorocarbons and/or Hydrochlorofluorocarbons	13
4.4 Fluorescent Light Tubes	13
4.5 Miscellaneous Hazardous Materials	14
4.6 Conclusions and Recommendations	14
5.0 LIMITATIONS	15
6.0 SIGNATURES	16
 APPENDICES	
APPENDIX A - Asbestos Laboratory Analytical Reports & Sample Logs	17
APPENDIX B – Previous Lead Laboratory Analytical Reports, Sample logs, XRF Logs	18
APPENDIX C - Site Diagrams	19
APPENDIX D - State of California Asbestos and Lead Inspector Certifications	20

1.0 INTRODUCTION

ATC Associates Inc. (ATC) was retained by Santa Monica Malibu Unified School District (SMMUSD) to conduct a hazardous material survey of Building E at Lincoln Middle School located at 1501 California Avenue, Santa Monica California. The purpose of the survey was to determine the presence of hazardous materials located at Building E prior to the modernization and renovation activities.

The scope of the project was to identify any accessible suspect asbestos-containing materials (ACM), lead-containing materials, and other hazardous materials including devices containing mercury, equipment containing polychlorinated biphenyls (PCBs), equipment containing chlorofluorocarbons (CFCs) and/or hydrochlorofluorocarbons (HCFCs), fluorescent light tubes, and other miscellaneous hazardous materials, from Building E. The Modernization of Building E which will involve the renovation of the Library (Room 212) and the installation of fire sprinklers throughout the building will impact the interior/exterior walls, ceiling materials, and flooring materials. ATC also conducted inspection of the attic and crawl spaces which will require access for the planned project.

This hazardous materials survey was conducted on November 9 & 10 by the following State of California Division of Occupational Safety and Health (DOSH) Certified Asbestos Consultant (CAC), Certified Site Surveillance Technician (CSST), and California Department of Public Health (DPH) Certified Lead-Related Construction Inspector/Assessor (LRCIA) staff:

Mr. Robert Medina (CSST #99-2673) and (LRCST #1087)

Mr. Carlos A. Galdamez (CAC #98-2379) and (LRCIA #7843)

Prior to this hazardous materials survey, ATC was provided with the following asbestos and lead reports for Lincoln Middle School. Previous surveys are included in Appendices E in this report:

- ACM-LBP-HAZMAT Report, prepared by ATC Associates, Inc. (ATC), dated April 3, 2009.
- Asbestos Survey Project Record, prepared by CTL Environmental Services (CTL), dated May 13, 2008.
- Exterior Lead-Based Paint Survey Project Record, prepared by CTL, dated January 10, 2007.

All field work and report preparation was performed under the direction and guidance of Mr. Carlos A. Galdamez (Project Manager) and reviewed by Mr. Stephen Drengson (CAC #06-3975 and LRCIA #2895).

2.0 ASBESTOS

2.1 Sampling Methodology and Analysis

ATC typically surveys buildings in teams of two, one person documenting the proceedings of the survey, the other performing bulk sampling and other miscellaneous activities. The team performs a preliminary visual inspection of the building impacted to identify and quantify suspect ACM. A sampling strategy is then developed to provide representative sampling of the suspect ACM in accordance with the methods and procedures identified in the Asbestos Hazard Emergency Response Act (AHERA).

ATC field staff utilized semi-destructive sampling methods to collect samples of accessible suspect asbestos-containing building materials. Some areas of the buildings, e.g. occupied units, edges of roof, pipes, chases, etc. may not have been accessible at the time of the inspection.

Each sample is placed in a container; the container is sealed, labeled and placed in a storage bag. Samples are documented by entering the sample data on a bulk log, including a description of the material, sample number, location, condition, accessibility, friability, potential for damage, and quantity. Typically, the sample location is marked on an 8-1/2 x 11 inch not-to-scale floor plan. Throughout the process, special care is taken to prevent cross-contamination of the collected samples. Sampling equipment is cleaned after each sample is obtained. In addition, sample containers are placed directly beneath each sample location, when feasible, to collect any materials which may become dislodged during the sampling process. Any debris generated by the sampling is cleaned by wet-cleaning methods. Sample locations are appropriately repaired.

All bulk sample analysis is conducted by Polarized Light Microscopy (PLM) with dispersion staining as described in the *"Method for the Determination of Asbestos in Bulk Building Materials"* (EPA-600/R-93/116, July 1993). A suspect material is immersed in a solution of known refractive index and subjected to illumination of polarized light. The color displayed enables mineral identification. Quality control samples at a rate of 10% or one per project, whichever is greater, are reanalyzed by a second, independent analyst.

Please note, in California the abatement of materials with detectable quantities of asbestos - legally defined as materials containing percentages of asbestos greater than one-tenth of one percent ($>0.1\%$) by area are defined as asbestos-containing construction material (ACCM) and regulated by Cal/OSHA.

The amended National Emission Standard for Hazardous Air Pollutants (NESHAP), November 20, 1990, included a requirement that when the asbestos content of a bulk sample material is determined using procedures outlined and the asbestos content is estimated to be less than 10% by a method other than point counting, the parties legally responsible for a building (owner/operator) may (1) elect to assume the amount to be greater than 1% and treat the material as a regulated asbestos-containing material, or (2) require verification of the amount by the Point Counting method. The purpose of this procedure is to minimize false negative analysis (reporting the samples as containing less than 1% asbestos for asbestos-containing samples actually containing greater than 1%) and false positives (reporting the sample as containing greater than 1% asbestos for samples containing less than 1% asbestos). Point

Counting was included in NESHAP in response to an EPA study that found an unacceptable amount of false negative and false positive analyses by methods outlined in the interim method.

The samples were analyzed by Hygeia Laboratories, Inc. (Hygeia) located in Sierra Madre, California. Hygeia is certified by the State of California Department of Health Services Environmental Laboratory Accreditation Program (ELAP) and accredited by the United States Department of Commerce National Institutes of Standards and Technology's (NIST) National Voluntary Laboratory Accreditation Program (NVLAP) for asbestos bulk fiber analysis.

2.2 Results

A total of thirty-eight (38) bulk asbestos samples were collected and analyzed by Polarized Light Microscopy (PLM) with dispersion staining.

The following table details the materials sampled and the location from which the samples were collected during the current survey. Table I lists the asbestos bulk sampling results. Materials identified as ACM or ACCM are denoted in **bold**. The asbestos laboratory analytical report and asbestos sampling logs of the materials sampled during the field survey are included in Appendix A. Site sampling diagrams are included in Appendix C.

Table I –Asbestos Survey Results – Building E

Sample #	Sampling Location	Material Description	Approx. Quantity	Analysis Results
126	Attic Space	TSI – Pipe Insulation & Associated Debris	~ 30 LF ~ 20 SF	15% Chrysotile 10% Amosite
127	Attic Space	Sheet flooring, Brown Battleship	N/A	ND
128	Attic Space	Sheet flooring, Brown Battleship	N/A	ND
129	Attic Space	Sheet flooring mastic, Brown Battleship	N/A	ND
130	Attic Space	Roofing Debris	N/A	ND
131	Attic Space	Roofing Debris	N/A	ND
132	Attic Space	Roofing Debris	N/A	ND
133	Room 205	2'x2' Fissured Ceiling Tiles (Lay-In)	N/A	ND
134	Room 211	2'x2' Fissured Ceiling Tiles (Lay-In)	N/A	ND
135	Room 217	2'x2' Fissured Ceiling Tiles (Lay-In)	N/A	ND
136, 139	Room 212 (Library)	12"x12" Random Holes Wall Tiles and Associated Mastic	N/A	ND
137, 140	Room 218	12"x12" Random Holes Wall Tiles and Associated Mastic	N/A	ND
138, 141	Room 220	12"x12" Random Holes Wall Tiles and Associated Mastic	N/A	ND

Sample #	Sampling Location	Material Description	Approx. Quantity	Analysis Results
142, 145	Room 212 (Library)	12"x12" Fissured Wall Tiles and Associated Mastic	N/A	ND
143, 146	Room 212 (Library)	12"x12" Fissured Wall Tiles and Associated Mastic	N/A	ND
144, 147	Room 212 (Library)	12"x12" Fissured Wall Tiles and Associated Mastic	N/A	ND
148	Room 217	4" Gray Base Cove and Associated Mastic	N/A	ND
149	Room 212	4" Gray Base Cove and Associated Mastic	N/A	ND
150	2 nd Floor Hallway	4" Gray Base Cove and Associated Mastic	N/A	ND
151	2 nd Floor Boy's Restroom Wall Cavity	Black – Wall Barrier Moisture Paper	N/A	ND
152, 155	1 st Floor Hallway above the 2'x4' Ceiling Tiles	12"x12" Straight Holes Ceiling Tiles and Associated Mastic	N/A	ND
153, 156	1 st Floor Hallway above the 2'x4' Ceiling Tiles	12"x12" Straight Holes Ceiling Tiles and Associated Mastic	N/A	ND
154, 157	1 st Floor Hallway above the 2'x4' Ceiling Tiles	12"x12" Straight Holes Ceiling Tiles and Associated Mastic	N/A	ND
158	1 st Floor @ Hallway above the Ceiling Tiles	Fireproofing-Like Material (Gray)	N/A	ND
159	1 st Floor @ Hallway above the Ceiling Tiles	Fireproofing-Like Material (Gray)	N/A	ND
160	1 st Floor @ Hallway above the Ceiling Tiles	Fireproofing-Like Material (Gray)	N/A	ND
161	Crawl Spaces	TSI – Air Cell Pipe Debris	~200 SF	60% Chrysotile
162	Crawl Spaces	TSI – Pipe Insulation Debris	~300 SF	10% Chrysotile 15% Amosite
163	Attic Space above Room 308	TSI – Pipe Fittings (Elbows) Debris	~10 SF	10% Chrysotile 15% Amosite

ND = None Detected

N/A = Not Applicable

SF = Square Feet

LF = Linear Feet

2.3 Conclusions and Recommendations

Based on the ATC survey results and previous ATC's survey and CTL survey, asbestos was identified in the materials listed in the following table (Table II). It should be assumed that any of the materials listed below if encountered within the building should be treated as ACM or ACCM.

Table II – Asbestos-Containing Materials and Approximate Quantities (Building E)

Material Description	Location	Condition	Friable (F) / Non-Friable (NF)	Results	Approx. Quantity
9" x 9" Floor tile, light brown & Mastic	Rooms 110, 110A, 110B, 110C (Underneath the 12"x12" Floor Tiles)	Good	NF	7% Chrysotile	900 SF
9" x 9" Floor tile, tan & Mastic	Room 116 (Underneath the 12"x12" Floor Tiles)	Good	NF	5% Chrysotile	1,800 SF
9"x9" Floor Tile, dark green, & Mastic	Rooms 111, 111A (Under the Carpet)	Good	NF	7% Chrysotile	1,000 SF
Pipe insulation	Attic Space and Crawl Spaces	Poor	F	20% Chrysotile 10% Amosite	30 LF (Attic) 300 LF (Crawl Space)
Pipe insulation debris	Attic Space and Crawl Spaces	Poor	F	20% Chrysotile 7% Amosite	20 SF (Attic) 300 SF (Crawl Spaces) 6,300 SF (Crawl Space)
Air Cell Pipe Insulation Debris	Crawl Spaces	Poor	F	60% Chrysotile	200 SF 6,300 SF (Crawl Space)
Pipe Insulation Fittings (Elbows)	1 st Floor Ceiling Space above the Drywall and Plaster Ceiling	Unk.	F	10% Chrysotile 15% Amosite	Unk.*
Cement fitting	Bldg. E – Basement, Storage Area, Southwest Closets	Good	NF	20% Chrysotile 10% Amosite	4 EA
Stucco	Bldg. E – Exterior Walls	Good	NF	<1% Amosite 3% Chrysotile	14,000 SF
Window putty	Bldg. E – Exterior Windows	Good	NF	4% Chrysotile	900 LF
Wallboard & joint compound	Bldg. E – Floor 1/ 102, 104, 106, 118, 120, Floor 2/ 202, 204, 206, 212, 212A, 212B, 212C, 212D (Above the Ceiling Tiles)	Fair	NF	1% Actinolite 3% Chrysotile	6,300 SF
Roofing mastic, black	Bldg. E – S/W Roof	Good	NF	10% Chrysotile	200 SF

SF = Square Feet

LF = Linear Feet

NA = Not Applicable

*Unk. – Unknown

*At the time of the inspection, ATC was not able to determine the entire condition and estimate of how many pipe fittings (elbows) are present throughout the building. ATC was able to determine that the pipe fittings are located above the drywall ceiling and plaster ceiling on the 1st floor of the building.

If additional suspect materials are observed by the contractor during the planned project, the consultant should be notified and the presence of these materials should be verified. All materials listed above should be removed and disposed of as ACM prior to any modernization/demolition activities.

Asbestos is a hazardous substance. Its condition, handling and disposal are regulated by Federal, State, and local agencies. ACMs and ACCMs generally do not pose a health threat unless the asbestos fibers are disturbed by renovation, construction or demolition and may become airborne and inhaled.

Prior to the planned modernization activities, ATC recommends removal of the ACMs and ACCMs noted above that will be disturbed. Contractors must use asbestos safe work practices when disturbing the material listed above. In regards to the attic and crawl spaces, clean up of the pipe insulation debris is required prior to any access to these areas.

A building material is considered to be ACM if at least one sample collected from the homogeneous material shows asbestos present in an amount greater than one percent (>1%) by weight. Materials with less than one percent (<1%) asbestos are not regulated by the United States Environmental Protection Agency (USEPA) or Federal Occupational Safety and Health Administration (OSHA). However, the State of California, Division of Occupational Safety and Health (DOSH) does regulate materials with greater than one-tenth of one percent (>0.1%) by weight under California Code of Regulations (CCR) Title 8, Section 1529. These materials are considered ACCM.

If PLM results indicate a material to contain trace amounts of asbestos (<1%), the building owner may choose to treat this material as ACM or have the material analyzed using the 1000 point count method. If the point count analysis is used, this result will be used for reporting purposes.

Building occupants and contractors working in an area where asbestos is present must be informed of the type and location of ACM. Since these materials are going to be impacted during the planned building demolition, ATC recommends abatement of all identified ACM by a California licensed, certified and registered asbestos abatement contractor. Asbestos abatement must be performed in accordance with Federal and State Occupational Safety and Health Administration (OSHA and CAL/OSHA) respectively, and South Coast Air Quality Management District (SCAQMD) regulations.

CAL/OSHA also requires employers to implement specific work practices, which protect workers from airborne asbestos exposure. Building materials, which contain even low levels of asbestos (trace amounts), can potentially generate significant concentrations of airborne asbestos fibers when disturbed. Therefore, control measures should be instituted which adequately addresses worker health and safety during the planned demolition activities involving these materials.

Notes:

- 1) ATC observed fiberglass pipe insulation with ACM pipe fittings (Elbows) above the drywall and plaster ceiling which are above the lay-in ceiling tiles throughout the 1st floor. At the time of the inspection, ATC only observe several spot on the 1st floor where the drywall ceiling and plaster ceiling had an opening to observe the pipe fittings (elbows) and where intact at that time with no damages or debris.
- 2) At the time of the inspection, ATC was not able to verify any windows which were covered during the last renovation to the Library (Room 212); however, if the windows are still present, then the window putty is assumed to be asbestos until testing can be conducted.
- 3) At the time of the inspection, the attic space is off-limits until decontamination of the pipe insulation debris is conducted.
- 4) At the time of the inspection, the crawl spaces located in the basement of the building are off-limits until decontamination is conducted.

3.0 LEAD-CONTAINING MATERIALS

ATC's field technicians conducted a visual inspection of Building E and determined that no additional testing and/or sampling were required. The table below identifies the lead-containing materials located in Building E. A copy of the ATC's previous report is located in Appendix B of this report.

Table III – Lead-Containing Materials and Quantities (Building E)

Material Description	Location	Condition	Approx Quantity
Wood Door, orange	Basement / 116	Peeling	1 EA
Wood Support Column, yellow	Basement / 116	Peeling	5 EA
Wood Door Frame, yellow	Basement/ 116	Intact	1 EA
Wood Baseboard, tan	Floor 1/ 109	Intact	40 LF
Wood Baseboard, tan	Floor 1/ 111A	Intact	12 LF
Wood Baseboard, tan	Floor 1/ 117A Conference Room	Intact	54 LF
Wood Window Sill, tan	Floor 1/ 156	Peeling	1 EA
Metal Vault Door, blue	Floor 1/ Main Office	Intact	1 EA
Wood Baseboard, tan	Floor 2/ 205	Intact	64 LF
Cast Iron Sink, white	Floor 2/ 212D	Intact	1 EA
Cast Iron Sink, white	Floor 2/ 215 Faculty Lounge	Intact	1 EA
Metal Ladder, tan	Floor 2/ 215 Faculty Lounge	Intact	1 EA
Wood Baseboard, tan	Floor 2/ 217	Intact	65 LF
Wood Door Casing, tan	Floor 2/ 217	Intact	2 EA
Wood Window Sill, white	Floor 2/ 217	Intact	5 EA
Wood Door Casing, tan	Floor 2/ 217A	Intact	1 EA
Metal Water Heater Platform, tan	Floor 2/ 217A Custodian Room	Intact	1 EA
Wood Door Casing, tan	Floor 2/ 221	Intact	1 EA
Wood Window Sill, white	Floor 2/ 221	Intact	5 EA
Wood Door Casing, tan	Floor 2/ 223	Intact	1 EA
Wood Window Sill, white	Floor 2/ 223	Intact	6 EA
Concrete Riser, white	Floor 2/ Center Stairwell	Intact	12 LF
Wood Baseboard, tan	Floor 2/ Hallway	Intact	600 LF
Masonry Stair Riser, tan	Floor 2/ Stairs	Intact	12 LF

EA = Each

SF = Square Feet

LF = Linear Feet

Lead is a hazardous substance. Its condition, handling and disposal are regulated by Federal, State, and local agencies. Lead-containing materials, LBP and LCP generally do not pose a health risk unless the material is disturbed or sufficiently deteriorated to produce dust, which may become airborne and inhaled or ingested. Based on the ATC previous survey results and the CTL exterior lead survey, the lead-containing materials listed above meets the definition of lead-based paint. The California Department of Public Health (DPH) (as defined in Title 17 California Code of Regulations) and United States Department of Housing and Urban Development (HUD) define lead-based paint (LBP) as paints containing greater than 1.0 mg/cm², as well as, paints containing greater than or equal to 0.5% lead by weight or 5,000 milligrams per kilogram (mg/kg) or parts per million (ppm) total lead. Paint containing less than these amounts is generally termed "lead-containing paint" (LCP).

Cal/OSHA regulations (8 CCR 1532.1 - Lead Construction Standard) do not provide a definition for "lead-based paint," but rather provide a Permissible Exposure Limit (PEL) for worker exposure to airborne lead particles of 50 micrograms per cubic meter of air (50 µg/m³ for an 8-hour time-weighted average). The OSHA Lead Construction Standard also lists an Action Level of 30 µg/m³ for an 8-hour time-weighted average. All employees (workers) and supervisors who are engaged in lead related construction and shown to be exposed to lead at or above the Permissible Exposure Limit, shall be trained by state-accredited training providers and certified by the California Department of Public Health.

If lead-containing material, LBP or LCP will be impacted (activities such as such as demolition, sanding, sand /shot blasting, chipping or any other method of surface preparation which may cause potential airborne lead concentrations to exceed the CAL/OSHA action level) during the building renovation, ATC recommends removal and/or stabilization of those building materials denoted above that will be disturbed during the upcoming demolition, as well as, other surfaces of similar substrate, color and condition. Contractor must use lead safe work practices when disturbing any of the materials listed above.

Work activities impacting the lead-containing materials pose a potential exposure risk for workers and/or building occupants. Workers trained in proper safety and respiratory techniques should perform work activities that may impact the LBP. All construction work where an employee may be occupationally exposed to lead must comply with CAL/OSHA requirements. This regulation requires initial employee exposure monitoring to evaluate worker exposure during work that disturbs lead-containing materials (lead present in detectable levels). Any disturbance to LBP surfaces or materials, such as demolition, sanding, sand /shot blasting, chipping or any other method of surface preparation which may cause potential airborne lead concentrations above current regulatory levels are prohibited by state law.

4.0 OTHER HAZARDOUS MATERIALS

ATC's field technicians conducted a visual inspection of Building E for the presence of Mercury in devices including thermostats and exterior flood lights, equipment containing Polychlorinated Biphenyls (PCBs) such as light ballasts, equipment containing Chlorofluorocarbons (CFCs) and Hydrochlorofluorocarbons (HCFCs) such as air conditioning units and refrigerators, fluorescent light tubes and compact fluorescent lights, and other miscellaneous hazardous materials. There was no change from ATC's previous report. Below is a summary of the hazardous materials from the previous report.

4.1 Devices Containing Mercury

From ATC's previous report no thermostats were observed throughout Building E but fifteen (15) Mercury Vapor Lights (MVL) throughout the interior and exterior of Building E were observed.

Table IV – Devices Containing Mercury

Building	Material / Approx. Quantity
Building E	Thermostats – 0 MVLs – 15

Mercury is a heavy, shiny, silvery-white poisonous metal that is a liquid at room temperature. Liquid mercury evaporates at room temperature and gives off harmful, invisible, odorless vapors. Breathing these vapors causes the most harm to people, but mercury can also be harmful when swallowed or when it contacts broken skin. Mercury is quite toxic: it causes birth defects and works its way into the food chain. Women and children are most at risk from mercury poisoning, which can cause brain and nerve damage resulting in impaired coordination, blurred vision, tremors, irritability and memory loss.

Mercury is a fast-moving liquid that spreads quickly. Prompt containment and control of both the liquid and its vapors is very important. In general, do not remove the mercury from a device such as a switch.

4.2 Equipment Containing Polychlorinated Biphenyls

From ATC's previous report, approximately one-thousand one hundred (1,100) ballasts throughout the classrooms and offices in Building E. All ballasts that potentially contain PCBs should be closely inspected and removed prior to the planned modernization project.

Table V – Ballast Locations and Quantities

Building	Approx. Quantity
Building E	1,100

PCBs are a family of chlorinated compounds that were dielectric or especially non-conductive.

PCBs are oily liquids that are usually pale yellow to clear. PCBs are a family of chemicals manufactured and used in the United States until the late 1970's, which were mostly used in electrical devices like capacitors, transformers and lighting ballasts to protect their oils from breaking down at high temperatures. These substances are strictly regulated because of their toxicity and persistence in the environment.

PCBs continue to be a major source of fish contamination, leading to fish consumption advisories for people. Management of PCBs is based on their concentration in an item. Materials with PCB concentrations of 50 parts per million (ppm) or greater are regulated by the U.S. EPA under the Toxic Substances Control Act.

All PCB light ballasts should be kept intact, removed, and containerized in a manner that will prevent breakage, spillage, or release. Label and store the PCBs to ensure proper handling, transportation and disposal prior to the planned modernization project.

4.3 Equipment Containing Chlorofluorocarbons and Hydrochlorofluorocarbons

From ATC's previous report, approximately two (2) air conditioning units were observed in Building E. These units may contain CFC's or HCFC's (Freon) and should be properly recovered prior to any impact to the units.

Table VI – Air Conditioning Unit Locations and Quantities

Building	Approx. Quantity
Building E	2

CFCs and HCFCs are man-made refrigerants that destroy the ozone layer. Federal laws also prohibit releases and also require recovery of these substances, as well as other refrigerants that are global warming gases or pose other health or environmental problems. They must be properly recovered, using approved equipment operated by qualified technicians. The entity recovering these refrigerants must be registered with the DNR and supply documentation to whomever receives the scrapped equipment that the refrigerants were properly removed.

4.4 Fluorescent Light Tubes

From ATC's previous report, approximately two thousand and two hundred (2,200) fluorescent light tubes and eleven (11) Compact Fluorescent Lights (CFLs) throughout the classrooms and offices in Building E. These tubes should be removed and disposed if impacted by the planned modernization project.

Table VII – Fluorescent Light Tube / CFLs Locations and Quantities

Building	Material / Approx. Quantity
Building E	Tubes – 2,200 CFLs – 11

4.5 Miscellaneous Hazardous Materials

From ATC's previous report, the following were observed throughout the building: motion detectors, heat detectors, smoke detectors, hydraulic door closers, and miscellaneous cleaning and chemical supplies.. These materials should be removed and disposed of properly (e.g., recycled) prior to planned modernization project.

Table X – Miscellaneous Materials Locations and Quantities

Building	Material / Approx. Quantity
Building E	Motion Detectors – 25 Smoke Detectors – 36 Hydraulic Door Closers – 86 Exit Signs – 27 Misc. Cleaning and Chemical Supplies – Observed Fire Extinguishers – 32 Fixed Refrigerators – 0

4.6 CONCLUSIONS AND RECOMMENDATIONS

Based on information collected from the Hazardous Material Survey, ATC offers the following recommendations:

- All items identified and listed above in Table II (ACM), Table III (lead), and Section 4 (other hazardous materials) of this report which will be impacted by the planned Modernization Project shall be remove in accordance with all applicable Federal, State and local regulations.
- Use lead safe work practices when impacting lead of any level above the detection limit.

5.0 LIMITATIONS

Our professional services have been performed, our findings obtained, and our recommendations prepared in accordance with principles and practices in the fields of environmental science and engineering. The results, findings, conclusions, and recommendations expressed in the report are based only on conditions that were noted during the noted dates of fieldwork. This warranty is in lieu of all other warranties either expressed or implied. This company is not responsible for the independent conclusions, opinions, or recommendations made by others based on the results and designs presented in this report.

The passage of time may result in a change in the environmental characteristics at this site and surrounding properties. This report does not warrant against future operations or conditions, nor does it warrant operations or conditions present of a type or at a location not investigated.

Reasonable effort is made by ATC personnel to locate and sample materials representative of the site structures. However, for any facility, the existence of unique or concealed materials or debris not observed by ATC is a possibility. ATC does not warrant, guarantee or profess to have the ability to locate or identify all concealed hazardous materials at the facility. This report is intended for the sole use of SMMUSD. This report is not intended to be utilized as a construction and/or bidding document, nor is this document designed to be used as a remediation or abatement specification. The scope of services performed in execution of this evaluation may not be appropriate to satisfy the needs of other users, and use or re-use of this document or the findings, conclusions, or recommendations is at the risk of said user.

This inventory does not represent an exhaustive listing of types of materials that may be required to be removed from a building prior to demolition. Any conditions or materials that could not be visually identified on the surface were not inspected and may differ from those conditions or materials noted.


6.0 SIGNATURES

ATC appreciates the opportunity to be of service to SMMUSD on this project and looks forward to working with you on future assignments. In the meantime, if you have questions or comments regarding the information in this report or if we can be of further assistance, please do not hesitate to contact the undersigned in the ATC Los Angeles, California office at (323) 517-9780.

Respectfully submitted,
ATC ASSOCIATES INC.



Carlos A. Galdamez
Project Manager
CAC No. 98-2379 / LRCIA No. 7843



Stephen R. Drengson
Program Manager
No. 06-3975 / LRCIA No. 2895

APPENDIX A

Asbestos Laboratory Analytical Report & Sample Logs

00052100664

ASBESTOS BULK SAMPLE LOG


 25 CUPANIA CIRCLE
 MONTEREY PARK, CA 91755

 BLDG. TYPE School

 PAGE 1 OF 4

 DATE 11/10/10

 TASK NO. 00003

 AREA 0009

AREA NAME/DESCRIPTION

 PROJECT: Sm mvsd/Parsons
 CLIENT: Licold ms
 EVALUATOR: C. Galda m r z / R. Medina

AREA	AREA NAME/DESCRIPTION	AREA	AREA NAME/DESCRIPTION
01	Attic		
02	2nd Floor Areas		

SAMPLE #	BLDG/FLOOR	AREA #	AREA USAGE	MTRL CODE	MATERIAL DESCRIPTION	ESTIMATED QUANTITY										OTHER
126	Attic	01	4	65	TST Pipe Debris					3 LF	23	1	1	1	P1510	
127				34	Group Sheet flooring (Battleship)					200 SF	13	1	1	1	NO	X
128															NO	
129															NO	
130				65	Roofing Debris					5F	13	1	1	1	NO	
131															NO	
132															NO	
133	2nd	02	5	26	2nd floor - Room 205										NO	
134															NO	
135															NO	

MATERIAL CODES (SEE BELOW)										AREA USAGE CODES				FRAILITY CODES		CONDITION CODES		AIR EROSION CODES		CONTACT CODES		VIBRATION CODES		WATER CODES																	
25	ACOUSTIC PANEL	26	ACOUSTIC PANEL (7'X7')	27	ACOUSTIC PANEL (7'X4')	28	ACOUSTIC TILE (1'X1')	29	ACOUSTIC TILE (1'X2')	30	ACOUSTIC TILE MASTIC	31	RESILIENT FLOOR TILE (12"X12")	32	FLOOR TILE MASTIC	33	RESILIENT SHEET FLOORING	34	SHEET FLOORING MASTIC	35	CARPET MASTIC	36	BASEBOARD	37	BASEBOARD MASTIC	38	SPRAY-APPLIED FIREPROOFING	39	HYVAC FLEXIBLE CONNECTOR	40	DUCT INSULATION	41	DUCT INSULATION LAGGING	42	DUCT TAPE						
43	BOILER INSULATION	44	BOILER LAGGING	45	BREACHING INSULATION	46	CHILLER INSULATION	47	CHILLER LAGGING	48	STORAGE TANK/EXCHANGER INSUL.	49	STORAGE TANK/EXCHANGER LAGG	50	PUMP HOUSING INSULATION	51	PUMP HOUSING LAGGING	52	CASKETRY	53	FUEL INSULATION	54	TRANSITE PIPE	55	PIPE FITTING INSULATION	56	PIPE FITTING LAGGING	57	PIPE RUN LAGGING	58	PLASTER BROWNSCRATCH	59	PLASTER FINISH COAT	60	WALL BOARD	61	JOINT COMPOUND	62	PAINT/COATING	63	SPRAY-APPLIED ACOUSTIC MATL
										1 VOID/CHASE/	3 STORAGE			1 GOOD		1 LOW		1 LOW		1 LOW		1 LOW			1 LOW																
										2 MECHANICAL	6 CONTINUOUS			2 DAMAGED		2 MODERATE		2 MODERATE		2 MODERATE		2 MODERATE			2 MODERATE																
										2 FRABLE				3 SIGNIFICANTLY DAMAGED		3 HIGH		3 HIGH		3 HIGH		3 HIGH			3 HIGH																

FOR LAB USE ONLY

 ANALYST'S SIGNATURE/DATE
[Signature] 11-22-10
 LAB DIRECTOR'S SIGNATURE/DATE

 65
 66
 67
 68
 69

00052 10 06674

ASBESTOS BULK SAMPLE LOG



25 CUPANIA CIRCLE
MONTEREY PARK, CA 91755

School

PAGE 3 OF 4

ADDRESS

DATE 11/10/10

TASK NO. 00003

AREA 0009

AREA 25526

PROJECT NO.

CLIENT

SMMUSD/Paisers

PROJECT

Lincoln MS

EVALUATOR

C. Galdamez/
R. Medina

AREA	AREA NAME/DESCRIPTION	AREA	AREA NAME/DESCRIPTION
02	2nd floor Acen		
03	3rd floor Acen		

SAMPLE #	BLDG/FLOOR	AREA #	AREA USAGE	MTRL CODE	MATERIAL DESCRIPTION	ESTIMATED QUANTITY	UNIT CODES	POSITIVE CODES	PERCENTAGES
145	2nd	02	5	3	01x1' wall tile mastic - Ann 212		1 2 2 1 2 1	LF = LINEAR FEET SF = SQUARE FEET EA = EACH	CHRYSOCTILE AMOSITE CROCIDOLITE OTHER
146		11	1	3		2145			
147		11	1	3		2145			
148		11	1	3	4th floor - Ann 217		1 2 1 2 2 2		
149		11	1	3	- Ann 212	2148			
150		11	1	3	- staircase	2148			
151		11	1	3	64 Bldg - Boy's RR wall cavity		1 2 1 1 1 3		
152	1st	03	1	2	straight mastic above fire 2nd fl @		1 3 2 1 2 1		
153		11	1	3		2152			
154		11	1	3		2152			

MATERIAL CODES (SEE BELOW)										AREA USAGE CODES										FRIABILITY CODES										CONDITION CODES										AIR EROSION CODES										CONTACT CODES										VIBRATION CODES										WATER CODES																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																									

FOR LAB USE ONLY

ANALYST'S SIGNATURE: *[Signature]* 11-22-10
LAB DIRECTOR'S SIGNATURE: *[Signature]*

00052 10 0664

ASBESTOS BULK SAMPLE LOG



25 CUPANIA CIRCLE
MONTEREY PARK, CA 91755

School

Bldg. Type

Page 4 of 4

DATE: 11/10/10

TASK NO. 0003

52 25526

SMMSD/Parsons
Lincoln MS
C. Galdamez
R. Medina

AREA	AREA NAME/DESCRIPTION	AREA	UNIT CODES	POSITIVE	PERCENTAGES
03	1st Floor		LF = LINEAR FEET SF = SQUARE FEET EA = EACH	P POSITIVE ND NON DETECT T TRACE (< 1%)	CHRYSOITILE AMOSITE CROCIDOLITE OTHER
04	Common Space				
05	Attic - All Area				

SAMPLE #	Bldg. Floor	Area #	Area Usage	MTRL CODE	MATERIAL DESCRIPTION	ESTIMATED QUANTITY	UNIT CODES	POSITIVE	PERCENTAGES
155	1st	03	1	30	insulation - above the roof structure	2155	132121	ND	
156									
157									
158				39	Ging - insulation by Am 103	2155	222121	ND	
159									
160									
161	Basement	04	1	65	Am-cell pipe debris	2158	231111	P 60	
162		04	1	65	Attic pipe debris		231111	P 1015	
163	Attic	05	1	65	Attic Elbow Debris		231111	P 1015	

- 01 BOILER INSULATION
02 BOILER LAGGING
03 BREACHING INSULATION
04 BREACHING LAGGING
05 CHILLER INSULATION
06 CHILLER LAGGING
07 STORAGE TANK/EXCHANGER INSUL
08 STORAGE TANK/EXCHANGER LAGG
09 PUMP HOUSING INSULATION
10 PUMP HOUSING LAGGING
11 GASKETRY
12 FUEL INSULATION
13 TRANSITE PIPE
14 PIPE FITTING INSULATION
15 PIPE FITTING LAGGING
16 PIPE RUN INSULATION
17 PIPE RUN LAGGING
18 PLASTER BROWN/SCRATCH
19 PLASTER FINISH COAT
20 PLASTER COMPOSITE
21 WALLBOARD
22 JOINT COMPOUND
23 PAINT/COATING
24 SPRAY-APPLIED ACOUSTIC MAT'L
- 25 ACOUSTIC PANEL
26 ACOUSTIC PANEL (2'X2')
27 ACOUSTIC PANEL (2'X4')
28 ACOUSTIC TILE (1'X1')
29 ACOUSTIC TILE (1'X2')
30 ACOUSTIC TILE MASTIC
31 RESILIENT FLOOR TILE (9'X9')
32 RESILIENT FLOOR TILE (12'X12')
33 FLOOR TILE MASTIC
34 RESILIENT SHEET FLOORING
35 SHEET FLOORING MASTIC
36 CARPET MASTIC
37 BASEBOARD
38 BASEBOARD MASTIC
39 SPRAY-APPLIED FIREPROOFING
40 HVAC FLEXIBLE CONNECTOR
41 DUCT INSULATION
42 DUCT INSULATION LAGGING
43 DUCT TAPE
- 43 ROOF COMPOSITE (ROOF CORE)
44 ROOF CAP SHEET (ROLLED)
45 ROOF SHINGLE
46 ROOF FLASHING
47 ROOF FELT
48 ROOF MASTIC
49 ROOF PENETRATION MASTIC
50 THERMAL INSULATION
51 HEAT SHIELD
52 TRANSITE SHEET MAT'L
53 MORTAR/GROUT
54 SINK UNDERCOAT MATERIAL
55 ELECTRICAL WIRE INSULATION
56 WALL PAPER
57 FABRIC/ROPE
58 WOOD FLOOR MASTIC
59 FIRE-RATED/INSULATED DOOR CORE
60 EXTERIOR STUCCO
61 MIRROR MASTIC
62 LEVELING COMPOUND
63 WINDOW PUTTY
64 BARRIER PAPER
- 1 VOID/CHASE/ CAVITY
2 MECHANICAL
3 STORAGE
4 OCCASIONAL
5 CONTINUOUS
6 DAMAGED
7 SIGNIFICANTLY DAMAGED
- 1 LOW
2 MODERATE
3 HIGH
- 1 LOW
2 MODERATE
3 HIGH
- 1 LOW
2 MODERATE
3 HIGH
- 1 LOW
2 MODERATE
3 HIGH

FOR LAB USE ONLY

ANALYST'S SIGNATURE: *[Signature]* DATE: 11-22-10

LAB DIRECTOR'S SIGNATURE: _____



Hygeia Laboratories Inc.

82 W. Sierra Madre Blvd
Sierra Madre, CA 91024-2434
(626) 355-4711 (626) 355-4497 Fax

NIST/NVLAP Lab Code 102116-0
California ELAP Certificate No. 1269

Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

November 22, 2010

Mr. Carlos Galdamez ATC Los Angeles 25 Cupania Circle Monterey Park, CA 91755		Hygeia Reference No.: 00052 10 0664																
		Samples Analyzed: 38 Sampler: C. Galdamez/R. Medina Sample Condition: Acceptable								Date Collected: November 10, 2010 Date Received: November 11, 2010 Date Analyzed: November 22, 2010								
Client Reference: 52.25526.0009 (T3) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %							QC		
Client Sample ID Hygeia Sample ID	Sample Description - color Comments	Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders	Paint		Petite	Cork
126 1248771	TSl pipe debris - white	Yes	15	10								75						
127 1248772	Sheet flooring - brown/tan	No							10			5		5			80	X
128 1248773	Sheet flooring - brown/tan	No							10			5		5			80	
129 1248774	Sheet flooring - brown/tan	No							10			5		5			80	
130 1248775	Roofing debris - black	No							70	2	3	5		20				
131 1248776	Roofing debris - black	No							70	2	3	5		20				
132 1248777	Roofing debris - black	No							70	2	3	5		20				
133 1248778	2' x 2' ceiling panel - white/grey	No							77	3		5			3	12		
134 1248779	2' x 2' ceiling panel - white/grey	No							77	3		5			3	12		X
135 1248780	2' x 2' ceiling panel - white/grey	No							77	3		5			3	12		
136 1248781	1' x 1' ceiling tile - white/brown	No							95			3			2			
137 1248782	1' x 1' ceiling tile - white/grey	No							77	3		5			3	12		
138 1248783	1' x 1' ceiling tile - white/grey	No							95			3			2			



Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

November 22, 2010

Client Reference: 52.25526.0009 (T3) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %							QC	
		Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders	Paint		Petite
Client Sample ID Hygeia Sample ID	Sample Description - color Comments																
139 1248784	Acoustic tile mastic - brown	No							3			47	50				
140 1248785	Acoustic tile mastic - brown	No							3			47	50				
141 1248786	Acoustic wall mastic - brown	No							3			47	50				
142 1248787	1' x 1' wall tile - white/grey	No							2	78		18		2			
143 1248788	1' x 1' wall tile - white/grey	No							2	78		18		2			X
144 1248789	1' x 1' wall tile - white/grey	No							2	78		18		2			
145 1248790	Acoustic tile mastic - brown	No										30	70				
146 1248791	Acoustic tile mastic - brown	No										30	70				
147 1248792	Acoustic tile mastic - brown	No										30	70				
148 1248793	Baseboard mastic - tan	No										30	70				
149 1248794	Baseboard mastic - tan	No										30	70				
150 1248795	Baseboard mastic - tan	No										30	70				
151 1248796	Barrier paper - black	No							75			5	20				
152 1248797	1' x 1' ceiling tile - white/orange	No							90			5		5			
153 1248798	1' x 1' ceiling tile - white/orange	No							90			5		5			
154 1248799	1' x 1' ceiling tile - white/orange	No							90			5		5			



Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

November 22, 2010

Client Reference: 52.25526.0009 (T3) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %									
		Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders	Paint	Perlite	Cork	QC
Client Sample ID Hygeia Sample ID	Sample Description - color Comments																	
155 1248800	Ceiling tile mastic - brown	No							5			45		50				
156 1248801	Ceiling tile mastic - brown	No							5			45		50				
157 1248802	Ceiling tile mastic - brown	No							5			45		50				X
158 1248803	Fireproofing - grey	No							40			60						
159 1248804	Fireproofing - grey	No							40			60						
160 1248805	Fireproofing - grey	No							40			60						
161 1248806	Pipe debris - grey	Yes	60						20			20						
162 1248807	Pipe debris - white	Yes	10	15								75						
163 1248808	Pipe debris - white	Yes	10	15								75						

Guillermo Hernandez

Microscopist - Guillermo Hernandez

The analyses of the samples in this report were performed using polarized light microscopy using the EPA method 600/R-93/116. The phase abundances provided are visually estimated and expressed as percent area. Total percentage of sample constituents may total greater than 100 due to trace amounts. The limit of detection for this analytical method is less than one percent. In multilayer samples, unless otherwise specified, the asbestos concentration is reported for the layer where asbestos is found. These results lie within the statistical limits of variability calculated for standard reference samples routinely analyzed in the laboratory. On a per sample basis, the accuracy and precision of the results depend on the type of sample and its asbestos content.

Hygeia recommends transmission electron microscopy (TEM) analysis on organically bound bulk materials (eg., vinyl floor tile, mastics, roofing materials, joint compounds) when PLM analysis shows undetectable quantities of asbestos. These materials often contain milled asbestos with fiber diameters and lengths too small to be resolved by the PLM and the analysis may yield a false negative result.



Hygeia Laboratories Inc. is accredited under the NIST/NVLAP program for asbestos in bulk material by polarized light microscopy and the State of California for asbestos analysis.

Hygeia Laboratories Inc. and its personnel shall not be liable for any misinformation provided to us by the client regarding these samples or for any misuse or interpretation of information supplied by us. Liability shall extend to providing replicate analyses only. This report must not be used to claim product endorsement by NVLAP or any agency of the US Government. Hygeia will retain samples for a period of three months unless otherwise specified. This report relates only to samples submitted and analyzed. This report may not be reproduced except for in full, without the written approval of this laboratory. Please feel free to contact Hygeia regarding any questions about these results, this report, or the analytical methods employed.

Arturo Casas

Arturo Casas - Supervisor of Optical Microscopy

ATC Request for Laboratory Services / Chain of Custody - Asbestos

Send Report To <u>CARLOS GALDAMEZ</u> Company Name <u>ATC Los Angeles</u> Company Address <u>25 Cupania Circle</u> Company Address <u>Monterey Park, CA 91755</u> Phone <u>(323) 517-9780</u> Fax <u>(323) 517-9781</u> Client Project No <u>52.2556.000 9 T 0003.</u> Client Project Ref <u>SMMUSD Lincoln M.S.</u> Bill Branch No. _____ (For Inter-Company billing purposes, please provide correct Project and Task No.) Samples Submitted <u>38</u> Samples Analyzed <u>38</u> Hygeia Reference No <u>00052 10 0664</u>		Hygeia Laboratories Inc. 82 W. Sierra Madre Blvd. Sierra Madre, CA 91024 (626) 355-4711 (626) 355-4497 FAX		
Reporting Fax _____ Cell/Pager _____ Phone _____ E-mail <u>Stephen.Drengson@atcassociates.com</u>				
Turnaround Time ☒ Normal (3-5 business days) _____ Next Day (24 hrs) _____ Same Day (Rush) _____ Weekend Rush _____				
Type of Sample _____ Air ☒ Bulk _____ Dust (microvac) _____ Dust (wipe) _____ Soil _____ Paint _____ Water _____ Other _____				
Asbestos (Optical) ☒ PLM _____ PLM Point Count 400 pts _____ PLM Point Count 1000 pts _____ PCM	Asbestos (TEM) _____ AHERA _____ EPA Level II _____ NIOSH 7402 (PCM Equivalent) _____ ISO 10312	_____ Qualitative Dust (microvac or wipe) _____ Quantitative Dust (microvac or wipe) _____ Drinking Water (potable) _____ Wastewater (non-potable)	_____ Qualitative Bulk _____ Semi-Quantitative Bulk _____ Full-Quantitative Bulk _____ Particle Characterization _____ Supplies	
Additional Instructions ☒ Written Report Requested <i>PLEASE CONTACT CARLOS GALDAMEZ w/ RESULTS.</i>				
For Lab Use Only Sample Integrity ☒ accept _____ reject _____		1st Sample No <u>1248771-808</u> Price / Sample <u>7-</u>		
Results reported by: _____ Date _____ Time _____ Initials _____ Verbal Fax E-mail _____ Date _____ Time _____ Initials _____ Verbal Fax E-mail _____ Date _____ Time _____ Initials _____ Verbal Fax E-mail _____		Invoice No. <u>77-</u> Log Out Date _____		
Comments				
Relinquished By (Signature) 	Received By (Signature) 	Time <u>3:30 PM</u>	Date <u>11-11-10</u>	Reason for Change of Custody

The sample collector is responsible for ensuring that all samples have been preserved according to the appropriate and applicable methodology.

00052 09 0062

PAGE 1 OF 13

BULK TYPE

52 25526

6009

00001

DATE 02 06 09

BULK SAMPLE LOG



25 CUPANJA CIRCLE

MONTEREY PARK, CA 91755

POSITIVE
CODESP POSITIVE
ND NON DETECT
T TRACE (<1%)
N NEGATIVE BY
POINT COUNT (<0.1%)

PERCENTAGES

CHRYSOTILE
AMOSITE
CROCIDOLITE
OTHER

AREA NAME/DESCRIPTION

AREA

AREA NAME/DESCRIPTION

AREA #

BUILDING/FLOOR

CLIENT

PROJECTED

EVALUATOR

AREA	AREA NAME/DESCRIPTION	AREA	AREA NAME/DESCRIPTION	AREA	AREA NAME/DESCRIPTION	AREA #	BUILDING/FLOOR
01	Classroom #217	05	Classroom #209				
02	Classroom #207						
03	Classroom #205						
04	Classroom #101						

ESTIMATED QUANTITY

MATERIAL DESCRIPTION

MTRL CODE

MATERIAL CODES (SEE BELOW)

SAMPLE #

SAMPLE #	AREA #	BUILDING/FLOOR	MATERIAL CODES (SEE BELOW)	AREA USAGE CODES	FRAGILITY CODES	CONDITION CODES	AIR EROSION CODES	CONTACT CODES	VIBRATION CODES	WATER CODES
001	01	2nd Fl	34	1 VOID/CHASER CAVITY	1 NON-FRAGILE	1 GOOD	1 LOW	1 LOW	1 LOW	1 LOW
002	01	2nd Fl	34	2 MECHANICAL	2 FRAGILE	2 DAMAGED	2 MODERATE	2 MODERATE	2 MODERATE	2 MODERATE
003	01	2nd Fl	34	3 STORAGE	3 SIGNIFICANTLY DAMAGED	3 SIGNIFICANTLY DAMAGED	3 HIGH	3 HIGH	3 HIGH	3 HIGH
004	01	2nd Fl	34	4 OCCASIONAL	4 OCCASIONAL	4 OCCASIONAL	4 OCCASIONAL	4 OCCASIONAL	4 OCCASIONAL	4 OCCASIONAL
005	01	2nd Fl	34	5 CONTINUOUS	5 CONTINUOUS	5 CONTINUOUS	5 CONTINUOUS	5 CONTINUOUS	5 CONTINUOUS	5 CONTINUOUS
006	01	2nd Fl	34	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)	6 ROOFING COMPOSITE (ROOF CUT)
007	01	2nd Fl	34	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET	7 ROOFING CAP SHEET
008	01	2nd Fl	34	8 ROOFING SHINGLE	8 ROOFING SHINGLE	8 ROOFING SHINGLE	8 ROOFING SHINGLE	8 ROOFING SHINGLE	8 ROOFING SHINGLE	8 ROOFING SHINGLE
009	01	2nd Fl	34	9 ROOFING FLASHING	9 ROOFING FLASHING	9 ROOFING FLASHING	9 ROOFING FLASHING	9 ROOFING FLASHING	9 ROOFING FLASHING	9 ROOFING FLASHING
010	01	2nd Fl	34	10 ROOFING FELT	10 ROOFING FELT	10 ROOFING FELT	10 ROOFING FELT	10 ROOFING FELT	10 ROOFING FELT	10 ROOFING FELT
011	01	2nd Fl	34	11 ROOFING MASTIC	11 ROOFING MASTIC	11 ROOFING MASTIC	11 ROOFING MASTIC	11 ROOFING MASTIC	11 ROOFING MASTIC	11 ROOFING MASTIC
012	01	2nd Fl	34	12 THERMAL INSULATION	12 THERMAL INSULATION	12 THERMAL INSULATION	12 THERMAL INSULATION	12 THERMAL INSULATION	12 THERMAL INSULATION	12 THERMAL INSULATION
013	01	2nd Fl	34	13 HEAT SHEILD	13 HEAT SHEILD	13 HEAT SHEILD	13 HEAT SHEILD	13 HEAT SHEILD	13 HEAT SHEILD	13 HEAT SHEILD
014	01	2nd Fl	34	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT	14 TRANSITE SHEET MATT
015	01	2nd Fl	34	15 MORTAR/ROUT	15 MORTAR/ROUT	15 MORTAR/ROUT	15 MORTAR/ROUT	15 MORTAR/ROUT	15 MORTAR/ROUT	15 MORTAR/ROUT
016	01	2nd Fl	34	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL	16 SINK UNDERCOAT MATERIAL
017	01	2nd Fl	34	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION	17 POWER LEAD INSULATION
018	01	2nd Fl	34	18 WALL PAPER	18 WALL PAPER	18 WALL PAPER	18 WALL PAPER	18 WALL PAPER	18 WALL PAPER	18 WALL PAPER
019	01	2nd Fl	34	19 FIBROGLASS	19 FIBROGLASS	19 FIBROGLASS	19 FIBROGLASS	19 FIBROGLASS	19 FIBROGLASS	19 FIBROGLASS
020	01	2nd Fl	34	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC	20 WOOD FLOOR MASTIC
021	01	2nd Fl	34	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE	21 FIRE-RATED INSULATED DOOR CORE
022	01	2nd Fl	34	22 DUCT TAPE	22 DUCT TAPE	22 DUCT TAPE	22 DUCT TAPE	22 DUCT TAPE	22 DUCT TAPE	22 DUCT TAPE

FOR LAB USE ONLY

#1,2,3 Appears to be leveling compound.

50 EXTERIOR STUCCO
60 ROOF PENETRATION
MASTIC
61 CARPET MASTIC
62 OTHER (DESCRIBE)

ANALYST'S SIGNATURE/DATE

2/18/09

LAB DIRECTOR'S SIGNATURE/DATE

2/18/09

BULK SAMPLE LOG



25 CUPANIA CIRCLE
MONTEREY PARK, CA 91765

DATE: 020609

0	0	0	0	1
---	---	---	---	---

2	5	5	2	6
5	2			

3444

_____ LINCOLN M.S.

P. Chavre

14	Rm # 110 B	18	Classroom # 262
15	Classroom # 220		
16	Rm # 111 A		
17	1st Floor Hallway		

UNIT	POSSNEG.	PERCENTAGES
CODE	CODE	
YEAR FEET	P POSITIVE	
INCHES FEET	ND NON DETECT	
MARK YARDS	T TRACE (<1%)	
INCH	N NEGATIVE BY	
CH	POINT COUNT (<0.1%)	
		CHRYSOTILE
		AMOSITE

SAMPLE #	BLDG/FLOOR	AREA #	AREA MEASURE	MTRL CODE	MATERIAL DESCRIPTION	ESTIMATED QUANTITY	OTHER
031	1st Fl	11		33	YELLOW FIBROITE MASTIC	12002	
032		12					
033		13					
034	1st Fl	14		34	Blue Mosaic Floor Sheeting w/ Paper Backing	1502	
035							
036							
037	2nd Fl	15		37	White Base Coat mastic under Black Base Coat	12001	
038	1st Fl	16					
039	2nd Fl	17		37	White Base Coat mastic under Grey Base Coat	50001	
040		18		21	White Drywall wall	200002	

[illegible]

FOR LAB USE ONLY

58 EXTERIOR STUCCO	ANALYST'S SIGNATURE	DATE
59 ROOF PENETRATION	LAS ORSE FORTY SIGNATURE	DATE
60 MASTIC		
61 CARPET MASTIC		
62 OTHER (DESCRIBE)		

58 EXTERIOR STUCCO
90 ROOF PENETRATION
MASTIC
51 CARPET MASTIC
52 OTHER (DESIGNER)

BULK SAMPLE LOG



25 CUPANIA CIRCLE
MONTEREY PARK, CA 91755

DATE: 02/10/09

TASK NO. 00001

52 25526

SMUSD

LINCOLN M.S.

D-CATION

AREA	AREA NAME/DESCRIPTION	AREA	UNIT CODES
24	Bldg A S/E ROOF		1 LINEAR FEET 2 SQUARE FEET 3 CUBIC YARDS 4 CUBIC INCH 5 EACH
25	Bldg A North ROOF		
26	Bldg A S/W ROOF		
27	Bldg A South ROOF		

SAMPLES	AREA	AREA NAME	ESTIMATED QUANTITY	PERCENTAGES
051	ROOF	48	2002	ND
052		48	102	ND
053		42	102	P 10
054		42	102	ND
055		42	102	ND
056		42	102	ND
057		42	102	ND
058		42	102	ND
059		42	102	ND
060		42	102	ND

AREA	AREA NAME/DESCRIPTION	AREA	UNIT CODES
24	Bldg A S/E ROOF		1 LINEAR FEET 2 SQUARE FEET 3 CUBIC YARDS 4 CUBIC INCH 5 EACH
25	Bldg A North ROOF		
26	Bldg A S/W ROOF		
27	Bldg A South ROOF		


AREA	AREA NAME/DESCRIPTION	AREA	UNIT CODES
24	Bldg A S/E ROOF		1 LINEAR FEET 2 SQUARE FEET 3 CUBIC YARDS 4 CUBIC INCH 5 EACH
25	Bldg A North ROOF		
26	Bldg A S/W ROOF		
27	Bldg A South ROOF		

AREA	AREA NAME/DESCRIPTION	AREA	UNIT CODES
24	Bldg A S/E ROOF		1 LINEAR FEET 2 SQUARE FEET 3 CUBIC YARDS 4 CUBIC INCH 5 EACH
25	Bldg A North ROOF		
26	Bldg A S/W ROOF		
27	Bldg A South ROOF		

ANALYST'S SIGNATURE
DATE: 2/18/09

FOR LAB USE ONLY

59 EXTERIOR STUCCO	60 ROOF PENETRATION	61 CARPET MASTIC	62 OTHER (DESCRIBE)
--------------------	---------------------	------------------	---------------------



Hygeia Laboratories Inc.

82 W. Sierra Madre Blvd
Sierra Madre, CA 91024-2434
(626) 355-4711 (626) 355-4497 Fax

NIST/NVLAP Lab Code 102116-0
California ELAP Certificate No. 1269

Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

February 18, 2009

Mr. Paul Cota ATC Los Angeles 25 Cupania Circle Monterey Park, CA 91755		Samples Analyzed: 114 Sampler: D. Carrier Sample Condition: Acceptable														Hygeia Reference No.: 00052 09 0062 Date Collected: Feb. 6 & 10, 2009 Date Received: February 12, 2009 Date Analyzed: February 16, 2009	
Client Reference: 52.25526.0009 (T1) SMMUSD - Lincoln MS		Asbestos Type, %						Non-Asbestos Constituents, %								QC	
Client Sample ID Hygeia Sample ID	Sample Description - color Comments	Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders			
001 1161746	Sheet flooring - grey <i>Appears to be leveling compound.</i>	No										100			X		
002 1161747	Sheet flooring - grey <i>Appears to be leveling compound.</i>	No										100					
003 1161748	Sheet flooring - grey <i>Appears to be leveling compound.</i>	No										100					
004 1161749	Flooring mastic - yellow	No										40		60			
005 1161750	Flooring mastic - yellow	No										40		60			
006 1161751	Flooring mastic - yellow	No										40		60			
007 1161752	Carpet mastic - yellow	No									2	38		60			
008 1161753	Carpet mastic - yellow	No									2	38		60	X		
009 1161754	12" x 12" floor tile - grey	No										80		20			
010 1161755	12" x 12" floor tile - grey	No										80		20			
011 1161756	Floor tile mastic - black	No										30		70			
012 1161757	Floor tile mastic - black	No										30		70	X		
013 1161758	Sheet flooring - tan/brown	No							50			30		20			
014 1161759	Sheet flooring - tan/brown	No							50			30		20			
015 1161760	Sheet flooring - tan/brown	No							50			30		20			

Bldg
E
↓



Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

February 18, 2009

Client Reference: 52.25526.0009 (T1) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %							QC
Client Sample ID Hygeia Sample ID	Sample Description - color Comments	Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders		
019 1161764	Linoleum flooring - pink/tan	No							60			20		20		
020 1161765	Linoleum flooring - tan	No							60			20		20		X
023 1161768	Linoleum flooring - green	No							60			20		20		
024 1161769	Linoleum flooring - green	No							60			20		20		
025 1161770	Barrier paper - black	No							75		5	5		15		
026 1161771	Barrier paper - black	No							75		5	5		15		X
027 1161772	Barrier paper - black	No							75		5	5		15		
028 1161773	12" x 12" floor tile - grey	No										80		20		
029 1161774	12" x 12" floor tile - grey	No										80		20		
030 1161775	12" x 12" floor tile - grey	No										80		20		
031 1161776	Floor tile mastic - yellow	No							5			30		65		
032 1161777	Floor tile mastic - yellow	No							5			30		65		
033 1161778	Floor tile mastic - yellow	No							5			30		65		
034 1161779	Sheet flooring - grey	No							30	5	5	40		20		X
035 1161780	Sheet flooring - grey	No							30	5	5	40		20		
036 1161781	Sheet flooring - grey	No							30	5	5	40		20		
037 1161782	Covebase mastic - white	No										70		30		
038 1161783	Covebase mastic - white	No										70		30		




Bulk Sample Analysis Summary

Analytical Method: EPA 600/R-93/116

February 18, 2009

Client Reference: 52.25526.0009 (T1) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %							QC
Client Sample ID Hygeia Sample ID	Sample Description - color Comments	Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders		
039 1161784	Covebase mastic - white	No										70	30			
040 1161785	Drywall - white	No							5			95				
041 1161786	Drywall - black	No							5			95				
042 1161787	Roofing core - black	No							25	15		30	30			
043 1161788	Roofing core - black	No							20	20		30	30			
044 1161789	Roofing core - black	No							20	20		30	30			
045 1161790	Roofing cap sheet - grey/black	No								20		40	40			
046 1161791	Roofing cap sheet - grey/black	No								20		40	40			
047 1161792	Roofing cap sheet - grey/black	No								20		40	40			
048 1161793	Roof shingle - grey/black	No								20		50	30			
049 1161794	Roof shingle - grey/black	No								20		50	30			
050 1161795	Roof shingle - grey/black	No								20		50	30			
051 1161796	Roofing mastic - black	No							2			38	60			
052 1161797	Roofing mastic - silver/black	No							5			35	60			
053 1161798	Roofing mastic - white/black	Yes	10									20	70			
054 1161799	Duct tape - white/tan	No							50			30	20			
055 1161800	Duct tape - grey/silver/tan	No							50			30	20			

Bldg
E
↓



Bulk Sample Analysis Summary

Analytical Method: EPA 800/R-93/116

February 18, 2009

Client Reference: 52.25526.0009 (T1) SMMUSD - Lincoln MS		Asbestos Type, %							Non-Asbestos Constituents, %							QC
Client Sample ID Hygeia Sample ID	Sample Description - color Comments	Asbestos Detected	Chrysotile	Amosite	Crocidolite	Tremolite / Actinolite	Anthophyllite	Other	Cellulose	Fiberglass	Synthetic	Mineral Fillers	Vermiculite	Organic Binders		
056 1161801	Duct tape - grey/white	No							10			50	40			
057 1161802	Roofing core - black	No							10	20		40	30			
058 1161803	Roofing core - black	No							10	20		40	30			
059 1161804	Roofing core - black	No							10	20		40	30			
060 1161805	Roofing mastic - grey/	No							20			30	50			
061 1161806	Roofing mastic - grey/black	Yes	5									35	60			X
063 1161808	12" x 12" floor tile - tan	No										80	20			
064 1161809	12" x 12" floor tile - tan	No										80	20			
065 1161810	12" x 12" floor tile - tan	No										80	20			
066 1161811	Floor tile mastic - black	No							5			30	65			
067 1161812	Floor tile mastic - black	No							5			30	65			
068 1161813	Floor tile mastic - black	No							5			30	65			
069 1161814	Pipe insulation - white	Yes	20	10								70				
072 1161817	Roofing core - black	No							10	20		40	30			
073 1161818	Roofing core - black	No							10	20		40	30			
074 1161819	Roofing core - black	No							10	20		40	30			
075 1161820	Roof shingle - black	No								20		50	30			
076 1161821	Roof shingle - black	No								20		50	30			X

Bldg
E
F

MATERIAL INVENTORY **ASBESTOS**

CLIENT: Santa Monica-Malibu School District

PROJECT NO: 107-0008

PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403

Page 1 of 6

Building E

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Repairable	Damage
Stucco	L-46-01 Through L-46-20	None Detected Trace Amosite 2% 3% Chrysotile	Previously sampled, Cape Environmental, 1994	Exterior walls	74,000 sq. ft.	No	No
Gypsum board with tile compound	L-32-01 Through L-33-25	None Detected 1% Actinolite Trace 3% Chrysotile	Previously sampled, Cape Environmental, 1994	First floor rooms 102, 104, 106, 118, 120 (ceilings only) second floor- 202, 204, 206 212 A, B, C, D, 212	6,500 sq. ft.	No	No
Window putty	L-48-01 Through L-48-03	None Detected 4% Chrysotile	Previously sampled, Cape Environmental, 1994	Exterior windows	900 lin. ft.	No	No
9"x9" tan floor tile with mastic	L-01-01 L-01-01M	5% Chrysotile (tile) 3% Chrysotile (mastic)	Previously sampled, Cape Environmental, 1994	Rooms 112, 112A, B, C, D, E, F, 116	11,800 sq. ft.	No	No
9"x9" light brown floor tile with mastic	L-02-01 L-02-02M	3% Chrysotile (tile) 7% Chrysotile (mastic)	Previously sampled, Cape Environmental, 1994	Rooms 110, 110A, 110B, 110C	900 sq. ft.	No	No
9"x9" dark brown floor tile with mastic	L-03-01 L-03-02M	3% Chrysotile (tile) 10% Chrysotile (mastic)	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Red linoleum with mastic	L-18-01 L-18-01M	None Detected (tile and mastic)	Previously sampled, Cape Environmental, 1994	Rooms 123, 218, 205, 220, 222	4,500 sq. ft.	No	No
Pink linoleum with mastic	L-19-01 L-19-01M	None Detected (tile and mastic)	Previously sampled, Cape Environmental, 1994	Rooms 103, second floor- 221, 223, 215, 217, 203	5,400 sq. ft.	No	No
Rough plaster walls	L-34-01 Through L-34-07	None Detected	Previously sampled, Cape Environmental, 1994	Basement entry ways, first floor rooms-121, vault, 117A, 117B, 117, 113, 109, 109A, 110A, 111, 111A, 105, 108, 108A, B, C, 112, 112B, C, D, E, F, 116, 116A, 123; second floor- 225	28,800 sq. ft.	No	No
Rough plaster ceiling	L-28-01 Through L-28-07	None Detected	Previously sampled, Cape Environmental, 1994	Hallway, 217A, 217, 215A, 215, 211, 209, 205, 203 217, 212A, B, C, D	28,800 sq. ft.	No	No
Green linoleum with mastic	L-20-01 L-20-01M	None Detected (tile and mastic)	Previously sampled, Cape Environmental, 1994	First floor- room 121, 105	1,800	No	No

MATERIAL INVENTORY **ASBESTOS**

CLIENT: Santa Monica-Malibu School District

PROJECT NO: 107-0008

PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403
Building E

Page 2 of 6

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Remediable	Damage
2'x4' pitted tile and 2'x4' fissured ceiling tile	L-23-01 Through L-23-03	None Detected	Previously sampled, Cape Environmental, 1994	First floor: hallway, rooms- 120, 123, 121, 117 A, 117B, 117, 113, 113A, 111, 111A, 105, 103, 101, 102, 104, 106, 110A, B, C, 116, 116A, 118, second floor- 223, 221, 217, 215, 211, 209, 205, 203, 202, 204, 206, 218, 220, 222	30,000 sq. ft.	No	No
1'x1' fissured ceiling tile	L-25-01 Through L-25-03	None Detected	Previously sampled, Cape Environmental, 1994	First floor- 102, 104, 108, 106, 108A, second floor rooms 202, 204, 206	7,200 sq. ft.	No	No
1'x1' fissured ceiling tile mastic	L-61-01 Through L-61-03	None Detected	Previously sampled, Cape Environmental, 1994	First floor- 102, 104, 108, 106, 108A, second floor rooms 202, 204, 206	7,200 sq. ft.	No	No
1'x1' random peghole ceiling tile	L-26-01 Through L-26-03	None Detected	Previously sampled, Cape Environmental, 1994	First floor rooms- 116, 118, 120, second floor rooms- 225, 223, 221, 217, 215, 211, 209, 205, 203, 208, 218, 220, 222, 212	4,000 sq. ft.	No	No
1'x1' random peghole ceiling tile mastic	L-57-01 Through L-57-05	None Detected	Previously sampled, Cape Environmental, 1994	First floor rooms- 116, 118, 120, second floor rooms- 225, 223, 221, 217, 215, 211, 209, 205, 203, 208, 218, 220, 222, 212	4,000 sq. ft.	No	No
Smooth plaster ceiling	L-29-01 Through L-29-06	None Detected	Previously sampled, Cape Environmental, 1994	First floor- boys restroom, 117 closet, 117 restroom; girls restroom, second floor- girls restroom, boys restroom, storage room 1	2,800 sq. ft.	No	No
Smooth plaster walls	L-35-01 Through L-35-06	None Detected	Previously sampled, Cape Environmental, 1994	First floor- boys restroom, 117 closet, 117 restroom; girls restroom, second floor- girls restroom, boys restroom, storage room 1	2,800 sq. ft.	No	No
Vinyl coated gypsum	L-36-01	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A

MATERIAL INVENTORY **ASBESTOS**

CLIENT: Santa Monica-Malibu School District

PROJECT NO: 107-0008

PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403

Building E

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
Pipe insulation	L-38-01	20% Chrysotile 10% Amosite	Previously sampled, Cape Environmental, 1994	Basement-crawl space	100 lb. ft.	No	No
Cement-titting	L-39-01 Through L-39-03	3%-7% Chrysotile 15% Amosite	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Valve insulation	L-39-05	4%-5% Chrysotile 8% Amosite	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Pipe insulation debris	L-44-01	20% Chrysotile 7% Amosite	Previously sampled, Cape Environmental, 1994	Basement-crawl space	10 sq. ft.	No	No
Cardboard damproofing	L-47-01	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Covebase adhesive	L-50-01 Through L-50-03	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
1'x1' straight peghole ceiling tile	L-27-01 Through L-27-03	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
1'x1' straight peghole ceiling tile mastic	L-54-01 Through L-54-03	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Soft rough plaster ceiling	L-55-01 Through L-55-05	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
Cement fittings on pipe insulation	L-56-01	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
White carpet glue underlayment	L-58-01	None Detected	Previously sampled, Cape Environmental, 1994	Not observed, as stated in previous report	N/A	N/A	N/A
12"x12" grey speckled floor tile with mastic	3510	None Detected	First floor room 119, southeast corner	First floor hallway, rooms 120, 119, vault, 117B, 111, 101, 108, 108A, 110A, B, C, 116, 116A, 118, 118A, second floor, 225, hallway, 217A, 209, 218	23,000 sq. ft.	No	No

MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica-Malibu School District
PROJECT NO: 107-0008
PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403
Building E

Page 4 of 6

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Remediable	Damage
4" gray covebase with adhesive	3511	None Detected	First floor room 119, northwest corner	First floor hallway, rooms 121, 120, 123, 119, 117B, 111, 105, 103, 101, 102, 104, 105, 108, 108A, 116, 116A, 118, 118A, second floor hallway, 225, 221, 223, 217A, 217, 215, 211, 209, 203, 202, 204, 206, 218, 222, 212, 212A, B, C, D	5,000 ln. ft.	No	No
Blue carpet glue	3512	None Detected	Room 121, southwest corner	First floor rooms 123, 125, main office, 117A, 117, 113A, 113, 111A, 109, 109A, 105, 103, 101, 102, 104, 105, 112A, 112, 112B, C, D, E, F, second floor rooms-221, 223, 217, 215, 211, 209, 205, 203, 202, 204, 206, 220, 222	22,500 sq. ft.	No	No
Joint compound	3513	None Detected	Room 113A, southeast corner	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Joint compound	3514	None Detected	Room 102, south wall center	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No

MATERIAL INVENTORY **ASBESTOS**

CLIENT: Santa Monica-Malibu School District

PROJECT NO: 107-0008

PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403
Building E

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Remediable	Damage
Joint compound	3514	None Detected	Room 102, south wall center	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Joint compound	3515	None Detected	Room 112A, northwest corner	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Joint compound	3516	None Detected	Second floor room 203, northeast corner	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Joint compound	3517	None Detected	Second floor room 202, south wall center by entry	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Joint compound	3518	None Detected	Second floor room 209, south wall center by entry	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No

MATERIAL INVENTORY ASBESTOS

CLIENT: Santa Monica-Malibu School District
 PROJECT NO: 107-0008
 PROJECT NAME: Lincoln Middle School- 1501 California Avenue, Santa Monica, California 90403
 Building E

Page 6 of 6

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Frangible	Damage
Drywall	3520	None Detected	Room 112A, northwest corner	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
Composite- drywall with joint compound	3521	None Detected	Room 112A, northwest center	First floor hallway, faculty restrooms, 113, 113A, 111, 111A, 105, 103, 102, 104, 106, 108, 108A, 112A, 118, 120, Second floor rooms 203, 202, 204, 206, 218, 220, 222, stair ways	20,000 sq. ft.	No	No
4" black covebase with adhesive	3522	None Detected	First floor room 117A, southwest corner	First floor rooms 117A, 117, 117 closet, main office, 113, 113A, 111A, 109A, 109, 112A, second floor room 209, 220	1,200 ln. ft.	No	No
9"x9" dark green floor tile with mastic	L-07-01 Through L-07-01M	3% Chrysotile (tile) 7% Chrysotile (mastic)	Previously sampled, Cape Environmental, 1994	First floor room 111, 111A, 105, 109A	1,000 sq. ft.	No	No
Black sheet vinyl flooring with mastic	3523	None Detected (flooring and mastic)	Basement, storage area center	Basement, storage area	1,000 sq. ft.	No	No
Cement- fitting	L-38-01	20% Chrysotile 10% Amosite	Previously sampled, Cape Environmental, 1994	Basement, storage area southwest closets	4 fitting	Yes	No



CTL Environmental Services

APPENDIX B

**Lead Laboratory Analytical Report, Sample Logs,
XRF Logs**



Hygeia Laboratories Inc.

82 W. Sierra Madre Blvd
Sierra Madre, CA 91024-2434
(626) 355-4711 (626) 355-4497 Fax

Analytical Report

February 18, 2009

Mr. Paul Cota
ATC Los Angeles
25 Cupanla Circle
Monterey Park, CA 91755


Hygeia Reference No.: **00052 09 0063**

Date Sampled: February 2, 2009
Date Received: February 13, 2009
Date Analyzed: February 18, 2009
Analyst: Nahid Motamedi

Client Ref. 52.25526.0009 (T1) SMMUSD - Lincoln MS Samples and data provided by: D. Carrier/P. Cota
Analyte: Lead Analytical Method: EPA 7420 Detection Limit: 25 ppm Samples Analyzed: 32
Sample Matrix: paint Digestion Method: EPA 3050B Reporting Limit: 120 ppm Sample Condition Acceptable ☒

<u>Hygeia Sample ID</u>	<u>Client Sample ID</u>	<u>Lead Conc. (ppm)</u>	<u>Lead Conc. (wt%)</u>
1161884	001	<120	<0.012
1161885	002	2312	0.231
1161886	003	830	0.083
1161887	004	568	0.057
1161888	005	594	0.059
1161889	006	23720	2.37
1161890	007	344	0.034
1161891	008	1068	0.107
1161892	009	367	0.037
1161893	010	<120	<0.012
1161894	011	<120	<0.012
1161895	012	<120	<0.012
1161896	013	<120	<0.012
1161897	014	8716	0.872
1161898	015	18930	1.89
1161899	016	2523	0.252
1161900	017	3639	0.364
1161901	018	182	0.018
1161902	019	7879	0.788
1161903	020	12280	1.23

BLDG
E
↓



Analytical Report

February 18, 2009

Hygeia Reference No. 00052 09 0063

Client Reference: 52.25526.0009 (T1) SMMUSD - Lincoln MS

<u>Hygeia Sample ID</u>	<u>Client Sample ID</u>	<u>Lead Conc. (ppm)</u>	<u>Lead Conc. (wt%)</u>
1161904	021	87410	8.74
1161905	022	21310	2.13
1161906	023	171980	17.2
1161907	024	857	0.086
1161908	025	166	0.017
1161909	026	680	0.068
1161910	027	45090	4.51
1161911	028	6019	0.602
1161912	029	796	0.08
1161913	030	443	0.044
1161914	031	<120	<0.012
1161915	032	556	0.056

ppm = parts per million = mg/kg

Nahid Motamedi

Supervisor of Chemistry Laboratory

Nahid Motamedi

Sample results have not been blank corrected. All quality control results meet the QC requirements of AIHA ELLAP. This report only pertains to the samples investigated and does not apply to other similar material. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without authorization is prohibited.

00052 09 0063

LEAD BULK SAMPLE _OG



25 CUPANIA CIRCLE
MONTEREY PARK, CA 91755

PAGE 2 OF 4

0001 TASK NO. 00009

52 25526

PROJECT NO.

PROJECT: LINCOLN M.S.

SURVEYOR: D. Carver / P. Cota

DATE: 020209

AREA AREA NAME DESCRIPTION AREA AREA NAME DESCRIPTION

09	Bldg D Student Dining	13	Bldg E Rm 109
10	Bldg D Serving Area	14	Bldg E 2nd Fl Stairs
11	Bldg D Faculty Dining	15	Bldg E Main Office
12	Bldg E Rm 217	16	Bldg E Rm 217A

ESTIMATED QUANTITY

UNIT CODES

1 LINEAR FEET
2 SQUARE FEET
3 SOAKWAY
4 CUBIC INCH
5 EACH

PERCENTAGES

P- POSITIVE
N- NEGATIVE
WATER
DUST
O.A.
OTHER

ESTIMATED QUANTITY

UNIT CODES

PERCENTAGES

SAMPLE #	BLDG/FLOOR	AREA USAGE	CON'T CODE	MATERIAL DESCRIPTION / COLOR	ESTIMATED QUANTITY	PEELING CODE	SUBSTRATE CODE	CREVABLE SURFACE	CONTACT CODE
011	1st Fl	09		22 - Brown Paint / Plaster Wall					
012		10		TAN Paint / Wall					
013		11		TAN Paint / Chair Rail					
014		10		Blue Paint / Poster Board Frame	15				
015	2nd Fl	12		TAN Paint / Door Casing	15				
016	1st Fl	13		TAN Paint / Base Board	401				
017	2nd Fl	14		TAN Paint / Stair Riser	121				
018		12		TAN Paint / Window Sill	55				
019	1st Fl	15		Blue Paint / Vault Door	15				
020	2nd Fl	16		TAN Paint / Door Casing	15				

- 01 WATER

02 DUST

03 DOOR, HEADER

04 DOOR, JAMB

05 DOOR, CASING

06 STAIR, TREADS

07 STAIR, RISERS

08 STAIR, STRINGER

09 BALLUSTER

10 RAILING CAP

11 NEWEL POST

12 WINDOW, HEADER

13 WINDOW, CASING

14 WINDOW, SILL

15 WINDOW, SASH

16 WINDOW, STOPS

17 MULLIONS

18 APRON

19 WINDOW GRATE

20 DOOR GRATE
- 21 BASEBOARD

22 WALLS

23 WALLS, LOWER

24 WALLS, UPPER

25 CHAIR RAIL

26 DOOR, EXTERIOR

27 EXTERIOR, DOOR CASING

28 EXTERIOR, WINDOW CASING

29 EXTERIOR, WINDOW MULLIONS

30 THRESHOLD

31 NEWEL POST

32 DRIPEBOARD

33 LOWER TRIM

34 UPPER TRIM

35 CORNERBOARD

36 SIDING

37 CELLAR WINDOW UNIT

38 FLOOR

39 RAILING CAPS

40 SUPPORT COLUMN
- 41 JOIST

42 CEILING

43 RADIATOR

44 ACCESS HATCH COVER

45

46

47

48

49

50
- 1 PEELING

2 NOT PEELING

3 UNPEELING

4 CHIPPED

5 CHALKING
- 1 WOOD

2 METAL

3 MASONRY

4 DRYWALL

5 PLASTER
- 1 YES

2 NO
- 1 LOW

2 MODERATE

3 HIGH

FOR LAB USE ONLY

Poster Board Frame

Vault Door

ANALYST'S SIGNATURE/DATE

LAB DIRECTOR'S SIGNATURE/DATE

00052 09 0063

LEAD BULK SAMPLE LOG


 25 CUPANIA CIRCLE
 MONTEREY PARK, CA 91755

PAGE 3 OF 4

0009 00001

52 25526

PROJECT NO.

PROJECT: LINCOLN M.S.

SURVEYOR: D. Carver / P. Cota

DATE: 020209

AREA	AREA NAME/DESCRIPTION	AREA	AREA NAME/DESCRIPTION
17	Bldg E Basement	21	Bldg F Rm 325 Restroom
18	Bldg C Rm 152		
19	Bldg G Rm 310		
20	Bldg F Rm 312		

SAMPLE #	BUILDING/FLOOR	AREA	CONT CODE	MATERIAL DESCRIPTION/ COLOR	ESTIMATED QUANTITY					5 EACH						
021	2nd fl		16	TAN paint / hot water heater platform	49							15				22
022	Basement		17	Yellow paint / support column	40							55				11
023	↓		17	Orange paint / door	46							15				11
024	1st fl		18	TAN paint / air vent	50							25				32
025	↓		18	TAN paint / window casing	13											12
026	↓		19	TAN paint / plaster wall	42							90	02			15
027	↓		19	TAN paint / teacher counter metal post	51							25				42
028	1st fl		20	TAN paint / window casing	13							85				21
029	2nd fl		21	TAN paint / plaster wall	22							20	02			25
030	↓		21	Blue paint / door	46							15				21

61 WATER	62 DUST	63 DOOR, HEADER	64 DOOR JAMB	65 DOOR, CASING	66 STAIR, TREADS	67 STAIR, RISERS	68 STAIR, STRINGER	69 BALLUSTER	70 RAILING CAP	71 KNEEL POST	72 WINDOW, HEADER	73 WINDOW, CASING	74 WINDOW, SILL	75 WINDOW, SASH	76 WINDOW, STOPS	77 MILLIONS	78 APRON	79 WINDOW GRATE	80 DOOR GRATE
41 JOIST	42 CEILING	43 RADIATOR	44 ACCESS HATCH COVER	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

FOR LAB USE ONLY

ANALYST'S SIGNATURE/DATE

LAB DIRECTOR'S SIGNATURE/DATE

51. Teachers counter metal post

Calibration Check Test Results

RMD XRF Unit

PAGE 1 OF

Address / Unit No. LINCOLN MS - 1501 CALIFORNIA AVE
SANTA MONICA, CA 90403

Device: RMD XRF

Date: 1-29-09 XRF Serial No. 1332

Contractor: ATC ASSOCIATES

Inspector Name: DAMON CARRIAR Signature 

NIST SRM Used 1.0 mg/cm² Calibration Check Tolerance Used mg/cm²

First Calibration Check

NIST SRM			First Average	Difference Between First Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>0.6</u>	<u>0.8</u>	<u>0.2</u>

Second Calibration Check

NIST SRM			Second Average	Difference Between Second Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Third Calibration Check (if required)

NIST SRM			Third Average	Difference Between Third Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Fourth Calibration Check (if required)

NIST SRM			Fourth Average	Difference Between Fourth Average and NIST SRM*
First Reading	Second Reading	Third Reading		

* If the difference of the Calibration Check Average from the NIST SRM film value is greater than the specified Calibration Check Tolerance for this device, consult the manufacturer's recommendations to bring the instrument back into control. Retest all testing combinations tested since the last successful Calibration Check test.

Calibration Check Test Results

RMD XRF Unit

PAGE 1 OF

Address / Unit No. LINCOLN MS - 1501 CALIFORNIA AVE
SANTA MONICA, CA 90403

Device: RMD XRF

Date: 1-29-09 XRF Serial No. 1332

Contractor: ATC ASSOCIATES

Inspector Name: DAMON CARRIAR Signature 

NIST SRM Used 1.0 mg/cm² Calibration Check Tolerance Used mg/cm²

First Calibration Check

NIST SRM			First Average	Difference Between First Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>0.6</u>	<u>0.8</u>	<u>0.2</u>

Second Calibration Check

NIST SRM			Second Average	Difference Between Second Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Third Calibration Check (if required)

NIST SRM			Third Average	Difference Between Third Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Fourth Calibration Check (if required)

NIST SRM			Fourth Average	Difference Between Fourth Average and NIST SRM*
First Reading	Second Reading	Third Reading		

* If the difference of the Calibration Check Average from the NIST SRM film value is greater than the specified Calibration Check Tolerance for this device, consult the manufacturer's recommendations to bring the instrument back into control. Retest all testing combinations tested since the last successful Calibration Check test.

Calibration Check Test Results
RMD XRF Unit


PAGE 1 OF

Address / Unit No. LINCOLN MS - 1501 CALIFORNIA AVE
SANTA MONICA, CA 90403

Device: RMD XRF

Date: 1-30-09 XRF Serial No. 1332

Contractor: ATC ASSOCIATES

Inspector Name: DAMON CARRIER Signature 

NIST SRM Used 1.0 mg/cm² Calibration Check Tolerance Used mg/cm²

First Calibration Check

NIST SRM			First Average	Difference Between First Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Second Calibration Check

NIST SRM			Second Average	Difference Between Second Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Third Calibration Check (if required)

NIST SRM			Third Average	Difference Between Third Average and NIST SRM*
First Reading	Second Reading	Third Reading		

Fourth Calibration Check (if required)

NIST SRM			Fourth Average	Difference Between Fourth Average and NIST SRM*
First Reading	Second Reading	Third Reading		

* If the difference of the Calibration Check Average from the NIST SRM film value is greater than the specified Calibration Check Tolerance for this device, consult the manufacturer's recommendations to bring the instrument back into control. Retest all testing combinations tested since the last successful Calibration Check test.

Calibration Check Test Results

RMD XRF Unit

PAGE 1 OF

Address / Unit No. LINCOLN MS - 1501 CALIFORNIA AVE
SANTA MONICA, CA 90403

Device: RMD XRF

Date: 1-30-09 XRF Serial No. 1332

Contractor: ATC ASSOCIATES

Inspector Name: DAMON CARRIER Signature 

NIST SRM Used 1.0 mg/cm² Calibration Check Tolerance Used mg/cm²

First Calibration Check

NIST SRM			First Average	Difference Between First Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Second Calibration Check

NIST SRM			Second Average	Difference Between Second Average and NIST SRM*
First Reading	Second Reading	Third Reading		
<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>1.0</u>	<u>0</u>

Third Calibration Check (if required)

NIST SRM			Third Average	Difference Between Third Average and NIST SRM*
First Reading	Second Reading	Third Reading		

Fourth Calibration Check (if required)

NIST SRM			Fourth Average	Difference Between Fourth Average and NIST SRM*
First Reading	Second Reading	Third Reading		

* If the difference of the Calibration Check Average from the NIST SRM film value is greater than the specified Calibration Check Tolerance for this device, consult the manufacturer's recommendations to bring the instrument back into control. Retest all testing combinations tested since the last successful Calibration Check test.



XRF LEAD BASEL INT SURVEY

Date: 1-29-09

Project No.: 52.25526.0009

Task No.: 00001

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Inspector(s): DAMON CARRIER / PAUL COTA

19034

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
1		CALIBRATION							1.0
2									1.0
3									6.6
4	1st Fl	Main Bldg Rm 120	I		S	Canvas wall covering	wall Board	TAN	0
5					N	window casing	metal	white	0
6					↓	window frame	wood	↓	0
7					E	Door	↓	Blue	0
8					↓	Door frame	metal	white	0
9					N	support column	Drywall	↓	0
10		Main Bldg 118/14			N	wall		white	0
11					E				0
12					W				0
13					S	↓	↓	↓	0
14					S	Door	wood	Blue	0
15					↓	Door frame	metal	white	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

PAGE

1 OF 20



XRF LEAD BASEL INT SURVEY

Date: 1-29-09

Project No.: 52.25526.0009

Task No.: 00001

Client: SANTA MONICA MARLBORO

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Inspector(s): DAMON CARRIER / PAUL COTA

Spectrum Analyzer ID #:

19034

SANTA MONICA, CA 90403

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
1		CALIBRATION							1.0
2									1.0
3									6.6
4	1st Fl	Main Bldg Rm 120	I		S	Canvas wall covering window casing	wall Board metal	TAN	0
5					N	windows	wood	white	0
6					↓	wood frame	wood	↓	0
7					E	Door	↓	Blue	0
8					↓	Door Frame	metal	white	0
9					N	support column	Drywall	↓	0
10		Main Bldg 118/14			N	wall		white	0
11					E				0
12					W				0
13					S				0
14					S	Door	wood	Blue	0
15					↓	Door Frame	metal	white	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

19034

Spectrom Analyzer ID #:

Client: SANTA MONICA MARLBOROUGH

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Date: 52.25526.0001

Project No.:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
16	1st Fl	MAIN BLDG RM 118	I		E	Canvas wall covering	will Board	tan	0
17					W	Window casing	Metal	white	0
18					↓	Window frame	wood	↓	0
19					E	Door	↓	Blue	0
20					↓	Door frame	metal	white	0
21					W	Support column	Drywall	↓	0
22					N	wall	Plaster	white	0
23					E				0
24					W				0.1
25					S				0
26					N	Door	wood	gray	0
27					↓	Door frame	metal	↓	0
28					W	Window casing	↓	white	0
29					↓	Window sill	wood	↓	0
30					S	Cabinet	wood	white	0

COMMENTS: metal sink @ Classroom

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupanle Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

19034

Client: SANTA MONICA MARLBORU USO

Spectrum Analyzer ID #:

Project No.: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
16	1st Fl	Main Bldg Rm 118	I		E	Canvas wall covering	wall Board	tan	0
17			I		W	Window casing	Metal	white	0
18			I		↓	Window frame	wood	↓	0
19			I		E	Door	↓	Blue	0
20			I		↓	Door frame	metal	white	0
21			I		W	Support column	Drywall	↓	0
22		Rm 114 work Rm	I		N	wall	Plaster	white	0
23			I		E		↓	↓	0
24			I		W		↓	↓	0.1
25			I		S		↓	↓	0
26			I		N	Door	wood	gray	0
27			I		↓	Door frame	metal	↓	0
28			I		W	Window casing	↓	white	0
29			I		↓	Window sill	wood	↓	0
30			I		S	Cabinet	wood	white	0

COMMENTS: metal sink @ Classroom

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

25 Cupania Circle
Monterey Park, CA 91755

1-29-09

SANTA MONICA MARLBORO

19034

Date:

Project No: 52.25526.0001

Client:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Spectrum Analyzer ID #:

Task No: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
31	1st	MAIN BLDG - Rm 116			S	WALL	PLASTER	WHITE	0.2
32					W	"	"	"	0
33					"	WINDOW CASING	WALL	"	0
34					"	WINDOW SILL	WOOD	"	0
35					E	DOOR	"	BLUE	0
36					"	DOOR FRAME	METAL	TAN	0
37					S	WINDOW FRAME	"	"	0
38	Basement	Rm 116 Basement			N	WALL	CONCRETE	YELLOW	0
39					W	"	"	"	0.1
40					E	"	"	"	0.2
41			INTACT	5 ea	CENTRAL	SUPPORT COLUMN WOOD	"	"	2.8
42					"	SUPPORT BEAM	"	WHITE	0
43					"	FIRE UNIT FILING	METAL	"	0.1
44					"	CERILING	PLASTER	"	0
45					N	CEILING	WOOD	YELLOW	0

COMMENTS:

SHEDDING

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

25 Cupania Circle
Monterey Park, CA 91755

1-29-09

Client: SANTA MONICA MARLBORO

19034

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s): JAMON CARROLL / PAUL COTA

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
31	1ST	MAIN BLDG - Rm 116			S	WALL	PLASTER	WHITE	0.2
32					W	"	"	"	0
33					"	WINDOW CASING	PLASTER	"	0
34					"	WINDOW SILL	WOOD	"	0
35					E	DOOR	"	BLUE	0
36					"	DOOR FRAME	MOISTURE	TAN	0
37					S	WINDOW FRAME	"	"	0
38	Basement	Rm 116 Basement			N	WALL	CONCRETE	YELLOW	0
39					W	"	"	"	0.1
40					E	"	"	"	0.2
41			INTACT	5 ea	CENTRAL	SUPPORT COLUMN WOOD		"	2.8
42					"	SUPPORT BEAM	"	WHITE	0
43					"	FIRE UNDER PILING	MOISTURE	"	0.1
44					"	CERULINE	PLASTER	"	0
45					N	CASING	WOOD	YELLOW	0

SHELVING

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amount Flaking

XRF LEAD BASEL INT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARZIBU USO

Spectrum Analyzer ID #: _____

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s): _____

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
46	BASMENT	MAIN SWC - RAIL			R	CASNET	WOOD	YELLOW	0
47					S	HAND RAIL	METAL	OLIVE	0
48					W	WINDOW CASING	"	YELLOW	0
49			I	1 ea	R	DOOR	WOOD	OLIVE	79.9
50			I	1 ea	"	DOOR FRAME	"	YELLOW	79.9
51		DISMANT ELECTRICAL RM.			W	WALL	CONCRETE	BLACK	0
52					E	"	"	"	0
53					N	"	"	"	0.2
54	1ST	- RM 112			N	WALL	POSSIBLE BRICK	TAN	0
55					W		DRYWALL		0
56					S		PLASTER		0
57					E		"		0
58					E	DOOR	WOOD	BROWN	0
59					"	DOOR FRAME	METAL	"	0
60					S	"	"	GRAY	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Survey Location:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
46	BASMENT	MAIN BLDG - RM 112			E	CARBONAT	WOOD	yellow	0
47					S	HAND PAINT	METAL	orange	0
48					W	WINDOW CASING	"	yellow	0
49			I	1 ea	E	DOOR	WOOD	orange	79.9
50			I	1 ea	"	DOOR FRAME	"	yellow	79.9
51		BASMENT ELECTRICAL RM.			W	WALL	CONCRETE	black	0
52					E	"	"	"	0
53					N	"	"	"	0.2
54	1ST	- RM 112			N	WALL	plaster	TAN	0
55					W		plaster		0
56					S		plaster		0
57					E		"		0
58					E	DOOR	WOOD	black	0
59					"	DOOR FRAME	METAL	"	0
60					S	"	"	gray	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASED PAINT SURVEY



25 Cupanis Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
61	1ST	MAIN BUDG RM 112B			N	DOOR	PAINT	GRAY	0
62					N	WALL	PLASTER	TAN	0
63					W		u	h	0.2
64					S		u	h	0.1
65					E		u	h	0.1
66		RM 112			S	CHAIR	WOOD	TAN	0
67		RM 112C			N	WALL	PLASTER	TAN	0.3
68					E				0
69					S				0
70					W				0.2
71					N	WINDOW	PLASTER		0
72					W	WINDOW	PLASTER		0
73					u	WINDOW	WOOD		0
74		RM 112D			N	WALL	PLASTER	TAN	0
75					E		u	h	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASED PAINT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
 Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
 Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
61	1ST	MAIN BUDG RM 112B			N	DOOR WARE	PAINT	GRAY	0
62					N	WALL	PLASTER	TAN	0
63					W		LI	h	0.2
64					S		h	h	0.1
65					E		h	h	0.1
66		RM 112			S	CHAIR PAINT	WOOD	TAN	0
67		RM 112C			N	WALL	PLASTER	TAN	0.3
68					E				0
69					S				0
70					W				0.2
71					N	WINDOW FRAME	METAL		0
72					W	WINDOW CASING	↓		0
73					h	WINDOW SILL	WOOD		0
74		RM 112D			N	WALL	PLASTER	TAN	0
75		h			E		h	h	0

COMMENTS:

CONDITION OF PAINT:
 I INTACT
 F FAIR - Small Amount Flaking
 P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
74	1ST	MAIN LAB - RM 112D			S	WALL	PLASTER	TAN	0
77					W	"	"	"	0
78					W	WINDOW CASING	METAL	"	0
79					"	WINDOW SILL	WOOD	"	0
80		RM 112E			N	WALL	PLASTER	TAN	0
81		RM 112F			E	"	PLASTER	"	0
82		RM 112A			N	"	"	"	0.3
83		"			S	"	DRYWALL	"	0
84		RM 110			N	WALL	PLASTER	TAN	0.5
85		(NURSE)			E				0
86					S				0
87					W				0
88					E	DOOR	WOOD	BLUE	0
89					E	DOOR FRAME	METAL	TAN	0
90		RM 110A			W	WALL	PLASTER	"	0.1

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
76	1ST	MAIN LOBBY - RM 112D			S	WALL	PLASTER	TAN	0
77					W	"	"	"	0
78					W	WINDOW CASING	METAL	"	0
79					"	WINDOW SILL	WOOD	"	0
80		RM 112E			N	WALL	PLASTER	TAN	0
81		RM 112F			E	"	PLASTER	"	0
82		RM 112A			N	"	"	"	0.3
83		"			S	"	DRYWALL	"	0
84		RM 110			N	WALL	PLASTER	TAN	0.5
85		(NURSE)			E				0
86					S				0
87					W				0
88					E	DOOR	WOOD	BLUE	0
89					E	DOOR FRAME	METAL	TAN	0
90		RM 110A			W	WALL	PLASTER	"	0.1

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Date: 52.25526.0001
Project No.: 00001
Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
91	1st	MAIN BLDG - RM 110A			S	POLYURETHANE	METAL	TAN	0.1
92					E	WALL	DRYWALL	TAN	0
93					S				0
94					W				0
95					N				0
96					E	TOILET	PORCELAIN	WHT	0
97					"	SINK	"	"	0
98		RM 110E			CENTER	CEILING	DRYWALL	TAN	0
99		RM 110C			N	WALL	PLASTER	TAN	0
100					E	"	DRYWALL	"	0
101					W	WINDOW CASING	METAL	"	0
102					S	DOOR	WOOD	BUR	0
103					S	DOOR FRAME	METAL	TAN	0
104					N	WALL	DRYWALL	TAN	0
105		RM 108			W	"	"	"	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO
Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: 00001

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
91	1st	MAIN BLDG - RM 110A			S	POLYMER	METAL	TAN	0.1
92					E	WALL	DRYWALL	TAN	0
93					S				0
94					W				0
95					N				0
96					E	TOILET	PORCELAIN	WHT	0
97					"	SINK	"	"	0
98					CENTER	CEILING	DRYWALL	TAN	0
99					N	WALL	PLASTER	TAN	0
100					E	"	DRYWALL	"	0
101					W	WINDOW CASING	WOOD	d	0
102					S	DOOR	WOOD	BUR	0
103					S	DOOR FRAME	METAL	TAN	0
104					N	WALL	DRYWALL	TAN	0
105					W	"	"	"	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
106	1ST	MAIN DUPLO - RM 108			S	WALL	DRYWALL	TAN	8
107					E	"	PLASTER	"	0.1
108					"	SINK	ONSTEEL	WHT	8
109					W	DOOR	WOOD	GRAY	8
110					"	WOOD FRAMING	METAL	"	8
111		- RM 106			N	WALL	DRYWALL	TAN	8
112					E	"	"	"	8
113					E	"	"	"	8
114					W	"	"	"	8
115					W	WOOD FRAMING	WOOD	TAN	8
116					"	WOOD SILL	"	"	8
117					N	DOOR	WOOD	BLUE	8
118		- RM 104			N	WALL	DRYWALL	TAN	8
119					E	"	"	"	8
120					S	"	"	"	8

COMMENTS: RM 108 A - INACCESSIBLE

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SA 90403
Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Date: 52.25526.0001
Project No.: 00001
Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
106	1ST	MAIN DUPD - RM 108			S	WALL	DRYWALL	TAN	8
107					E	"	PLASTER	"	0.1
108					"	SINK	ONST. IRON	WHIT.	8
109					W	DOOR	WOOD	GRAY	8
110					"	WOOD FRAMING	METAL	"	8
111		- RM 106			N	WALL	DRYWALL	TAN	8
112					SE				8
113					E				8
114					W				8
115					W	WOOD FRAMING	WOOD	TAN	8
116					"	WOOD SILL	"	"	8
117					N	DOOR	WOOD	BROWN	8
118		- RM 104			N	WALL	DRYWALL	TAN	8
119					E				8
120					S				8

COMMENTS: RM 108A - INACCESSIBLE

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



Date: 52.25526.0001
 Project No.: 52.25526.0001
 Task No.: 00001
 Client: SANTA MONICA MARLBORO
 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403
 Spectrum Analyzer ID #:
 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
121	1st	MARTIN 6006 - RM 104			W	WALL	drywall	TAN	0
122						WINDOW FRAME	WOOD	TAN	0
123						WINDOW SILL	"	"	0
124						HEATER CASING	METAL	TAN	0
125					N	DOOR	WOOD	BLUE	0
126					"	DOOR FRAME	"	TAN	0
127		- RM 102			N	WALL	drywall	TAN	0
128					E				0
129					S				0
130					W				0
131						WINDOW FRAME	WOOD	TAN	0
132						WINDOW SILL	"	"	0
133					E	DOOR	"	BLUE	0
134					"	DOOR FRAME	METAL	TAN	0
135					W	HEATER CASING	"	"	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupanin Circle
Monterey Park, CA 91755

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
 Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
 Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
121	1st	MAIN BUDG - RM 104			W	WHL	DAYWDR	TAN	0
122						WINDOW FRAME	WOOD	TAN	0
123						WINDOW SILL	"	"	0
124						HEATER CASING	METAL	TAN	0
125					N	DOOR	WOOD	BLUE	0
126					"	DOOR FRAME	"	TAN	0
127		- RM 102			N	WHL	DAYWDR	TAN	0
128					E				0
129					S				0
130					W				0
131						WINDOW FRAME	WOOD	TAN	0
132						WINDOW SILL	"	"	0
133					E	DOOR	"	BLUE	0
134					"	DOOR FRAME	METAL	TAN	0
135					W	HEATER CASING	"	"	0

COMMENTS:

CONDITION OF PAINT:
 I INTACT
 F FAIR - Small Amount Flaking
 P POOR - Large Amounts Flaking



25 Cupanla Circle
Monterey Park, CA 91755

XRF LEAD BASED SURVEY

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Survey Location:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
136	1ST	MARKIN BUDG - RM 101			N	WALL	PLASTER	TAN	0.1
137					E				0.2
138					S				0
139					W				0
140					N	WINDOW CASING	METAL	TAN	0
141					S	DOOR	WOOD	BLUE	0
142					"	DOOR FRAME	METAL	TAN	0
143					"	BASEBOARD	WOOD	TAN	0
144		- RM 103			E	WALL	PLASTER	TAN	0.2
145					S		DRYWALL		0
146					W				0
147					N				0
148					E	WINDOW CASING	METAL	TAN	0
149					"	WINDOW SILL	WECO	"	0
150					W	DOOR	WOOD	BLUE	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

PAGE

10 OF 70



25 Cupanla Circle
Monterey Park, CA 91755

XRF LEAD BASED .NT SURVEY

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Date: 52.25526.0001

Project No.: 00001

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
136	1ST	MARKIN BUDG - RM 101			N	WALL	PLASTER	TAN	0.1
137					E				0.2
138					S				0
139					W				0
140					N	WINDOW CASING	METAL	TAN	0
141					S	DOOR	WOOD	BLUE	0
142					"	DOOR FRAME	METAL	TAN	0
143					"	BASEBOARD	WOOD	TAN	0
144					E	WALL	PLASTER	TAN	0.2
145					S		DRYWALL		0
146					W				0
147					N				0
148					E	WINDOW CASING	METAL	TAN	0
149					"	WINDOW SILL	WEGG	"	0
150					W	DOOR	WOOD	BLUE	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL ANT SURVEY



25 Cupertio Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
151	1ST	MAIN BUDG - RM 103			W	DOOR FRAME	METAL	TAN	0
152		RM 105			N	WALL	DRYWALL	TAN	0
153					E		PLASTER		0
154					S				0
155					W				0.1
156					E	WINDOW CASING	METAL	TAN	0
157					"	WINDOW SILL	WOOD	"	0
158					W	DOOR	WOOD	BLUE	0
159					"	DOOR FRAME	METAL	TAN	0
160		RM 107 G205 R.R.			N	WALL	CERAMIC	WHY	0
161					CENTR	FLOOR	TERRAZO	ORANGE	0
162					N	SINK	PORCELIN	WHY	0
163					S	TOILET	"	"	0
164					"	STALL WALL	WOOD	BLUE	0
165					E	WINDOW CASING	METAL	WHY	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupanla Circle
Monterey Park, CA 91755

XRF LEAD BASEL ANT SURVEY

Client: SANTA MONICA MARZIBU USO

Spectrum Analyzer ID #:

Inspector(s):

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
151	1ST	MAIN Bldg - RM 103			W	DOOR FRAME	METAL	TAN	0
152					N	WALL	DRYWALL	TAN	0
153					E		PLASTER		0
154					S				0
155					W				0.1
156					E	WINDOW CASING	METAL	TAN	0
157					"	WINDOW SILL	WOOD	"	0
158					W	DOOR	WOOD	BLUE	0
159					"	DOOR FRAME	METAL	TAN	0
160					N	WALL	CERAMIC	WHY	0
161					CENTR	FLOOR	TERRAZZO	DRABGR	0
162					N	SINK	PORCELIN	WHY	0
163					S	TOILET	"	"	0
164					"	STAIR WALK	WOOD	BLUE	0
165					E	WINDOW CASING	METAL	WHY	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL NT SURVEY

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Survey Location:

LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Date: _____

Project No.: 52.25526.0001

Task No.: 00001

Inspector(s): _____

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
166	1ST	MAIN BLDG - RM 107 GALS			W	DOOR	WOOD	BLUE	0
167		"			W	DOOR FRAME	WOOD	TAN	0
168		"			S	WHL	WOOD	TAN	0
169		RM 108 B CONF RM			N	"	"	"	0
170		"			E	"	PLASTER	"	0.4
171		"			W	"	"	"	0
172		"			E	WINDOW CASING	METAL	TAN	0
173		"			"	WINDOW SILL	WOOD	"	0.2
174		RM 109			S	WHL	PLASTER	TAN	0
175		"			E	"	"	"	0.2
176		"			N	"	"	"	0.1
177		"			W	"	"	"	0.1
178		"			E	WINDOW FRAME	WOOD	"	0
179		"			W	DOOR	"	BLUE	0
180		"			"	DOOR FRAME	METAL	TAN	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL NT SURVEY

25 Cupertio Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Survey Location:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
166	1ST	MAIN BLDG - RM 107 GALS			W	DOOR	WOOD	BLUE	0
167					W	DOOR FRAME	METAL	TAN	0
168					S	WHL	DRYWALL	TAN	0
169		RM 108 B CONC PM			N		u		0
170					E		PLASTER		0.4
171					W		u		0
172					E	WINDOW CASING	METAL	TAN	0
173					u	WINDOW SILL	WOOD	u	0.2
174		RM 109			S	WHL	PLASTER	TAN	0
175					E				0.2
176					N				0.1
177					W				0.1
178					E	WINDOW FRAME	WOOD		0
179					W	DOOR	u	BLUE	0
180					u	DOOR FRAME	METAL	TAN	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL ANT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO USO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Survey Location:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
181	1st	MAIN BLDG Rm 109	I	40 LF	W	BASEBOARD	WOOD	TAN	4.1
182		- Rm 111A			E	WALL	PLASTER	TAN	0.4
183					N		DRYWALL		0
184					W		"		0
185					S		"		0
186					E	WINDOW CASING	METAL	TAN	0
187					"	WINDOW SILL	WOOD	"	0
188			I	12 LF	"	BASEBOARD	"	"	1.7
189		- Rm 111			E	WALL	DRYWALL	TAN	0
190					S		"		0
191					N		PLASTER		0.2
192					W		"		0
193					"	DOOR CASING	WOOD	TAN	0.4
194		- Rm 113 - Admin Off			N	WALL	DRYWALL	TAN	0
195					W	"	PLASTER	"	0.2

COMMENTS:

BASEBOARD - Rm 111B - 24 LF (I)

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL NT SURVEY

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
181	1st	MAIN BLDG RM 109	I	40 LF	W	BMS BORD	WOOD	TAN	4.1
182		- RM 111A			E	WALL	PLASTER	TAN	0.4
183					N		DRYWALL		0
184					W		"		0
185					S		"		0
186					E	WINDOW CASING	METAL	TAN	0
187					"	WINDOW SILL	WOOD	"	0
188			I	12 LF	"	BMS BORD	"	"	1.7
189		- RM 111			E	WALL	DRYWALL	TAN	0
190					S		"		0
191					N		PLASTER		0.2
192					W		"		0
193					"	DOOR CASING	WOOD	TAN	0.4
194		- RM 113 - ADMIN OFF			N	WALL	DRYWALL	TAN	0
195					W	"	PLASTER	"	0.2

COMMENTS:

BMS BORD - RM 111B - 24 LF (I)

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupanito Circle
Monterey Park, CA 91755

XRF LEAD BASEL NT SURVEY

Date: 52.25526.0001 Client: SANTA MONICA MARIBU USO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
196	1ST	MAIN BUILD - RM 113			S	WALL	PLASTER	TAN	0.1
197					E	"	"	"	0.1
198					E	WINDOW SILL	WOOD	"	0
199					S	WINDOW FRAME	"	"	0
200					S	DOOR	WOOD	BLUE	0
201					"	DOOR FRAME	METAL	TAN	0
202		RM 115 MAIN OFFICE			N	WALL	DRYWALL	TAN	0
203					E		PLASTER		0.5
204					S				0.1
205					W				0
206					E	WINDOW CASING	METAL	WHT	0
207					"	WINDOW SILL	WOOD	"	0.2
208					"	DOOR	METAL	BLUE	0
209					"	DOOR FRAME	"	TAN	0
210			I	1 ea	W	VAULT DOOR	"	BLUE	5.0

COMMENTS:

RM 113 - DISABLING - 28 VP

RM 115 " 49 VP

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBOROUGH
Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: 00001

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
211	1st	MAIN BLDG - RM 117			S	WALL	PLASTER	TAN	0.3
212					W				0
213					N				0
214					E				0.1
215						WINDOW CASING	WPTL	WHT	0
216						WINDOW SILL	WOOD	"	0
217					N	DOOR	WOOD	BUR	0
218					"	DOOR FRAME	METAL	TAN	0
219					S	WALL	PLASTER	TAN	0
220					W	"	CERAMIC	WHT	0
221					CENTER	FLOOR	"	GRAY	0
222					N	SINK	PORCELIN	WHT	0
223					"	TOILET	"	"	0
224					CENTER	CEILING		TAN	0
225					E	DOOR FRAME	METAL	TAN	0

COMMENTS:

Rm 117 - Bathroom - GOLF

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL. INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
211	1st	MAIN Bldg - RM 117 - PRINC. OFF			S	WALL	PLASTER	TAN	0.3
212					W				0
213					N				0
214					E				0.1
215						WINDOW CASING	METAL	WHT	0
216						WINDOW SILL	WOOD	"	0
217					N	DOOR	WOOD	BLUE	0
218					"	DOOR FRAME	METAL	TAN	0
219					S	WALL	PLASTER	TAN	0
220					W	"	CERAMIC	WHT	0
221					CENTER	FLOOR	"	GRAY	0
222					N	SINK	PORCELAIN	WHT	0
223					"	TOILET	"	"	0
224					CENTER	CEILING		TAN	0
225					E	DOOR FRAME	METAL	TAN	0

COMMENTS:

Rm 117 - Bathroom - GOLF

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking

XRF LEAD BASEL. NT SURVEY



Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
 Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
 Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
226	1st	MAIN BUBB - PAINTA ONLY RM			W	WALL	DRYWALL	TAN	0
227					N	"	PLASTER	"	0
228					E	"	"	"	0
229					S	"	"	"	0
230			I	54 UP	N	BASEBOARD	WOOD	TAN	3.7
231		- B/G RESTROOM			N	WALL	CERAMIC	WHT	0
232					CENTRAL	FLOOR	"	GRAY	0
233					E	SINK	PORCELIN	WHT	0
234					"	TOILET	"	"	0
235					W	DOOR FRAME	WSTAL	TAN	0
236					"	DOOR	WOOD	DOOR	0
237					"	DOOR CASING	"	TAN	0.2
238		BOYS RA			S	WALL	CERAMIC	WHT	0
239					E	SINK	PORCELIN	"	0
240					W	TOILET	"	"	0

COMMENTS:

RM 117 - INACCESSIBLE

CONDITION OF PAINT:
 I - INTACT
 F - FAIR - Small Amount Flaking
 P - POOR - Large Amounts Flaking

XRF LEAD BASEL. INT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORUS Spectrum Analyzer ID #: 16
Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Date: 52.25526.0001

Inspector(s): 00001

Task No.: 00001

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
226	1st	MAIN BUDG - PAINT			W	WALL	drywall	TAN	0
227					N		plaster		0
228					E				0
229					S				0
230			I	54 UP	N	BASEBOARD	WOOD	TAN	3.7
231		- B/G RESTROOM			N	WALL	CERAMIC	WHT	0
232					CENTRAL	FLOOR	"	GRAY	0
233					E	SINK	PORCELAIN	WHT	0
234					"	TOILET	"	"	0
235					W	DOOR FRAME	METAL	TAN	0
236						DOOR	WOOD	DOOR	0
237						DOOR CABLING	"	TAN	0.2
238		BOYS RA			S	WALL	CERAMIC	WHT	0
239					E	SINK	PORCELAIN		0
240					W	TOILET	"		0

COMMENTS:

Rm 117 B - INACCESSIBLE

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



Date: 52.25526.0001 Client: SANTA MONICA MAZIBU USO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
 Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
 Task No.: 00001 Inspector(s): _____

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm²)
241	1st	MAIN BUNG - BOYS RR			S	UPPWR	PORECLIN	WHT	0
242					W	STAIR	WOOD	BLUE	0
243			I	5 LF	N	H2O PIPE	METAL	WHT?	1.0
244		- ELEC TRUM RM BOYS RR			W	WALL	PUNSTON	TAN	0
245					E	H2O PIPE	METAL	"	0
246					S	DOOR FRAME	"	GRAY	0
247					N	DOOR	WOOD	"	0
248		- RM 121			S	WALL	PLASTER	TAN	0.1
249					E	WINDOW CASING	METAL	TAN	0
250					"	WINDOW SILL	WOOD	WHT	0
251					W	DOOR	"	BLUE	0
252					"	DOOR CASING	"	TAN	0
253		- RM 123			E	WALL	PLASTER	TAN	0
254					"	WINDOW FRAME	METAL	TAN	0
255					"	WINDOW SILL	WOOD	WHT	0.1

COMMENTS: _____



XRF LEAD BASEL INT SURVEY

25 Cupanla Circle
Monterey Park, CA 91755

Date:

Project No.: 52.25526.0001

Task No.: 00001

Client:

SANTA MONICA MARLBORO

Survey Location:

LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Spectrum Analyzer ID #:

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
241	1ST	MAIN BUNG - BOYS RR			S	UPPER	POCELYN	WHT	0
242					W	STAIR	WOOD	BLUE	0
243			I	5 LF	N	HYD PIPE	METAL	WHT	1.0
244		- ELECTION RM P Boys RR			W	WALL	PLASTER	TAN	0
245					E	HYD PIPE	METAL	"	0
246					S	DOOR FRAME	"	GRAY	0
247					N	DOOR	WOOD	"	0
248		- RM 121			S	WALL	PLASTER	TAN	0.1
249					E	WINDOW CASING	METAL	TAN	0
250					"	WINDOW SILL	WOOD	WHT	0
251					W	DOOR		BLUE	0
252					"	DOOR CASING		TAN	0
253		- RM 123			E	WALL	PLASTER	TAN	0
254					"	WINDOW FRAME	METAL	TAN	0
255					"	WINDOW SILL	WOOD	WHT	0.1

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL. INT SURVEY

25 Cuponia Circle
Monterey Park, CA 91755

Date:

Project No.: 52.25526.0001

Client:

SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Survey Location:

LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.:

00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
256	1ST	MAIN BUILD - RM 103			W	DOOR	WOOD	TAN	0
257		"			"	DOOR FRAME	METAL	"	0
258		"			S	WALL	PLASTER	TAN	0.1
259		"			E				0
260		"			W				0
261		"			"	WALL	DRYWALL	TAN	0
262		"			S	HAND RAIL	METAL	GREEN	0
263		"			W	LOCKER	"	LT BLUE	0
267		"			E	DRINKING FOUNTAIN	PORCELIN	WHT	0
265		"			W	FLOR. ROSE CABINET	WOOD	TAN	0
266		"			"	STAIR NEWEL POST	"	TAN	0
267		"			"	STAIR TREAD	CANCLITE	GRAY	0
268		"			"	DISPLAY CASE	WOOD	TAN	0
269	2ND	"			N	WALL	PLASTER	TAN	0
270	11	"			S	CONDUIT	METAL	"	0

COMMENTS:

1ST FL HALLWAY - BUREAU - 10 LF

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupanito Circle
Monterey Park, CA 91755

XRF LEAD BASEL. INT SURVEY

Client: SANTA MONICA M921BU USO

Spectrum Analyzer ID #:

SANTA MONICA, CA 90403

Date:

Project No.: 52.25526.0001

Survey Location:

LINCOLN M.S. - 1501 CALIFORNIA AVE.

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
256	1ST	MAIN BLDG - RM 103			W	DOOR	WOOD	TAN	0
257		"			"	DOOR FRAME	METAL	"	0
258		"			S	WALL	PLASTER	TAN	0.1
259		"			E	"	"	"	0
260		"			W	"	"	"	0
261		"			"	WALL	PAINTED	TAN	0
262		"			S	HAND RAIL	METAL	GREEN	0
263		"			W	LOCKER	"	LT BLUE	0
267		"			E	DRINKING FOUNTAIN	PORCELIN	WHT	0
265		"			W	FLOR. ROSE CABINET	WOOD	TAN	0
266		"			"	STAIR NEWEL POST	"	TAN	0
267		"			"	STAIR TREAD	CERAMIC	GRAY	0
267		"			"	DISPENSING CABINET	WOOD	TAN	0
269	2ND	"			N	WALL	PLASTER	TAN	0
270	11	"			S	CONDUIT	METAL	"	0

COMMENTS:

1ST FL HALLWAY - BASEBOARD - 60 LF

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

25 Cupanito Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
271	2ND	MAIN HALL - RM 203			N	WALL	PLASTER	TAN	0.1
272					W	"	DRYWALL	"	0
273					N	WINDOW CASING	METAL	WHT	0
274					"	WINDOW SILL	WOOD	"	0
275					E	BASEBOARD	"	TAN	0
276		RM 205			N	WALL	DRYWALL	TAN	0
277					W	"	PLASTER	"	0
278			I	64 LF	"	BASEBOARD	WOOD	"	2-3
279					E	WINDOW CASING	METAL	WHT	0
280					E	WINDOW SILL	WOOD	"	0
281					W	DOOR	WOOD	BLK	0
282					I	DOOR FRAME	METAL	TAN	0
283					I	DOOR CASING	WOOD	"	0.2
284		RM 207 BDR			S	WALL	CERAMIC	LT GRAY	0
285		"			"	SINK	PORCELIN	WHT	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: 19
 Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403
 Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
271	7th	MAIN HALL - RM 203			N	WALL	PLASTER	TAN	0.1
272					W	"	DRYWALL	"	0
273					N	WINDOW CASING	METAL	WHT	0
274					"	WINDOW SILL	WOOD	"	0
275					E	BASEBOARD	"	TAN	0
276		RM 205			N	WALL	DRYWALL	TAN	0
277					W	"	PLASTER	"	0
278			I	64UF	"	BASEBOARD	WOOD	"	2-3
279					E	WINDOW CASING	METAL	WHT	0
280					E	WINDOW SILL	WOOD	"	0
281					W	DOOR	WOOD	BLUE	0
282					I	DOOR FRAME	METAL	TAN	0
283					I	DOOR CASING	WOOD	"	0.2
284		RM 207 Boys			S	WALL	CERAMIC	LT GRAY	0
285		"			"	SINK	PORCELIN	WHT	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
 F FAIR - Small Amount Flaking
 P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: SANTA MONICA, CA 90403

Project No.: 00001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
286	2ND	MAIN BUILD - RM 207 (BAY)			N	URINAL	PORCELAIN	WHIT	0
287					↓	TOILET	"	"	0
288					E	WINDOW CABINETS	METAL	WHIT	0
289					N	WALL	drywall	TAN	0
290					"	SINK	cast iron	WHIT	0
291					N	WALL	plaster	TAN	0.4
292					S	"	drywall	"	0
293					↓	DOOR	WOOD	BUE	0
294					↓	DOOR FRAME	METAL	TAN	0
295					W	DOOR CASING	WOOD	"	0
296					E	WALL	plaster	TAN	0
297					↓	WINDOW CABINETS	METAL	WHIT	0
298					↓	WINDOW SILL	WOOD	"	0
299					S	WALL	plaster	TAN	0.1
300	4			1 ea	"	LADDER	METAL	"	> 9.9

COMMENTS:

RM 211 - RENOVATED - 65 LF

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cupania Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Project No.: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Inspector(s):

Task No.: 00001

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
286	2ND	MAIN BUILD - RM 207 (BAY)			N	URINAL	PORCELAIN	WHIT	0
287						TOILET	"	"	0
288					E	WINDOW CASING	METAL	WHIT	0
289					N	WALL	drywall	TAN	0
290					"	SINK	cast iron	WHIT	0
291					N	WALL	plaster	TAN	0.4
292					S	"	drywall	"	0
293					I	DOOR	WOOD	BUE	0
294					I	DOOR FRAME	METAL	TAN	0
295					W	DOOR CASING	WOOD	"	0
296					E	WALL	plaster	TAN	0
297					I	WINDOW CASING	METAL	WHIT	0
298					I	WINDOW SILL	WOOD	"	0
299					S	WALL	plaster	TAN	0.1
300	4			1 ea	"	LADDER	METAL	"	> 9.9

COMMENTS:

RM 211 - RENOVATED - 65 LF

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

Date: 52.25526.0001 Client: SANTA MONICA MARLBORUS Spectrum Analyzer ID #: SANTA MONICA, CA 90403
Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.
Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
301	2ND	WALKIN BUBB - RM 215			E	WINDOW CASING	METAL	FAIR WHT	0
302					E	WINDOW PLANK	WOOD	WHT	0
303			I	1 ea	W	SINR	CRST. PAN	"	79.9
304					I	DOOR	WOOD	DRK	0
305					I	DOOR CASING	"	TAN	0
306		RM 215A REST ROOM			S	WALL	CERAMIC	WHT	0
307					E	FLOOR	"	GRAY	0
308					W	SINK	POURCON	WHT	0
309					"	TOILET	"	"	0
310					CENTRAL	CEILING	DRYWALL	WHT	0
311					E	DOOR	WOOD	DRK	0
312					I	DOOR PLANK	METAL	TAN	0
313		RM 217			W	WALL	PURTEAL	"	0
314			I	65 LF	"	DISKBOARD	WOOD	"	3.3
315			I	2 ea	"	DOOR CASING	"	"	7.7

COMMENTS:

CONDITION OF PAINT:
I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO Spectrum Analyzer ID #: 90403
Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403
Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
301	2ND	WIKIN BUDG - RM 215			E	WINDOW CASING	METAL	TAN WHT	0
302					E	WINDOW FRAME	WOOD	WHT	0
303			I	1 ea	W	SINL	CST, RON	"	79.9
304					I	DOOR	WOOD	DRK	0
305						DOOR CASING	"	TAN	0
306		RM 215A REST ROOM			S	WHL	CERAMIC	WHT	0
307					E	FLOOR	"	GRY	0
308					W	SINK	POURCON	WHT	0
309					"	TOILET	"	"	0
310					CENTRAL	CEILING	DRYWALL	WHT	0
311					E	DOOR	WOOD	DRK	0
312					I	DOOR FRAME	METAL	TAN	0
313		RM 217			W	WHL	PLASTER	"	0
314			I	65 LF	"	DRY BOARD	WOOD	"	3.3
315			I	2 ea	"	DOOR CASING	"	"	7.7

COMMENTS:

CONDITION OF PAINT:
I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cuponia Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

Client: SANTA MONICA MARZIBU USO

Spectrum Analyzer ID #:

SANTA MONICA, CA 90403

Date: 52.25526.0001

Survey Location:

LINCOLN M.S. - 1501 CALIFORNIA AVE.

Project No: 00001

Inspector(s):

Task No: 00001

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
316	2ND	MAIN Bldg - Rm 217			E	WINDOW CASING	METAL	WHT	0.1
317		"		5 Ea	"	WINDOW SILL	WOOD	"	2.7
318		- Rm 217A			N	WALL	PLASTER	TAN	0
319		(BUSSTOOL Rm)			E	WINDOW CASING	METAL	WHT	0
320					"	WINDOW SILL	WOOD	WHT	0
321					S	SINK	ENGT IRON	"	0
322					"	W/D PIPE	METAL	TAN	0
323					W	DOOR CASING	WOOD	"	0.6
324			I	1 ea	S	HOT W/D HEATER PLATFORM	METAL	"	79.9
325					"	SHELVING	WOOD	"	0
326		Rm 219 G.R.S RR			S	WALL	CERAMIC	WHT	0
327					N	SINK	PORCELIN	↓	0
328					"	TOILET	"	↓	0
329					W	DOOR	WOOD	BLUE	0
330					"	DOOR FRAME	METAL	TAN	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

Client: SANTA MONICA MARLBORO USO

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
316	2ND	MAIN Bldg - Rm 217			E	WINDOW CASING	METAL	WHT	0.1
317		"		5 Ea	"	WINDOW SILL	WOOD	"	2.7
318		- Rm 217A			N	WALL	PLASTER	TAN	0
319		(EUSTONIAN RM)			E	WINDOW CASING	METAL	WHT	0
320					"	WINDOW SILL	WOOD	WHT	0
321					S	SINK	CAST IRON	"	0
322					"	W/D PIPE	METAL	TAN	0
323					W	DOOR CASING	WOOD	"	0.6
324			I	1 Ca	S	HOT W/D HEATER PLATFORM	METAL	"	79-9
325					"	SHELVING	WOOD	"	0
326		Rm 219 G.R.S RR			S	WALL	CERAMIC	WHT	0
327					N	SINK	PORCELAIN	↓	0
328					"	TOILET	"	↓	0
329					W	DOOR	WOOD	BLUE	0
330					"	DOOR FRAME	METAL	TAN	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL ANT SURVEY



Date: 52.25526.0001 Client: SANTA MONICA MARLBORO USO Spectrum Analyzer ID #: SANTA MONICA, CA 90403

Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
331	2ND	RM 219A ELEC RM			S	WALL	PLASTER	TAN	0.2
332		"			N	CONDUIT	METAL	"	0
333		RM 221			N	WALL	PLASTER	TAN	0.1
334					E	WINDOW CASING	METAL	WHT	0
335			I	5 cm	"	WINDOW SILL	WOOD	"	2.0
336			I	1 cm	W	DOOR CASING	"	TAN	4.4
337					"	BASEBOARD	"	"	0.2
338		RM 223			W	WALL	PLASTER	TAN	0
339					E	WINDOW CASING	METAL	WHT	0
340			I	6 cm	E	WINDOW SILL	WOOD	"	3.8
341					W	DOOR	"	BLUE	0
342			I	1 cm	"	DOOR CASING	"	TAN	3.0
343		RM 225			N	WALL	PLASTER	"	0
344					W	WINDOW CASING	METAL	WHT	0
345					"	WINDOW SILL	WOOD	"	0

COMMENTS:

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL _____ NT SURVEY

Date: _____ Client: SANTA MONICA M421BU USO Spectrum Analyzer ID #: _____
Project No.: 52.25526.0001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403
Task No.: 00001 Inspector(s): _____

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
331	2ND	MAIN BUDB - RM 219A ELEC RM			S	WALL	PLASTER	TAN	0.2
332					N	CONDUIT	METAL	"	0
333		RM 221			N	WALL	PLASTER	TAN	0.1
334					E	WINDOW CASING	METAL	WHT	0
335			I	5 cm	"	WINDOW SILL	WOOD	"	2.0
336			I	1 cm	W	DOOR CASING	"	TAN	4.4
337					"	BASEBOARD	"	"	0.2
338		RM 223			W	WALL	PLASTER	TAN	0
339					E	WINDOW CASING	METAL	WHT	0
340			I	6 cm	E	WINDOW SILL	WOOD	"	3.8
341					W	DOOR	"	BLUE	0
342			I	1 cm	"	DOOR CASING	"	TAN	3.0
343		RM 225			N	WALL	PLASTER	"	0
344					W	WINDOW CASING	METAL	WHT	0
345					"	WINDOW SILL	WOOD	"	0

COMMENTS: _____



25 Cupanla Circle
Monterey Park, CA 91755

XRF LEAD BASEL NT SURVEY

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

SANTA MONICA, CA 90403

Date: 52.25526.0001

Survey Location:

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
346	2ND	MAIN BUILD - HALLWAY			S	WALL	PLASTER	TAN	0.2
347					E	LOCKER	METAL	LT. BLUE	0
348			I	600 LF	S	PASSEBOARD	WOOD	TAN	79.9
349			R	600 LF	S	DOOR FRAME	WOOD	GRAY	0
350					W	"	METAL	TAN	0
351					"	ELECT. PANEL	"	"	0
352					"	FIRE HOSE CABINET	"	"	0
353					"	DISPLAY CASE	WOOD	TAN	0
354					E	DRINKING FOUNTAIN	PORCELAIN	WHT	0
355					"	HAND RAIL	METAL	GREEN	0
356					"	ABE LINCOLN MURAL WALL	PLASTER	BRICK TONES	0.3
357					"	DOOR CASING	DOOR WOOD CASING	GREEN	0
358									1.0
359									1.0
360									1.0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL NT SURVEY



25 Cupanla Circle
Monterey Park, CA 91755

Client: SANTA MONICA MARLBOROUGH

Spectrum Analyzer ID #:

Date: 52.25526.0001

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
346	2ND	MAIN BUILD - 2ND FL			S	WALL	PLASTER	TAN	0.2
347					E	LOCKER	METAL	LT. BLUE	0
348			I	600 LF	S	BASEBOARD	WOOD	TAN	79.9
349			R	600 LF	S	DOOR FRAME	WOOD	GRAY	0
350					W	"	METAL	TAN	0
351					"	ELECT. PANEL	"	"	0
352					"	FIRE HOSE CABINET	"	"	0
353					"	DISPLAY CASE	WOOD	TAN	0
354					E	DRINKING FOUNTAIN	PORCELAIN	WHT	0
355					W	HAND RAIL	METAL	GREEN	0
356					W	ABE LINCOLN MURAL WALL	PLASTER	PAINT TONES	0.3
357					W	DOOR CASING	DOOR WOOD CASING	GREEN	0
358									1.0
359									1.0
360									1.0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASELINT SURVEY

1-30-09

Date:

Project No.: 52.25526.0001

Task No.: 00001

Client: SANTA MONICA MARLBORUS

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
361		Calibration							1.0
362									1.0
363	2nd Fl								1.0
364		Main Bldg Rm 222			S	wall	Drywall	white	0
365					w	window casing	metal		0
366					w	window frame	wood		0
367					E	Door		Blue	0
368					E	Door frame	metal	white	0
369					N	wall	Drywall	white	0
370		Rm 220			w	window casing	metal		0
371					w	window sill	wood		0.2
372					E	Door	wood	Blue	0
373					E	wall	Drywall	white	0
374		Rm 218			w	window casing	metal		0
375					w	window sill	wood		0

COMMENTS: lead windows Each @ Rm's 222, 220, 218

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

Date: 1-30-09

Project No.: 52-25526.0001

Task No.: 00001

Client: SANTA MONICA MARLBORUS

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Spectrum Analyzer ID #:

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
361	/	Calibration	/	/	/	/	/	/	1.0
362	/	/	/	/	/	/	/	/	1.0
363	2nd Fl	/	/	/	/	/	/	/	1.0
364	/	Main Bldg	/	/	S	wall	Drywall	white	0
365	/	/	/	/	W	window casing	metal	/	0
366	/	/	/	/	W	window frame	wood	/	0
367	/	/	/	/	E	Door	/	Blue	0
368	/	/	/	/	E	Door frame	metal	white	0
369	/	/	/	/	N	wall	Drywall	white	0
370	/	Rm 220	/	/	W	window casing	metal	/	0
371	/	/	/	/	W	window sill	wood	/	0.2
372	/	/	/	/	E	Door	wood	Blue	0
373	/	/	/	/	E	wall	Drywall	white	0
374	/	Rm 218	/	/	W	window casing	metal	/	0
375	/	/	/	/	W	window sill	wood	/	0

COMMENTS: low windows Each @ Rm's 222, 220, 218

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

Date: 1-30-09

Project No.: 52.25526.0001

Task No.: 00001

Client: SANTA MONICA MAG21BU USO

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Spectrum Analyzer ID #:

SANTA MONICA, CA 90403

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
376	2nd	main Bldg Rm 218			E	Door	wood	Blue	0.1
377					E	Door Frame	metal	white	0
378		Library Rm 212			E	wall	Plaster		0
379					S		Drywall		0
380					E	Door	metal	TAN	0
381					E	Door Frame		metal white	0
382		Rm 212 A			N	wall	Drywall	white	0
383		Rm 212 B			E				0.1
384					N	Door	metal	Blue	0
385					N	Door Frame	white	white	0
386		Rm 212 C			E	wall	Drywall		0
387					N	Door	metal	Blue	0
388		Rm 212 D			N	wall	Drywall	white	0
389					S	Door	wood	Blue	0
390						Door Frame	metal	white	0

COMMENTS: Library ~~not~~ repainted Aluminum windows

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASELINT SURVEY

Date: 1-30-09

Client: SANTA MONICA MARLBORO USO

Project No: 52.25526.0001

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
376	2nd	Main Bldg Rm 218			E	Door	wood	Blue	0.1
377					E	Door Frame	metal	white	0
378		Library Rm 212			E	wall	Plaster	↓	0
379					S	↓	Drywall	↓	0
380					E	Door	metal	Tan	0
381					E	Door Frame	↓	metal white	0
382		Rm 212 A			N	wall	Drywall	white	0
383		Rm 212 B			E	↓	↓	↓	0.1
384					N	Door	metal	Blue	0
385					N	Door Frame	white	white	0
386		Rm 212 C			E	wall	Drywall	↓	0
387					N	Door	metal	Blue	0
388		Rm 212 D			N	wall	Drywall	white	0
389					S	Door	wood	Blue	0
390					↓	Door Frame	metal	white	0

COMMENTS: Library metal unpainted Aluminum windows

CONDITION OF PAINT:

- I INTACT
- F FAIR - Small Amount Flaking
- P POOR - Large Amounts Flaking



25 Cupanla Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

1-30-09

Date: _____

Project No.: 52.25526.0001

Client: SANTA MONICA MARLBORO

Spectrum Analyzer ID #: _____

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s): _____

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
391	2nd	main 6106	I	1ea	E	sink	cast iron	white	79.9
392					S	wall	drywall	↓	0
393					EU	window casing	metal	white	0
394					EU	window frame	unpainted wood	↓	0
395					E	door	wood	blue	0
396					E	door frame	metal	white	0
397					EU	window casing	↓	white	0
398					W	window frame	wood	↓	0
399					E	door	↓	blue	0
400					E	wall	drywall	white	0
401					N	wall	↓	↓	0
402					W	window casing	metal	↓	0
403					W	window sill	wood	↓	0
404					E	door	↓	blue	0
405					↓	door frame	metal	white	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

XRF LEAD BASEL INT SURVEY



25 Cuponia Circle
Monterey Park, CA 91755

1-30-09

Date: 52.25526.0001
Project No:

Client: SANTA MONICA MAGNIBU USO

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
391	2nd	main 6106	I	1 ea	E	sink	cast iron	white	79.9
392		2nd 212 D			S	wall	drywall	↓	0
393		2nd 206			EU	window casing	wind metal casing	white	0
394					EU	window frame	wind metal frame	↓	0
395					E	Door	wood	Blue	0
396					E	Door Frame	metal	white	0
397		2nd 204			EU	window casing	↓	white	0
398					W	window frame	wood	↓	0
399					E	Door	↓	Blue	0
400					E	wall	drywall	white	0
401		2nd 202			N	wall	↓	↓	0
402					W	window casing	metal	↓	0
403					W	window sill	wood	↓	0
404					E	Door	↓	Blue	0
405					↓	Door Frame	metal	white	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

1-30-09

Date:

Project No: 52.25526.0001

Client: SANTA MONICA MARLBORU USO

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N.E.S.W	Surface	Substrate	Color	Result (mg / cm ²)
406	2nd Fl	Main Bldg 2nd Fl Center Stairwell			N	wall	Drywall	white	0
407	↓	↓	I	12 in ft	S	riser	concrete	↓	3.5
408	↓	↓			N	hand rail	metal	Blue	0
409	1st Fl	Main Bldg - Family Lounge			N	wall	plaster	white	0.3
410	↓	↓			E	↓	↓	↓	0
411	↓	↓			W	↓	↓	↓	0.1
412	↓	↓			S	↓	↓	↓	0.2
413	↓	↓			S	window casing	metal	↓	0
414	↓	↓			E	Door	wood	Blue	0
415	↓	↓			E	Door frame	metal	white	0
416	↓	↓			N	wall	plaster	white	0
417	↓	↓			E	wall	ceramic	gray	0
418	↓	↓			N	sink	porcelain	white	0
419	↓	↓			N	toilet	↓	↓	0
420	↓	↓			C	Door	wood	Blue	0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

PAGE

28

OF

20



25 Cuponia Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

1-30-09

Date:

Project No.: 52.25526.0001

Client: SANTA MONICA MAGNIBU USO

Spectrum Analyzer ID #:

Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE. SANTA MONICA, CA 90403

Task No.: 00001

Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
406	2nd Fl	Main Bldg 2nd Fl Central Stairwell	I	12 in ft	N	wall	Drywall	white	0
407	↓	↓	↓	↓	S	riser	concrete	↓	3.5
408	↓	↓	↓	↓	N	hand rail	metal	Blue	0
409	1st Fl	Main Bldg - Am 300 Faculty Lounge			N	wall	plaster	white	0.3
410	↓	↓	↓	↓	E	↓	↓	↓	0
411	↓	↓	↓	↓	W	↓	↓	↓	0.1
412	↓	↓	↓	↓	S	↓	↓	↓	0.2
413	↓	↓	↓	↓	S	window casing	metal	↓	0
414	↓	↓	↓	↓	E	Door	wood	Blue	0
415	↓	↓	↓	↓	E	Door frame	metal	white	0
416	↓	↓	↓	↓	N	wall	plaster	white	0
417	↓	Am 300 B 300 Rest rm	↓	↓	E	wall	ceramic	gray	0
418	↓	↓	↓	↓	N	sink	porcelain	white	0
419	↓	↓	↓	↓	N	toilet	↓	↓	0
420	↓	↓	↓	↓	C	Door	wood	Blue	0

COMMENTS:

CONDITION OF PAINT:

I INTACT

F FAIR - Small Amount Flaking

P POOR - Large Amounts Flaking

PAGE

28

OF

20



25 Cupania Circle
Monterey Park, CA 91755

XRF LEAD BASEL INT SURVEY

1-30-09

Date: 52.25526.0001 Client: SANTA MONICA MARLBORO USO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
Project No.: 00001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
421	1st F	MAIN Bldg			E	wall	Cement Tile	Gray	0.1
422					E	sink	Porcelain	white	0
423					W	urinal			0
424					W	toilet			0
425					S	Door	metal	Gray	0
426					S	Door frame			0
427		606-G- RM 310			N	wall	Plaster	white	0.5
428					E				0
429					W				0.5
430					S				0
431					E	window casing	metal	white	0
432					E	windowsill	wood		0
433					E	Door	metal	Blue	0
434					E	Door frame	metal	white	0
435					N	Cabinet	wood		0

COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking



XRF LEAD BASEL INT SURVEY

25 Cupania Circle
Monterey Park, CA 91755

1-30-09

Date: 52.25526.0001 Client: SANTA MONICA MAYIBU USO Spectrum Analyzer ID #: SANTA MONICA, CA 90403
Project No.: 00001 Survey Location: LINCOLN M.S. - 1501 CALIFORNIA AVE.

Task No.: 00001 Inspector(s):

Sample No.	Floor	Room / Area	Condition Of Paint	Quantity Of Lead	Location N,E,S,W	Surface	Substrate	Color	Result (mg / cm ²)
421	1st F	main 151017			E	wall	Ceramic Tile	Gray	0.1
422					E	sink	Porcelain	white	0
423					W	urinal			0
424					W	toilet			0
425					S	Door	metal	Gray	0
426					S	Door frame			0
427		606-G- Rm 310			N	wall	Plaster	white	0.5
428					E				0
429					W				0.5
430					S				0
431					E	window casing	metal	white	0
432					E	window sill	wood		0
433					E	Door	metal	Blue	0
434					E	Door frame	metal	white	0
435					N	Cabinet	wood		0


COMMENTS:

CONDITION OF PAINT:

I INTACT
F FAIR - Small Amount Flaking
P POOR - Large Amounts Flaking

APPENDIX C

Site Diagrams



LEGEND:


= Capital Spelling

Building "E" West First Floor Plan NOT TO SCALE

Santa Monica Malibu Unified School District
LINCOLN MIDDLE SCHOOL
MODERNIZATION/DEMOLITION PROJECT
1501 CALIFORNIA AVENUE
SANTA MONICA, CALIFORNIA 90403

PROJECT NUMBER: 052.25526.0009 TASK NO.: 01 DRAWING
REVIEW BY: P. COTA DRAWN BY: DAW 6 of 13

VATC 25 Cupania Circle
ASSOCIATES, INC. Monterey Park, CA 91755
Ph: (323) 517-9780 *** Fax: (323) 517-9781




Building "E" & "G" East First Floor Plan-

NOT TO SCALE

Santa Monica Malibu Unified School District
 LINCOLN MIDDLE SCHOOL
 MODERNIZATION/DEMOLITION PROJECT
 1501 CALIFORNIA AVENUE
 SANTA MONICA, CALIFORNIA 90403

PROJECT NUMBER: 052.25526.0009	TASK NO.: 01	DRAWING
REVIEW BY: P. COTA	DRAWN BY: DAW	7 of 13
VATC ASSOCIATES, INC. 25 Cupania Circle Monterey Park, CA 91755 Ph: (323) 517-9780 *** Fax: (323) 517-9781		



LEGEND:


- (X) = Attic Samples
- 126 = T&E Pipe Debris
- 127-129 = Brown Battleship flooring
- 130-132 = Roofing debris
- 133-135 = 2'x2' fissured ceiling tiles
- (see book) →

Building "E" East Second Floor Plan-
NOT TO SCALE

PROJECT NUMBER: 052.25526.0009		TASK NO.: 01	DRAWING
REVIEW BY: P. COTA		DRAWN BY: DAW	8 of 13
 VATC 25 Cupania Circle Monterey Park, CA 91755 Ph: (323) 517-9780 *** Fax: (323) 517-9781		Santa Monica Malibu Unified School District LINCOLN MIDDLE SCHOOL MODERNIZATION/DEMOLITION PROJECT 1501 CALIFORNIA AVENUE SANTA MONICA, CALIFORNIA 90403	

APPENDIX D

State of California Asbestos and Lead Inspector Certifications



State of California
Division of Occupational Safety and Health
Certified Site Surveillance Technician

Robert Medina



Name

Certification No. **99-2673**

Expires on **10/15/11**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7160 et seq. of the Business and Professions Code.

State of California Department of Public Health

Lead-Related
Construction
Certificate

Certificate
Type

Expiration
Date

Sampling Technician 05/19/2012



Robert B. Medina

ID #: 1087