

# MONITORING SERVICES DURING ASBESTOS AND LEAD REMOVAL WORK

Window Retrofit Project Grant Elementary School 2365 Pearl Avenue Santa Monica, California 90405

#### Prepared for:

Santa Monica-Malibu Unified School District 1651 Sixteenth Street Santa Monica, California 90404

Project No.: SMSD-17-6801 Date: September 28, 2017

#### **EXECUTIVE SUMMARY**

Alta Environmental (Alta) conducted monitoring and air sampling services during asbestos and lead-based paint removal completed for the Window Retrofit Project completed at Grant Elementary School located at 2365 Pearl Avenue, Santa Monica, California 90405. The monitoring was conducted from June 12, 2017 through July 24, 2017 by Alta representatives Cesar Ruvalcaba, David Schack, Jorge Robles, Victor Sanchez, and Gustavo Sanchez. Alta completed the following activities during the project:

- Monitoring services during all asbestos and lead related work
- · Air sampling during the asbestos and lead related work
- Final visual inspection and clearance testing at the completion of the asbestos and lead related work, as needed

During this project, asbestos-containing window putty was removed from Buildings A, C, E, H, and K. Following removal activities, the areas were inspected by the Contractor and an Alta representative; each area was found to be acceptably clean. Upon passing of a through visual inspection, the work areas were removed for re-occupancy. The project was limited to the removal of asbestos-containing construction (ACCM), and asbestos-containing (ACM) window putty. Other identified ACMs remain on this campus. All construction material should be assumed to contain asbestos until the materials are verified for asbestos content by reviewing the Asbestos Management Plan Record.

During this project, minor planned disturbances to lead-based paints was completed. These disturbances included the stabilization of damaged loose and flaky paint for preparation for repainting in affected by the window retrofit in Buildings A, C, E, and K. The work was completed using proper engineering controls including barriers signs, drop floors, and a worker decontamination facility. The areas were released for reoccupancy by non-protected personnel upon passing of a thorough visual inspection conducted by the Contractor Supervisor and Alta representative. Alta collected representative surface lead wipe samples following the stabilization work. Results of all samples collected were reported to be below the clearance criteria established for this project. LBP remains on this campus. Any future disturbance to LBP shall be conducted using proper engineering controls, work protections, and proper waste disposal.

## **CONTENTS**

1	INTRODUCTION	1
2	PROJECT BACKGROUND	1
2.1	Alta Monitoring and Sampling	1
2.2	Asbestos and Lead Related Work	1
3	FIELD AND ANALYTICAL METHODOLOGY	2
3.1	Lead Air Analysis	2
3.2	Lead Wipe Sample Analysis	2
4	MONITORING AND RESULTS	2
4.1	Monitoring	2
5	RESULTS	2
5.1	Lead Air Sample Results	2
5.2	Lead Wipe Sample Results	3
5.3	Final Visual Inspection Results	3
5.4	Post Abatement Sample Results	3
5.4.1	Lead Clearance Sampling	3
6	CONCLUSIONS AND RECOMMENDATIONS	3
7	ASSUMPTIONS AND LIMITATIONS	3
8	SIGNATORY	4

### **Appendices**

Appendix A: Daily Field Reports and Field Testing

Appendix B: Laboratory Reports, Lead Air and Wipe Sample Analysis

Appendix C: Alta Environmental Employee Certifications

REPORTED: September 28, 2017 PROJECT NO.: SMSD-17-6801

**CLIENT:** Santa Monica-Malibu Unified School District

1651 Sixteenth Street

Santa Monica, California 90404

ATTENTION: Mr. Chris Emmett

**REF:** Monitoring Services During Asbestos and Lead-Based Paint Removal Work

Window Retrofit Project Grant Elementary School 2365 Pearl Avenue

Santa Monica, California 90405

#### 1 INTRODUCTION

Alta Environmental (Alta) conducted monitoring and air sampling services during asbestos and lead-based paint removal completed for the Window Retrofit Project completed at Grant Elementary School located at 2365 Pearl Avenue, Santa Monica, California 90405.

#### 2 PROJECT BACKGROUND

### 2.1 Alta Monitoring and Sampling

The Santa Monica-Malibu Unified School District retained Alta for the monitoring services. The monitoring was conducted from June 12, 2017 through July 24, 2017 by Alta representatives Cesar Ruvalcaba, David Schack, Jorge Robles, Victor Sanchez, and Gustavo Sanchez, all Cal-OSHA Certified Site Surveillance Technicians, Certified Asbestos Consultants and California Department of Public Health Certified Inspector Assessor and Project Monitors. Alta completed the following activities during the project:

- Monitoring services during all asbestos and lead related work,
- Air sampling during the asbestos and lead related work,
- Final visual inspection and clearance testing at the completion of the asbestos and lead related work, as needed.

#### 2.2 Asbestos and Lead Related Work

The asbestos and lead removal work was completed by Resource Environmental. (Cal License No. #864417) located in Paramount, California.

Resource removal scope of work included the following:

1. ACCM window putty, all exterior windows of Building A,

- 2. ACCM window putty, all exterior windows of Building C,
- 3. ACM window putty, all exterior windows of Building E,
- 4. ACCM window putty, all exterior windows of Building H, and
- 5. ACCM window putty, all exterior windows of Building K.
- 6. LBP, damaged paint stabilization, all interior and exterior identified painted components affected with the window retrofit project.

#### 3 FIELD AND ANALYTICAL METHODOLOGY

## 3.1 Lead Air Analysis

Alta collected air samples during the asbestos related work using high and low-flow air sampling pumps. The flow rate of each pump was checked before and after each use with a calibrated precision rotameter.

## 3.2 Lead Wipe Sample Analysis

Alta collected representative wipe samples following the lead related work. The samples were analyzed in accordance with NIOSH Method 7082 by AQ Laboratories located in Signal Hill, California, a laboratory accredited by the Environmental Laboratory Accreditation Program (ELAP).\

#### 4 MONITORING AND RESULTS

### 4.1 Monitoring

Alta representatives were on site during the removal work to document the work completed by the contractor.

The window panels were removed intact. Minimal to no disturbances to the window putty were observed. Engineering controls and removal methods used for the work included the following:

- 1. Critical barriers inside the buildings,
- 2. Demarcation signage approximate 10 feet pass the work areas,
- 3. 2-stage worker decontamination facility,
- 4. Window panels were separated from the window casing by cutting the metal arms using a saw,
- 5. Worker protection included full body disposable coveralls, ½ face air purifying respirators, hand, foot, and eye protection,
- 6. Each window panel was burrito wrap, labeled and taken to a storage bin,
- 7. Waste was dispose an approved waste disposal facility.

## 5 RESULTS

#### 5.1 Lead Air Sample Results

Results of representative samples collected during the project were reported below Cal-OSHA Permissible Exposure Level.

#### 5.2 Lead Wipe Sample Results

All samples collected following the lead related work were reported by the laboratory to be below the recommended clearance levels established for this project.

#### 5.3 Final Visual Inspection Results

Before asbestos and lead work areas were released, they were inspected by the Contractor's supervisor and Alta representatives for evidence of residual dust and debris. The work areas were found to be acceptable. No dust or debris was observed.

#### 5.4 Post Abatement Sample Results

#### 5.4.1 Lead Clearance Sampling

Alta conducted random wipe samples representative of each building following the lead related work. All samples collected were reported by the laboratory to be below the recommended clearance levels of 400 micrograms of lead per square foot of area for exterior floors. The areas were deemed acceptable to occupy by non-protected personal and the containment areas were removed.

#### 6 CONCLUSIONS AND RECOMMENDATIONS

The abatement removal project was limited to the removal of window panels containing asbestos window putty in Buildings A, C, E, H, and K. No other materials or paints were included in the scope. Asbestos and lead-based paint has been identified on this site. Alta recommends that prior to any construction or renovation project, a survey of the impacted area be conducted by a Cal-OSHA Certified Asbestos Consultant to determine if any material impacted contain asbestos. Refer to the asbestos and lead survey records prepared for this site for material and locations.

Following the asbestos and lead related work in each area, the areas was inspected by both the Abatement Contractor Supervisor and Alta representative. The areas were found to be acceptably clean of visible loose dust and debris.

For lead-related work, following the passing of the final visual inspection, Alta collected surface dust wipes. Alta conducted random wipe samples representative of each building following the lead related work. All samples collected were reported by the laboratory to be below the recommended clearance levels of 400 micrograms of lead per square foot of area for exterior floors. The areas were deemed acceptable to occupy by non-protected personal and the containment areas were removed.

#### 7 ASSUMPTIONS AND LIMITATIONS

This report was prepared exclusively for use by the Santa Monica-Malibu Unified School District, and may not be relied upon by any other person or entity without Alta Environmental's express written permission. The information, conclusions and recommendations described in this report apply to conditions existing at certain locations when services were performed and are intended only for the specific purposes, locations,

time frames and project parameters indicated. Alta Environmental cannot be responsible for the impact of any changes in environmental standards, practices or regulations after performance of services.

In performing our professional services, we have applied present engineering and scientific judgment and used a level of effort consistent with the current standard of practice for similar types of studies.

As applicable, Alta Environmental has relied in good faith upon representations and information furnished by individuals with respect to operations and existing property conditions, to the extent that they have not been contradicted by data obtained from other sources. Accordingly, Alta Environmental accepts no responsibility for any deficiencies, omissions, misrepresentations, or fraudulent acts of persons interviewed.

Alta Environmental will not accept any liability for loss, injury claim, or damage arising directly or indirectly from any use or reliance on this report. Alta Environmental makes no warranty, expressed or implied.

This report is issued with the understanding that the client, the property owner, or its representative is responsible for ensuring that the information, conclusions, and recommendations contained herein are brought to the attention of the appropriate regulatory agencies, as required.

If you have any questions, please do not hesitate to contact the undersigned at (562) 495-5777. We appreciate the opportunity to be of service to Santa Monica-Malibu Unified School District.

#### 8 SIGNATORY

Submitted for and on behalf of Alta Environmental.

Respectfully Submitted by:

Cesar Ruvalcaba Project Manager

Certified Asbestos Consultant 95-1799

CDPH Certified Project Monitor and Inspector

Assessor I6855

Appendix A

Daily Field Reports

Date:	6/19/17	Alta representative:	Cesar Ruvalcaba
Project No.:	<u></u>	Project name:	Grant ES
Project location:	Exterior windows	Project area:	Building K
Time of observation	Observations	187	
0930	Arrived on site to relieved David Schack. Currently removing the window panels. the panels are removed intact. No impacritical barriers, drop floors, signs and a 2 face APR, hand, foot, and eye protection.	The panels are removed ets to putty, minor impa 2-stage decon. Worker	d by cutting the support arms and acts to paint. Area set up includes,
1000	David Schack leaves the site		
1200	Work in building F completed, removed 4 loose dust and debris. Alta collects samp	1 panels. Area inspecte les for delivery to labor	d, and found to be clean of visible ratory.
1400	Sample is delivered to AQ Labs in Signal H	Hill for lead in wipe anal	lysis.
1800	Received results, passing. Results forwar	ded to contractor.	
	Contractor: Resource Environmental, Sup	pervisor, Miguel Barrerr	a and two workers
		- 40	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
			\$ 1
	***		
	3100		
		990000 999	
	11-000-	7	
	300000000000000000000000000000000000000		
·			
	$\wedge$		
Alta Representative Signature: Cal/OSHA Cert. No.:		Date: 6/19/17	

PROJECT LOG/DAILY INSPECTION CHECKLIST						
Date:	6/29/17 Alta representative: Desar Runcland					
Project No.:	Project name: Winder project					
Project location:	Natar Sa. Windows Project area: Bldg. A.					
Time of observation	Observations Grant 25					
0700	Arrival, Rosovico alvedo an site, 3. Norkar plur on saporuses					
0300	Thing cert up a U.ldg A Hang S, water, or					
(200)	Window promise Calbre is used using HERM 41/chiants.					
	5-ty- knited b-wies dup ylours signs: docon.					
	Notal site with core B bridge worth words by					
-	enjoyen to be sof winder have been renewed , west complete					
	Alt fell-its - wipe Kern. Rosource is =150 0 regisal-ting -					
	C-p-lens on theyinder to work is do completed- Alto collects ?					
_	C-po-lens officiended the Work is ASD confilled - Alf Collects &					
0,00	Att 100 lower sto for other District Sites to drop					
	a pick cp guspnart Superison Mignel is given by					
1200	I notion, to site the north findes of rea ex completed					
	encapialited and area cheange wop. Alto collecte a wife					
	Canord Framewal In process at South Winders 9 bow					
1345	Alth Leoner Site, West Completed for today, Contret					
725	posepinor for and j stript.					
	Remore					
	Confecto: Resource Supervisor - Miguel Bos ()					
(						
2-						
Alta Representative	: Obser Parolcolo- Date: 6/23/17					
Signature:						

Cal/OSHA Cert. No.:



## PROJECT LOG/DAILY WORK AREA INSPECTION CHECKLIST

Date: 6/26/17		Alta representative:	rge Robles
Project No.: SANSO -	17-6801	Project name:	int Elementury School
Project location: Grant E	.5.	Project area:	13 3 4,5 Bldg A
· · · · · · · · · · · · · · · · · · ·	/ wirdow frames		J. J. Slag !!
Type of Containment:	/	Respiratory Protection Use	ed:
Full: 3-stage decon/walls/ceiling/showe	г .	½ face: P100	
plash3stage decon-shower	wash station	½ face: P100/Organic	
		•	
Mini: 2-stage decon-shower	wash station	Full face: P100	
Glovebag/secondary containment	wash station	PAPR-HEPA	
other (describe)			
Arrival time (Alta):	Ahatement contract	ar Resource Co	che chia
1=0=	Abatement contract	or: <u>Resource Cou</u> or's name: <u>Miguel Ba</u>	Carcon
Departure time (Alta): 7500	Contractor supervis	or's name: /// ywel /36c	
	(first and last)		
	Contractor arrival tir	ne: <u>0/0</u> 0 D	eparture: /445
# of workers present:	Worker certifications	current/available on-site	<u> </u>
		Reviewed by Alta	
Contract in the bound on the Lindbutton	0.1/00114 1/0 //		2
Contractor's job board present includin			
Other contractors on-site/activities:	Installment of	new windows	
DAILY WORK AREA INSPE	CTION (Check 4 Times	Shift)	
Decontamination Unit	Time of Inspection	A Pressure Differential Isolation Bar	riers Time of Inspection QA
Proper signs at entrance and bag-out		Proper # of AFDs for area	
Airlock flaps intact (not taped open)		☐ Containment smoke-tested	
Street clothing properly stored		☐ AFDs properly vented	
Suits/respirator filters present		☐ Pre-filter clean	
Area clean: waste bags not obstructing path		☐ Exhaust tubing intact	
Shower/pump/filters operating properly		☐ Critical barriers intact	
Work Practices		Waste Disposal	Time of Inspection QA
No saws/brooms in work area		Waste/debris bagged	
Material kept wet		Waste double-bagged, sealed,	
Material promptly bagged	0,000 0 1	decontaminated, labeled prior to rem  Dumpster lined, labeled	
Workers in proper PPE: no cut-off sleeves of sui		Dumpster closed top/locked	De Tour III II
no cut-off feet of suit, eye protection used, glove			
used, hood up, respirator straps inside hood	1 , , ,		3 - VAII - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 -
No eating, smoking, drinking in work area	□ □ □ □ □ □ □	Type of manifest (HAZ/FRI.	ABLE) (NON-FRIABLE)
		# of bags N	lanifest #

Date:	6/26/17	Alta representative:	Jorge Robins
Project No.:	SMSO-17-6801	Project name:	Grant E.S.
Project location:	2368 Pearl St. Senta Monica	Project area:	100ml 3, 4, 5

Time of observation	Observations
0700	workers Sunt Amezena and Ciro Rodriguez begin work on window
	12 moral 17 100m 5 and 100m 4
	the work area
	- plastic laid out on ground 20' ft from building
	- containment on inside of building room 5 and toom 4
	- windows previously removed are now boarded up
4	- hose with zoray handle in use to vet debriand waste
	o workers wearing gropes PPE
	- full sout, half face PIDD respirator with full face visor
	-helmets and gloves worn at all times
	mini 2 stage decon-shower present
	-wash station and first did station present
0730	- wolkers begin using power saw and hammer to take down
	windows in come 5 and room 4
	- worker continually bag and wet debits once taken down
	- windows are removed by the taping entire window, then slowly hannering
	glass to break and separate from Pame
octor.	- one glass is seniver, metal trank is comover using source saw
08'00	- WORK area 100ks cream, took photos or work area
0830	- workers continue using hose to gorang debrie
0900	- Mignel begins prepping com 3 for containment - contemment inside classrooms are intact and no debis vinble
1015	Confess ment prosted classifooms are intract and py octors you be
1473	- workers Sant and Ciro began boarding up window spaces where
1100	- wolkers break for funch
// 1/0	- work area looks clean, no visable debri
	- west is taken to appropriate dumposter for repestor waste
	-dumpste is properly labeled
1200	-workers cotion from lanch
1245	- work on windows in room 5 is complete, window spaces are your board
1300	- work on windows in room 5 in completes window spaces are now board - workers take break and begin cleaning up work area and dispose of waste
	to the dumpster

Alta Representative:	Jorge Robbes	Date:	6/26/17
Signature:	182		, , _
Cal/OSHA Cert. No.:			_

Date:	(0/24/17 Alta representative:	Usrge Robbis
Project No.:	Project name:	Grant E.S.
Project location:	Project area:	
Time of observation	Observations	
1400	- workers have stopped work on window I cun using power bods or hammer - they continue to band up window spaces	oval and are no longer
	using power bods or hammer	
	- they continue to board up window spaces	and prepare work area for
	TOMOTOW	
	- Mignel Sunt and Ciro begin work on cour	Hainment tol room 3
	- rown 3 now has containment barries invide	1000 COOM 3 COOM 7
	- coom 5 containment is taken down inside a coom 5 ingde and out is clean. no visit	Le delas
1445	- Miguel, Saul and Ciro finish for the da	C MUSTS
	- work area is clean	<del>-</del>
	- coon 5,4 and 3 are clean	
	- room 4 and 3 containments are intac	+ duel peopely get up
<del></del>		

Alta Representative: XXXX Robbes	Date:	6/26/17
Signature:	_	
Cal/OSHA Cert. No.:		_



## PROJECT LOG/DAILY WORK AREA INSPECTION CHECKLIST

Date:	6/27/17			A	ta representative:	Jorge	Ko	660	ع		
Project No.:	MSD-17-	6801		P	roject name;	Brant	E. S				
	1368 Pearl	-			107	100m 4					_
	windows/u				_		1 -				
Type of Containment:	/				Respiratory Protection	n Used:					
Full: 3-stage decon/walls/d	ceiling/shower			1/	2 face: P100						
plash3stage decon-showe	r wa	ash st <u>ati</u> o	П	(1)	face: P100/Organic						
Mini: 2-stage decon-show	er (wa	ash statio	$\supset$	4	all face: P100						
Glovebag/secondary conta	ainment wa	ash statio	n	F	PAPR-HEPA						
ther (describe)											
				-	4						
Arrival time (Alta):	<u>9790</u>	_ Abaten	nent contr	actor:	Resource	Constru	ctro	24			
Departure time (Alta):	1500	Contra	ctor super	visor's	Resource sname: Miguel 1	Sarrera					
250		(first an			0						
		Contrac	ctor arriva	l time:	0700	Departu	re:	14	50		
# of workers present:	3				urrent/available on-site						
# of workers prosent.		_ WOINEI	Ceruncau	0113 00							
Reviewed by Alta Yes											
						•					
Contractor's job board pre-					QMD if applicable	7					
Contractor's job board pre- Other contractors on-site/a					QMD if applicable	•					
	activities: <u>In s</u>	tallm	ent 6	of n	QMD if applicable	•					
Other contractors on-site/a	activities: <u>Ins</u>	tallm	ent 6	of n	QMD if applicable	-					
Other contractors on-site/a  DAILY WORK ARE	A INSPECTION	Jallm ON (Che	ent 6	es/Sh	QMD if applicable  ew windows  ift)	-					
Other contractors on-site/a  DAILY WORK ARE  Decontamination Unit	A INSPECTION  1  g-out	ON (Che	ent 6 eck 4 Tim pection	es/Sh	QMD if applicable とい いたくのいら ift) Pressure Differential Isolat	-	Time	of Ins	pection	n	QA
Other contractors on-site/a  DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba	A INSPECTION  g-out en)	ON (Che	eck 4 Tim pection	es/Sh	QMD if applicable  www.wirlows  ift)  Pressure Differential Isolat  Proper # of AFDs for area	-	Time	of Ins	pection	n	QA
Other contractors on-site/a  DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba  Airlock flaps intact (not taped op	A INSPECTION  g-out en)	ON (Che	eck 4 Tim pection	es/Sh	Ift)  Pressure Differential Isolat  Proper # of AFDs for area  Containment smoke-tested	-	Time	of Ins	pection	n	QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst	activities: In s  A INSPECTION  g-out en)	ON (Che	eck 4 Tim  pection  Ø  Ø  ©  Ø  ©  Ø  ©  Ø  Ø  Ø  Ø  Ø  Ø	es/Sh	QMD if applicable  ew windows  ift)  Pressure Differential Isolat  Proper # of AFDs for area  Containment smoke-tested  AFDs properly vented	-	Time	of Ins	pection	n	QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr	activities: In s  A INSPECTION  g-out en)	ON (Che	eck 4 Tim  pection  Ø  Ø  ©  Ø  ©  Ø  Ø  Ø  Ø  Ø  Ø  Ø  Ø	es/Sh	QMD if applicable  ift)  Pressure Differential Isolat  Proper # of AFDs for area  Containment smoke-tested  AFDs properly vented  Pre-filter clean  Exhaust tubing intact  Critical barriers intact	-	Time	of Ins	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst	activities: In s  A INSPECTION  g-out en)	ON (Che	eck 4 Tim  pection  Ø  Ø  ©  Ø  ©  Ø  Ø  Ø  Ø  Ø  Ø  Ø  Ø	es/Sh	Ift)  Pressure Differential Isolate Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal	-	Time	of Insp	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr	g-out en)  ructing path	ON (Che Fime of Ins.	eck 4 Tim  pection  Ø  Ø  ©  Ø  ©  Ø  ©  Ø  Ø  Ø  Ø  Ø  Ø	es/Sh	QMD if applicable  ift)  Pressure Differential Isolat  Proper # of AFDs for area  Containment smoke-tested  AFDs properly vented  Pre-filter clean  Exhaust tubing intact  Critical barriers intact	-	Time	of Insp	pection		QA
Other contractors on-site/a  DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba  Airlock flaps intact (not taped op  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obst  Shower/pump/filters operating pr  Work Practices	g-out en)  ructing path	ON (Che	eck 4 Tim  pection  Ø  Ø  ©  Ø  ©  Ø  Ø  Ø  Ø  Ø  Ø  Ø  Ø	es/Sh	QMD if applicable  ift)  Pressure Differential Isolat  Proper # of AFDs for area  Containment smoke-tested  AFDs properly vented  Pre-filter clean  Exhaust tubing intact  Critical barriers intact  Waste Disposal  Waste/debris bagged  Waste double-bagged, sealed	ion Barriers	Time	of Insp	pection		QA
Other contractors on-site/a  DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr Work Practices  No saws/brooms in work area Material kept wet	g-out en)  ructing path	ON (Che lime of Ins	eck 4 Time pection Description	es/Sh	Ift)  Pressure Differential Isolate Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed decontaminated, labeled prio	ion Barriers	Time	of Insp	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr Work Practices No saws/brooms in work area Material kept wet  Material promptly bagged	g-out en)	ON (Che Fime of Ins.	eck 4 Time pection of or	es/Sh QA	Pressure Differential Isolate Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed decontaminated, labeled Dumpster lined, labeled	ion Barriers	Time	of Insp	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr Work Practices No saws/brooms in work area Material kept wet  Material promptly bagged Workers in proper PPE: no cut-o	g-out en)  ructing path roperly  ff sleeves of suit,	ON (Che lime of Ins	eck 4 Time pection Description	es/Sh	Ift)  Pressure Differential Isolate Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed decontaminated, labeled prio	ion Barriers	Time	of Insp	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr Work Practices No saws/brooms in work area Material kept wet  Material promptly bagged	g-out en)  ructing path roperly  ff sleeves of suit, tion used, gloves	ON (Che Fime of Ins.	eck 4 Time pection	es/Sh QA	Pressure Differential Isolate Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed decontaminated, labeled Dumpster lined, labeled	ion Barriers	Time	of Insp	pection		QA
DAILY WORK ARE  Decontamination Unit  Proper signs at entrance and ba Airlock flaps intact (not taped op Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obst Shower/pump/filters operating pr Work Practices  No saws/brooms in work area Material kept wet  Material promptly bagged Workers in proper PPE: no cut-ono cut-off feet of suit, eye protect	g-out en)  ff sleeves of suit, tion used, gloves inside hood	ON (Che Fime of Ins.	eck 4 Time pection	es/Sh QA	ift)  Pressure Differential Isolat Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed decontaminated, labeled prio Dumpster lined, labeled Dumpster closed top/locked	ion Barriers	Time	of Insp	pection		QA

Date:	6/27/17	Alta representative:	Jarge Robbes
Project No.:	SMSD-17-6801	Project name:	Grant E.S.
Project location:	2-368 PEAR St. Santa Mario	≤Project area:	Room 4,3

Time of observation	Observations
0700	-workers Sual America and Ciro Redriguer begin work on
	window removal in room 4 and room 3
	- proper signs for asbestos are in place as well as asbesto- tape
	eucling not area
	- plastic laid out on ground up to 20 feet from building
	- containment inside classroom Jand 3 is fully Intach and
	no desi's visible inside classrooms
	- window spaces inside room 4 and room 5 are boarded up
	- Other contractor for window installation begin setting up in room 5
	- hose with gray handle in use to wet debris and waste
	- workers wearing proper PPE
	- full suit, half face Plud with full face visors to protect from
	broken glass
	- helmets and gloves worn at all times
	-wash Station and first aid Station present as well as eye wash station
A = 0.0	Mecan room present and intact
0730	-workers saul and Ciro begis using hammer and power saw
0000	to remove windows and window frames
0800 0830	- Cesar Ruvalcasa arives on site to look over progress
0000	- some debris visible inside classroom 4
0845	- Mignel quickly vacuums and cleans room 4 - classroom 4 is now clean with no visible debris and containment
_0013	Del and angely intert
0930	- wirdow removal is complete in com 4
	- windows are boarded up
	- classioan is clean and containment is still partially intact
	-windows on North and south sile are bounded up
1000	- work is now solely on and worth side windows
	power saw and hammer in use with hose spraying debris every few w
1045	- work on window removal on north side of room 4 is complete
	- worker began por enganiating around window area
	- Mignel segins vacuuming with area
1100	- wolker break for lunch

Date: 6/27/17

Alta Representati	ve:
-------------------	-----

Signature:

Cal/OSHA Cert. No.:

Date:	6/27/17 Alta representative: Vorge Kobles
Project No.:	SMSO-17-6801 Project name: Orga Robles  Smso-17-6801 Project name: Grant C.S.
Project location:	2368 Pearl St. Santa Monica Project area: Cooms 4, 3
Time of observation	Observations
1210	-workers return from lunch
1230	on Room by
	- work on roof begins to access small windows on sonth side
1300	- work on root begins to access small windows on south side -work has stopped on North side of room 4 and room 3 - workers pause work on windows to vacuum and chan work area
/330	- notes pause work on windows to vacuum and chan workarea
	On to of root
	- horn side of building looks clean. No visible debris
11.20	- work is primarify on south side of room 4 and room 3
1430	- workers begin to board up windows on south side of room 4 and 3 - work on North side windows for room 4 and room 3 is finished
	- window spaces are boarded up on Mith side
1445	- Miguel and sant and Ciro Gegin Cleaning yo wide room 3
	Lusing vacuums HEPA

Date: 6/27/17

Alta Representative:

Signature:

Cal/OSHA Cert. No.:



## PROJECT LOG/DAILY WORK AREA INSPECTION CHECKLIST

Date: 6/28/17					_ A	ta representative: Vorge	Ra	sles					
Project No.: SMSO-	17-	681	DI		_ Pi	ta representative: Vorge Grant	6.5	) 0					
Project location: 2368 Pearl	154.	San:	ta 1	lanic	ー メ Pi				2				
Material Removed: windows/	inele	w h	ram	es		uantity removed:							
Type of Containment:					_	Respiratory Protection Used:							
Full: 3-stage decon/walls/ceiling/shower					7	ź face: P100							
plash3stage decon-shower	wash	statio	n		0	face: P100/Organic							
Mini: 2-stage decon-shower	wash	statio			F	Full face: P100							
Glovebag/secondary containment	wash	statio			F	APR-HEPA							
ther (describe)					·								
Z tilet (describe)													
Arrival time (Alta): 0700	A	batem	ent c	ontra	ctor:	Resource Cons	truct	01					
Departure time (Alta): 1445	c	ontrac	tor s	uperv	isor's	name: Mignel Barre	119						
		rst an				-0							
	•	ontrac		•	time:	<u>ම</u> 7ව <b>ග</b> Depa	ırture:	14-	37)				
# of workers present:						rrent/available on-site	_						
# of workers present:	vv	orker	сеги	ncano	ns cu					······································			
						Reviewed by Alta							
Contractor's job board present including	Cal/OS	HA no	otifica	ition a	nd A	QMD if applicable							
Contractor's job board present including Other contractors on-site/activities:	Cal/OS	HA no	otifica	ition a	nd A	QMD if applicable							
											_		
Other contractors on-site/activities:	TION		ck 4	Time			s Tim	e of Ins	pectio	n	QA		
Other contractors on-site/activities: DAILY WORK AREA INSPEC	TION	(Che	ck 4	Time	s/Sh	ift)	s Tim	e of Ins	spectio	en 🗆	QA 🗆		
Other contractors on-site/activities:  DAILY WORK AREA INSPECT	TION	(Che	ck 4	Time	s/Sh	ift) Pressure Differential Isolation Barriers							
Other contractors on-site/activities:  DAILY WORK AREA INSPECTOR  Decontamination Unit  Proper signs at entrance and bag-out	TION Timps	(Che	eck 4	Time	es/Sh	ift)  Pressure Differential Isolation Barriers  Proper # of AFDs for area							
Other contractors on-site/activities:  DAILY WORK AREA INSPECTION  Decontamination Unit  Proper signs at entrance and bag-out  Airlock flaps intact (not taped open)	Time	(Che of Insp 단 단	eck 4	Time	QA	ift)  Pressure Differential Isolation Barriers  Proper # of AFDs for area  Containment smoke-tested							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out  Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obstructing path	TION Timpe	(Che of Ins, 단 단 단	eck 4	Time	QA	ift)  Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obstructing path  Shower/pump/filters operating properly	Time	(Che of Insp 단 단	eck 4	Time	QA	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean	0						
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out  Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obstructing path	TION Timpe	(Che of Ins, 단 단 단	eck 4	Time	es/Sh	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obstructing path  Shower/pump/filters operating properly	TION Timpe	(Che of Ins, 단 단 단	eck 4	Time	es/Sh	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out  Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present  Area clean: waste bags not obstructing path  Shower/pump/filters operating properly  Work Practices	TION Timpe  Ø  Ø	(Che	eck 4	Time	QA	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed,							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obstructing path Shower/pump/filters operating properly  Work Practices  No saws/brooms in work area  Material kept wet	TION Timpe  Ø  Ø  Ø  Ø  Ø	(Che of Ins,	eck 4	Time	<b>QA</b>	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed, decontaminated, labeled prior to removal							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present Area clean: waste bags not obstructing path Shower/pump/filters operating properly  Work Practices  No saws/brooms in work area  Material promptly bagged	TION Time  El Se	(Che	eck 4	Time	s/Sh	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed, decontaminated, labeled Dumpster lined, labeled		o o o fins			QA .		
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present Area clean: waste bags not obstructing path Shower/pump/filters operating properly  Work Practices  No saws/brooms in work area  Material kept wet  Material promptly bagged  Workers in proper PPE: no cut-off sleeves of suit,	TION Time  EL  EL  EL  EL  EL  EL  EL  EL  EL  E	(Che of Ins,	eck 4	Time	<b>QA</b>	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed, decontaminated, labeled prior to removal							
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored  Suits/respirator filters present Area clean: waste bags not obstructing path Shower/pump/filters operating properly  Work Practices  No saws/brooms in work area  Material promptly bagged	TION Time  EL  EL  EL  EL  EL  EL  EL  EL  EL  E	(Che of Ins,	eck 4	Time	s/Sh	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed, decontaminated, labeled Dumpster lined, labeled		o o o fins			QA .		
Other contractors on-site/activities:  DAILY WORK AREA INSPECT  Decontamination Unit  Proper signs at entrance and bag-out Airlock flaps intact (not taped open)  Street clothing properly stored Suits/respirator filters present Area clean: waste bags not obstructing path Shower/pump/filters operating properly  Work Practices  No saws/brooms in work area  Material kept wet  Material promptly bagged  Workers in proper PPE: no cut-off sleeves of suit, no cut-off feet of suit, eye protection used, gloves	TION Time  EL  EL  EL  EL  EL  EL  EL  EL  EL  E	(Che of Ins,	eck 4	Time	s/Sh	Pressure Differential Isolation Barriers Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sealed, decontaminated, labeled Dumpster lined, labeled	Time	o of ins		0 0 0 0 0	QA .		

Date:	6/28/17	Alta representative:	Varge Robles
Project No.:	3MSD-17-6801	Project name:	Grant E.S.
Project location:	2368 Pea 1 St. Sunta Mo	Project area:	bldg A, Rm 2

Project location:	2 368 Pea 1 St. Sunta 100 "Project area: Olag 17, Rm L
Time of observation	Observations
0700	Miguel Barrera, Sant Amezona and (iro Rodríguez begin prepping
	Crassroom 2 tor window removal
	- laying one plastic 20 feel from un! on North side of building
	under unidous
	- taping off work area with aspestos warning the and the face
	- Alcan/shawer on site
	- washroom station and eye wash station / first aid present
	- askestos sign posted on decon/shower
	- Saul and Ciro begin laying window glass to limit glass debis
	before hammering for removal
	- Containment wall inside classroom 2 is fully intact and propole
	set up
	- no debris or wask visible in and around work grea
	- work today will be enticly on class-own 2 North and south
	side vindous
0745	Zant and Ciro begin using hammer and power sum on North side
	unacious
	- workers are wearing full suit, 1/2 face Plan with full face visors
	- helmets and gloves also worm
	- hose with soray handle in use to water down debris
	- Lett valuum ago in use to collect albris
0830	tworkers continue using power saw and hammer on Northside
	windows on classroom 2.
200:	- hose being used frequently to water down detris
0900	containment is side classroom 2 fully in tack and working property
10.0	-no visible debris posite classroom 2
1000	-workers continue wirdow removal on North side of coma
	- power saw, hose and bagging of debris = - work area looks clean. Containment wall inside soon 2 is
	still fully intact
	- delivery of waste in bags to askestos dumyster
1030	-dumps for has proper asbestos signs as well as being sealed shut
1030	worker cety are available on site
	- all are up to deste

Alta Representative	:
Signature:	

Cal/OSHA Cert. No.:

Lorge Robles	Date:	6/28/17
Reces		

Date:	6/28/17	Alta representative:	Jorge Robles
Project No.:	SMSD-17-6801	Project name:	Grant E.S.
Project location:	2368 Pearl St. Santa MON	Project area:	Bldg A m 2

Time of observation	Observations
1047	-worker stop so progress on windows to clean work area
	- bagging dibris and class
1054	- windows on Northside of room 2 are fully removed as
	well as wirdow frames
1100	- Saul and Ciro begin valuating North side of building - some desis leaked through containment inside room ?
	- Mignel quickly vacuumed debris inside classroom 2
	- Saul and Ciro begin encapsulating around window areas
1115	workers break for lanch
1210	- workers return from lunch
	- hegis setting up for south side windows to Room 2
	- laying out -lastic 20 feet from wall
	- Saul and Ciro suit up
	- Full Suit, 12 Plao, helmet, gloves, visors
	-hose spaying every few minutes
	- hose = praying every few minutes - lead hazard topse enclosing work area
	- USL of hammer and power saw
12 30	- Dave Schack visited the gite
	- walked around and observed the progress - workers finish removal of south side withous in Room 2
1320	-workers finish removal of south side windows in Room 2
	- begin taking down outdoor containment, clean up debris
1345	- south side 6+ Room 2 is clean. No visible debris
	-all windows on south side are boarded up
1400	- windows on North and South are boarded up
	- area looks clean, no visible debris
	- window removal for building A is complete
1730	- workers fingh and take off
·	

Alta Representative:	
Signature:	

Cal/OSHA Cert. No.:

SQL	a Robbles	Date:	6/28/17
-/5			
1			



## PROJECT LOG/DAILY WORK AREA INSPECTION CHECKLIST

Date: $\frac{6/29}{}$	/17	_ Alta representative:	Grant E.	206/	8		
Project No.: SMSD-1	Project No.:SMSD-17-6801			5.			
Project location: 2368 PENL		BLDI		_	5.	LIRL	
Material Removed: いいもい (	urry	Quantity removed:	ele Ros				
Type of Containment:		Respiratory Protect	ion Used:				
Full: 3-stage decon/walls/ceiling/shower		1/2 face: P100					
plash3stage decon-shower	wash station	½ face: P100/Organic					
Mini: 2-stage decon-shower	wash station	Full face: P100					
Glovebag/secondary containment	wash station	PAPR-HEPA					
ther (describe)							
Arrival time (Alta): 0700  Departure time (Alta): 1430	Abatement contra	-//	Bacrica	source	Cors	tru	ition
	(first and last)						
	Contractor arrival	ime: 0700	Departure	, ju	130	•	
# of workers present: 3		ns current/available on-site					
	*********************************	Reviewed by Alt					
Contractorio inh hannel account including t	CallOCUA antiensian a	-	10 705 4ES				
Contractor's job board present including (							
	•		a modern s				
DAILY WORK AREA INSPEC	TION (Check 4 Time	s/Shift)					
Decontamination Unit	Time of Inspection	QA Pressure Differential Iso	lation Barriers	Time of In	spectio	n	QA
Proper signs at entrance and bag-out		☐ Proper # of AFDs for area					
Airlock flaps intact (not taped open)		☐ Containment smoke-tester	d				
Street clothing properly stored	A 0 0 0	☐ AFDs properly vented					
Sults/respirator filters present		☐ Pre-filter clean					
Area clean: waste bags not obstructing path	<u> </u>	☐ Exhaust tubing intact					
Shower/pump/filters operating properly	Ø 0 0	☐ Critical barriers intact					
Work Practices		Waste Disposal		Time of In	spection	n	QA
No saws/brooms in work area		☐ Waste/debris bagged		<u> </u>			
Material kept wet		<ul> <li>Waste double-bagged, sea decontaminated, labeled p</li> </ul>					
Material promptly bagged		☐ Dumpster lined, labeled		4 0			
Workers in proper PPE: no cut-off sleeves of suit, no cut-off feet of suit, eye protection used, gloves used, hood up, respirator straps inside hood		☐ Dumpster closed top/locke	ed	<b>0</b> 0			
No eating, smoking, drinking in work area		☐ Type of manifest	(HAZ/FRIABLE)	(NON	-FRIABI	LE)	-
A CONTRACTOR OF THE CONTRACTOR		# of bags	Manifest	#			

PROJECT LOG/DAILY INSPECTION CHECKLIST Time of **Observations** observation Mignel Barrera, Saul America, and Cio Rodriguez la start-- began prepping windows in room 41, gills restroom, and Boys MOO - plastic laid out outside (Dm 41 15 feet from wall - decon/shower fixed on boys restroom - ItEPA vacuum, hose of spray port on side

- lead Hazard tage enclosing work area

- they will be removing windows from the inside of Loys and girls restroom

- containment inside restrooms consists of plastic living floor and walls undergenth windows to reason for removing bondows from inside - there was an electric power box on outside of restrooms room 41 windows will be removed from the outside - containment inside room 41 consists of plastic taped to the wall outlining Windows Sent and (10 suit up in PPE - full suit, 1/2 face P/DD, helmet, gloves 0715 0800 -change of dan. -girls and boy, restroom will be under full containment - plastic on wall walls and surfaces - 1 room decon shower connected to door + outside windows will be uncovered due to electric box being in way I (GABE PIVELA) ARRIVE ON SITE & TAKE OVER FOR JORGE ROBLES. 9900 I GIVE JOSEE MY SAMPLES POM AIR SLEAD WIPES DOUBLE WILL HAND DELINCE SANTUES TO AMERISCI, CONTRACTOR CONTINUES SCOPE OF WORK HALE IN LIKES & BOYS BATHLOOM UNDER FUN CONTAINMENT, NO OTHER ISSUES ON PROBLEMS P NERDUT " RESOURCE CONTINUES SCOPE OF WORK. WORK DUES PROPERTY 1000

> SEALED OFF W CONTIN TAPE. WORK OVER UNDER CONTAINMENT & WORLENS USING PROPER P.P.E.

OF LAST WINDOWS LOCATED IN ROOM HUI.

RESOURCE EXIT CONTAINMENT & BREAK FOR LUNCH

PESOURCE RETURNS FROM LUNCH ( STOLTS REMOVAL

Alta Representative:	GABE DUGLA	Date:	6/29/2017
Signature:	Dul:		•
Cal/OSHA Cert. No.:	04	-3560	

1100

1200

PROJECT LO	OG/DAILY INSPECTION CHECKLIS	ST	
Date:	6/29/2017	Alta representative:	GABE KIVERA
Project No.:	SMSD-17-6801		GLANT E.S.
	368 PEARL ST. SOWM MONICE	Project area:	BLOG. C Boys Gress
	The G. HALL DOCK	- Toject area.	(Coors HU)
Time of observation	Observations		5
1300	RESOURCE COMPLETE W L	UNDOWN CEMOUR	c of liver. C
	THEY STALT FINAL OF THE	L OF WORLE	MSA.
1330	I PENTORM FINAL UISHAL	AFTEL MINOR	CORRECTION
	1 PENFORM FINAL VISUAL 1 PASS WORK AREA S PI SAMPLES . (1) WIPE PER RESOURCE WILL NOW BE	WIKED BC	WHENT LEAD WIFE
	PESCHOLOGY ACUT BE	KOOM OF DU	06.6
1430	PESOURCE HAS VEFT WOR \$ IOR SUPPLIES RESOUR FROUNDS, NO OTHER	K DIGA WITH	NO EQUIPTIMENT
0	\$ ION SUPPLIES . RESOUR	CE SAUTA L	EAVE SCHOOL
	GROUNDS, NO OTHER	issues or Pru	BLENC IN REPORT
	e PHIS TIME.		
		<u> </u>	
		<del></del>	
			<del>_</del>
		<u> </u>	
		. <u>-</u>	
Alta Representati	Ve: GABE JUEVA	Date: C 2q	<u>2</u> 017

04-3560

Cal/OSHA Cert. No.:



## PROJECT LOG/DAILY WORK AREA INSPECTION CHECKLIST

Date:	(0/30/1-	7				_ Al	ta representative:	Vorge R	06k	S			
Project No.:	ect No.: _ S M S O - 17 - 680		Pr	oject name:	Jorge Robbes Grant E.S.								
Project location:	2368 Pearl	54.	Sheri	ta 1	wide	– A Pr	oject area;	m 36,30			31/13	de	<del>/_</del>
Material Removed:	windows / win						uantity removed:						
Type of Containmen	nt:					F	tespiratory Protection	on Used:					
Full: 3-stage decon/wal	ls/ceiling/shower					(7	face: P100						
plash3stage decon-sho	wer	wash s	tatio	1		1/	face: P100/Organic						
Mini: 2-stage decon-sh	DWED (	wash s	tation	1	)	F	ull face: P100						
Glovebag/secondary co	ontainment	wash s	tation	1		Р	APR-HEPA						
ther (describe)													
,				·									
Arrival time (Alta):	_0700	Ab	atem	ent c	ontra	tor:	Resource	Constr	net	107			
Departure time (Alta):	9 13	30 Co	ntrac	tor su	ıpervi	sor's	name: Miguel	Barrer	·a				
				d last									
		Co	ntrac	tor a	rival t	ime:	0700	Departui	re: <u>/</u>	320			
# of workers present:	3	W	orker	certif	icatio	ns cı	rrent/available on-site	Tes					
		_					Reviewed by Alta						
Contractor's job board	oresent including C	al/OSH	НА по	tificat	lion a	nd A							
Other contractors on-si	_	7. a cho	lt.a.	120.4	· //24		1000 1 Santon 25						
Other contractors on-signal DAILY WORK AF	te/activities:												
DAILY WORK AF	te/activities:	ION	(Che	ck 4	Time	s/Sh	ift)						QA .
DAILY WORK AF	REA INSPECT		(Che	ck 4	Time	s/Sh QA	ift) Pressure Differential Isol			of Ins	pection	1	QA
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and	REA INSPECT	Time o	(Che	ck 4	Time	s/Sh	ift)	ation Barriers	Time	of Ins <sub>j</sub>			
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped	REA INSPECT  I bag-out I open)	Time o	(Che	eck 4	Time	s/Sh QA	Pressure Differential Isol Proper # of AFDs for area	ation Barriers	Time	of Ins	pection	,	
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and	REA INSPECT  I bag-out I open)	Time o	(Che	eck 4	Time	s/Sh QA	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested	ation Barriers	Time	of Ins	pection	,	
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store	REA INSPECT  I bag-out I open)  Id	Time o	(Che	eck 4	Time:	s/Sh	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented	ation Barriers	Time	of Insp		0	
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present	REA INSPECT  I bag-out I open)  Id t obstructing path	Time of	(Che	eck 4	Time	s/Sh	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean	ation Barriers	Time	of Insp			
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of	REA INSPECT  I bag-out I open)  Id t obstructing path	Time of	(Che	eck 4	Time	s/Sh	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact	ation Barriers	Time	of Insp	Dection		
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operating	REA INSPECT  I bag-out I open)  Id t obstructing path g properly	Time of	(Che	eck 4	Time	s/Sh	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact	ation Barriers	Time	of Ins <sub>i</sub>	Dection		0 0 0 0 0
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operating	REA INSPECT  I bag-out I open)  Id t obstructing path g properly	Time of	(Che	eck 4	Time	QA	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal	ation Barriers	Time	of Ins <sub>i</sub>	Dection		
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters presen Area clean: waste bags not of Shower/pump/filters operatin  Work Practices  No saws/brooms in work are	REA INSPECT  I bag-out I open)  Id t obstructing path g properly	Time of the control o	(Che	eck 4	Time	QA	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operating Work Practices No saws/brooms in work are Material kept wet  Material promptly bagged	REA INSPECT  I bag-out I open)  I t obstructing path g properly	Time of the control o	(Che	eck 4	Time	QA	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sea decontaminated, labeled properly interesting the property of th	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operation Work Practices  No saws/brooms in work are Material kept wet  Material promptly bagged Workers in proper PPE: no of	REA INSPECT  I bag-out I open)  I open)  I open bet to be tructing path g properly  a ut-off sleeves of suit,	Time of the control o	(Che	eck 4	Time	QA O	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sea decontaminated, labeled pressure in the contained of the contained in th	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operation Work Practices  No saws/brooms in work are Material kept wet  Material promptly bagged Workers in proper PPE: no of no cut-off feet of suit, eye pro-	REA INSPECT  I bag-out I open)  Id t bbstructing path g properly  a  ut-off sleeves of suit, otection used, gloves	Time of the control o	(Che	eck 4	Time	QA O	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sea decontaminated, labeled properly interesting the property of th	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0
Dailly WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operating Work Practices  No saws/brooms in work are Material kept wet  Material promptly bagged Workers in proper PPE: no of no cut-off feet of suit, eye pro used, hood up, respirator street	REA INSPECT  I bag-out I open)  I out I open)  I d  I open)  I open  I ope	Time of the control o	(Che	eck 4	Time	QA O	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sea decontaminated, labeled propurpster lined, labeled Dumpster closed top/locked	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0
DAILY WORK AF  Decontamination Unit  Proper signs at entrance and Airlock flaps intact (not taped Street clothing properly store Suits/respirator filters present Area clean: waste bags not of Shower/pump/filters operation Work Practices  No saws/brooms in work are Material kept wet  Material promptly bagged Workers in proper PPE: no of no cut-off feet of suit, eye pro-	REA INSPECT  I bag-out I open)  I out I open)  I d  I open)  I open  I ope	Time of the control o	(Che	eck 4 pection  Dection  Dectio	Time	QA O	Pressure Differential Isol Proper # of AFDs for area Containment smoke-tested AFDs properly vented Pre-filter clean Exhaust tubing intact Critical barriers intact Waste Disposal Waste/debris bagged Waste double-bagged, sea decontaminated, labeled properly lined, labeled Dumpster lined, labeled Dumpster closed top/locked	lation Barriers	Time	of Insp	Dection		0 0 0 0 0 0 0 0 0 0 0

Project No.:  Project Iocation:  Project area:  Observation  Observation  Observation  Other death of the project area:  Observation  Other death of the project area:  Other death of the project area:  Other death of the project area:  Other death of the project area and are death of the project award of the project of the	Date:	6/30/17	Alta representative:	Jorge Robbes
Project location:  Project area: rm 36,30 boy & gills off observation  Observations  O700 Maguel Baccera, Sunt America and Ciro Radriques begin work  ph justodian (com 36 east windowing girls destroom to the left of 100m 36, boys restroom, and Room 30  - all windows will be removed from outside the building with confarmment barrier insule contring windows competelling  - Sunt and Ciro suit you in PPE  - thill sunt, be face 1100, believe, visor, gloves  - laid out pleastic outside windows to room 36 15 H firm window  O715 workers begin removing windows from am 36  - use of power saw and harmer to present  - hose af going sandle to use frequently as well as HEFFI wavening  - what station as well as 2 song decar from in with area  - what station as well as 2 song decar from in with area  - workers begin removing allows and delaning work area  - begin bagging wisk and to delivering them to the demostre  - lead the rand for leadings around window area  O810 - workers begin reagons lating around window area  O810 - workers begin reagons lating around window area  O810 sondows from girls and boys restroom to the 16th of 12m 36.  I low flow sump with lead easie the on autside Ru 36 windows  O100 - workers bagin recommended by settloom have been encaptulated  - workers have begin recommended and clean worker area to kanster  look and room 30  - workers there looks chann no visible dehirs  - workers there to man break  O140 - workers begin talting down windows in Run 30  - Run 30, boys 4 gills Pethoom look chan, Run 30  - workers bagen talting down windows in Run 30  - workers bagen talting down windows in Run 30  - workers bagen talting down windows in Run 30  - workers bagen talting down windows in Run 30  - workers bagen talting of leading and clean Run 30  - workers bagen talting of leading and clean Run 30  - workers bagen talting of leading and clean Run 30  - workers bagen talting of leading and leading and clean Run 30  - workers bagen talting of leading and leading and leading and clean Run 30  - workers bagen t	Project No.:	SMSD-17-6801	Project name:	•
Observations  Otherwitions  Otherwitions  Otherwitions (com 36 east windows, girls restroom to the feld of 100 m 36, boys restroom, and Room, 30 m 30 the feld of 100 m 36, boys restroom, and Room, 30 m 30 the feld of 100 m 36, boys restroom, and Room, 30 mysterial will be removed from outside the building with containment burrier inside contring analows completely and and city suit is face 1100, telenet, visor, gloves - fall suit is the face 1100, telenet, visor, gloves - laid out playtic putside windows to noom 36 16 ft from window of north of power saw and harmace the great as 4 from window - hose of power saw and harmace the great as 4 from window - hose of power saw and harmace the great as 4 from window - hose say young hardle in use frequently as well as 4 from window - worker begin vacuuming debois and delaning work area - begin bagging wash and the proposed delaning work area - begin bagging wash and the same removed - workers begin vacuuming debois and delaning work area of 160 ft and 5 fape encloses work are  Office workers begin recognishing around window area of the fame of the fam	Project location:		Project area:	1
of noom 36, boys restroom, and Room, 30 restroom to the feld of noom 36, boys restroom, and Room, 30 and Rolling with contament barrow inside contring windows completely "Sent and Cio suit you in PPE"  - half suit, to face HOO, helmet, visor, glores "laid out plants outside windows to noom 36 15 ft from windows on the sent of prosess been removing windows from am 36 15 ft from windows "hove of power saw and harmoner of present "hove of power saw and harmoner of present "hove of sover saw and harmoner of present of the form as well as 2 song decan noon in with area "hove of song handle in use frequently as well as HEPA vacuum "hove a song windows in Rem 36 than seen removed "windows in Rem 36 than seen removed "begin begging waste and there is not delivering than to the dangoste lead that and top encloses on the girls restroom to the left of Rem 36.  1815 workers begin encloses on the girls restroom to the left of Rem 36.  1816 those from girls dud boys restroom have been removed "windows from girls dud boys restroom have been removed "windows in Rem 36, girls floys restroom have been encapentated around the edges of sells (sean, no visible dehris "windows in Rem 36, boys a girls floys restroom have been encapentated around the edges of sells (estroom windows in Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows been they funch there have been to the for hand they have been to the form of the selection windows been to the first from the selection windows been to the form of the selection windows there is the form the selection will be the selection to the selection windows there is the first from the selection windows the selection to	l	Observations		
of noom 36, boys restroom, and Room, 30 restroom to the feld of noom 36, boys restroom, and Room, 30 and Rolling with contament barrow inside contring windows completely "Sent and Cio suit you in PPE"  - half suit, to face HOO, helmet, visor, glores "laid out plants outside windows to noom 36 15 ft from windows on the sent of prosess been removing windows from am 36 15 ft from windows "hove of power saw and harmoner of present "hove of power saw and harmoner of present "hove of sover saw and harmoner of present of the form as well as 2 song decan noon in with area "hove of song handle in use frequently as well as HEPA vacuum "hove a song windows in Rem 36 than seen removed "windows in Rem 36 than seen removed "begin begging waste and there is not delivering than to the dangoste lead that and top encloses on the girls restroom to the left of Rem 36.  1815 workers begin encloses on the girls restroom to the left of Rem 36.  1816 those from girls dud boys restroom have been removed "windows from girls dud boys restroom have been removed "windows in Rem 36, girls floys restroom have been encapentated around the edges of sells (sean, no visible dehris "windows in Rem 36, boys a girls floys restroom have been encapentated around the edges of sells (estroom windows in Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows have been longth they removed from Rem 30 "windows been they funch there have been to the for hand they have been to the form of the selection windows been to the first from the selection windows been to the form of the selection windows there is the form the selection will be the selection to the selection windows there is the first from the selection windows the selection to	0700	Miguel Barrera, Saul Amez	una and lin 1	Rodriques begin work
- all wirdows will be removed from outside the building with containment barrier inside contring windows completely - Seul and Ciro smit up in PPE - tall sout, to have 400, helmet, visor, gloves - laid out plushic outside windows no room 36 15 ft from window 0715 - workers begin removing windows from am 36 - use of power sam and harmer at gresent - hose af gray handle in use frequently as well as HEPA vacuum - hash station as well as 2 stay decar Dom in with area - workers begin vacuuming debris and cleaning work area - begin bagging work and the per delivering them to the dungste leld the sand tope encloses work area  0810 - workers begin encapsulating around window area  0815 work begin encapsulating around window area  0815 work fow pump with lead easile the on autside Ru 36 windows MOD windows from girls and boys extroom have been removed - workers have begun vacuuming and clean gurker area to fransfer  1804 and room 30 - workers have begun vacuuming and clean gurker area to fransfer  1805 and room 30 - workers take 10 min break  0930 workers take 10 min break  0940 - workers have begin fating down windows in Ru 30 - Ru 30, boys 4 girls restroom look clean. No vision debris  ass 0+ hose, and bagging kehniques in com 30 - widows have been couple they removed from Ru 30 - widows have been couple they removed from Ru 30 - widows have been couple they removed from Ru 30 - withers yaccuum up debris		Da custodian room 36 e	ast windows, gi	ils restroom to the left
containment barrier inside collering windows completely  Sent and Cio Smit ago in PPE  - full sout plastic pubside windows to soon, glowers  -laid out plastic pubside windows to soon 36 16 H from window  O715 - workers begin removing windows from am 36 - use of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - hose of power saw and harmoner of present  - worker begin recurring alkoris and deaning work area  - bein bagging week and the delivering thren to the dumpste-  - lead the rad type encloses work area  O310 - workers begin encapsulating around window area  O315 work the promp with lead easiet on matride Ru 16H of Rom 36.  I law flow pump with lead easiet from antide Ru 36 windows  Windows from girls and bagge subsoom have been semaphed  - workers have begin incumning and clean worker area to frans Rer  - look anto room 30  - workers have begin taking down windows in Run 30  - rookers take 10 min break  O940 - workers begin taking down windows in Run 30  - Ru 30, bogs 4 gills sestroom book clean, No visible debris  will 04 hose, and bagging kechniques in soon 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking down windows in Run 30  - workers begin taking the present the proper take the present the present the present the present		Of room 36, boys restroom	, and Room ;	30
- Seul and Ciro suit you in 1996  - full suit to face 1900, helmet, visor, gloves  - faid out plastic outside windows no room 36 15 H from window  1715 - workers begin removing windows from am 36  - use of power saw and harmon at present  - hore af some handle in use frequently as well as HEPA vacuum  - pash station as well as 2 song decan from in work area  0800 - windows in any 36 have been removed  - workers begin vacuuming debris and defaning work area  - testin baggine wish and the per delivering thrun to the dumpster  - lead the and tope recloses work area  0810 - workers begin encapsulating around window area  0815 work toping view lead cases the on outside the 36 windows  Rlow-flow pump with lead east the on outside in 36 windows  MOD windows from girls and boys estroom have been removed  - workers have begun uncuuming and clean worker area to frans fer  100k anto room 30  - workers have begun uncuuming and clean worker area to frans fer  100k anto room 30  - workers take 10 min break  0940 - workers begin taking down windows in Run 30  - Run 30, boys a gills restroom bot clean. No vision debris  - use of hore, and bagging kechniques in com 30  - Run 30, boys a gills restroom bot clean. No vision debris  - workers take 10 min break  0940 - widows have been completely removed from Run 30  - workers take 10 min break  0950 - widows have been completely removed from Run 30  - workers take for furth		- all wirdows will be removed	& from outside	the building with
- Seul and Ciro suit you in 1996  - full suit to face 1900, helmet, visor, gloves  - faid out plastic outside windows no room 36 15 H from window  1715 - workers begin removing windows from am 36  - use of power saw and harmon at present  - hore af some handle in use frequently as well as HEPA vacuum  - pash station as well as 2 song decan from in work area  0800 - windows in any 36 have been removed  - workers begin vacuuming debris and defaning work area  - testin baggine wish and the per delivering thrun to the dumpster  - lead the and tope recloses work area  0810 - workers begin encapsulating around window area  0815 work toping view lead cases the on outside the 36 windows  Rlow-flow pump with lead east the on outside in 36 windows  MOD windows from girls and boys estroom have been removed  - workers have begun uncuuming and clean worker area to frans fer  100k anto room 30  - workers have begun uncuuming and clean worker area to frans fer  100k anto room 30  - workers take 10 min break  0940 - workers begin taking down windows in Run 30  - Run 30, boys a gills restroom bot clean. No vision debris  - use of hore, and bagging kechniques in com 30  - Run 30, boys a gills restroom bot clean. No vision debris  - workers take 10 min break  0940 - widows have been completely removed from Run 30  - workers take 10 min break  0950 - widows have been completely removed from Run 30  - workers take for furth		containment barrier inside i	overing windows	completely
O715 workers begin removing undows from 86 15H from windly  - 1080 of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - work station as well as 2 says decan soom in work area  - workers begin vacuuming clearis and cleaning work area  - begin bagging wask and the delivering threm to the dunyoste-  - lead the zard type encloses work area  0810 workers begin encypse laking around window area  0815 work the row functs on the girls controlow to the left of Rm 36.  R law flow pump with lead easse the on autside Ru 36 windows  MOO windows from girls and boys astroom have been removed  - workers have begun encumning and clean gwrker area to frans fer  - book anto room 30  - workers have looks clean no visible debris  - windows in Rm 36e, girls & boys restroom have been encapsulated  around the edges  0930 workers take 10 min break  0940 workers begin taking down windows in Ru 30  - Ru 30, boys & girls (estroom look clean, No visible debris  - usel of hose, and baggins kichniques in room 30  1030 windows have been tomply kichniques in room 30  - workers break for furth		- Saul and Ciro suit up by PP	<i>E</i>	V
O715 workers begin removing undows from 86 15H from windly  - 1080 of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - hose of power saw and harmour the gressent  - work station as well as 2 says decan soom in work area  - workers begin vacuuming clearis and cleaning work area  - begin bagging wask and the delivering threm to the dunyoste-  - lead the zard type encloses work area  0810 workers begin encypse laking around window area  0815 work the row functs on the girls controlow to the left of Rm 36.  R law flow pump with lead easse the on autside Ru 36 windows  MOO windows from girls and boys astroom have been removed  - workers have begun encumning and clean gwrker area to frans fer  - book anto room 30  - workers have looks clean no visible debris  - windows in Rm 36e, girls & boys restroom have been encapsulated  around the edges  0930 workers take 10 min break  0940 workers begin taking down windows in Ru 30  - Ru 30, boys & girls (estroom look clean, No visible debris  - usel of hose, and baggins kichniques in room 30  1030 windows have been tomply kichniques in room 30  - workers break for furth		- full suit, /2 face P100,	helmet, visor, go	ones
- Use of power ship and harmer the present  - hose af soray handle in use frequently as well as HEPA vacuum  - wash station as well as 2 stay dean Dom in work area  - workers begin vacuuming clebris and cleaning work area  - workers begin vacuuming clebris and cleaning work area  - begin bagging wash and the delivering thum to the dungste-  - ledd the zard type encloses work area  08/0 - workers begin encapsulating around window area  08/5 - work the now the tead casse the on outside Rin 36 windows  R low flow pump with lead casse the on outside Rin 36 windows  MOO windows from girls and boys asknown have been removed  - workers have begun vacuuming and clean worker area to transfer  100/2 motor room 30  - york area looks clean no visible debris  - windows in Rin 36, girls though restroom have been encapsulated  around the edges  0930 - workers take 10 min break  0940 - workers begin taking down windows in Ron 30  - windows have been longek they Rundwed from Run 30  - windows break for hanch		- laid out pristic outside win	OUWS to room	36 15H FIRM WINDOW
- hose af sonay handle in use frequently as well as HEPA vacuum  - wash station as well as 2 stay decon soom in work area  - workers begin vacuuming debois and cleaning work area  - token begging wash and to delivering them to the dungste-  - lead the zand tope encloses work area  - supplies begin encounting around window area  - 108/5 work begin encounted to a cass the mountain to the left of Rm 36.  - 100 town pump with lead ease the sost own to the left of Rm 36.  - 100 town from girls and boys restoom have been removed  - workers have begin vacuuming and clean gwiker area to fransfer  - 100k and room 30  - 100k area looks clean no visible debois  - windows in Rm 36, girls thous restoom have been encapsulated  around the edges  - 9940 - workers take 10 min break  0940 - workers take 10 min break  0940 - workers take 10 min break  0940 - workers begin tating down windows in Ran 30  - RM 30, boys a girls restoom look clean. No visible debris  - ush of the edges  1030 - windows have been lempte they removed from Run 30  - windows have been lempte they removed from Run 30  - windows have been lempte they removed from Run 30  - windows have been lempte they removed from Run 30  - windows beent for hand	0715	- workers begin removing window	US from Rm 36	,
- Wash station as well as 2 stay decar Dom in Wik area  - windows in Rm 36 have been removed  - workers begin vacuuming debris and cleaning work area  - begin bagging week and to delivering thrum to the dunposter  - lead the zard type encloses work area  0810 - workers begin encapse lating around window area  0815 - work to pump with lead easys the on outside Ru 36 windows  Rlow flow pump with lead easys the on outside Ru 36 windows  PADO windows from girls and boys restoom have been removed  - workers have begun vacuuming and clean goorker area to frans Fer  100k anto room 30  - Work area looks clean, no visible debris  - windows in Rm 36, girls floors restoom have been encapsulated  around the edges  0930 - workers take 10 min break  0940 - workers begin taking down windows in Ru 30  - RM 36, boys a sills clestroom took clean. No visible debris  - undows have been completely remained from Ru 30  - windows have been completely remained from Ru 30  - windows have been completely remained from Ru 30  - windows have been completely remained from Ru 30  - windows have been completely remained from Ru 30  - windows have been completely remained from Ru 30  - windows have been completely remained from Ru 30		- Use of power saw and	hammer and pr	esent
- windows in Rm 36 have been removed  - workers begin vacuuming clebris and cleaning work area  - begin bagging wask and to the delivering thum to the dumpster  - lead the zard type recloses work area  08/0 - workers begin energy lating around window area  08/5 work to now facuses on the girls constroom to the left of Rm 36.  **R/ow-flow pump with lead easie the DM Outside Rm 36 winefows  09/00 windows from girls and boys restoom have been removed  - workers have begun vacuuming and clean worker area to transfer  100k and room 30  - work area looks clean, no visible debris  - windows in Rm 36, girls boys restoom lave been encapsulated.  Office workers take 10 min break  09/30 workers take 10 min break  09/40 - workers begin taking down windows in Run 30  - RM 30, boys & girls restoom look clean. No visible debris  - use of hore, and bagging kichniques in com 30  - windows have been completely stimpled from Run 30  - windows have been completely stimpled from Run 30  - windows have been completely stimpled from Run 30  - wikers break for much		- hose uf garay handle in us	e frequently as	well as HEPA vacuum
- workers begin vacuuming clebris and cleaning work area  - begin bagging wask and the delivering thrum to the dumposter  - lead the zard type encloses work area  08/0 - workers begin encapsen lating around window area  08/5 - work the now fleutes on the girls cost oom to the left of Rm 36.  **R low-flow pump with lead easie the on outside Rm 36 windows  0900 windows from girls and boys restroom have been removed  - workers have begun uncumming and clean worker area to transfer  took anto room 30  - york area looks clean no visible debris  windows in Rm 36, girls \$ boys restroom have been encaps neated.  around the edges  0930 - workers take 10 min break  0940 - workers begin taking down windows in Ron 30  - RM 30, boys & sirls (estroom look clean, No visible debris  - use of hose, and bagging kichniques in room 30  1030 - windows have been completely removed from Run 30  - writers vacuum up debris  1100 - workers break foor hanch	2060			in work area
- Leid Hazard tope encloses work are  - Leid Hazard tope encloses work are  08/0 - workers begin encapsen lating around window area  08/5 - work top now thenses on the girls restroom to the left of Rm 36.  R/ow flow pump with lead easis the on outside Rn 36 windows  0900 - windows from girls and boys restroom have been removed  - workers have begun incuming and clean worker area to transfer  100k anto room 30  - work area looks clean no visible debris  - windows in Rm 36, girls floors restroom have been encapsen lated  around the edges  0930 -workers take 10 min break  0940 - workers begin taking down windows in Ren 30  - RM 36, boys a girls restroom look clean. No visible debris  - use 0+ hose, and bagging kichniques in room 30  1030 - windows have been completely removed from Rm 30  - workers vacuum up debris  1100 - workers break foo lunch	0800	- windows in Rm 36 have 6	nen removed	
- Leid Hazard tope encloses work are  - Leid Hazard tope encloses work are  08/0 - workers begin encapsen lating around window area  08/5 - work top now thenses on the girls restroom to the left of Rm 36.  R/ow flow pump with lead easis the on outside Rn 36 windows  0900 - windows from girls and boys restroom have been removed  - workers have begun incuming and clean worker area to transfer  100k anto room 30  - work area looks clean no visible debris  - windows in Rm 36, girls floors restroom have been encapsen lated  around the edges  0930 -workers take 10 min break  0940 - workers begin taking down windows in Ren 30  - RM 36, boys a girls restroom look clean. No visible debris  - use 0+ hose, and bagging kichniques in room 30  1030 - windows have been completely removed from Rm 30  - workers vacuum up debris  1100 - workers break foo lunch		- workers begin vacuuming o	lebris and clean	ing work area
08/0 - workers begin encypsialating around window area  08/5 - work by now fexicus on the girls restroom to the left of Rm 36.  R low flow pump with lead eass & the on outside Rm 36 winelows  0900 windows from girls and boys restroom have been removed  - workers have begun incumming and clean worker area to transfer  took anto room 30  - work area looks clean no visible debris  windows in Rm 36e, girls & boys restroom have been encapsulated  around the edges  0930 -workers take 10 min break  0940 - workers begin taking down windows in Rm 30  - RM 36, boys & girls (estroom look clean. No visible debris  - usl 0+ hose, and bagging kichniques in room 30  1030 - windows have been completely reindived from Rm 30  - withers vacuum up debris  1100 - workers break for lanch		· befin bagging wask and -	deliveri	a thum to the dungste-
0815 work from now truges on the girls castoom to the left of Rm 36.  Rlow flow pump with lead eass the on outside Rm 36 winelows  0900 windows from girls and boys restroom have been removed  wrkers have begun vacuuming and clean gwrker area to frans ter  took and o room 30  - work area looks clean, no visible debris  windows in Rm 36, girls floys restroom have been encapsulated around the edges  0930 workers take 10 min break  0940 - workers begin taking down windows in Rm 30  -RM 36, boys & girls restroom look clean. No visible debris  use of hose, and bagging kichniques in room 30  1030 - windows have been completely removed from Rm 30  "invers yacuum up debris  1100 - workers break for lanch	00/-	- Lead Hazard type encloses	work aree	
1000 twindows from girls and boys restroom have been removed  - workers have begun uncumming and clean worker area to frant fer  took anto room 30  - workers looks clean no visible debris  - windows in Rm 36, girls & boys restroom have been encapsulated  around the edges  0930 workers take 10 min break  0940 - workers begin taking down windows in Run 30  - RM 36, boys & girls restroom look clean. No visible debris  - use O+ hose, and bagging kichniques in room 30  1030 windows have been completely removed from Run 30  - workers vacuum up debris		- workers begin encapsulating	around window	v area
1000 windows from girls and boys restoom have been removed  - workers have begun incuming and clean worker area to transfer  tooks and ordern 30  - work area looks clean no visible debris  - windows in Rm 36, girls & boys restoom have been encapsulated.  around the edges  0930 -workers take 10 min break  0940 -workers begin taking down windows in Rm 30  - RM 30, boys & girls restroom look clean. No visible debris  - use of hose, and bagging kichniques in room 30  1030 -windows have been completely removed from Rm 30  - inters yacuum up debris  1100 - workers break for lunch	08/5	work town towness on	the girls cestroon	to the left of Rm 30.
took anto room 30  - Work area looks clean no visible debris  - windows in Rm 36, girls & boys cestroom have been encapentated.  around the edges  0930 - workers take 10 min break  0940 - workers begin taking down windows in Ron 30  - RM 36, boys & girls restroom look clean. No visible debris  - use O+ hose, and bagging kichniques in room 30  1030 - windows have been completely reinduced from Run 30  - inters vacuum up debris  1100 - workers break foor lanch	1900	100 From pupp with read to	SSEIFE ON OUT.	Side RM 36 WINENUWS
- workers begin taking down windows in Ren 30  - RM 36, girls & boys restroom have been encapsulated.  Oggo - workers take 10 min break.  Oggo - workers begin taking down windows in Ren 30  - RM 36, boys & girls restroom book clean. No visible debris.  - use 0+ hose, and bagging kichniques in room 30  1030 - windows have been completely removed from Run 30  - writers vacuum up debris.	0,00	worker have have	15 restroom racce	seen removed
- Work area looks chean no visible debris  - windows in Rm 36, girls floys restroom have been encapsulated  around the edges  0930 -workers take 10 min break  0940 -workers begin taking down windows in Ren 30  - RM 30, boys & girls restroom look chean. No visible debris  - use 0+ hose, and bagging kichniques in room 30  1030 -windows have been completely reinduced from Rm 30  - workers vacuum up debris  1100 - workers break for lanch		took and come 30	ming and clean	worker aren to framster
- windows in Rm 36, girls & boys restroom have been encapentated  around the edges  0930 -workers take 10 min break  0940 - workers begin taking down windows in Ron 30  - RM 30, boys & girls restroom look clean. No visible debris  - use Ot hose, and bagging kichniques in room 30  1030 - windows have been completely reindred from Rm 30  - writers vacuum up debris  1100 - workers break for lunch			wishle datas	<del></del> -
1030 -workers take 10 min break  0940 -workers begin taking down windows in Ren 30  -RM 30, boys & gills Cestroom look clean. No visible debris  - use 0+ hose, and bagging kechniques in room 30  1030 -windows have been completely reinduced from Rm 30  - workers vacuum up debris  1100 - workers break for lunch		- windows in Run 31 citle Bhow	c costania lava	from encore lated
1030 -workers take 10 min break  0940 -workers begin taking down windows in Ren 30  -RM 30, boys & gills Cestroom look clean. No visible debris  - use 0+ hose, and bagging kechniques in room 30  1030 -windows have been completely reinduced from Rm 30  - workers vacuum up debris  1100 - workers break for lunch		assund the edges	2 1 CON DOM TUCK	sur incupsarian
0940 - workers begin taking down windows in Ran 30 -RM 36, boys & gills Clastropin look clean. No visible debris - use O+ hore, and bagging kechniques in room 30 - windows have been completely reinduced from Run 30 - workers vacuum up debris 1100 - workers brenk for lunch	0930	workers take 10 min break		
1030 - windows have been completely reinived from Run 30  - withers yacuum up debris  1100 - workers brenk for Junch		-workers bean taking down	windows in R	cu 30
1030 - windows have been completely reinived from Run 30  - withers yacuum up debris  1100 - workers brenk for Junch		- RM 30, boys & sills (estrone	n look chean No	Visible debris
1000 - workers brenk for Junch		- use 0+ hose, and bagging	Echniques in co	om 3D
1100 - workers break for Junch	1030	- windows have been comple	tely removed	from Run 30
1100 - workers break for Junch		- workers vacuum up debris		
- will finish the day with bourding up the windows in Run 36, boys & gills restroom and Run 30.	1100	- workers break for bunch		
36, boys & gills cestroom and Rm 30.		- will finish the day wit	h bourding up ,	En windows in Run
		36, boys & gills clestroom	and Rm 31	2.

Alta Representative:	Uprae Robles	Date:	6/30/17
Signature:	1000		
Cal/OSHA Cert. No.:			

Date:	6/30/17	Alta representative:	Vorge RObbes
Project No.:		Project name:	0
Project location:		Project area:	
Time of observation	Observations		
1/35	in RM 36, RM 30 a Resource Finish boarding	k and begin boxes	ling up the windows
4 -	in RM 36, RM 30	and girly boys res	room
1300_	girls RR	i go me windows 1	For Rin 36, 30, 60% A
1320	- Resource finish for the d	lac	
7.,72.0	- area looks clean. No	issues to report	**
	7, 00	33.67.49.5	
			,
		<u> </u>	
		<u></u>	
			· <del>-</del>
	,,,		
			U U
<u> </u>			
<del></del>		#:	

Alta Representative:

Signature:

Cal/OSHA Cert. No.:

Date: 6/30/1



## Log Sheet

Project Name:	RUM E.S		Date: 7-13	-2017	
Project Location: 2368 Pearl S.J. Sunda Human Job No.: 5K15D-17-6801					
Project Location: 2368 Pearl S.J. Soute Minim Job No.: 5M15D-17-680)  CA 90405  Project/Area Description: Allinin Blug Room 24 (0 1/102)  (Scloud floor)					
Scope of Work:	ndow sash 12.	coral.	ZBP. (Zlary	( woudows)	
		r.			
Type of Containment	borra Lape, L	rop flo	y Lecas unit.		
Respiratory Protectio	n: 1/2 face API	21.5			
Abatement Contracto	,				
Contractor Superviso	r. Myrel Barn	s.			
Alta Rep. On-Site:	VICTOR Sunce	loz.			
Project Manager: Cesar Ruvalcaba.					
Time Arrived (Military	):063 <i>v</i>	Sh	nift Start Time:	530	
	1500				
Type of Sample	Number of Samples	Taken	Highest (f/cc)	Lowest (f/cc)	
Inside Work Area					
Outside Work Area	2 PS				
Personal					
Clearance			1,118,118,118		
Background					
Manor	neter Reading (Time re	ading was	taken/Actual Readin	g	
1	1		<del>/</del>	1	
Other Contra	ctors On-Site		Contractor Activ	ities	
Wuldow 12	stullers				
60mil	Cantroln				
0.000 1 00 0000					



Client: 5 M USD	Page/_ of
Project Name: Grant Elemetery	Alta Job No.: 543D-17-6801

TIME OF OBSERVATION	COMMENTS
0615	Alta quel Resume aconste
0630	G.C. shows up to give aires for work ener
	Today's scope of weak is to pressory received of
	2139. usulaw sashs in Admin. bldy soom 14 Coffee
	world start work over setup. ou sccoul Hou
6740	finishes would over set you Alter portuge
	a result in pecting ouch obey, won 4 to
	stort
6800	Encuoval of glass is occirng, by breaking glass
	to wices por day soon matel holder cellylas
	1) Lut toped prier to braking, wonders one
	wearing adequate PT. windows putry'is bagged
69N1	into buil poly bugs.
	are bugging generated weste ruto Busty by
	huss
6920	Perioral of wouldow sades is now ocurring, by cutsing
	netul cortain arm to distodige carriers from.
1000	nudal track.
	(000)
1100	
1220	prists willow necessary shorts ne formy weeky
7200	
	and pely floor.
1300	funds Infail clemp A/k prefers a visual
	uspetan out collects cleaned with super
134	Alta kan jobsik to Lohon sugas lo
	1aD.
1)16	End of Stuft

For Bag-Out Shift Only

# of Bags	Manifest #

Alta Rep. Signature:
Cert. Number: 10148
Date: 7/13/2012



Client:

## Air Sampling Form

		Ad.	Admin bldg Pm 14 (office)				Date: 12/13/2017 Page: 1 of 1					
Sample #	Pump #		Sample Location	Туре	Activity in Progress	Start Time	Stop Time	LPM Start	LPM Stop	Volume	Fibers/ Fields	F/CC*
7/3-01		Pr4 14	Coffice Lecon	ows	2BD window	0753	1329	2-0	2.0	336/672		
713-02		exten	office decon	ous		0757	1332	2~	20	535/670		_
										,		
		<u> </u>										
								<del></del>				
Type: OWA	= Outside	Work Area; I	WA = Inside Work Area; B =	Background	; P = Personal; C = Cle	arance	<u> </u>			D	etection limit	is 5.5 f/cc
Analytica			Sample Analysis:		oscopist:			Comment	s:			
PCM-Nios TEM-AHE			Alta On-site		oscope #:						· · · · · · · · · · · · · · · · · · ·	
TEM-EPA			Outside Lab		icle field area (mm²	):						
NIOSH-70		<del></del>	E. H. D.		Filter area (mm²):							
1410311-70	102/FU		Field Blank		slide readable:							
Sample # Fiber/Fields		Rotometer #: 2FV5-01.						/				
Sample Media: Fiber/Fields 25 mm MCE 0.8 µg								1/	_			
25 mm MCE 0.6 μg Lab Blank						On-Site Te		: V2000	Sou	cher		
37 mm MC		2	Sample #				5	Signature		////		
27 71111 1010			Fiber/Fields				_		2/		·	
			I IDGI/I IGIUS					Cert Num	oer: と	DBH 1	84101	
\\server-lb-	-1\ctldata\a	alta docum	ents\field forms\whs\air sa	ampling for	m2011 doc							



## Log Sheet

Project Name: Grant Elementary Scholate: 7/24/17								
Project Location: Office Job No.:								
Project/Area Description: Blds J								
Scope of Work: Window Removel								
Type of Containment: Demarcated Work Arca								
Respiratory Protection: Half Mask respirator								
Abatement Contractor: Revolute Environmental								
Contractor Supervisor: Michal Ibarra								
Alta Rep. On-Site: Gustavo Scheher								
_								
Project Manager: Cesar Pulvacaba								
Time Arrived (Military): 0700 Shift Start Time: 7am								
Time Left (Military): 1530 Shift End Time: 30pm								
Type of Sample Number of Samples Taken Highest (f/cc) Lowest (f/cc)								
Inside Work Area								
Outside Work Area								
Personal								
Clearance								
Background								
Manometer Reading (Time reading was taken/Actual Reading								
Other Contractors On-Site Contractor Activities								

## ALTA ENVIRONMENTAL LOG SHEET

Project Name: Date: Date:										
Project Location: Admin blog Job No.:										
Project/Area Description: N/E Admin										
Scope of Work: WILDOU Renoval										
Type of Containment:	Type of Containment: Demorcated Arra									
Respiratory Protection:	Helf Mosle									
	Resource									
Contractor Supervisor:	Migrel Ba	rria								
	Alta Rep. On-Site: Cosho San has									
Project Manager:	Project Manager: Epi800 Rulva (cba									
Time Arrived (Military	Time Arrived (Military): 0700 Shift Start Time: 765									
	1530									
Type of Sample	Number of Samples	Taken	Highest (f/cc)	Lowest (f/cc)						
Inside Work Area										
Outside Work Area	2									
Personal										
Clearance										
Background										
Man	ometer Reading (Time r	eading wa	s taken/Actual Res	ading)						
1	1	/ /								
Other Contra		Contractor A	Activities							

Client: SMMUSD

Page \_\_\_\_ of \_\_\_

Project Name: Grant Elementery School

Alta Job No.:\_\_\_\_\_

TIME OF OBSERVATION	COMMENTS
0700	Alta Rep arrives on-site to meet with Resource rep
	Miguel I barra plus two certified abetement worker
	at building D room is. Todays scope of work will
	consist of removing windows At bldg J.
0710	Crew begins demorcating the work area
	Area is now sctup. Containment sctup consist of a
	drop cloth, critical barrier at the interior of room,
	mouning tape and two stage de con.
0 130	Crew now begins donning PPE to enter the work are
-11	PIE CONSIST OF a PULL GODY TYVER, NOT MAIL PESTIVATOR, GLOVES
	Jakety slesses and hard hats.
	Crew now begins removing window. Resource crew is
	equipped with pry bars, hammers, electral saws with
	heps attachments and hudson sprayers.
	Crew continues to perform undow removal. Once removed
1100	all window are burito wrapped and set aside.
•	The state of the s
1 200	Krew returns from lunch to continue with the scope of
	work. All PPE has been re-applied prior to re-ente
1300	Crew continues to remove windows.
12 20	Resource has now remard eight windows.
1550	Cru begins hepe veccuming and wet wipin
	the area and boarding up the open
	windows
1530	Shift ends. Area is now cleaned up and
	window are now boarded up.

For Bag-Out Shift Only

# of Bags	Manifest #



Client: SMMUS	O Pr	age of
Project Name: 6	*** T.T.	No.:
TIME OF OBSERVATION	COMMENTS	
0700	Alta Rep arrives on-site to meet with Rep Miguel Barrera plus two cert	ried workers
	Landows from the admin building	15.
0710	Crew begins demarcating the wo begin with the scope of work. Sctup consist of drop cloth, critic	u gree 10
	take demarkating the area and	) a two
0740	stage decon attached.  The area is now setup. Craw to  PPE. PPE consist of full body type  mask respirator, gloves safety glo	ew, vict
0745	Cress bears removed the in	ndows, Resource
09 00	is equipped with pry burs, elect with Nepa attachment, and Crew continues to remove w	indow Once
/100	Crew now breek for lunch	1
//00	Crew returns from I which to con the scope of work. All PPT is re-applied prior to re-entrin Resource his now removed	populy the crea.
1400	( vew begins often cleaning	The
15 60 <b>3</b> 530	The aven is properly clear Shiff ends	ued.
For Bag-O	ut Shift Only	7 0

For Bag-Out Shift Only


# of Bags Manifest # Alta Rep. Signature:

Cert. Number: // - 4757

Date: 7/7 s // 7

# Appendix B

Laboratory Reports-Lead Air and Wipe Sample Analysis





Alta Environmental 3777 Long Beach Boulevard Long Beach, CA 90807 Attention: Cesar Ruvalcaba **Project Number:** 

Project Name: Grant Elem. School

Location: 2365 Pearl St.

Santa Monica, CA

Building H

Report Number: 1728065

Date Received: 6/13/2017
Date Analyzed: 6/14/2017
Date Reported: 6/15/2017

Date Sampled: 6/13/2017 Sampled By: Victor Sanchez

Total Samples: 4


Analytical Method: NIOSH 7082 Reporting Limit: 4.0 µg

Lead (Pb) in Air by Flame AAS						
Lab ID Client ID	Location/Description	Sample Volume (L)	Lead Concentration (ug/m³)			
1728065-001 612-01	OWA - Bldg H North Side	610	< 6.6			
1728065-002 612-02	OWA - Bldg H Rm 55 (Dining Rm)	608	< 6.6			
1728065-003 613-01	OWA - Bldg H East Side Kitchen	642	< 6.2			
1728065-004 613-02	OWA - Bldg H Rm 57	640	< 6.3			

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert#2823

Approved Signatory- Cristina E. Tabatt





Alta Environmental 3777 Long Beach Boulevard Long Beach, CA 90807

Attention: Cesar Ruvalcaba

**Project Number:** 

Project Name: Grant Elementary School

Location: 2368 Pearl St.

Santa Monica, CA 90405

Report Number: 1728092

Date Received: 6/15/2017
Date Analyzed: 6/19/2017
Date Received: 6/19/2017

Date Reported: 6/19/2017

Date Sampled: 6/14/2017-6/15/2017 Sampled By: Victor Sanchez

Total Samples: 5

Analytical Method: NIOSH 7082 Reporting Limit: 4.0 µg

Lead (Pb) in Air by Flame AAS							
Lab ID Client ID	Location/Description	Sample Volume (L)	Lead Concentration (ug/m³)				
1728092-001 614-01	OWA Bldg F S/W Side (Office 51) Exterior	552	< 7.3				
1728092-002 614-02	OWA Bldg F/G (Center Hall) Interior	556	< 7.2				
1728092-003 614-03	OWA Bldg G North Ctr. (Exterior)	558	< 7.2				
1728092-004 615-01	OWA Bldg G Exterior South-North	600	< 6.8				
1728092-005 615-02	OWA Bldg G Rm 46 (Interior)	594	< 6.8				

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert#2823




## **CHAIN OF CUSTODY**

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

(Lab) Order No. 1728092

CUSTOMER INFORMATION			Turnaround Time Shippe			ped By Report Send Via			1:
Company	Alta Environmental	Same Day		Fedex		Web			
Address	3777 Long Beach Blvd.		1 Day		UPS		Email	4	
	Long Beach CA 90807		2 Day	W Ain	USPS	` <u></u>	Fax		
Contact	Cesar Ruvalcaba	3 Day		Drop Off	12	Verbal			
Office Phone	562 495-5777	5 Day		Drop Box		Mail			
Cell	310 951-9485	Weekend		Other		Pick up			
Fax	562 495-5877	Special Instructions:							
Email	cesarruvalcaba@altaenviro								
		PROJECT	INFORMAT	TION				14	
Project Name:	Grant Elcunfing	School	PO Number	·:	T,				
Project Number:			Work Order	No.:					
Location:	2368 Peur St. Sout	9 Monica	Sampled By	<i>/</i> :		Victor sa	nchez		
	CA 90 405								
PL		CM		MOLD		LEAD (Pb)			
PLM EPA 600/R-9				oore Trap		Air		TTLC	
PLM 400 Pt. Cour PLM 1000 Pt. Cou		400B	Tape Lift			Paint		STLC TCLP	
PLIVI 1000 Pt. CO.	unt (<0.1%) LJ W/ TVVA		DI	ılk Sample		Wipe Soil		TOLP	
SAMPLE ID	SAMPLE TYPE		LOCATI	ON		Date	Start Time	Avg	Volume
						Sampled	Stop Time	Flow Rate	(L)
614-01	ous.	BldgF	5/w 3	ide (of	hiesi)	6/11/17	08/1	2.0	275
614-07	ouA	bldg F/	6. (cen	ler hal	)		1252	2.0	566
6/4-03	6WA	Bldg G	. 10027	the conte	mm)	·	0816	20	558
615-01	ous	Bldg	. 10027 CTV e)	oferion	のメナル	6/15/17	07-56 1276	2.0	600
615-02	ous	bldg G	. Ru	46(14)	Lenny)		6801	20	5901
	-								
							MA AND DIS DAY NOW THE AND DIS DOC TO		
							and and him gas one and one and the pro on		
			0				an on an an an an an an an an an		
								2	
Relinquished By:	ne hy		Received B	y:	mek	mon			
Date/Time:	6/15/2013		Date/Time:		6/13/1	17	14:2	5	

Lab Forms Ver. 082411





Alta Environmental 3777 Long Beach Boulevard Long Beach, CA 90807 Attention: Eric Fleming Project Number: SMSD-17-6801
Project Name: Grant Elem. School
Location: 2368 Pearl St.

Santa Monica, CA

90405

Report Number: 1728380

Date Received: 7/14/2017

Date Analyzed: 7/14/2017

Date Reported: 7/14/2017

Date Sampled: 7/13/2017 Sampled By: Victor Sanchez


Total Samples: 2

Analytical Method: NIOSH 7082 Reporting Limit: 4.0 µg

	Lead (Pb) in Air by Flame AAS										
Lab ID	Location/Description	Sample Volume	Lead Concentration								
Client ID	Location/Description	(L)	(ug/m³)								
1728380-001	OWA A L : BU B 44 B	070									
713-01	OWA - Admin Bldg. Rm 14 Decon	672	< 6.0								
1728380-002	OWA - Admin Bldg. Exterior No.	070	.00								
713-02	Side	670	< 6.0								

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert#2823





Alta Environmental 3777 Long Beach Boulevard Long Beach, CA 90807 Attention: Eric Fleming Project Number: SMSD-17-6801
Project Name: Grant Elem. School
Location: 2368 Pearl St.

Santa Monica, CA

90405

Report Number: 1728381

Date Received: 7/14/2017

Date Analyzed: 7/14/2017

Date Reported: 7/14/2017

Date Sampled: 7/13/2017 Sampled By: Victor Sanchez

Total Samples: 2

Analytical Method: EPA 7420/3050

Reporting Limit: 10 μg

	AAS		
Lab ID	Location/Description	Area	Lead Concentration
Client ID	Location/Description	(ft <sup>2</sup> )	(ug/ft²)
1728381-001	El 01 B 44		. 10
713-03	Floor Clearance - Room 14	1	< 10
1728381-002	51 OI 51 N OI	,	
713-04	Floor Clearance - Exterior No. Side	1	11

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823



ENVIRONMENTAL LABORATORIES


# **CHAIN OF CUSTODY**

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

(Lab) Order No. 417 1728380 | Wipe 1728381

	CUSTOMER INFORMATION			Turnaround	Time	Shippe	ed By	Repor	t Send Via	:
Company	Alta Environmenta			Same Day		Fedex		Web		
Address	3777 Long Beach	Annex Bu	ilding	1 Day		UPS		Email		
	Long Beach CA 90	807		2 Day		USPS		Fax		
Contact	Eric Fleming			3 Day		Drop Off		Verbal		
Office Phone	562 495-5777			5 Day		Drop Box		Mail		
Cell	310 95- 9486			Weekend		Other		Pick up		
Fax	562 495-5877		Special In	structions	:					
Email	ericfleming@altaer	nviro.com								
			PROJECT	NFORMAT	ION					
Project Name:	GRUNT Elec			PO Number						
Project Number:	SMSD-17.			Work Order						
Location:	2368 Pearl 5		ta Klouna	Sampled By	:		Victor sa	nchez		
	CH 90403									
PL PLM EPA 600/R-9			CM		MOLD	_		LEAD		
PLM 400 Pt. Cour		NIOSH 74 NIOSH 74		'	ore Trap pe Lift		Air Paint		TTLC	
PLM 1000 Pt. Cou		w/ TWA			ik Sample		Wipe		TCLP	
					iii Gairipio	_	Soil		. 02.	
SAMPLE ID	SAMPLE TYPE	PE		LOCATI	ON		Date	Start Time	Avg	Volume
							Sampled	Stop Time	Flow Rate	(L)
71301	OUA		Hamin	Ruy.	14 Dec	01	7/13/17	1329	2.0	672
7-13-02	ous		1	exple	nu Dec	o.side.	1	0757	2.0	670
713-03	floor		720024	14.			7/13/17	_2'X/	1	
713-04	1		crter.	14.	side		1	1/X/		
	,									
	=									
"				1:						
		- 3	- /							27
Relinquished By:		- Lu	/	Received By	<i>y</i> : (\)	me	pont	V		
	113/2017			Date/Time:		7/14/		8:00		

Lab Forms Ver. 082411





Attention: Cesar Ruvalcaba

**Project Number:** 

Project Name: Grant Elem. Location: Building H

Report Number: 1728048

Date Received: 6/12/2017

Date Analyzed: 6/12/2017

Date Reported: 6/12/2017

Date Reported: 6/12/2017

Date Sampled: 6/12/2017

Sampled By: Victor Sanchez

Total Samples: 2

Analytical Method: EPA 7420/3050

Reporting Limit: 10 μg

	Lead (Pb) in Du	AAS	
Lab ID	Location/Description	Area	Lead Concentration
Client ID	Location/Description	(ft <sup>2</sup> )	(ug/ft²)
1728048-001	Clearance Pb - Building H North	,	. 10
HW-01	Floor 1'x1'	1	< 10
1728048-002	Clearance Pb - Building H West	4	. 10
HW-02	Floor 1'x1'	1	< 10

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823




# **CHAIN OF CUSTODY**

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

(Lab) Order No. 1728048

	CUSTOMER INFO	RMATIO	N	Turnaround	Time	Shippe	d By	Report	t Send Via	:
Company	AHa En	Vi	Z.	 Same Day		Fedex		Web		
Address	3777 Long F.	Becel 1	Bld.	1 Day	□.	UPS		Email		
City/State/Zip	Lucy Beach	CA, 9	10807	2 Day		USPS		Fax		
Contact	Cesan Ru			3 Day		Drop Off		Verbal		
Office Phone	(562)495			5 Day		Drop Box		Mail		
Cell	(310) 951-9			Weekend		Other		Pick up		
Fax	(GOZ) 4955			Special In	structions					
Email	cesannoule	ubio Al	Haennen.							
			PROJECT	INFORMA	ΓΙΟΝ					
Project Name:	GRUNT	The second second		PO Numbe						
Project Number:				Work Orde	r No.:					
Location:	Burlding	21		Sampled B	y:		Vic	Ton Su	neber	
PLI	M	P	CM		MOLD			LEAD	(Ph)	
PLM EPA 600/M4-		NIOSH 74		s	pore Trap		Air		TTLC	
PLM 400 Pt. Coun	it (<0.25%)	NIOSH 74	400B 🗆	T:	ape Lift		Paint			
PLM 1000 Pt. Cou	int (<0.1%)	w/ TWA			ulk Sample		Wipe			
CAMPI E ID	0.115/5 77/				wab		Soil			
SAMPLE ID	SAMPLE TY	PE		LOCAT	ION		Date	Start Time	Avg	Volume
1/1.2 01	,	~ /	<b>A</b> ,				Sampled	Stop Time		
HW-01	cleanance	75	Horld	my H	worth	7	6/12/17			X
HN-02	cleanure		Bridge	ing H	West.		3	<u> </u>	_	
			6	1						
			-27.7							
			98							
					•					
8			.8							
Relinquished By:	25/	hil		Received E	By:	mue	onn	v	14 (£)	1941
Date/Time: 6	112/2017	15	DU T	Date/Time:	0	6/12/1		5-00		
Relinquished By:				Received E	By:			33	r	iti
Date/Time:				Date/Time:						





Attention: Cesar Ruvalcaba

**Project Number:** 

Project Name: Grant Elem. School

Location: 2365 Pearl St.

Santa Monica, CA

Building H

**Report Number:** 1728064

Date Received: 6/13/2017 Date Analyzed: 6/13/2017 Date Reported: 6/13/2017 Date Sampled: 6/13/2017

Sampled By: Victor Sanchez

Total Samples: 2

**Analytical Method:** EPA 7420/3050

**Reporting Limit:** 10 µg

	Lead (Pb) in Dus	st Wipe by Flame	AAS
Lab ID	Location/Description	Area	Lead Concentration
Client ID	Location/Description	(ft <sup>2</sup> )	(ug/ft²)
1728064-001	Clearance Floor Bldg H Exterior	4	. 10
BHNE-03	Kitchen	1	< 10
1728064-002	Clearance Floor Bldg H Exterior Rm	4	. 10
BHSE-04	57	1	< 10

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823

# **CHAIN OF CUSTODY**




1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

(Lab) Order No. Wipe 1728064 Air 1728065

	CUSTOMER INFO	Turnaround Time Shipped By			Report Send Via:					
Company	Alta Environmenta			Same Day	wipe	Fedex		Web		
Address	3777 Long Beach	Blvd.		1 Day		UPS		Email		
	Long Beach CA 90	807		2 Day	DAir	USPS		Fax		
Contact	Cesar Ruvalcaba			3 Day		Drop Off		Verbal		
Office Phone	562 495-5777			5 Day		Drop Box		Mail		
Cell	310 951-9485			Weekend		Other		Pick up		
Fax	562 495-5877			Special In:						
Email	cesarruvalcaba@a	Itaenviror	n.com	wipa	e sample	o Rus	h. plu	45C.		
			PROJECT	INFORMAT	ION					
Project Name:	GRUNT Eles	n. See	1001	PO Number	:					
Project Number:				Work Order		2.0				
Location:	236I Pearlo	- Secuta	Horicala	Sampled By	r.		Victor sa	nchez		
	Buildne	H								
PLN		1	CM		MOLD			LEAD		
PLM EPA 600/R-9		NIOSH 7			ore Trap		Air		TTLC	
PLM 400 Pt. Count	•	NIOSH 74 w/ TWA	400B		pe Lift		Paint Wipe		STLC	
PLM 1000 Pt. Coul	nt (<0.1%)	WIIVA		Du	ik Sample		Soil		ICLF	
SAMPLE ID	SAMPLE TYP	PE PE		LOCATI	ON		Date	Start Time	Avg	Volume
							Sampled	Stop Time	Flow Rate	(L)
612-01	ous		BlogH	side			6/12/10	1320	5-0	616
61202	ous		2116H		(m			0819	2.0	608
613-01	ous		Bidy H	EAST PER	side Leben		6/13/2	0806	20	6112
613-02	ous		BugH	pm 5	7.			0809	2.0	640
BHNE-0	elearance 3 floor		Bldy H	exte	rior je, tel	ws	4/13/12			I'XI,
BHSE-W	eleurance floor			erten				/_		1'XI'
2										
	÷									
			7/						21	5
Relinquished By:	2//	hy		Received B	y:	mu	pmon			
	13/2017			Date/Time:		,/13/17		:10		

Lab Forms Ver. 082411





Attention: Cesar Ruvalcaba

**Project Number:** 

Project Name: Grant Elem. School

Location: 2365 Pearl St.

Santa Monica, CA

Report Number: 1728079

Date Received: 6/14/2017

Date Analyzed: 6/15/2017

Date Reported: 6/15/2017

Date Sampled: 6/14/2017 Sampled By: Victor Sanchez

Total Samples: 3

Analytical Method: EPA 7420/3050

Reporting Limit: 10 μg

Lead (Pb) in Dust Wipe by Flame AAS						
Lab ID Client ID	Location/Description	Area (ft²)	Lead Concentration (ug/ft²)			
1728079-001 FW-01	Clearance - Bldg F West Side	1	< 10			
1728079-002 FG-02	Clearance - Bldg F-G North	1	< 10			
1728079-003 FG-03	Clearance - Bldg F-G South	1	< 10			

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823






1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

128079

	CUSTOMER INFO	PMATIO	NI -	Turnaround	Timen	Chinne	el Du	Popos	t Sand Via	
	Alta Environmental	-SHORE				Shippe	а ву		t Send Via	
				Same Day		Fedex		Web		
***	3777 Long Beach			1 Day		UPS				
	Long Beach CA 90	807		2 Day		USPS		Fax		
, 270 Cart 1/10 1/10 1/10 1/10 1/10 1/10 1/10 1/1	Cesar Ruvalcaba			3 Day		Drop Off		Verbal		
Explores and	562 495-5777			5 Day		Drop Box		Mail		
	310 951-9485			Weekend		Other		Pick up		
-	562 495-5877			Special In	structions					
Email <u>c</u>	cesarruvalcaba@a	Itaenviror	n.com				•			
			PROJECT	NFORMAT	rion					
Project Name:	GRONT Elen	- Sch	00 1	PO Number	:	Q.				
Project Number:				Work Order						
Location:	2365 Pearl St.	Santo	Monnesch	Sampled By	<b>/</b> :		Victor sa	inchez		
PLM		Di	CM		MOLD		r	LEAD	(Ph)	
PLM EPA 600/R-93		NIOSH 74		Sr	ore Trap		Air		TTLC	
PLM 400 Pt. Count		NIOSH 74			ape Lift		Paint		STLC	
PLM 1000 Pt. Coun	it (<0.1%)	w/ TWA		Ві	ılk Sample		Wipe Soil		TCLP	
SAMPLE ID	SAMPLE TYP	E		LOCATI	ION		Date	Start Time	Avg	Volume
FW-01	e learance.		BldgF	West 5	ide		Sampled 4/14/17	Stop Time	on Rate	(L)
FG-02 FG-03	e karawa		Bldg F Bldgs	F-G NO	sed 4.		1			
E6-03	charme		BldnF	-G SOV	14.		1.			
16-05	current		7				1		-in-iii-n-	
			9		41					
				7						,
								and the local data has been been seen to the		
								and that the last look and look look look look		
	4			0						
		//	/						21	
Relinquished By:	1/1	1	L	Received B	v:	mme	DN	no-		
Date/Time: 6/	/14/2012.			Date/Time:		6/14	_	1:58		

Lab Forms Ver. 082411





Attention: Cesar Ruvalcaba

Project Number: SMSD-17-Project Name: Grant Windows

Location:

Report Number: 1728188

Date Received: 6/22/2017 Date Sampled: 6/22/2017

Date Analyzed: 6/22/2017 Sampled By:
Date Reported: 6/22/2017 Total Samples: 5

Analytical Method: EPA 7420/3050

Reporting Limit: 10 μg

	Lead (Pb) in Dust Wipe by Flame AAS							
Lab ID Client ID	Location/Description	Location/Description  Area  (ft²)						
1728188-001 62217-1	Wipe - Cafeteria - North East	1	< 10					
1728188-002 62217-2	Wipe - Cafeteria - North West	1	< 10					
1728188-003 62217-3	Wipe - Rm 26 West Exterior	1	< 10					
1728188-004 62217-4	Wipe - Rm 26 North Exterior	1	< 10					
1728188-005 62217-5	Wipe - Blank		< 10 µg					

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823




# CHAIN OF CUSTODY

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

-	(Lab) Order No.	1728188	
1	(Lab) Order No.	, , , , , , ,	

			Turnaround Time Shippe		d By Report		Send Via:			
Company	ALTA			Same Day	-	Fedex		Web		
Address	3777 LB B	SLUD		1 Day	□ -	UPS		Email 🤊		1
City/State/Zip	63 CA 90607		2 Day		USPS		Fax		1	
Contact	C254E RI	OVAZO	454	3 Day		Drop Off	B	Verbal		
Office Phone	5/495-57	77		5 Day		Drop Box		Mail		
Cell	310 951 94	185		Weekend		Other		Pick up		
Fax				Special Instructions:						
Email	CESHE EUVIN	CADA 6	2							
	AUAZHV113	ON.COI	M							
			PROJECT	INFORMA	TION					
Project Name:	SMSD 17		- WIHDOWS	PO Numbe	er:					
Project Number:	SMSD-17-	. 1/2	,	Work Orde	r No.:					
Location:				Sampled B	y:					
PLI	VI	P	CM	1	MOLD	-		LEAD	(Pb)	
PLM EPA 600/M4-	-82-020 <u></u>	NIOSH 74		S	pore Trap		Air		TTLC	
PLM 400 Pt. Coun	' '	NIOSH 74	100B 🗆	Т	ape Lift		Paint			
PLM 1000 Pt. Cou	nt (<0.1%)	w/ TWA		H	ulk Sample		Wipe			
SAMPLE ID	CANADI E TVI				Swab		Soil			
SAIVIPLE ID	SAMPLE TYP	7E		LOCAT	TION		Date	Start Time	Avg	Volume
						×1====================================	Sampled	Stop Time	Flow Rate	(L)
1-41254	W(1-2	1	CAFSTER	ZIA - N	KE HISK	451	60217		\	1594
62217-2	WIPS		CATERIA- MORTH WEDT			TOST	62217		\	1
62217-3	WIPS				Exte				\	- 1
	00112		P. ( 0 0	00051	01/5	ICHE	62217			
Ce2217-4	WITZ		ZMZ	6 NOE	THE STR	ECLOR	62217			
622.17.5	WIPZ		BIAN	K			62217		1	MA
					ë v					
	**- ;				-Antonia					
		-4								
										an y
Relinquished By:	Received By: Received By: Received By:									
Date/Time: 6/22/17 @:15/1				Date/Time: 6/22/17  5:12						
Relinquished By:				Received By:						
Date/Time:				Date/Time:						
		Transcript State of			-	-			A-100	





Attention: Cesar Ruvalcaba

**Project Number:** 

Date Sampled:

Project Name: Windows Project

Location: Grant E.S.

Report Number: 1728212

Date Received: 6/23/2017

Date Analyzed: 6/24/2017 Sampled By: Cesar Ruvalcaba

Date Reported: 6/26/2017 Total Samples: 3

Analytical Method: EPA 7420/3050

Reporting Limit: 10 μg

	Lead (Pb) in Dus	AAS	
Lab ID Client ID	Location/Description	Area (ft²)	Lead Concentration (ug/ft²)
1728212-001 623W1	Kitchen Area - East Ctr - Floor - (12"x12")	1	< 10
1728212-002 623W2	Bldg. B Exterior - Rm. 26 - SE- (12"x12")	1	< 10
1728212-003 623W3	Bldg. A Exterior - Rm. 25 - North Ctr - (12"x12")	1	< 10

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823



# CHAIN OF CUSTODY

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

	2:	(Lab) Order No.	1728	212					
	CUSTOMER INFO	RMATION	Turnaround	Time	Shippe	d By	Report	Send Via:	
Company	Alta en	)·	Same Day	A.	Fedex		Web		
Address			1 Day		UPS		- Email		
City/State/Zip	0		2 Day		USPS		Fax		
Contact	Jasen Kung	cabe	3 Day		Drop Off		Verḫal		
Office Phone			5 Day		Drop Box		Mail	₩.	
Cell			Weekend		Other		Pick up		
Fax			Special In	nstructions					
Email									
**************************************		PROJECT	INFORMA	TION					-
Project Name:	Widaws	Brokeat	PO Numbe	Marine Marine					
Project Number:		J.	- Work Orde				^		
Location;	Grant B	5.	Sampled B	By:	C	esa.	Ruralo	B-	
PL	28	PCM	T	MOLD			LEAD (		
PLM EPA 600/M4 PLM 400 Pt. Coul		NIOSH 7400A	V	pore Trap		Air		TTLC	
PLM 1000 Pt. Cou	` ′	NIOSH 7400B ☐ w/ TWA ☐	B	ape Lift Bulk Sample		Paint Wipe			
			8	Swab		Soil			
SAMPLE ID	SAMPLE TYP	E	LOÇAT	TION		Date	Start Time	Avg	Volume
					^	Sampled	NStop Time	Flow Rate	(L)
623W1	Kitchen ar	ea- Oast C	N-Slo	or-(,	12" 7	12"	<del>                                     </del>		
623W2	Bldg. B	pateria,	Pm. 2	26 SE	- /1	2118	1211		^
623W2 623WS	Bldg. A E	ea-Oast C paterior	Dm. 2	5 po		h. (	124	X 12"	· )
	J					**			/
		3.54							

Received By: Cosm Run (cob Received By: Market By: Date/Time: 6/23/17 / 6:18

Received By: Received By: Received By: Date/Time: Date/Time:

Page \_\_\_\_

Lab Forms Ver. 2016-06-27





# AmeriSci Los Angeles

24416 S. Main Street, Ste 308 Carson, California 90745 TEL: (310) 834-4868 • FAX: (310) 834-4772

### FACSIMILE TELECOPY TRANSMISSION

Cesar Ruvalcaba

From:

AmeriSci Job #: 417061461

Fax #:

Lead (wipe) 6 hour Results Subject:

Client Project: Grant E.S.; Abatement

cesar.ruvalcaba@altaenviron.com Email:

Alta Environmental

Date: Friday, June 30, 2017

Number of Pages:

(including cover sheet)

Time: 19:06:15

Comments:

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Preliminary data reported here will be verified before final report is issued. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

> Competitive Prices Certified Analysis Service 24 Hours A Day • 7 Days A Week visit our web site - www.amerisci.com



# AmeriSci Los Angeles

24416 S. Main Street, Ste 308 Carson, California 90745 TEL: (310) 834-4868 • FAX: (310) 834-4772

AmeriSci Job #: 417061461

**Lead Analysis Results** 

Date Received: 06/30/17

Date Analyzed: 06/30/17

Dust Wipes EPA Method 3050B/7000B

### Alta Environmental

Long Beach, CA

Job Site: Grant E.S.; Abatement

AmeriSci # 417061461	Client Number	Sample Location	Area (ft2)	Lead Content (µg/ft2)
01	L1	Bldg. C, Boy's RR Floor	1	<10
02	L2	Bldg. C, Girl's RR Floor	1	<10
03	L3	Rm 41 Floor	1	<10
04	L4	Blank	0	<10

AmeriSci Reporting Limit is 10 ug/wipe, prior to any dilutions due to high analyte concentrations or matrix interferences. AmeriSci does not correct sample results by the blank value. All analytical batch data met quality control criteria unless otherwise noted. CA ELAP No. 2322.

HUD guidelines for dust wipes are:

40 ug/ft2 for floors, 250 ug/ft2 for interior window sills, 400 ug/ft2 for interior window

Reviewed by:

Analyzed by:

Soheir Galess, Chemist

ELAP No: CA 2322

Page 1 of 1



# Asbestos, Lead Analysis Chain of Custody

AMERISCI JOB #:

417061461

### AMERISCI LOS ANGELES 24416 S Main St. Suite 308

4416 S Main St. Suite 30Carson, CA 9074Phone (310) 834-486Fax (310) 834-477

COMPANY:		ADDRESS:						P.O.#:	
ALTA Eneiro	nuental	3777 Long Black Blid, Long Beach CA 90807							
PROJECT INFORMATION		ANALYSIS							FILTER
		TYPE	Rush	24 HR	48 HR	72 HR	5 DAY		RMATION:
JOB NAME:	1	ASBESTOS TEM AHERA						MCE	
Grount E	. 5.	ASBESTOS PLM BULK						PC	
JOB NUMBER:		ASBESTOS PCM AIR						25 mm	
		ASBESTOS PLM 1000 P.C.						37 mm	
JOB MANAGER:		LEAD AIR						0.45 um	
Cesar Ruvalcaka		LEAD WIPE	10					0.80 um	
JOB DESCRIPTION:		LEAD PAINT / SOLID						TEMP:	
A basement		OTHER:						OTHER:	
		EMAIL   VERBAL   MA	AIL ONLY			RETURN	I SAMPLE	S YES	
		saQalfaenuron.com				PHONE:			
NVOICE TO:	J-11 8 - 0 0 0 - 11 COL	- Common.com				FAX:			
COMMENTS:									
JOMMEN 13.		. *				EMAIL:			
Anjara						PAGER/			
SAMPLE ID		SAMPLE LOCATION		START TIME	STOP TIME	TOTAL LITERS TOTAL TIME X /MIN. = VOLUME		AREA SQUARE F1	
4	Bldg. C, r.	Boy's RR floor							144cm2
42		irls RR Floor	7						144cm2
43	Rm 41	floor							14/4cm 2
24	Blank								
			j)						
***									
					-:				
	P								
									15%
AMPLED BY:		DATE/TIME:	RECE	IVED BY:					DATE/TIME
	7.			IVED D1.					
Gabe & ELINQUISHED BY: Jorge K	Wern	6/29/17 1400 DATE/TIME: 1/30/17: 1430							
ELINQUISHED BY:		DATE/TIME:	RECE	IVED BY:					DATE/TIME:
JOTGL K	06/es 6	130/17. 1430							
ELINQUISHED BY:		DATE/TIME:		IVED IN L	AB By: S	1	4.	P	DATE/TIME:
						Y 1580	m	town	DATE/TIME:
			4						P

# Appendix C

Alta Environmental Employee Certifications

# State of California Division of Occupational Safety and Health Certified Asbestos Consultant

## Cesar Ruvalcaba


Name



Certification No. 95-1799

Expires on 10/27/18

This certification was issued the Division of Occupational Service and Health as authorized by Sections 710 at 12 day the Business and Professions Code.



### State of California Division of Occupational Safety and Health **Certified Asbestos Consultant**

## David R Schack

Certification No. 192-0219

Expires on 07709718

This certification was issued by the Division of Occupational Sent and Health as authorized by Sections 7180 et al. of the Business and Professions Code.



# State of California Division of Occupational Safety and Health Certified Asbestos Consultant

# Victor M Sanchez

Name

Certification No. 08-4470


Expires on 01/15/18

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.




# State of California Department of Public Health

Lead-Related Construction Certificate



11/09/2017



11/09/2017

11/09/2017



Victor M. Sanchez

ID# 10148

# Said California Division of Occupational Safety and Health Certified Site Surveillance Technician

**Gustavo J Sanchez** 



Name

Certification No. 11-4732

Expires on \_07/20/17

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



# Certificate Of Completion

Asbestos 40 Hr. Contractor / Supervisor Course

DOSH #: CA-015-03

Jorge Robles

ASI0515170003N12258

**Alan Dages** 

**Principal Instructor** 

5/15/2017

Course Start Date

5/19/2017

Course End Date

Michael W. Home

Michael W. Horner

Training Director

5/19/2017

Exam Date

5/19/2018

**Expiration Date** 

This course satisfies the education requirements for Asbestos accreditation under the Toxic Substances Control Act, Title II. This course has been approved by the Department of Industrial Relations, Division of Occupational Safety and Health of the State of California

NATEC International, Inc.

National Association of Training and Environmental Consulting

1100 Technology Circle- Suite A, Anaheim, CA 92805 • www.natecintl.com • 800-969-3228

140693

Form Number

# CDPH COURSE COMPLETION FORM AND TRAINING CERTIFICATE

**Instructions:** The top half of this form is to be completed by the student, and the bottom half is to be completed by the accredited training provider. The accredited training provider must submit the top (white) copy of this form to CLPPB **and** the last two (pink and yellow) copies to the student within **30 calendar days** of the student's successful completion of the final examination. *I Instrucciones:* La parte superior de este formulario deberá ser completada por el estudiante y la parte inferior por el Proveedor acreditado del entrenamiento. El Proveedor del entrenamiento tiene que mandar la copia blanca a CLPPB y las copias rosada y amarilla al estudiante dentro de los siguientes 30 días después de haber pasado el examen final.

Student Information – To be completed by the student. Please								
Name / Nombre (last / apellido paterno) (first / pri	imer nombre)	(middle initial / segundo no	ombre) Telephone	number / Número de teléfono				
Rostesses behinder y build so parted	Maged senio	ento par Ploma en la		218619 7619 normal				
Home address (number, street, apartment number, PO box number / D apartado postal)	Date of birth (month/day/year)/ Fecha de nacimiento (mes/dia/año)							
apartau o postar)		esta interineción ser	recha de hacilment	o (mes/dia/ano)				
Centarina (Car CornA), y oras signicias y		gundeu y Le Santo s	Dhata idanification	1 Todate do 11 + 15 - 15 - 15 - 15				
sus documentos comunicase Alvas Byis 80 %		fornia. Para informa		Tarjeta de identificación con foto				
City / Ciudad	Type / Tipo	Prayanción de Envenena						
Luce	CA	ZIP code / Código postal		☐ Driver's license / Licencia de conducir ☐ Resident alien card / Tarjeta de residencia				
Mailing address, if different (employer or union name, number, street,	apartment number, PO	box number) /		tipo de ID (specify / especifique):				
Dirección de correo, si es diferente (nombre de patron or unión, núme	ero, calle, número de ap	partamento, apartado postal)	anthropolal as	and a Cope of the state of the				
CDPH require nw completion of this		uma, Department of	Gender / Sexo	RE U I SE DU SUIT PROUEZ				
ALTO Excursionental		ficanon	med beautions					
073		11:	Male / Masculino	☐ Female / Femenino				
City / Ciudad	State / Estado	ASIA CALLA CALLA CALLA	If currently CDPH ce	rtified, provide CDPH certificate ID				
City / Ciudad	State / Estado	ZIP code / Código postal	número de CDPH	tificado por CDPH, favor de dar su				
barn Roach	CA	90207						
Race/Ethnicity / Raza/Étnia								
☐ Asian / Asiático ☐ Black/African American / Negro/Afric		Z Latino/Hispanic / Latino/Hi	ispano 🗆 Nat	ive American / Americano Nativo				
		Other / Otro:	CONTRACTOR OF THE PARTY OF	A STANCE MORAL AND				
Prior to signing, read the Privacy Statement and oth Antes de firmar, lea la Declaración Sobre la Privacion			rás de este formi	lario Aswerier				
Signature of student / Firma del estudiante		t sustitues as an about		n/day/year) / Fecha (mes/dia/año)				
			y min main Fran	10, Odinia 205/7				
		t						
Training Information – To b  Accredited Training Provider name and address	e completed by accredi	ted training provider. Please pri	int or type. Press firmly	/. Training Provider Phone Number				
Accredited Training Provider haine and address	JUHP(V	WHOMIT	NO -	7// LOO O				
IIm-	TOMA	0100110	N .	114111111111111111111111111111111111111				
1100	150.11U	10100 LICIT		Course Number				
1-1/1/	WISK	CH 4 1980		LUS-ST				
Course title:				Instructor Name(s):				
☐ Work	Continuing Educ	ation for Workers						
☐ Inspection/Assessment	General Continu	ing Education		Marmas				
☐ Certified Industrial Hygienist	□ Supervision and     □	Project Monitoring	3 / 06 3 50	HIGHI TOPIE				
Sampling Technician	J Supplemental Su	pervision and Project Mo	nitoring	English				
			100	☐ Spanish				
Course dates (mm/dd/yy)	Number of conta		ed course or continuing					
10 1 10 10 1 -	of instruction comp	education final exa	amination (mm/dd/yy)	Core instruction CCF number				
	0		117	1				
Location of course Core CCF date (mm/dd/yy)								
THE HOUNDINGLESS HANDEN CHURSOS								
As Training Director, I hereby certify, under penalty of perjury, that the information provided herein is true and correct.								
Name of Training Director – please print or type	Signature of Train	ing Director		Date (mm/dd/yy)				
MICHAEL W. HOUSE	11).	J.1		6.5.17				
White copy - CLPPB Blue copy - Training Pro	vider Pink	copy - Student (for Certification	Application)	YELLOW copy - Student				