

June 28, 2017

Santa Monica-Malibu Unified School District Facilities Improvement Projects 2828 4th Street Santa Monica, California 90405

Attention: Nelson Martinez, CCM, LEED AP

Re: Release of Work Area following Abatement of Hazardous Materials Malibu High School, Building E

1 PROJECT BACKGROUND

Alta Environmental (Alta) conducted full-time monitoring during the removal of identified asbestos containing materials, lead-based paints, and PCB related removal work including removal of window and door caulking and surrounding porous surfaces.

2 PROJECT OBSERVATIONS

The removal of ACM, LBP, and PCB was completed by Integrated Demolition and Remediation Inc., a California DOSH license contractor (#1137), located in Anaheim, California.

2.1 Asbestos Removal Activities

Asbestos removal work was performed using wet methods, proper isolation measures including containment, critical barriers, and temporary negative pressure differential and worker decontamination. The work was performed by asbestos trained workers using disposable clothing, air purifying respirators, hand, and foot and eye protection.

Following the removal, IDR and Alta field personnel performed a final visual inspection. The areas were released when no visible dust and debris was found within the containment work area.

Alta Environmental completed air clearance following the removal of identified asbestos containing materials. The samples were collected in accordance with the NIOSH Method 7400 utilizing Phase Contrast

Microscopy (PCM). Results of the sample were consistent at equal to or below 0.01 f/cc, the level recommended by the Environmental Protection Agency (EPA) for area re occupancy following an asbestos response action.

2.2 Lead-Related Construction Activities

Removal of lead-based paint ceramic tile removal work was performed using wet methods, proper isolation measures including containment, signs, critical barriers, and temporary negative pressure differential and worker decontamination, as necessary. The work was performed by lead trained workers using disposable clothing, air purifying respirators, hand, and foot and eye protection.

Area was released upon passing of a through visual inspection by IDR and Alta field representatives.

2.3 PCB Related Removal Work Activities

IDR removed all exterior doors and window casings and 12" of surrounding porous materials. A full containment work area including critical barriers, 3 stage worker decontamination facility, and temporary negative pressure differential was established. The removal was completed using manual means and wet methods. The work was completed by HAZWOPER trained technicians.

The area was released upon passing of thought visual inspection completed by IDR and Alta field representative, and surface wipe samples collected in each containment. Alta collected a floor and window sill samples within a 100 cm2 area. The results were reported as not detected by the laboratory.

3 CONCLUSIONS

3.1 Asbestos

The asbestos removal was completed in accordance with NESHAPS Standards (locally enforced by the South Coast Air Quality Management District), Cal-OSHA regulation, and project abatement plan. All identified ACM have been removed from Building E.

3.2 Lead

The lead-related construction work was completed in accordance with Cal/OSHA lead in construction standard "Cal/OSHA Title 8 CCR, Section 1532.1 (d)", and project abatement plan requirements. All identified LBP, or damaged LBP has been removed or stabilized.

3.3 PCBs

All PCB related work was completed in accordance with the "Specific PCB Removal/Remediation Plan" (#SMSD-16-6543), completed by Alta for this project, dated, March 30, 2017. All identified PCBs have been removed from Building E.

4 SIGNATORY

Respectfully submitted by:

Alta Environmental

Cesar Ruvalcaba Project Manager Certified Asbestos Consultant #95-1799 CDPH Certified Lead Project Monitor I-6855