

LIMITED ASBESTOS AND LEAD SURVEY

Playground Project Webster Elementary School 3602 Winter Canyon Rd Malibu, California 90265

Prepared for:

Santa Monica-Malibu Unified School District 1651 Sixteenth Street Santa Monica, California 90404

Project No.: SMSD-19-8519 Date: February 15, 2019

EXECUTIVE SUMMARY

On February 07, 2019, Alta Environmental conducted a limited survey for asbestos-containing materials and lead-based paints impacted by the Playground Project at Webster Elementary School located at 3602 Winter Canyon Road, Malibu, California. Our Cal/OSHA and California Department of Public Health (CDPH) Certified Professionals conducted the following activities:

- Review of previous reports completed by Alta Environmental (SMSD-16-6285, 10/2017)
- Initial investigation to locate suspect asbestos-containing materials (ACM), and lead-based paints;
- · Physical assessment of suspect ACM, painted surfaces;
- · Collection of bulk samples from suspect ACM;
- Laboratory analysis of samples collected.

Lead-containing paints (LCP) were detected in building areas affected by the project. Lead-based paint (LBP) was assumed on ceramic floor and wall tile in the restroom of Building B (due to non-destructive sampling). When disturbed for construction purposes, impacts may be subject to Cal/OSHA worker protection requirements such as but not limited to initial employee exposure monitoring, worker protection etc.

Refer to section 5 in this report for a summary of LCP and LBP.

CONTENTS

1	INTRODUCTION	1
2	PROJECT BACKGROUND	1
3	SCOPE OF WORK	1
4	METHODOLOGY	2
4.1	Asbestos	2
4.2	Lead	2
5	RESULTS	2
5.1	Asbestos	2
5.2	Lead	2
6	CONCLUSIONS AND RECOMMENDATIONS	3
6.1	Lead-based paints	3
6.2	Lead-containing Paints	4
7	ASSUMPTIONS AND LIMITATIONS	4
8	SIGNATORY	5

Appendices

Appendix A: Field Bulk Sample list: Asbestos

Appendix B: Laboratory Analytical Report: Asbestos

Appendix C: Sample Location Map: Asbestos

Appendix D: Paint Chip Sample List: Lead

Appendix E: Alta Environmental Employee Certifications

Appendix F: Previous Alta Report

REPORTED: February 15, 2019 **PROJECT NO**.: SMSD-19-8519

CLIENT: Santa Monica-Malibu Unified School District

1651 Sixteenth Street

Santa Monica, California 90404

ATTENTION: Ms. Barbara Chiavelli

REF: Limited Asbestos and Lead Survey

Playground Project

Point Dume Elementary School 3602 Winter Canyon Road

Malibu, California

1 INTRODUCTION

On February 07, 2019, Alta Environmental conducted a limited survey for asbestos-containing materials and lead-based paints impacted by the Playground Project at Webster Elementary School located at 3602 Winter Canyon Road, Malibu, California.

2 PROJECT BACKGROUND

Santa Monica-Malibu Unified School District retained Alta Environmental for the limited survey. The survey was completed by Scott Fan, a Cal/OSHA Certified Site Surveillance Technician (CSST) and California Department of Public Health (CDPH) Lead Sampling Technician under the direction of Scott Nunes a Cal/OSHA Certified Asbestos Consultant (CAC) and California Department of Public Health (CDPH) Inspector/Accessor.

3 SCOPE OF WORK

The limited survey included the following:

- Review of previous reports completed by Alta Environmental (SMSD-16-6285, 10/2017)
- Initial investigation to locate suspect asbestos-containing materials (ACM), and lead-based paint;
- Physical assessment of suspect ACM, painted surfaces;
- · Collection of bulk samples from suspect ACM;
- Laboratory analysis of samples collected.

4 METHODOLOGY

4.1 Asbestos

Bulk samples of representative observed construction materials were collected. The sampling was conducted using guidelines set forth in *Federal Register 40 CFR Part 763*. Alta Environmental conducted an initial walkthrough of the Site to develop a listing and sampling scheme of suspect materials. Samples were placed in sealable sample containers and assigned a unique sample identification number.

Bulk samples collected from the Site were subsequently analyzed by polarized light microscopy (PLM) for asbestos content in accordance with the United States Environmental Protection Agency's (USEPA) *Determination of Asbestos in Bulk Building Materials: EPA/600/R-93/116, July 1993*, at AQ Environmental Laboratories located in Signal Hill, California. a laboratory accredited by the National Voluntary Laboratory Accreditation Program.

Based on the requirements of the USEPA as set forth in *40 CFR* 763, a homogeneous material is defined as "an area of surfacing material, thermal system insulation material or miscellaneous material that is uniform in color and texture." Furthermore, the regulation requires that a minimum number of samples be collected from each identified homogeneous material. If one sample in a homogeneous material is found to contain asbestos, the entire homogeneous material is considered to be asbestos-containing.

Caution is advised in interpreting results provided herein.

4.2 Lead

Paint chip samples were collected (previous report) for construction safety as defined by *Title 8 CCR Section* 1532.1. Paint chip sample analysis was conducted by EPA Method SW846/7420 at AQ Environmental Laboratory, located in Signal Hill, California, a laboratory accredited by the Environmental Laboratory Accreditation Program

5 RESULTS

5.1 Asbestos

The results for all materials sampled were reported as "none detected," based on the limitations of the analytical method. Please refer to Appendix A for a complete listing of materials sampled, locations, and material conditions.

5.2 Lead

Lead-based paint, according to, the State of California, HUD, and the USEPA is defined as paint or other surface coatings with lead content equal to or greater than 1.0 mg/cm² of surface area by XRF testing or 5,000 parts per million (ppm) by paint chip analysis. However, a more stringent level has been established by the Los Angeles County Department of Health Services, which defines "dangerous level of lead-bearing substances" as paint or other surface coatings with lead content greater than 0.7 mg/cm² (Los Angeles County Code, Title 11, Chapter 11.28, Section 11.28.010 C).

Lead-containing paints according to Cal/OSHA *Title 8 CCR*, *Section 1532.1(d)* are defined as paints reported with any detectable levels of lead by paint chip analysis. When disturbed for construction purposes, these surfaces are subject to Cal/OSHA exposure assessment requirements. Amongst other things, this regulation requires initial employee exposure monitoring to evaluate worker exposure during work tasks that disturbs paint with any detectable level of lead. If airborne lead levels are above the established Cal/OSHA action limit or permissible exposure limit, additional monitoring and respiratory protection are required.

Summary of LBP

Wall/Floor Tile-Ceramic-Gray (assumed)

Summary of LCP

Wall-Drywall-White

Component results are summarized in Appendix D Paint Chip Sample List and Appendix E Analytical Results.

6 CONCLUSIONS AND RECOMMENDATIONS

This limited survey was conducted to identify accessible asbestos-containing materials, and lead-based paints and was limited to the areas impacted by the Playground Project. No other areas were included in the scope of work.

Alta recommends that during removal, or demolition, if suspect ACMs or lead materials are discovered that have not been previously sampled, that the materials be assumed to contain asbestos and lead. The suspect ACM and lead materials should be properly characterized by a Cal-OSHA certified professional prior to disturbance or removal.

6.1 Lead-based paints

Lead-based paints (assumed ceramic wall and floor tile in the restroom of Building B) have been identified on the Site. Refer to Section 5 of this report for a summary of LBP.

Impacts to LBP, when disturbed for construction purposes, are subject to Cal/OSHA worker protection requirements such as but not limited to initial employee exposure monitoring, worker protection, etc. Impacts to LBP may also be subject to California Department of Public Health requirements if results of worker exposure monitoring exceed the Cal/OSHA permissible exposure limit.

An O&M program is also recommended for the identified LBP in good condition. An O&M program or interim control is a set of measures designed to temporarily reduce human exposure or possible exposure to LBP hazards. Such measures may include specialized cleaning, repairs, maintenance, painting, temporary containment and management and resident education programs. Visual monitoring conducted by owners and/or reevaluations by risk assessors are integral elements of an interim control. An initial evaluation of

potential LBP hazard by a certified risk assessor is recommended for a successful implementation of the interim controls.

Abatement (e.g., stabilization) is recommended for damaged LBP, or if the condition of the materials noted as being in good condition should change. According to Federal regulations and guidelines, LBP abatement is the permanent (defined as designed to last at least 20 years or, in case of encapsulation, a 20-year product warranty) elimination of LBP hazards through replacement, enclosure, encapsulation, paint removal and cleaning to remove lead-contaminated dust.

Work activities impacting LBP pose a potential exposure risk for workers and/or building occupants. Workers trained in proper safety and respiratory techniques should perform renovation activities that may impact the LBP described in this report.

6.2 Lead-containing Paints

Lead-containing paints have been identified at the Site. Refer to Section 5 in this report for a summary of LCP.

Workers who disturb surfaces with lead-containing paint are subject to regulation under *Title 8 CCR*, *Section 1532.1 (d)*. These requirements include awareness training, monitoring to determine worker exposure. This regulation requires initial and on-going (if necessary) employee exposure monitoring to evaluate lead work exposure that disturbs paint with any detectable level of lead. Alta Environmental suggests that engineering controls, respiratory protection and personal protective equipment be employed at the start of any project that disturbs painted surfaces.

7 ASSUMPTIONS AND LIMITATIONS

This report was prepared exclusively for use by Santa Monica-Malibu Unified School District and may not be relied upon by any other person or entity without Alta Environmental's express written permission. The information, conclusions and recommendations described in this report apply to conditions existing at certain locations when services were performed and are intended only for the specific purposes, locations, time frames and project parameters indicated. Alta Environmental cannot be responsible for the impact of any changes in environmental standards, practices or regulations after performance of services.

In performing our professional services, we have applied present engineering and scientific judgment and used a level of effort consistent with the current standard of practice for similar types of studies.

As applicable, Alta Environmental has relied in good faith upon representations and information furnished by individuals with respect to operations and existing property conditions, to the extent that they have not been contradicted by data obtained from other sources. Accordingly, Alta Environmental accepts no responsibility for any deficiencies, omissions, misrepresentations, or fraudulent acts of persons interviewed.

Alta Environmental will not accept any liability for loss, injury claim, or damage arising directly or indirectly from any use or reliance on this report. Alta Environmental makes no warranty, expressed or implied.

This report is issued with the understanding that the client, the property owner, or its representative is responsible for ensuring that the information, conclusions, and recommendations contained herein are brought to the attention of the appropriate regulatory agencies, as required.

Material quantities are in some cases listed within this document. These quantities are not intended to be used for removal bidding purposes. Nor is this document intended as a contract manual. Work methods and sequence, coordination of participants, applicable codes, engineering controls, required submittals and notifications should in all cases be addressed in a separate and independent bidding and contract document.

If you have any questions, please do not hesitate to contact the undersigned at (562) 495-5777. We appreciate the opportunity to be of service to Santa Monica-Malibu Unified School District.

8 SIGNATORY

Respectfully submitted by:

Alta Environmental

Scott Fan Certified Site Surveillance Technician Cal/OSHA Cert. #18-6195

Lead Sampling Technician CDPH Cert. #31232

Reviewed by:

Scott M. Nunes

Certified Asbestos Consultant Cal/OSHA Cert. # 92-0547 Lead Inspector/Assessor

CDPH Cert. # I-1085

Appendix A
Asbestos Field Bulk Sample List

Appendix B
Laboratory Analytical Report: Asbestos

MATERIAL INVENTORY ASBESTOS SAMPLES

CLIENT: SMMUSD PROJECT NO: SMSD-19-8519

SCHOOL: Webster Elementary School

PROJECT NAME: Playground project

Building B and H

A-1	None detected	Building H exterior				
	None detected	Building H exterior southwest corner Building H exterior center Building H exterior center	of impact		Yes	
A-2	None detected			1,600 SF		No
A-3	None detected	Building H exterior east center	or impact			
A-4	None detected	Building B exterior west end	Building B exterior, area	1,000,05	Vaa	No
A-5	None detected	Building B exterior center		1,000 SF	Yes	No
A-6	None detected	Building B exterior east				
A-7	None detected	Building B, B-2 center				
A-8	None detected	Building B restroom, center	Building B restroom and	1,000 SF	Yes	No
A-9	None detected	Building B restroom, south center	storage area of impact	,		
	A-3 A-4 A-5 A-6 A-7 A-8 A-9	A-3 None detected A-4 None detected A-5 None detected A-6 None detected A-7 None detected A-8 None detected	A-3 None detected Building H exterior east center A-4 None detected Building B exterior west end A-5 None detected Building B exterior center Building B exterior center Building B exterior east Building B exterior east Building B, B-2 center Building B restroom, center Building B restroom, south center	A-3 None detected Building H exterior east center A-4 None detected Building B exterior west end A-5 None detected Building B exterior center A-6 None detected Building B exterior center Building B exterior east Building B restroom, center Building B restroom, south storage area of impact	A-3 None detected Building H exterior east center A-4 None detected Building B exterior west end A-5 None detected Building B exterior center A-6 None detected Building B exterior center Building B exterior east A-7 None detected Building B, B-2 center A-8 None detected Building B restroom, center Building B restroom, south storage area of impact 1,000 SF Building B restroom and storage area of impact 1,000 SF	A-3 None detected Building H exterior east center A-4 None detected Building B exterior west end A-5 None detected Building B exterior center A-6 None detected Building B exterior center Building B exterior east Building B exterior east Building B exterior east Building B exterior east Building B exterior and storage area of impact 1,000 SF Yes Building B restroom and storage area of impact 1,000 SF Yes A-9 None detected Building B restroom, south center

Page 1 of 2

MATERIAL INVENTORY ASBESTOS SAMPLES

CLIENT: SMMUSD SMSD-19-8519

SCHOOL: Webster Elementary School

PROJECT NAME: Playground project


Building B and H

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage	
Note: Floor tile and mastic were abated in the following rooms; 11A, 12A, storage in room 11, and storage in room 12. Please see Monitoring Services During								
Asbestos Related Work Report (dated 11/9/17) for details.								
Note: There may be remaining asbestos-containing floor tile and mastic underneath walls, cabinets, and casework that were not previously accessible.								

Page 2 of 2

Appendix C

Sample Location Map: Asbestos



RE FOR NEW CONSTRUCTION, SEE CIVIL NEW COMPACTED GRANITE SURFACE EW CONSTRUCTION, SEE CIVIL EXISTING CHAIN-LINK FENCE TO REMAIN OOTS. SEE CIVIL. EXISTING ORNAMENTAL FENCE TO REMAIN DARD, PATCH & PAINT (E) WALL AS REQ'D TO MATCH EXISTING O ROOTS AND PREPARE FOR NEW WORK.

IG. CAP PIPING AS INDICATED ON PLAN: PATCH & PAINT WALL AS PING. NEW CHAIN-LINK FENCE CLASSROOM H4 (A02) (A32) KEY PLAN (A 16) INTERIOR OF BUILDING H NOT IN SCOPE (A 10) (A0A) FNI ARC

Supervisor at the for

IR AS REQUIRED DUE TO DEMOLITION WORK.

Appendix D

Paint Chip Sample List: Lead

CLIENT: SMMUSD PROJECT NO: SMSD-19-8519

SCHOOL: Webster Elementary School

PROJECT NAME: Playground project

Building B and H

Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Approx. Damage
Wall	Stucco	PC-11	White	Previously sampled, 10/2016 Alta Environmental	Exterior all buildings	520	No	N/A
Wall	Drywall	PC-16	White	Previously sampled, 10/2016 Alta Environmental	Interior buildings all buildings	<50	No	N/A
Wall and Floor	N/A	Ceramic	Gray	Assumed due to non- destructive sampling	Building B Restroom	Assumed (See Note)	No	N/A

Note: Ceramic wall and floor tiles to be impacted are assumed to be lead-based paint until tested

Note: Gates and railings to be impacted were not painted - no samples collected

Appendix E

Alta Environmental Employee Certifications





Scott Fan

Name
Certification No. 18-6195

Expires on _05/15/19

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code.



Appendix F

Previous Alta Report



LIMITED ASBESTOS AND LEAD SURVEY

Floor and Paint Project Webster Elementary School 3602 Winter Canyon Road Malibu, California

Prepared for:

Santa Monica-Malibu Unified School District 1651 Sixteenth Street Santa Monica, California 90404

Project No.: SMSD-16-6285 Date: October 26, 2016

EXECUTIVE SUMMARY

On September 26 and 27, 2016, Alta Environmental conducted a limited survey for asbestos, and lead in paint for the Floor and Paint Project to be completed at Webster Elementary School located at 3602 Winter Canyon Road, Malibu, California. Our Cal/OSHA and California Department of Public Health (CDPH) Certified Professionals conducted the following activities:

- Initial investigation to locate suspect asbestos-containing materials (ACM), and lead in paint;
- Physical assessment of suspect ACM, painted surfaces;
- Collection of bulk samples from suspect ACM, painted surfaces;
- Direct readings of lead painted surfaces with an x-ray fluorescence spectrum analyzer; and
- Laboratory analysis of samples collected.

Asbestos-containing materials (ACMs) were detected in building areas affected by the project. Removal may be subject to regulation under USEPA 40 CFR 61, locally enforced by South Coast Air Quality Management District (SCAQMD) and Cal/OSHA regulation (Title 8 CCR Section 1529).

Lead-based paints (LBPs) was detected on building areas affected by the project. Impacts to LBP when disturbed for construction purposes are subject to Cal/OSHA worker protection requirements such as but not limited to initial employee exposure monitoring, worker protection etc. Impacts to LBP may also be subject to California Department of Public Health requirements if results of worker exposure monitoring exceed the Cal/OSHA permissible exposure limit.

Lead-containing paints (LCP) were detected in building areas affected by the project. When disturbed for construction purposes, impacts may be subject to Cal/OSHA worker protection requirements such as but not limited to initial employee exposure monitoring, worker protection etc.

i

Coated materials such as ceramics, toilets, sink urinal etc. were not included in our scope of work per District request.

Refer to section 5 in this report for a summary of findings.

CONTENTS

1	INTRODUCTION	1
2	PROJECT BACKGROUND	1
3	SCOPE OF WORK	1
4	METHODOLOGY	2
4.1	ASBESTOS	2
4.2	LEAD	2
5	RESULTS	3
5.1	ASBESTOS	3
5.2	LEAD	6
6	CONCLUSIONS AND RECOMMENDATIONS	7
6.1	ASBESTOS	7
6.2	LEAD	8
7	ASSUMPTIONS AND LIMITATIONS	9
8	SIGNATORY	10

CONTENTS

Appendices

Appendix A: Field Bulk Sample list: Asbestos

Appendix B: Laboratory Analytical Report: Asbestos

Appendix C: Sample Location Map: Asbestos

Appendix D: Paint Chip Sample List: Lead

Appendix E: Laboratory Analytical Report: Lead

Appendix F: Sample Location Map: Lead

Appendix G: XRF Lead Inspection, Instrument Calibration, and DHS 8552

Appendix H: Alta Environmental Employee Certifications

Appendix I: Summary of Lead-Containing Paints

REPORTED: October 26, 2016 PROJECT NO.: SMSD-16-6285

CLIENT: Santa Monica-Malibu Unified School District

1651 Sixteenth Street

Santa Monica, California 90404

ATTENTION: Mr. Chris Emmett

REF: Limited Asbestos and Lead Survey

Floors and Paint Project Webster Elementary School 3602 Winter Canyon Road

Malibu, California

1 INTRODUCTION

On September 26 and 27, 2016, Alta Environmental conducted a limited survey for asbestos, and lead in paint for the Floor and Paint Project to be completed at Webster Elementary School located at 3602 Winter Canyon Road, Malibu, California.

2 PROJECT BACKGROUND

Santa Monica-Malibu Unified School District retained Alta Environmental for the limited survey The survey was completed by Fabian Ruvalcaba, a Cal/OSHA Certified Asbestos Consultant and California Department of Public Health (CDPH) Certified Inspector Assessor and Anthony Vicente an EPA Accredited Asbestos Building Inspector.

3 SCOPE OF WORK

The limited survey included the following:

- Initial investigation to locate suspect asbestos-containing materials (ACM), and lead in paint;
- Physical assessment of suspect ACM, painted surfaces;
- Collection of bulk samples from suspect ACM, painted surfaces;
- · Direct readings of lead painted surfaces with an x-ray fluorescence spectrum analyzer; and
- · Laboratory analysis of samples collected.

The following buildings were included in the survey scope of work:

- Building A (Classroom 17 -20)
- Building B (Classrooms 11 and 12)
- Building C (Classrooms 13-16A)

Alta Environmental SMSD-16-6285 Webster Elementary School. October 26, 2016

- Building D (Main Office)
- Building E (Library and Room 7)
- Building F (Classrooms 8-10)
- Building G (Cafeteria and kitchen)
- Building H (Classrooms 1-4)

4 METHODOLOGY

4.1 Asbestos

Bulk samples of representative observed construction materials were collected. The sampling was conducted using guidelines set forth in *Federal Register 40 CFR Part 763*. Alta Environmental conducted an initial walkthrough of the Site to develop a listing and sampling scheme of suspect materials. Samples were placed in sealable sample containers and assigned a unique sample identification number.

Bulk samples collected from the Site were subsequently analyzed by polarized light microscopy (PLM) for asbestos content in accordance with the United States Environmental Protection Agency's (USEPA) *Determination of Asbestos in Bulk Building Materials: EPA/600/R-93/116, July 1993*, at AQ Environmental Laboratories located in Signal Hill, California. a laboratory accredited by the National Voluntary Laboratory Accreditation Program.

Based on the requirements of the USEPA as set forth in 40 CFR 763, a homogeneous material is defined as "an area of surfacing material, thermal system insulation material or miscellaneous material that is uniform in color and texture." Furthermore, the regulation requires that a minimum number of samples be collected from each identified homogeneous material. If one sample in a homogeneous material is found to contain asbestos, the entire homogeneous material is considered to be asbestos-containing.

Caution is advised in interpreting results provided herein.

4.2 Lead

Representative painted surfaces were tested using a portable XRF spectrum analyzer of representative painted surfaces. The XRF used was the LPA-1, manufactured by Radiation Monitoring Devices (RMD) of Watertown, Massachusetts. XRF readings were taken by using the device "Quick" mode option. No time setting is required with this option since the device automatically adjusts its reading time to the different paint substrates for precision. The duration of each test result was determined by the substrate density in combination with the age of the radioactive source of the device and the actual reading relative to the abatement level (threshold) chosen. The testing includes a unique combination of room equivalent, building component type, and substrate.

An XRF Performance Characteristic Sheet (PCS) developed jointly by the U.S. Department of Housing and Urban Development (HUD) and the USEPA for the RMD LPA-1 was used. The PCS provides information necessary to conduct an inspection of LBP using a specific XRF device. Based on the PCS, no

inconclusive readings in the "Quick" mode were encountered for LBP on brick, concrete, drywall, metal, plaster or wood substrates.

Field calibration checks were performed prior, during and after each XRF lead inspection to determine that the device was functioning within acceptable limits (tolerance) determined by the manufacturer. Three readings of a red 1.04 mg/cm² Standard Reference Material (SRM) paint film, developed by the National Institute of Standard and Technology (NIST), were taken in the "Time Corrected" mode option during each calibration check. Each set of readings was averaged and compared to the PCS calibration check limit for the device. Please refer to Appendix H Field Notes, for documentation of the quality-control calibration checks.

Paint chip samples were collected to determine the weight percent concentration in the painted surfaces that were analyzed by XRF and reported below the USEPA, HUD or Los Angeles County action levels. Paint chip samples were collected for construction safety as defined by *Title 8 CCR Section 1532.1*. Paint chip sample analysis was conducted by EPA Method SW846/7420 at AQ Environmental Laboratory, located in Signal Hill, California, a laboratory accredited by the Environmental Laboratory Accreditation Program

5 RESULTS

5.1 Asbestos

Asbestos-containing materials (ACM) are those materials found to contain greater than one percent asbestos by weight as determined by the PLM method of analysis. These materials are subject to regulation under USEPA 40 CFR 61, local South Coast Air Quality Management District (SCAQMD). These materials are also subject to Cal/OSHA regulation (Title 8 CCR Section 1529) when disturbed for construction purposes.

Asbestos-containing construction materials (ACCM) are those materials reported to contain less than one percent (<1%) by PLM or greater than one tenth of one percent (>0.1%) using a 1,000 point count analysis. ACCMs are subject to Cal-OSHA regulation when disturbed for construction purposes.

Summary of ACMs:

Material	Sample No.	Material Location	Asbestos Content	Est. Qty.	
Building A (Classrooms 17 – 20)					
Yellow adhesive with carpet	170-4, 170-5, 170-6	Rooms 17, 18, 19, 20	0.30% chrysotile- adhesive none detected-carpet (by 1,000 point count analysis)	1,300 sq.ft.	

Material	Sample No.	Material Location	Asbestos Content	Est. Qty.
12"x12" light grey floor tile with yellow adhesive	170-7, 170-8, 170-9	Rooms 17, 20	None detected-tile 0.32% chrysotile- adhesive	1,200 sq.ft.
12"x12" dark brown floor tile with black mastic	170-10, 170-11, 170-12	Room 19	<1% chrysotile-tile, 3%-5% chrysotile- mastic	400 sq.ft.
9"x9" beige floor tile with black mastic	170-13, 170-14, 170-15	Rooms 17, 18, 19, 20 (under carpets and new tile sections)	10% chrysotile-tile 8%-10% chrysotile- mastic	4,000 sq.ft.
	Building E	3 (Classrooms 11 and	12)	
9"x9" dark grey floor tile with black mastic	11-1, 11-2, 11-3	Rooms 11A and 12A	7% chrysotile-tile 8%-10%chrysotile- mastic	200 sq.ft.
12"x12" light blue speckled floor tile with black adhesive	11-4, 11-5, 11-6	Rooms 11 and 12	None detected-tile 2% chrysotile-mastic	1,500 sq.ft.
	Building	C (Classrooms 13-16	A)	
9"x9" beige floor tile and mastic	12A-13 13A-14 13A-15	Rooms 13, 14, 15, 16 (under carpet and new tile)	8% chrysotile-tile 2%-3% chrysotile- mastic	4,500 sq.ft.
12" beige floor tile with black mastic	13A-19 13A-20 13A-21	Room 16A	15% chrysotile-tile 5% chrysotile-mastic	500 sq.ft.
	Buile	ding D (Main Office)		
9"x9" dark brown floor tile and black mastic	MA-4, MA-5, MA-6	Server room	8% chrysotile-tile 2% chrysotile-mastic	100 sq.ft.

Material	Sample No.	Material Location	Asbestos Content	Est. Qty.			
Yellow adhesive with dark blue carpet and black residual mastic	MA-10, MA-11, MA-12	Lobby, principal's office	None detected, yellow adhesive and carpet 2% chrysotile-residual mastic	700 sq.ft.			
	Building I	E (Library and Room	7)				
Black mastic with dark grey carpet	L7-4, L7-5 L7-6	Library B (residual under floor tile)	None detected-carpet 2%-8% chrysotile- mastic	150 sq.ft.			
12"x12" light grey speckled floor tile and mastic	L7-10 L7-11 L7-12	Library rooms A and B	None detected-tile 2% chrysotile-mastic	350 sq.ft.			
Building F (Classrooms 8 – 10)							
9"x9" beige floor tile with black mastic	810-10, 810-11, 810-12	Rooms 8, 9, 10 (under carpet and new tile)	20% chrysotile-tile 5% chrysotile-mastic	3,300 sq.f.t.			
	Building	G (Cafeteria, Kitchen)				
12"x12" white with light grey specks floor tile and mastic	C-1, C-2, C-3	Cafeteria	2% chrysotile-tile none detected-mastic	4,000 sq.ft.			
9"x9" brown floor tile with black mastic	C-13 C-14, C-15	Janitors closet, food storage (under dark grey tile) closet, speech (under carpet)	7% chrysotile-tile <1% chrysotile-mastic	450 sq.ft.			
Building H (Classrooms 1-4)							
9"x9" beige floor tile with black mastic	234-4 234-5 234-6	Rooms 1, 2, 3, 4 (under carpet and new 12"x12" lt. grey floor tile and leveling compound)	8% chrysotile-tile <1% chrysotile-mastic	4,000 sq.ft.			

The results for all other materials sampled were reported as "none detected," based on the limitations of the analytical method. Please refer to Appendix A for a complete listing of materials sampled, locations, and material conditions.

5.2 Lead

Lead-based paint, according to, the State of California, HUD and the USEPA is defined as paint or other surface coating with lead content equal to or greater than 1.0 mg/cm² of surface area by XRF testing or 5,000 parts per million (ppm) by paint chip analysis. However, a more stringent level has been established by the Los Angeles County Department of Health Services, which defines "dangerous level of lead-bearing substances" as paint or other surface coating with lead content greater than 0.7 mg/cm² (Los Angeles County Code, Title 11, Chapter 11.28, Section 11.28.010 C).

Summary of LBP:

Sample #	Sampling method	Structure	Material Location	Paint Color & Condition	Substrate	Lead (mg/cm²/ PPM)
029, 068, 096, (9/26/16) 024, 043 (9/27/16) PC-19	XRF & PC	Roof flashing	Exterior, Buildings A, B, C, D, E, F, G, and H	Green/intact	Metal	0.8, 1.8, 2.0 mg/cm ² 6,900 ppm
028 (9/26/16)	XRF	Doorcasing	Exterior D, E, G and H	Green/intact	Metal	0.8 mg/cm²
024, 067 (9/26/16), 023, 041, (9/27/16) PC-17	XRF	Window casing	Exterior, Buildings A, B, C, D, E, F, G, H	Green/intact	Metal	0.8, 1.8, 2.2 mg/cm ² 18,000 PPM
66 (9/26/16)	XRF	Window casing	Exterior D	Green/intact	Wood	2.2 mg/cm²
005 (9/27/16)	XRF	Window casing	Interior building H	White/intact	Metal	2.3 mg/cm²
004 (9/27/16	XRF	Post	Interior building H	White/intact	Metal	0.8 mg/cm²

Sample #	Sampling method	Structure	Material Location	Paint Color & Condition	Substrate	Lead (mg/cm²/ PPM)
62 (9/26/16)	XRF	Wall	Exterior D	White/intact	Wood	1.5 mg/cm²
095, 096, 097,	XRF	Post, Downspout gutter, flashing	Covered Walkways, all on site	Green/intact	Metal	0.8, 1.5, 1.6, 1.7 mg/cm ²

Lead-containing paints according to Cal/OSHA *Title 8 CCR*, *Section 1532.1(d)* are defined as paints reported with any detectable levels of lead by paint chip analysis. When disturbed for construction purposes, these surfaces are subject to Cal/OSHA exposure assessment requirements. Amongst other things, this regulation requires initial employee exposure monitoring to evaluate worker exposure during work tasks that disturbs paint with any detectable level of lead. If airborne lead levels are above the established Cal/OSHA action limit or permissible exposure limit, additional monitoring and respiratory protection are required.

Summary of LCP

Lead-containing paint was detected during this survey. Refer to Appendix I for a listing of identified lead-containing paints.

Component results are summarized in Appendix D Paint Chip Sample List and Appendix E Analytical Results.

6 CONCLUSIONS AND RECOMMENDATIONS

The limited survey was conducted to identify asbestos in flooring materials including floor tiles, carpet, sheet vinyl etc. and base coves, and lead in paint in the interiors of all classrooms (except restrooms) and exterior trims of in buildings A, B, C, D, E, F, G, and H (all permanent buildings on site).

Coated materials such as ceramics, toilets, sink urinal etc. were not included in our scope of work per District request.

No other areas, or buildings were included in the Alta scope of work.

Alta recommends that during removal, or demolition, if suspect ACMs or lead materials are discovered, that the materials be assumed to contain asbestos and lead. The suspect ACM and lead materials should be properly characterized by a Cal-OSHA certified professional prior to disturbance or removal.

6.1 Asbestos

Asbestos-containing materials have been identified at the Site. Refer to Section 5 in this report for a summary of ACMs.

Removal of ACMs should be conducted by a licensed asbestos abatement contractor utilizing isolation control methods and dispose of properly. Workers handling ACM shall be asbestos trained and shall wear the appropriate personal protective equipment. Removal shall be conducted in accordance with South Coast Air Quality Management District (SCAQMD) Procedures 1 and or 3 as necessary.

Damaged asbestos materials should be removed, repaired, encapsulated or enclosed. The USEPA (locally enforced by South Coast Air Quality Management District (SCAQMD) requires that all asbestos materials be removed prior to any renovation or demolition activities that may impact the material. The USEPA recommends that a proactive, in-place management program be put in place whenever asbestos is discovered in a building. Asbestos materials that are not damaged may be managed in place with a good operations and maintenance (O&M) program.

Material quantities included in this report are of observed material and provided as a best estimate for information only and shall not be used as a reliable quantity by any contractor for preparing removal bids. The contractor shall be solely responsible for assessing the type, extent, and quantity of material to be removed in each area of the project in preparing each project bid.

Bulk samples were reported to contain low levels of asbestos, less than 1% (<1%), a gravimetric reduction followed by point count analysis is recommended. Gravimetric reduction through ashing and acid dissolution removes interfering organic binders and calcium carbonate facilitating a more accurate and reliable analysis. A predetermined number of points are counted (in California, 1000 for 0.1% detection limit). The number of asbestos points is divided by the total number of points counted to obtain the percent asbestos in the residue. The final result is then obtained by multiplying the percent asbestos in the residue by the percentage of the sample represented by the residue. Samples are analyzed following (USEPA) Determination of Asbestos in Bulk Building Materials: EPA/600/R-93/116, July 1999". A gravimetric reduction followed by point count analysis was recommended by Alta, the District decided not to complete the analysis at this time.

6.2 Lead

Lead-based paints have been identified in the Site. Refer to Section 5 in this report for a summary of LBP.

Impacts to LBP when disturbed for construction purposes are subject to Cal/OSHA worker protection requirements such as but not limited to initial employee exposure monitoring, worker protection etc. Impacts to LBP may also be subject to California Department of Public Health requirements if results of worker exposure monitoring exceed the Cal/OSHA permissible exposure limit.

An O&M program is also recommended for the identified LBP in good condition. An O&M program or interim control is a set of measures designed to temporarily reduce human exposure or possible exposure to LBP hazards. Such measures may include specialized cleaning, repairs, maintenance, painting, temporary containment and management and resident education programs. Visual monitoring conducted by owners and/or reevaluations by risk assessors are integral elements of an interim control. An initial evaluation of potential LBP hazard by a certified risk assessor is recommended for a successful implementation of the interim controls.

Abatement (e.g., stabilization) is recommended for damaged LBP, or if the condition of the materials noted as being in good condition should change. According to Federal regulations and guidelines, LBP abatement is the permanent (defined as designed to last at least 20 years or, in case of encapsulation, a 20-year Alta Environmental 8

product warranty) elimination of LBP hazards through replacement, enclosure, encapsulation, paint removal and cleaning to remove lead-contaminated dust.

Work activities impacting LBP pose a potential exposure risk for workers and/or building occupants. Workers trained in proper safety and respiratory techniques should perform renovation activities that may impact the LBP described in this report.

Lead-containing Paints

Lead-containing paints have been identified at the Site. Refer to Section 5 in this report for a summary of LCP.

Workers who disturb surfaces with lead-containing paint are subject to regulation under *Title 8 CCR*, *Section 1532.1 (d)*. These requirements include awareness training, monitoring to determine worker exposure. This regulation requires initial and on-going (if necessary) employee exposure monitoring to evaluate lead work exposure that disturbs paint with any detectable level of lead. Alta Environmental suggests that engineering controls, respiratory protection and personal protective equipment be employed at the start of any project that disturbs painted surfaces.

Lead-waste Disposal

Waste generated during removal or demolition of LBP and LCP components must be properly segregated into separate waste streams. Each waste stream should be randomly sampled and analyzed for lead by the California Waste Extraction Test for comparison to the Total Threshold Limit Concentration (TTLC), and Soluble Threshold Limit Concentration (STLC) and by Toxicity Characteristic Leaching Procedure (TCLP) as required, to determine the final disposition of the waste

7 ASSUMPTIONS AND LIMITATIONS

This report was prepared exclusively for use by Santa Monica-Malibu Unified School District and may not be relied upon by any other person or entity without Alta Environmental's express written permission. The information, conclusions and recommendations described in this report apply to conditions existing at certain locations when services were performed and are intended only for the specific purposes, locations, time frames and project parameters indicated. Alta Environmental cannot be responsible for the impact of any changes in environmental standards, practices or regulations after performance of services.

In performing our professional services, we have applied present engineering and scientific judgment and used a level of effort consistent with the current standard of practice for similar types of studies.

As applicable, Alta Environmental has relied in good faith upon representations and information furnished by individuals with respect to operations and existing property conditions, to the extent that they have not been contradicted by data obtained from other sources. Accordingly, Alta Environmental accepts no responsibility for any deficiencies, omissions, misrepresentations, or fraudulent acts of persons interviewed.

Alta Environmental will not accept any liability for loss, injury claim, or damage arising directly or indirectly from any use or reliance on this report. Alta Environmental makes no warranty, expressed or implied.

This report is issued with the understanding that the client, the property owner, or its representative is responsible for ensuring that the information, conclusions, and recommendations contained herein are brought to the attention of the appropriate regulatory agencies, as required.

Material quantities are in some cases listed within this document. These quantities are not intended to be used for removal bidding purposes. Nor is this document intended as a contract manual. Work methods and sequence, coordination of participants, applicable codes, engineering controls, required submittals and notifications should in all cases be addressed in a separate and independent bidding and contract document.

If you have any questions, please do not hesitate to contact the undersigned at (562) 495-5777. We appreciate the opportunity to be of service to Santa Monica-Malibu Unified School District.

8 SIGNATORY

Respectfully submitted by:

Alta Environmental

Cesar Ruvalcaba

Certified Asbestos Consultant Cal/OSHA Cert. #95-1799

Lead Inspector/Assessor, Project Monitor

CDPH Cert. #6855

CR:da

Appendix A
Asbestos Field Bulk Sample List

PROJECT NO: SMSD-16-6285

PROJECT NAME: Room 17,18,19,20 (Building A)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
4 inch black covebase with adhesive	170-1	None Detected	Room 18 North center	room 18	500 ln.ft.	no	no
4 inch black covebase with adhesive	170-2	None Detected	Room 18 Northeast				
4 inch black covebase with adhesive	170-3	None Detected	Room 18 Northwest				
Yellow adhesive with carpet	170-4	<1% chrysotile-tile None detected-carpet	Room 17 North center	Rooms 17,18,19,20	1,300 sq.ft.	no	no
Yellow adhesive with carpet	170-5	None Detected	Room 18 East center				
Yellow adhesive with carpet	170-6	None Detected	Room 20 center				
12 inch light grey floor tile with yellow adhesive	170-7	None Detected	Room 20 West center	Room 17, 20	1,200 sq.ft.	no	no
12 inch light grey floor tile with yellow adhesive	170-8	None Detected-tile <1% chrysotile-mastic	Room 17 Northwest				
12 inch light grey floor tile with yellow adhesive	170-9	None Detected	Room 20 Northwest				
12 inch dark brown floor tile with black mastic	170-10	<1% chrysotile-tile 5% chrysotile-mastic	Room 19 Northwest	Room 19	400 sq.ft.	no	no

12 inch dark brown floor tile with black mastic	170-11	<1% chrysotile-tile 5% chrysotile-mastic	Room 19 West center				
12 inch dark brown floor tile with black mastic	170-12	<1% chrysotile-tile 3% chrysotile-mastic	Room 19 Southwest				
9 inch beige floor tile with black mastic	170-13	10% chrysotile-tile 10% chrysotile-mastic	Room 19 Northeast	Room 17,18,19,20 (under carpets	4,000 sq	.ft. no	no
9 inch beige floor tile with black mastic	170-14	<1% chrysotile-tile None detected-mastic	Room 18 East center	and tile sections)			
9 inch beige floor tile with black mastic	170-15	<1% chrysotile-tile 8% chrysotile-mastic	Room 20 center				
4 inch grey covebase with adhesive	170-16	None Detected	Room 20 Southwest	Rooms 17,18,19,20	400 linear feet	no	no
4 inch grey covebase with adhesive	170-17	None Detected	Room 20 Northwest				
4 inch grey covebase with adhesive	170-18	None Detected	Room 17 Northwest				
4 inch blue covebase with adhesive	170-19	None Detected	Room 17 North center	Room 17	400 linear feet	no	no

4 inch blue covebase with adhesive	170-20	None Detected	Room 20 Southwest		
4 inch blue covebase with adhesive	170-21	None Detected	Room 20 Northwest		

PROJECT NO: SMSD-16-6285

PROJECT NAME: Room 11,12 (Building B)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
9 inch dark grey floor tile with black mastic	11-1	7% chrysotile-tile 8% chrysotile-mastic	Room 12A Northwest corner	Room 12A, Room 11A	200 sq.ft	no	yes
9 inch dark grey floor tile with black mastic	11-2	7% chrysotile-tile 10% chrysotile-mastic	Room 12A Southwest corner				
9 inch dark grey floor tile with black mastic	11-3	7% chrysotile-tile 8% chrysotile-mastic	Room 11A Northwest corner	-			
12 inch light blue speckled floor tile with black adhesive	11-4	None Detected-tile 2% chrysotile-mastic	Room 12 Southwest corner	Room 12, storage in room 12, 11 and	2,000 sq.ft	no	no
12 inch light blue speckled floor tile with black adhesive	11-5	None Detected	Room 12 Northeast corner	storage in room 11			
12 inch light blue speckled floor tile with black adhesive	11-6	None Detected	Room 11 Southeast corner				
Yellow adhesive with ocean blue carpet	11-7	None Detected	Room 12 Northwest corner				
Yellow adhesive with ocean blue carpet	11-8	None Detected	Room 12 Southeast corner				
Yellow adhesive with ocean blue carpet	11-9	None Detected	Room 11 Northeast corner				
4 inch grey covebase with adhesive	11-10	None Detected	Room 12 Southwest corner	Room 12, 11	200 In.ft.	no	no
4 inch grey covebase with adhesive	11-11	None Detected	Room 12 East center				

4 inch grey covebase with adhesive	11-12	None Detected	Room 11 Southeast corner				
4 inch dark blue covebase with adhesive	11-13	None Detected	Room 12 Southwest corner	Room 12, 11	200 In.ft.	no	no
4 inch dark blue covebase with adhesive	11-14	None Detected	Room 12 East center				
4 inch dark blue covebase with adhesive	11-15	None Detected	Room 11 Southeast corner				

PROJECT NO: SMSD-16-6285

PROJECT NAME: Rooms 13,14,15,16,16A (Building C)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
12 inch light grey speckled floor tile with yellow adhesive (and black residual mastic)	13A-1	None Detected	Room 13 West center	Rooms 13,14,15,16	1,600 sq.ft.	no	no
12 inch light grey speckled floor tile with yellow adhesive (and black residual mastic)	13A-2	None Detected	Room 15 West center				
12 inch light grey speckled floor tile with yellow adhesive (and black residual mastic)	13A-3	None Detected	Room 16 West Center				
4 inch grey covebase with adhesive	13A-4	None Detected	Room 13 West center	Rooms 13,14,15,16, 16A	500 ln.ft.	no	no
4 inch grey covebase with adhesive	13A-5	None Detected	Room 15 West center				
4 inch grey covebase with adhesive	13A-6	None Detected	Room 16 Southwest corner				
4 inch blue covebase with adhesive	13A-7	None Detected	Room 13 Southwest corner	Rooms 13,14,15,16	500 In.ft.	no	no
4 inch blue covebase with adhesive	13A-8	None Detected	Room 15 East cetner				
4 inch blue covebase with adhesive	13A-9	None Detected	Room 16 East center				
Yellow mastic with dark green carpet	13A-10	None Detected	Room 14 center	Rooms 13,14,15,16	2,600 sq.ft.	no	no

Yellow mastic with dark green carpet	13A-11	None Detected	Room 15 East cetner]				
Yellow mastic with dark green carpet	13A-12	None Detected	Room 16 East center					
9 inch beige floor tile with black mastic	13A-13	8% chrysotile-tile 3% chrysotile-mastic	Room 15 East cetner	Rooms 13,14,15,16 under carpet and	4,500	sq.ft.	no	no
9 inch beige floor tile with black mastic	13A-14	8% chrysotile-tile 2% chrysotile-mastic	Room 15 Northeast corner	tile				
9 inch beige floor tile with black mastic	13A-15	8% chrysotile-tile 3% chrysotile-mastic	Room 16 East center					
Yellow mastic with dark brown speckled carpet (over 12 inch beige floor tile)	13A-16	None Detected	16 A center	Room 16A	500	sq.ft.	no	no
Yellow mastic with dark brown speckled carpet (over 12 inch beige floor tile)	13A-17	None Detected	16 A Southwest					
Yellow mastic with dark brown speckled carpet (over 12 inch beige floor tile)	13A-18	None Detected	16 A Northwest					
12 inch beige floor tile with black mastic	13A-19	15% chrysotile-tile 5% chrysotile-mastic	16 A Northwest	Rooms 13,14,15,16 (under carpet)	500	sq.ft.	no	no
12 inch beige floor tile with black mastic	13A-20	15% chrysotile-tile 5% chrysotile-mastic	16 A center					
12 inch beige floor tile with black mastic	13A-21	15% chrysotile-tile 5% chrysotile-mastic	16 A Southwest					

CLIENT: Santa Monica Malibu USD

PROJECT NO: SMSD-16-6285

PROJECT NAME: Main Administration office (Building D)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
12 inch light grey speckled floor tile with yellow glue and residual black mastic	MA-1	None Detected	Lobby center	lobby, nurse office, copy room, hallway	1,000 sq.ft.	No	No
12 inch light grey speckled floor tile with yellow glue and residual black mastic	MA-2	None Detected	Nurse office west center				
12 inch light grey speckled floor tile with yellow glue and residual black mastic	MA-3	None Detected	Nurse office northwest corner				
9 inch dark brown floortile with black mastic	MA-4	8% Chrysotile-tile 2% Chrysotile-mastic	Sewer room northwest corner	server room	100 sq.ft.	no	yes
9 inch dark brown floortile with black mastic	MA-5	8% Chrysotile-tile 3% Chrysotile-mastic	Sewer room northeast corner				
9 inch dark brown floortile with black mastic	MA-6	8% Chrysotile-tile 3% Chrysotile-mastic	Sewer room southwest corner				
4 inch dark grey covebase with adhesive	MA-7	None Detected	HVAC room in hallway	throughout building	700 In.ft.	no	no
4 inch dark grey covebase with adhesive	MA-8	None Detected	Lobby southwest corner				
4 inch dark grey covebase with adhesive	MA-9	None Detected	Principal office southeast corner				

Page 8 of 18

CLIENT: Santa Monica Malibu USD

PROJECT NO: SMSD-16-6285

PROJECT NAME: Main Administration office (Building D)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
Yellow adhesive with	MA-10	None Detected-carpet	Principal office center	Lobby, Principal office	700 sq.ft.	no	no
dark blue carpet and		None-detected-carpet					
residual black mastic		none-detected-yellow					
		glue					
		2% chrysotile-mastic					
Yellow adhesive with	MA-11	None Detected	Principal office southeast				
dark blue carpet and			corner				
residual black mastic							
Yellow adhesive with	MA-12	None Detected	Lobby center	1			
dark blue carpet and							
residual black mastic							

Page 9 of 18

CLIENT: Santa Monica Malibu USD

PROJECT NO: SMSD-16-6285

PROJECT NAME: Library and Room 7 (Building E)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Q	ty. Fria	ble	Damage
Yellow mastic with dark blue carpet	L7-1	None Detected	Library South center	Library	3,200 so	q.ft. n	0	no
Yellow mastic with dark blue carpet	L7-2	None Detected	Library Northeast corner					
Yellow mastic with dark blue carpet	L7-3	None Detected	Library Southwest corner					
Black mastic with dark grey carpet	L7-4	8% chrysotile-mastic None detected-carpet	Library B center	Library B, residual mastic under floor tile of	150 sc	q.ft. n	0	no
Black mastic with dark grey carpet	L7-5	2% chrysotile-mastic None detected-carpet	Library B Northeast corner	room B				
Black mastic with dark grey carpet	L7-6	2% chrysotile-mastic None detected-carpet	Library B Southeast corner					
4 inch dark blue covebase with adhesive	L7-7	None Detected	Library B Northwest corner	Library B	42 In	n.ft. n	0	yes
4 inch dark blue covebase with adhesive	L7-8	None Detected	Library B West center					
4 inch dark blue covebase with adhesive	L7-9	None Detected	Library B southwest corner					

12 inch light grey speckeled floor tile and black mastic	L7-10	None Detected-tile 3% chrysotile-mastic	Library B center	Library A, and B	350 sq.ft.	no	no
12 inch light grey speckeled floor	L7-11	None Detected	Library room A Southwest corner	Library A, and B			
12 inch light grey speckeled floor	L7-12	None Detected	Library room A southeast corner	Library A, and B			
4 inch Black covebase with adhesive	L7-13	None Detected	Library room A Southwest corner	Library, Library A, Library C	600 In.ft.	no	no
4 inch Black covebase with adhesive	L7-14	None Detected	Library Southwest corner				
4 inch Black covebase with adhesive	L7-15	None Detected	Library Northwest corner				
12 inch light blue floor tile with yellow adhesive	L7-16	None Detected	Library C Northeast corner	Library C	640 sq.ft.	no	no
12 inch light blue floor tile with yellow adhesive	L7-17	None Detected	Library C Southeast corner				
12 inch light blue floor tile with yellow adhesive	L7-18	None Detected	Library C by the door of storage				
12 light blue floor tile with black mastic	L7-19	None Detected	Room 7 southwest corner	Room 7	260 sq.ft.	no	no
12 light blue floor tile with black mastic	L7-20	None Detected	Room 7 West center				
12 light blue floor tile with black mastic	L7-21	None Detected	Room 7 Northwest corner				

Black mastic with dark Blue carpet	L7-22	None Detected	Room 7 southwest corner	Room 7	770 sq.ft.	no	no
Black mastic with dark Blue carpet	L7-23	None Detected	Room 7 West center				
Black mastic with dark Blue carpet	L7-24	None Detected	Room 7 Northwest corner				

PROJECT NO: SMSD-16-6285

PROJECT NAME: Room 8,9,10 (Building F)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty.	Friable	Damage
12 inch light grey speckled floortile with yellow adhesive (on top of 9" beige floor tile)	810-1	None Detected	Room 8 West center	Room 8,9,10	1,800 sq.ft.	no	no
12 inch light grey speckled floortile with yellow adhesive (on top of 9" beige floor tile)	810-2	None Detected	Room 9 West center				
12 inch light grey speckled floortile with yellow adhesive (on top of 9" beige floor tile)	810-3	None Detected	Room 10 West center				
4 inch grey covebase with adhesive	810-4	None Detected	Room 8 Northwest corner	Room 8,9,10	300 In.ft.	no	no
4 inch grey covebase with adhesive	810-5	None Detected	Room 9 Southwest corner				
4 inch grey covebase with adhesive	810-6	None Detected	Room 10 Southwest corner	-			
4 inch blue covebase with adhesive	810-7	None Detected	Room 8 Southwest corner	Room 8,9,10	300 In.ft.	no	no
4 inch blue covebase with adhesive	810-8	None Detected	Room 9 West center				
4 inch blue covebase with adhesive	810-9	None Detected	Room 10 south center				

9 inch beige floor tile with black mastic	810-10		Room 9 Southwest corner	Room 8,9,10 underneath carpet and floor	3,300	sq.ft.	no	no
9 inch beige floor tile with black mastic	810-11	20% chrysotile-tile none detected-mastic	Room 9 North center	tile				
9 inch beige floor tile with black mastic	810-12	20% chrysotile-tile 5% chrysotile-mastic	Room 10 North center					
Yellow mastic with dark green carpet (over 9 inch beige floor tile)	810-13	None Detected	Room 9 Southwest corner	Room 9, 10	1,280	sq.ft.	no	no
Yellow mastic with dark green carpet (over 9 inch beige floor tile)	810-14	None Detected	Room 9 North center					
Yellow mastic with dark green carpet (over 9 inch beige floor tile)	810-15	None Detected	Room 10 Center					

CLIENT: Santa Monica Malibu USD

PROJECT NO: SMSD-16-6285

PROJECT NAME: Cafeteria, Stage, Kitchen(Building G)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx	. Qty.	Friable	Damage
12 inch white with light grey speckles floor tile with mastic	C-1	2% chrysotile-tile None detected-mastic	Cafeteria North center	Cafeteria	4,000	sq.ft.	no	no
12 inch white with light grey speckles floor tile with mastic	C-2	2% chrysotile-tile None detected-mastic	Cafeteria Northwest corner					
12 inch white with light grey speckles floor tile with mastic	C-3	2% chrysotile-tile None detected-mastic	Cafeteria center					
12 inch brown with white speckles floor tile with mastic	C-4	None Detected	Cafeteria Northeast corner	Cafeteria (patchwork)	200	sq.ft.	no	no
12 inch brown with white speckles floor tile with mastic	C-5	None Detected	Cafeteria East center					
12 inch brown with white speckles floor tile with mastic	C-6	None Detected	Cafeteria Southeast corner					
4 inch black covebase with brown mastic	C-7	None Detected	Cafeteria Northwest corner	Through out building	2,500 .	sq.ft.	no	no
4 inch black covebase with brown mastic	C-8	None Detected	Cafeteria West center					
4 inch black covebase with brown mastic	C-9	None Detected	Cafeteria South center					

12 inch beige with blue speckles floor tile with yellow adhesive	C-10	None Detected	Lounge North center	Lounge under carpet	400	sq.ft.	no	yes
12 inch beige with blue speckles floor tile with yellow adhesive	C-11	None Detected	Lounge Northeast corner	Lounge under carpet	400	sq.ft.	no	yes
12 inch beige with blue speckles floor tile with yellow adhesive	C-12	None Detected	Lounge Northwest corner	Lounge under carpet	400	sq.ft.	no	no
9 inch brown floortile with black mastic	C-13	7% chrysotile-tile <1% chrysotile-mastic	janitors closet center	janitors closet, food storage, closet, speech	450	sq.ft.	no	yes
9 inch brown floortile with black mastic	C-14	7% chrysotile-tile <1% chrysotile-mastic	speech room under blue carpet center	under carpet (residual mastic presient in				
9 inch brown floortile with black mastic	C-15	8% chrysotile-tile <1% chrysotile-mastic	food storage center	storage room under dark grey tile)				
Beige sheet vinyl	C-16	None Detected	Kitchen North center	Kitchen	600	sq.ft.	no	no
Beige sheet vinyl	C-17	None Detected	Kitchen Northwest corner					
Beige sheet vinyl	C-18	None Detected	Kitchen Northeast corner					
12 inch dark grey floortile	C-19	None Detected	Kitchen Northeast corner	storage	100	sq.ft.	no	no

PROJECT NO: SMSD-16-6285

PROJECT NAME: Rooms 1,2,3,4 (Building H)

Material	Sample No.	Asbestos Content	Sample Location	Material Location	Approx. Qty	r. Friable	Damage
12 inch light grey floor tile with white leveling compound (on top of 9" beige floor tile)	214-1	None Detected	Room 2 North center	Rooms 1,2,3,4	1,100 sq.	t. no	no
12 inch light grey floor tile with white leveling compound (on top of 9" beige floor tile)	214-2	None Detected	Room 3 North center				
12 inch light grey floor tile with white leveling compound (on top of 9" beige floor tile)	214-3	None Detected	Room 4 Northwest corner				
9 inch beige floor tile with black mastic	214-4	8% chrysotile-tile <1% chrysotile-mastic	Room 3 Northeast	Rooms 1,2,3,4 (under carpet and under 12	4,000 sq.:	t. no	no
9 inch beige floor tile with black mastic	214-5	8% chrysotile-tile <1% chrysotile-mastic	Room 3 Southeast	inch It. grey floor tile with leveling compound)			
9 inch beige floor tile with black mastic	214-6	8% chrysotile-tile <1% chrysotile-mastic	Room 3 Northwest				
12 inch light blue floor tile patchwork with yellow adhesive	214-7	None Detected	Room 3 North center	Room 3	6 sq.:	t. no	no
12 inch light blue floor tile patchwork with yellow adhesive	214-8	None Detected	Room 3 North center				
12 inch light blue floor tile patchwork with yellow adhesive	214-9	None Detected	Room 3 North center				

4 inch grey covebase with adhesive	214-10	None Detected	Room 2 Southwest corner	Rooms 1,2,3,4	300 In.ft.	no	no
4 inch grey covebase with adhesive	214-11	None Detected	Room 3 southwest corner	Rooms 1,2,3,5			
4 inch grey covebase with adhesive	214-12	None Detected	Room 4 West center	Rooms 1,2,3,6			
4 inch dark blue covebase with adhesive	214-13	None Detected	Room 2 East center	Rooms 1,2,3,4	300 In.ft.	no	no
4 inch dark blue covebase with adhesive	214-14	None Detected	Room 3 East center				
4 inch dark blue covebase with adhesive	214-15	None Detected	Room 4 East center				
Yellow adhesive with dark grey carpet (on top of 9 inch beige floor tile)	214-16	None Detected	Room 2 East center	Rooms 1,2,3,4	2,800 sq.ft.	no	no
Yellow adhesive with dark grey carpet (on top of 9 inch beige floor tile)	214-17	None Detected	Room 3 East center				
Yellow adhesive with dark grey carpet (on top of 9 inch beige floor tile)	214-18	None Detected	Room 4 East center				



170

Client:	SMMUSD - Wobster	52	Technician:	Fabian Ruvalcaba	
Project No.:			Date:	9/27/16	
Project Name:			Page:	(2
		2-DAUS 17 18.19.20	-(R)		

Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	ND	Glanda Block Covebage and	170-1	1879 18 N C/T	Room 18	500 viver	N	W
		0000102	-2	NE				
	130%	J J	-3	J NW	7	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	d	6
(1625718-09)	117 Ad	yellow mastle	- 4	17 N CF	ta loon, 17, 18, 17, 20	1300 59ft	N	N
	ND	advieste av	-5	18 E C/T				
			-6	20 C/T	V		1	4
	323	Fit with yellow ucheste	-7	19 W 41	17/19,20	1200 SCT	N	W
(1625715-016)	CII, M	udres 12	-8	17 NW				
	AN		-9	LONW	1			1
	Sy. 4	12x12 Davk Booch 15.7 outn Brock	- 10	·NW	19	55 FA	N	N
	51.1	uask	- (1	.w c/i			1	
	37I		-12	SW	V	1	1	1
	10% - T	9×9 Beise Fit. with Bluck	(3	19 NE	Rooms 17,18,19,20 under carpets and tile sections	4,000 39 ft	M	N
	<17. T ND-M	wastc	(4	18 E C/E				
	870-H		15	20 017				1



SMMUSD

Client:

11-

Asbestos Field Bulk Sample List

Technician: Fabian Ruvalcaba

Project No					Date: 9/26/	/ (6		
Project Na		Webster ES			/2 Page: /		2	
			Roo	m 11 812	(8)			
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	77T 874	9x4 Dark grey F.T W/ Black anastic	11-1 00	Rosa 12A NCU	Room 12 A, Room 11 A	200 5464	N	>
	77. T)	11-2	Nooa 12H SW Corner			1	
	370- 74	1	11-3	Room 11A Nu		1	1	1
	270-14	12×12 LTBlue Speckled F.T W/	11-4	Room 12 SW	Room 12, Room 11	1500	N	W
	NP	plack advestic	11-5 •	Room 12 NE				
	1		(1-6 •	Rosall SE		e e	1	1
	ND	yellow felies was	11-7	Room 12 NW	and Room 12 stouge, Room	500 5964	W	W
		(oupet votter	11-8 •	Room (2 SE coone			1	1
		8 fact maste	(1-9	Rosen 11 NE		1		1
		4 man Block grey	11-10-	Room/Z Scu	Room (2 1 Room 1)	200	W	W
		adues 1 re	11-14	ROOM/2 GCT		14		1
			1-12	Rosaill SE			1	1
		covebose as	-13.	Room 12 Sw (ovner		200 1100 H	N	W
i		adusta	-14 -	Room 12 ECT		1		1
	1		1-15.	Room 11 SE				



13A-

	^=	Asbestos Field Bulk Sample List				1. 1
Client:	SMMUSD - Websler	E.S.	Tech	nician:	Fabian Ruvalcaba	AN
Project No.:	2900			Date:	9/27/16	
Project Name:		(C		Page:		_ 2_

Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	Nis	F.T with Kellow q	134 1	R413 WC/T	Res 13,19,15,16	34.64 1600	N	W
		advestue & Black vestidual masile	1 2	Room 15 WC/T				
		J	3	Reson 16 CV C/T	★ ★ ★ ★		Y	4
		user corebase	14	RM 13 W C/T	+ 16A	500 Uneatt		
			5	RIN 15 W C/T				
		1	5	RM 16 SW rover	V			
		4" Blue coverse	7	Reng 13 Surcoce	Rus 13,14,15,16			
			9	RM 15 EC/T				
		V	9	RM16 E C/T		1		
		Yellow waster w/ dark given ! capet tot	10	RM 14 C/T		2,600 5984		
		Black Try Gen (1)	11	RM 15 E CT				
	/	1= Town Black	12	RM 16 EC/T	1			
	876-4	9x9 Belsh F.T With Blackmaste	13	Parls E C/T	under corpet and He	4,500 5-70+		
	86-1 271-4		19	NÉTOLEN				
	86-1 Do.M	J	15	PORIGE EST		2	1	



Client:	SMI	muso - webst	W 85		Technician: Fabian Ruva Date: 9/	caba /A, v.	7	
Project No					Date: 9/	27/16		
Project Na					(C) Page: Z	2	_	
7 70		y	Room.	6.100			Per 12-11-1	
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	ND	rellow ones He with dark Brown	134-16	IZA CIT	16A	500	M	Y
		Spedded copet over tens says 12x12 Besse	17	SW				1
	/	F.T	18	NW			J	1
	157 - 4 1 Si. 4	lexiz Belse	19	NW			N	N
		Fit with Block naght	20	clī			1	
	1	1	V 21	SW				
								T
			· · · · · · · · · · · · · · · · · · ·					
							-	+
								1



MA- Jewand

			-	spesies i leid baik od		1 4	2	
Client:		MUSD			Technician: Fabian Ruvalcal	a / A	V	
Project No).: <u> </u>	Webster &	- 6282	- >	() Date: 9/26/6			
Project Na	me:	Webster &	25.		Page: 1	1		
				mala adulu of	lce (B)			9
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	ND	12x12 Lt grey Speckled Fit our	MA-1	40667 C/T	Haller of	1,000	N	N
		relicu nosti	-2	Now office with	}		1	
	X	Black usidual chestic	-3	Nurse office Now Corner	V		J	1
	2/6-M	9×9 Dewle Boown	-4	NW comer	gener voon	3961	W	3
	8% - M	maste	-5	NE				
	8%-T	J	-6	Sw J	V			1
-	NP	(ove base W/)	-7	HEAC voom on Hallvog	through out Builden	700 Please	N	W
		adnestve	-8	Su course of body			1	
		\downarrow	- 9	Principal office SEcounce		V	1	
21	No GUA	yellow advester with down Blue	-10	Principal Officia	Lobby, Princepal office	700 5/14	N	W
	ND	corpet with	-11	principal office St comer			1	
	1	Block mostle /	-12	10007 center				1
							,	. +
1	1	I .	N. Carlotte	1			-	1





Client:	SMMUSD - Webstel E.S.		Technician:	Fabian Ruvalcaba	/A.V
Project No.:			Date:	9/26/16	
Project Name:	Webster E.S	(E)	Page:	1	2

Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	NP	yellow mathe with dark Blue,	L7-1	S CIT L'overy	Library & Procest.	3200 59 F+	N	~
		Coupet	L7-Z	NEcoma L'bren			1	
	,	1	L7-3	SW corne Library			J	
	870cm	Plack mostic with Davic guey coppet	L7-4	C/T	6+ room B.	150 85ft	N	N
	211-4' ND-C) ,	L7-5	NE				
	210.4 NO-C	I	L7-6	SĒ	\	1		1
	ND	4" Nauk Blue cove base w/ adhes luc	L7-7	NW cone	Å	18 cm et	N	Y
		1	1-8	W/ct				Ш
	1		-9	SW corner			V	4
	370.4	FIT - MESTE	-10	L'6ver voon 8 C/T	bibuay A, 8	350 37 ft	N	N
	NO-T ND-44		-11	Library voom A SW		1		1
	1	V	-(2	L'overy voon & SE	V	1		1
	ND	Here Dut Block Covebuse Wadhest	-13	Library A SW	Library. Library A, Library Com	GOO (I went	N	W
=			-14	616 very SW coner			1)	
			1-15	Libray Nasconor				1



Client:

SMMUSD - Nebster 2.5

Technician: Fabian Ruvalcaba

Project Na	ne:			Libra, & R	00 on 7 Page: 2	Access (Access	2	
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	NP	12K1ZLTBlue 1=T- with yellow adnesh	L7-16	Librar C NE conu	L'Ovay C, R	640 35 Et	N	W
			-17	Library (SEromer			1	1
			1-18	Library C by door of Storage			V	1
		12x12 LT Blue F.T with Blackmentic	-17	Food Swower	Room 7	260 5961	W	u
			-20	welt			11	
			1-21	NWconer	+		1	
		Bluek muster W/ Druk Blue cupet	1-22	Suconer		770 5464	N	W
		\	-23	wclt		1		
	Y	1	1-24	ww comer	V			1
							-	-
							-	-
						-	-	-
-								_
			***************************************				+-	+



810

Client:	SMMUSD-Webster Es.	Technician:	Fabian Ruvalcaba	1. V.
Project No.:	H 4 - 4 - 4	Date:	9/27/16	
Project Name:		Page:		2
	Room 8,9,10 /			

Homogenous	Photo		Roo			Est.	r -	
#	#	Material	Sample #	Sample Location	Material Location	Qty.	F	D
	ND	12x12 Liguer speaked	810-1	Room 8 WC/T	Room 8,9,10	59CH	N	N
		adhesive on on top of 9 kg Gelse F.T	- 2	Room9 W4T			1	
		J	1-3	Room 10 WYT	4	V		
		4" grey courbuse outh advestive	1-q	Por 8 NW Course		300 1100 (+		
5			-5	Roya Scrome				
		J	-6	Roy 10 Sw cover				
		4" Blue coveloose	-7	Per 8 Su cover				
			-8	RM9 NUT				
	1		-9	RM (0 5 c/T	4	1		
NA.	262-T NP-M	9x9 Belge Fi W/ Bluck mushe	-10	Kong Sw cole	+ underector coupert and IFT	3,300 596t		
			1-11	and Not				
	2011-T		1-12	RM 10 # C/7		1		
	NP	rellow mostic us donk green capet only	- 13	Raya sw	200m 9,10	1280 5964		
		gry Beise F.T	1-14	Rrag NC/T				
			1-15	4910 C/T		1.1		J



L

Project Na	me:	erita i due i	(al	eterlar, Staze, 1081	felien (G) Page:	E	2	Ā.
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	270-T ND-41	12 " white wit.	C-1	Cefetora-NCJ	Calcher	4000 Saft	N	W
	270-T ND-M	Fiti Waste	~-2	- N/W		1		1
	271- T NO-4	d	-3	d -ct	V	V	Ą	
	ND	Speck f.T.	4	cutetra.a-NE	Cafetra Patch wak	200	2	0
	- 1	works	5	- Ez+			(1
			6	d -5/E	d-	+	-	-
	-	ig " block lands	7	Caheters - No	caretora furognous Buildly	2,500 8ft	~	~
*		ſ	8	1 - w/cx			,	
		A	9	- 5/ch	4	7	5	-
		izinch Bedse woth	10	N C/7	under carpet in 10000 e	400 5784	N	Y
		w yellow adagha	11	NÈ correr			1	
	1		V 12	NW COVER	V	V	J	T
	771.7	9×9 Brown F.T with Black mistal	13	Jaullors closet	· Jan Govs closel - Food storge, closet, speech under carpet	450 Sg f+	N	Y
=	770-T <1-M		14	Speech under blue cape				
	81,-T		15	Food storge	residual mostic present on shouse I			U



Client:

SMMUSD - Websta es

Technician: Fabian Ruvalcaba

Project No.					Date: 9/26	16	1155	-
Project Na	me:		Cape	,	Page:	1 15 17 15 15 15 15 15 15 15 15 15 15 15 15 15	2	2
Homogenous #	Photo	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	MD	Belse sheet Vlugi	C-16	Kotchen NECT	kofcuen	600 5964	N	W
			C-17	Nu			= (
		L	C-18	VNE	V E= E	U	1	
	Y	12x12 Donkgue	C-19	NE couver	Storege	53 tt	1	W
								5
								5
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				#		
								+
	N							= 1
					Total Page Sign		 	+
					telline and property of			
	7							
المراجع المارية						6		



Client:

Asbestos Field Bulk Sample List

Technician: Fabian Ruvalcaba

Project No	.:	4 S.			Date: 9/27/(6) Page: 1			
Project Na	me:	. * 5	0		Page: 1		<u> </u>	p-2-000
Homogenous #	Photo	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	NP	12x12 in grey E.T with waste levelly	234 - 1	NC/T of Ronz	Room 1, 2, 3, 4	1100	N	N
		On 9x4 Betze F.T with blueknowth	1-2	NCT OF ROM 3				
	1	V	V -3	NW of Rm 4	1		1	
	87: - J 4 - M	9K9 Besse F.T w/ Black was No	-4	NE OF RM3	Room 1.2,34 under copet 2 under 12x12 ct grey F. Faller levelly	4,000 Sq.Et	N	N
			-5	SEOF ROY3				
	1	V	1 -6	NED OF RM3	↓	1	1	1
-	NP	12x12 ct flue F.T Palchuox k cu/ 7	-7	ROWS NCT	Room 3	63964	N	N
		xellow advestu	1 -8					\coprod
)	-9					101
		4" Grey coveringe	10	SW corner of 12rg Z	Room 1, 2, 3, 4	300 Nucert	N	a
			11 11	SW comer de RM3		11	1	
			12	W C/TOF RM4	1		2	1
		covebuse up	13	Ecli of RMZ		300 Freeze	N	a
		adhesive	14	EUT of RM3				1
			10	EUT of RM4			t	1



Client: Project No Project Na	# (A) (A)	MUSD -WOBS			Technician: Fabian Ruvalcal Date: 9/27//6 Page: 2		2	
Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	WD	Wellow odnesial	234-16	RMZ EC/T	Room 1, 2, 31 4	2800 Ser .	N	a
		carpet with 9×9 Beje F.T	117	RM3 ECT				
	1	indenicator)	18	RM4 EC/T		k		1
	l							
	•							



Client:	SMMUSD - Wobslar EC.	Technician:	Fabian Ruvalcaba	
Project No.:		Date:	9/27/16	
Project Name:	1.1. 1.1. 1.1. 1.1. 1.1. 1.1. 1.1. 1.1	Page:	2	2
		(A)		

Homogenous #	Photo #	Material	Sample #	Sample Location	Material Location	Est. Qty.	F	D
	h'b	rovebuje with	170- (6	20 FW	17-18,19,20	400 Mento	N	N
			1 (7	20 NW .17 NW 17 NC/T			1	
		4	18	.17 NW	*	U		V
		y mel Blue corebage with	19	17 NCG	17	How H	N	N
		odiestie	20	28 SW		<u> </u>		
	Y		V 2(ZO NW	V			1
								
								Ī
		0.08 1						=

Appendix B

Laboratory Analytical Report: Asbestos



10/11/2016

10/17/2016

10/17/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625831

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/30/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 2

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report						
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625831-001 1625715-007 (170 4A) 1000 pt. POINT CO	Webster Elementary School O- Adhesive, Black/ Yellow, Non- homogeneous UNT	LAYER 1 100%	Organic Material Non-Asbestos Residue	49.30% 50.40%	Chrysotile	0.30%
Asbestos Present: Yes		Total % Non-Asbestos:		99.7% Tot	al %Asbestos:	0.30%
1625831-002 1625715-016 (170 8B) 1000 pt. POINT CO	Webster Elementary School O- Adhesive, Black/ Yellow, Non- homogeneous UNT	LAYER 1 100%	Organic Material Non-Asbestos Residue	35.04% 64.64%	Chrysotile	0.32%
Asbestos Present: Yes		Total % Non-Asbestos:		99.7% Tot	al %Asbestos:	0.32%

Note: EPA 400 point count extended to 1000 points to meet the Cal OSHA regulatory limit of 0.1%.

Method Detection Limit: One tenth of one percent (0.1%). Asbestos content has been determined using the point count method. Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt

Lab Code 500044-0

PAGE: 1 of 1



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 42

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report						
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625715-001 170-1A	Webster Elementary School 4 inch Covebase, Black,	LAYER 1			None Detected	
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%		
	Asbestos Present: No	Tota	Il % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625715-002	Webster Elementary School					
170-1B	Adhesive, White, Homogeneous	LAYER 1	B'' ' M ' '	400/	None Detected	
		100%	Bituminous Matrix Organic Binders/Filler	40% 60%		
	Asbestos Present: No	Tota	Il % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625715-003	Webster Elementary School					
170-2A	4 inch Covebase, Black,	LAYER 1			None Detected	
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%		
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625715-004	Webster Elementary School					
170-2B	Adhesive, White, Homogeneous	LAYER 1 100%	Organic Rindors/Filler	100%	None Detected	
		100 /6	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	Il % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625715-005	Webster Elementary School					
170-3A	4 inch Covebase, Black,	LAYER 1	Oalahan Oal	050/	None Detected	
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%		
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625715-006	Webster Elementary School					
170-3B	Adhesive, White, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 1 of 7



09/30/2016

10/10/2016

10/10/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Sampled 09/27/2016

> Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 42

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

Test Report						
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %		(%)	Asbestos Type	(%)
1625715-007 170-4A	Webster Elementary School Adhesive, Black/ Yellow, Non- homogeneous	LAYER 1 100%	Synthetic Fiber Bituminous Matrix Organic Binders/Filler	<1% 30% 70%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	Il % Non-Asbestos:	100.0% T c	<1%	
1625715-008 170-4B	Webster Elementary School Carpet, Gray, Non-homogeneous	100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected
1625715-009 170-5A	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Synthetic Fiber Organic Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected
1625715-010 170-5B	Webster Elementary School Carpet, Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected
1625715-011 170-6A	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Synthetic Fiber Organic Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected
1625715-012 170-6B	Webster Elementary School Carpet, Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected

PAGE: 2 of



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 42

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)
1625715-013 170-7A	Webster Elementary School 12x12 FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625715-014 170-7B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625715-015 170-8A	Webster Elementary School 12x12 FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625715-016 170-8B	Webster Elementary School Adhesive, Yellow/ Black, Non- homogeneous	LAYER 1 100%	Cellulose Fiber Bituminous Matrix Organic Binders/Filler	<1% 70% 30%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	<1%
1625715-017 170-9A	Webster Elementary School 12x12 FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625715-018 170-9B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected

PAGE: 3 of 7



10/10/2016

10/10/2016

Alta Environmental

Date Received

Date Analyzed

Date Reported

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 42

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625715-019 170-10A	Webster Elementary School 12x12 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 45%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	I % Non-Asbestos:	100.0% Tota	l %Asbestos:	<1%
1625715-020 170-10B	Webster Elementary School Mastic, Black/ Brown, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	80% 15%	Chrysotile	5%
	Asbestos Present: Yes	Tota	Il % Non-Asbestos:	95.0% Tota	l %Asbestos:	5.0%
1625715-021 170-11A	Webster Elementary School 12x12 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 45%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	ıl % Non-Asbestos:	100.0% Tota	l %Asbestos:	<1%
1625715-022 170-11B	Webster Elementary School Mastic, Black/ Brown, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	80% 15%	Chrysotile	5%
	Asbestos Present: Yes	Tota	ıl % Non-Asbestos:	95.0% Tota	l %Asbestos:	5.0%
1625715-023 170-12A	Webster Elementary School 12x12 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 45%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	Il % Non-Asbestos:	100.0% Tota	l %Asbestos:	<1%
1625715-024 170-12B	Webster Elementary School Mastic, Black/ Brown, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	77% 20%	Chrysotile	3%
	Asbestos Present: Yes	Tota	I % Non-Asbestos:	97.0% Tota	l %Asbestos:	3.0%
1625715-025 170-13A	Webster Elementary School 9x9 FT, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 50%	Chrysotile	10%
	Asbestos Present: Yes	Tota	ıl % Non-Asbestos:	90.0% Tota	l %Asbestos:	10.0%

PAGE: 4 of



10/10/2016

10/10/2016

Alta Environmental

Date Received

Date Analyzed

Date Reported

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Sampled 09/27/2016

Fabian Ruvalcaba, Anthony Vice Sampled By

Total Samples 42

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

Test Report							
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)	
1625715-026 170-13B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100% E	Bituminous Matrix	90%	Chrysotile	10%	
	Asbestos Present: Yes	Total	% Non-Asbestos:	90.0% 7	otal %Asbestos:	10.0%	
1625715-027 170-14A	Webster Elementary School 9x9 FT, Beige, Homogeneous		Calcium Carbonate /inyl Binder	60% 40%	Chrysotile	<1%	
	Asbestos Present: Yes	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	<1%	
1625715-028 170-14B	Webster Elementary School Mastic, Yellow, Homogeneous Note: No black mastic present.		Bituminous Matrix Drganic Binders/Filler	5% 95%	None Detected		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected	
1625715-029 170-15A	Webster Elementary School 9x9 FT, Beige, Homogeneous		Calcium Carbonate /inyl Binder	60% 40%	Chrysotile	<1%	
	Asbestos Present: Yes	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	<1%	
1625715-030 170-15B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100% E	Bituminous Matrix	92%	Chrysotile	8%	
	Asbestos Present: Yes	Total	% Non-Asbestos:	92.0% T	otal %Asbestos:	8.0%	
1625715-031 170-16A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous		Calcium Carbonate /inyl Binder	35% 65%	None Detected		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected	
1625715-032 170-16B	Webster Elementary School Adhesive, White/ Brown, Non- homogeneous		Vollastonite Drganic Binders/Filler	2% 98%	None Detected		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected	

PAGE: 5 of



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 **Total Samples** 42

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

Test Report							
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)	
1625715-033	Webster Elementary School						
170-17A	4 inch Covebase, Gray,	LAYER 1			None Detected		
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected	
1625715-034	Webster Elementary School						
170-17B	Adhesive, Cream/Brown, Non-homogeneous	LAYER 1 100%	Wollastonite Organic Binders/Filler	5% 95%	None Detected		
	Asbestos Present: No	Total % Non-Asbestos:		100.0% To	No Asbestos Detected		
1625715-035	Webster Elementary School						
170-18A	4 inch Covebase, Gray,	LAYER 1			None Detected		
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% To	tal %Asbestos:	No Asbestos Detected	
1625715-036	Webster Elementary School						
170-18B	Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Total %Asbestos:		No Asbestos Detected	
1625715-037	Webster Elementary School						
170-19A	4 inch Covebase, Blue,	LAYER 1	\"	10001	None Detected		
	Homogeneous	100%	Vinyl Binder/ Filler	100%			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected	
1625715-038	Webster Elementary School						
170-19B	Adhesive, White, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
Asbestos Present: No			Total % Non-Asbestos:		otal %Asbestos:	No Asbestos Detected	

PAGE: 6 of



10/10/2016

10/10/2016

3777 Long Beach Blvd.

Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625715

Date Received

Date Analyzed

Date Reported

Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

1508 East 33rd Street

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

09/27/2016 **Date Sampled**

Fabian Ruvalcaba, Anthony Vice Sampled By

Total Samples

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

		Test Re	eport			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625715-039 170-20A	Webster Elementary School 4 inch Covebase, Blue, Homogeneous	LAYER 1 100% V	/inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To 1	tal %Asbestos:	No Asbestos Detected
1625715-040 170-20B	Webster Elementary School Adhesive, Tan, Homogeneous	LAYER 1 100% C	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	tal %Asbestos:	No Asbestos Detected
1625715-041 170-21A	Webster Elementary School 4 inch Covebase, Blue, Homogeneous	LAYER 1 100% V	/inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	tal %Asbestos:	No Asbestos Detected
1625715-042 170-21B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100% C	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	tal %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Cristina Tabatt

Approved Signatory Cristina E. Tabatt

Lab Code 500044-0

PAGE: 7 of



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625711

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 33

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625711-001 11-1A	Webster Elementary School 9 inch FT, Dk. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 58%	Chrysotile	7%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	93.0% Tota	l %Asbestos:	7.0%
1625711-002 11-1B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	92%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% Tota	l %Asbestos:	8.0%
1625711-003 11-2A	Webster Elementary School 9 inch FT, Dk. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 58%	Chrysotile	7%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	93.0% Tota	l %Asbestos:	7.0%
1625711-004 11-2B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	90%	Chrysotile	10%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	90.0% Tota	l %Asbestos:	10.0%
1625711-005 11-3A	Webster Elementary School 9 inch FT, Dk. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 58%	Chrysotile	7%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	93.0% Tota	l %Asbestos:	7.0%
1625711-006 11-3B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	92%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% Tota	l %Asbestos:	8.0%
625711-007 11-4A	Webster Elementary School 12 inch Speckled FT, Lt. Blue (Lt. Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected

PAGE: 1 of 5



10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625711

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 33

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625711-008 11-4B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix/Filler	98%	Chrysotile	2%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%		
1625711-009 11-5A	Webster Elementary School 12 inch Speckled FT, Lt. Blue (Lt. Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625711-010 11-5B	Webster Elementary School Mastic, Note: No Mastic Present	LAYER 1 100%						
1625711-011 11-6A	Webster Elementary School 12 inch Speckled FT, Lt. Blue (Lt. Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		
1625711-012 11-6B	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625711-013 11-7A	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625711-014	Webster Elementary School							
11-7B	Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		

PAGE: 2 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625711

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 33

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report							
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)	
1625711-015 11-7C	Webster Elementary School Residual Mastic, Note: No residual black mastic present.	LAYER 1 100%					
1625711-016 11-8A	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected	
1625711-017 11-8B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected	
1625711-018 11-8C	Webster Elementary School Residual Mastic, Note: No residual mastic present.	LAYER 1 100%					
1625711-019 11-9A	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected	
1625711-020 11-9B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	40% 60%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected	
1625711-021 11-9C	Webster Elementary School Residual Mastic, Note: No residual mastic present.	LAYER 1 100%					

PAGE: 3 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625711

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 3

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

<u></u>		Test Report		
Laboratory ID Sample No.	Sample Location Description	Layer No. Non-Asbestos Layer % Components	Asbestos (%) Type	(%)
1625711-022 11-10A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100% Vinyl Binder/ Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-023 11-10B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100% Organic Binders/Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-024 11-11A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100% Vinyl Binder/ Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-025 11-11B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100% Organic Binders/Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-026 11-12A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100% Vinyl Binder/ Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-027 11-12B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100% Organic Binders/Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected
1625711-028 11-13A	Webster Elementary School 4 inch Covebase, Dk. Blue, Homogeneous	LAYER 1 100% Vinyl Binder/ Filler	None Detected 100%	
	Asbestos Present: No	Total % Non-Asbestos:	100.0% Total %Asbestos:	No Asbestos Detected

PAGE: 4 of 5



Alta Environmental

3777 Long Beach Blvd.

Long Beach CA 90807

Report Number 1625711

Date Received

Attn.: Cesar Ruvalcaba

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Date Analyzed 10/07/2016 **Sampled By** Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 33

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test Re	eport			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625711-029 11-13B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100% C	organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected
1625711-030 11-14A	Webster Elementary School 4 inch Covebase, Dk. Blue, Homogeneous	LAYER 1 100% V	inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected
1625711-031 11-14B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100% C	organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Tot	al %Asbestos:	No Asbestos Detected
1625711-032 11-15A	Webster Elementary School 4 inch Covebase, Dk. Blue, Homogeneous	LAYER 1 100% V	inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected
1625711-033 11-15B	Webster Elementary School Adhesive, White/Brown, Non- homogeneous	LAYER 1 100% C	organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt



PAGE: 5 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test R	eport			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625714-001 13A-1A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous		Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625714-002 13A-1B	Webster Elementary School Mastic, Black/Yellow, Non- homogeneous		Bituminous Matrix Organic Binders/Filler	85% 15%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625714-003 13A-2A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous		Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625714-004 13A-2B	Webster Elementary School Mastic, Black/ Yellow, Non- homogeneous	100% E	Wood Fiber Bituminous Matrix Organic Binders/Filler	15% 65% 20%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625714-005 13A-3A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous		Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625714-006 13A-3B	Webster Elementary School Mastic, Yellow, Homogeneous Note: No black mastic present.	LAYER 1 100% (Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 1 of 7



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report							
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)	
1625714-007 13A-4A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected	
1625714-008 13A-4B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected	
1625714-009 13A-5A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected	
1625714-010 13A-5B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected	
1625714-011 13A-6A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected		
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected	
1625714-012 13A-6B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected	

PAGE: 2 of 7



10/10/2016

10/10/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report						
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625714-013 13A-7A	Webster Elementary School 4 inch Covebase, Blue, Homogeneous	LAYER 1 100% V	'inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected
1625714-014 13A-7B	Webster Elementary School Adhesive, White/ Brown, Non- homogeneous	LAYER 1	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No		% Non-Asbestos:		al %Asbestos:	No Asbestos Detected
1625714-015 13A-8A	Webster Elementary School 4 inch Covebase, Blue, Homogeneous	LAYER 1 100% V	/inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected
1625714-016 13A-8B	Webster Elementary School Adhesive, White, Homogeneous	LAYER 1 100% C	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected
1625714-017 13A-9A	Webster Elementary School 4 inch Covebase, Blue, Homogeneous	LAYER 1 100% V	/inyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected
1625714-018 13A-9B	Webster Elementary School Adhesive, White/ Brown, Homogeneous	LAYER 1 100% C	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected
1625714-019	Webster Elementary School					
13A-10A	Mastic, Yellow, Homogeneous	LAYER 1 100% C	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% Tot a	al %Asbestos:	No Asbestos Detected

PAGE: 3 of 7



10/10/2016

10/10/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625714-020 13A-10B	Webster Elementary School Carpet on 9x9 Beige FT, Gray, Homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-021 13A-11A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-022 13A-11B	Webster Elementary School Carpet on 9x9 Beige FT, Gray, Homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-023 13A-12A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-024 13A-12B	Webster Elementary School Carpet on 9x9 Beige FT, Gray, Homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-025 13A-13A	Webster Elementary School 9x9 FT, Beige (Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T	otal %Asbestos:	8.0%		
1625714-026 13A-13B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	97%	Chrysotile	3%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	97.0% T	otal %Asbestos:	3.0%		

PAGE: 4 of 7



10/10/2016

10/10/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)			
1625714-027 13A-14A	Webster Elementary School 9x9 FT, Beige (Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T	otal %Asbestos:	8.0%			
1625714-028 13A-14B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	98%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%			
1625714-029 13A-15A	Webster Elementary School 9x9 FT, Beige (Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T	otal %Asbestos:	8.0%			
1625714-030 13A-15B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	97%	Chrysotile	3%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	97.0% T	otal %Asbestos:	3.0%			
1625714-031 13A-16A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625714-032 13A-16B	Webster Elementary School Carpet, Black/Beige, Non- homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625714-033 13A-17A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Synthetic Fiber Organic Binders/Filler	<1% 100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			

PAGE: 5 of 7



10/10/2016

10/10/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625714

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625714-034 13A-17B	Webster Elementary School Carpet, Black/Beige, Non-		Synthetic Fiber	60%	None Detected			
	homogeneous Asbestos Present: No	100% Tota	Binder/Filler	40% 100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-035 13A-18A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Synthetic Fiber Organic Binders/Filler	2% 98%	None Detected			
	Asbestos Present: No	Tota	il % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-036 13A-18B	Webster Elementary School Carpet, Black/Gray, Non- homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected			
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625714-037 13A-19B	Webster Elementary School 12x12 FT, Beige (Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 45%	Chrysotile	15%		
	Asbestos Present: Yes	Tota	Il % Non-Asbestos:	85.0% T	otal %Asbestos:	15.0%		
1625714-038 13A-19B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	95%	Chrysotile	5%		
	Asbestos Present: Yes	Tota	Il % Non-Asbestos:	95.0% T	otal %Asbestos:	5.0%		
1625714-039 13A-20A	Webster Elementary School 12x12 FT, Beige (Gray), Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 45%	Chrysotile	15%		
	Asbestos Present: Yes	Tota	ıl % Non-Asbestos:	85.0% T	otal %Asbestos:	15.0%		
1625714-040 13A-20B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	95%	Chrysotile	5%		
	Asbestos Present: Yes	Tota	ıl % Non-Asbestos:	95.0% T	otal %Asbestos:	5.0%		

PAGE: 6 of



Alta Environmental 3777 Long Beach Blvd. Long Beach CA 90807 Attn.: Cesar Ruvalcaba

Report Number 1625714

09/30/2016 **Date Received**

Date Reported 10/10/2016

10/10/2016 **Date Analyzed**

Method of Analysis

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

1508 East 33rd Street Signal Hill, CA 90755

Toll: 888-207-2022

Tel: 562-206-2770 Fax: 562-206-2773

PO Number WO Number

09/27/2016 **Date Sampled**

Fabian Ruvalcaba, Anthony Vice Sampled By

Total Samples

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test R	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625714-041 13A-21A	Webster Elementary School 12x12 FT, Beige (Gray),	LAYER 1			Chrysotile	15%
	Homogeneous		Calcium Carbonate Vinyl Binder	40% 45%		
	Asbestos Present: Yes	Tota	I % Non-Asbestos:	85.0% To	tal %Asbestos:	15.0%
1625714-042 13A-21B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	95%	Chrysotile	5%
	Asbestos Present: Yes	Tota	I % Non-Asbestos:	95.0% To	tal %Asbestos:	5.0%

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt

Lab Code 500044-0

PAGE: 7 of



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625708

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %		(%)	Asbestos Type	(%)
1625708-001	Webster Elementary School					
MA-1A	12x12 Speckled FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-002	Webster Elementary School					
MA-1B	Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-003	Webster Elementary School					
MA-1C	Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-004	Webster Elementary School					
MA-2A	12x12 Speckled FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-005	Webster Elementary School					
MA-2B	Mastic, Gray, Homogeneous Note: No black residual mastic	LAYER 1 100%	Synthetic Fiber Organic Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-006	Webster Elementary School					
MA-2C	Mastic, Yellow, Homogeneous	LAYER 1 100%	Cellulose Fiber Organic Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected

PAGE: 1 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625708

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625708-007 MA-3A	Webster Elementary School 12x12 Speckled FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected		
1625708-008 MA-3B	Webster Elementary School Mastic, Gray, Homogeneous Note: No black residual mastic.	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected		
1625708-009 MA-3C	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	No Asbestos Detected		
1625708-010 MA-4A	Webster Elementary School 9x9 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T c	otal %Asbestos:	8.0%		
1625708-011 MA-4B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	98%	Chrysotile	2%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% Tc	otal %Asbestos:	2.0%		
1625708-012 MA-5A	Webster Elementary School 9x9 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% Tc	otal %Asbestos:	8.0%		
1625708-013 MA-5B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	97%	Chrysotile	3%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	97.0% Tc	otal %Asbestos:	3.0%		

PAGE: 2 of 5



10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625708

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	•	(%)	Asbestos Type	(%)			
1625708-014 MA-6A	Webster Elementary School 9x9 FT, Dk. Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0%	Γotal %Asbestos:	8.0%			
1625708-015 MA-6B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix/Filler	97%	Chrysotile	3%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	97.0%	Γotal %Asbestos:	3.0%			
1625708-016 MA-7A	Webster Elementary School 4 inch Covebase, Dk. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625708-017 MA-7B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625708-018 MA-8A	Webster Elementary School 4 inch Covebase, Dk. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625708-019 MA-8B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			

PAGE: 3 of 5



10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625708

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	•	(%)	Asbestos Type	(%)
1625708-020	Webster Elementary School					
MA-9A	4 inch Covebase, Black,	LAYER 1			None Detected	
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	35% 65%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected
1625708-021	Webster Elementary School					
MA-9B	Adhesive, Cream, Homogeneous	LAYER 1			None Detected	
		100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625708-022	Webster Elementary School					
MA-10A	Carpet, Black, Homogeneous	LAYER 1 100%	Synthetic Fiber	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625708-023	Webster Elementary School					
MA-10B	Adhesive, Yellow, Homogeneous	LAYER 1			None Detected	
		100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625708-024	Webster Elementary School					
MA-10C	Mastic, Black, Homogeneous	LAYER 1			Chrysotile	2%
		100%	Bituminous Matrix Organic Binders/Filler	40% 58%		
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%
1625708-025	Webster Elementary School					
MA-11A	Carpet, Black/Purple, Non-	LAYER 1	Synthetic Fiber	85%	None Detected	
	homogeneous	100%	Binder/Filler	15%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 4 of 5



3777 Long Beach Blvd.

Long Beach CA 90807

Report Number 1625708

Attn.: Cesar Ruvalcaba

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test R	eport			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625708-026 MA-11B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100% (Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-027 MA-11C	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100% (Organic Binders	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-028 MA-12A	Webster Elementary School Carpet, Black/Purple, Non- homogeneous		Synthetic Fiber Binder/Filler	85% 15%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-029 MA-12B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100% (Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625708-030 MA-12C	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100% (Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

CNITMA 21 ato

Approved Signatory Cristina E. Tabatt



PAGE: 5 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)				
1625710-001 L7-1A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-002 L7-1B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous		Synthetic Fiber Polystyrene Foam	60% 40%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-003 L7-2A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-004 L7-2B	Webster Elementary School Carpet, Black, Non-homogeneous		Synthetic Fiber Binder/Filler	20% 80%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-005 L7-3A	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-006 L7-3B	Webster Elementary School Carpet, Black, Non-homogeneous		Synthetic Fiber Binder/Filler	5% 95%	None Detected					
	Asbestos Present: No	Total	I % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected				
1625710-007 ₋ 7-4A	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	92%	Chrysotile	8%				
	Asbestos Present: Yes	Tota	I % Non-Asbestos:	92.0% T	otal %Asbestos:	8.0%				

PAGE: 1 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)			
1625710-008 L7-4B	Webster Elementary School Carpet, Dk. Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625710-009 L7-5A	Webster Elementary School Mastic, Yellow/Black, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	40% 58%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% 7	Γotal %Asbestos:	2.0%			
1625710-010 L7-5B	Webster Elementary School Carpet, Dk. Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625710-011 L7-6A	Webster Elementary School Mastic, Black/Yellow, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	50% 48%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% 7	Γotal %Asbestos:	2.0%			
1625710-012 L7-6B	Webster Elementary School Carpet, Dk. Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			
1625710-013 L7-7A	Webster Elementary School 4 inch Covebase, Dk. Blue-Green, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 65%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Γotal %Asbestos:	No Asbestos Detected			

PAGE: 2 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625710-014	Webster Elementary School					
L7-7B	Adhesive, Cream, Homogeneous	LAYER 1	O	1000/	None Detected	
		100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-015	Webster Elementary School					
L7-8A	4 inch Covebase, Dk. Blue-Green, Homogeneous	LAYER 1 100%	Calcium Carbonate	35%	None Detected	
	Homogeneous	100 /6	Vinyl Binder	65%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	otal %Asbestos:	No Asbestos Detected
1625710-016	Webster Elementary School					
L7-8B	Adhesive, Cream, Homogeneous	LAYER 1		4000/	None Detected	
		100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-017	Webster Elementary School					
L7-9A	4 inch Covebase, Dk. Blue-Green,	LAYER 1 100%	Calcium Carbonate	35%	None Detected	
	Homogeneous	100 %	Vinyl Binder	65%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-018	Webster Elementary School					
L7-9B	Adhesive, Cream, Homogeneous	LAYER 1			None Detected	
		100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-019	Webster Elementary School					
L7-10A	12 inch Speckled FT, Lt. Gray,	LAYER 1	Calairus Carbanat	050/	None Detected	
	Homogeneous	100%	Calcium Carbonate Vinyl Binder	65% 35%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 3 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625710-020 L7-10B	Webster Elementary School Mastic, Black/Yellow, Homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	65% 32%	Chrysotile	3%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	97.0% T	otal %Asbestos:	3.0%
1625710-021 L7-11A	Webster Elementary School 12 inch Speckled FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-022 L7-11B	Webster Elementary School Mastic, Yellow/Orange, Non- homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-023 L7-12A	Webster Elementary School 12 inch Speckled FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-024 L7-12B	Webster Elementary School Mastic, Yellow/Orange, Non- homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625710-025 L7-13A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	30% 70%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 4 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)			
1625710-026 L7-13B	Webster Elementary School Adhesive, Beige, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625710-027 L7-14A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	30% 70%	None Detected				
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T o	otal %Asbestos:	No Asbestos Detected			
1625710-028 L7-14B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625710-029 L7-15A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	30% 70%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625710-030 L7-15B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625710-031 L7-16A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected				
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected			

PAGE: 5 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625710-032 L7-16B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625710-033 L7-17A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		
1625710-034 L7-17B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625710-035 L7-18A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625710-036 L7-18B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625710-037 L7-19A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		

PAGE: 6 of 8



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625710

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)			
1625710-038 L7-19B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected			
1625710-039 L7-20A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected			
1625710-040 L7-20B	Webster Elementary School Mastic, Black/ Yellow, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	80% 20%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected			
1625710-041 L7-21A	Webster Elementary School 12 inch FT, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected			
1625710-042 L7-21B	Webster Elementary School Mastic, Black/ Yellow, Non- homogeneous	LAYER 1 100%	Cellulose Fiber Bituminous Matrix Organic Binders	<1% 60% 40%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected			
1625710-043 L7-22A	Webster Elementary School Mastic, Black/Yellow, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders	90% 10%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected			

PAGE: 7 of 8



3777 Long Beach Blvd.

Long Beach CA 90807

Report Number 1625710

Attn.: Cesar Ruvalcaba

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 48

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)
1625710-044 L7-22B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625710-045 L7-23A	Webster Elementary School Mastic, Black/ Yellow, Homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	15% 85%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625710-046 L7-23B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625710-047 L7-24A	Webster Elementary School Mastic, Yellow (Clear), Non- homogeneous	LAYER 1 100%	Cellulose Fiber Synthetic Fiber Organic Binders	<1% <1 100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625710-048 L7-24B	Webster Elementary School Carpet, Dk. Blue, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt





3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625713

Date Received

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 3

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %		(%)	Asbestos Type	(%)		
1625713-001 810-1A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder/ Filler	65% 35%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T (otal %Asbestos:	No Asbestos Detected		
1625713-002	Webster Elementary School							
810-1B	Mastic, Yellow, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625713-003 810-2A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder/ Filler	65% 35%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		
1625713-004 810-2B	Webster Elementary School Adhesive, Yellow, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected		
1625713-005 810-3A	Webster Elementary School 12x12 Speckled FT, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder/ Filler	65% 35%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T (otal %Asbestos:	No Asbestos Detected		
1625713-006	Webster Elementary School							
810-3B	Adhesive, Yellow, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected			
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected		

PAGE: 1 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625713

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)			
1625713-007	Webster Elementary School								
810-4A	4 inch Covebase, Gray,	LAYER 1			None Detected				
	Homogeneous	100%	Calcium Carbonate Vinyl Binder/ Filler	40% 60%					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625713-008	Webster Elementary School								
810-4B	Adhesive, Yellow, Homogeneous	LAYER 1			None Detected				
		100%	Calcium Carbonate Vinyl Binder/ Filler	40% 60%					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625713-009	Webster Elementary School								
810-5A	4 inch Covebase, Gray,	LAYER 1			None Detected				
	Homogeneous	100%	Calcium Carbonate Vinyl Binder/ Filler	40% 60%					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625713-010	Webster Elementary School								
810-5B	Adhesive, Cream, Homogeneous	LAYER 1			None Detected				
		100%	Adhesive Binders/Filler	100%					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625713-011	Webster Elementary School								
810-6A	4 inch Covebase, Gray,	LAYER 1			None Detected				
	Homogeneous	100%	Calcium Carbonate Vinyl Binder/ Filler	40% 60%					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			
1625713-012	Webster Elementary School								
810-6B	Adhesive, Yellow, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			

PAGE: 2 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625713

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)		
1625713-013	Webster Elementary School							
810-7A	4 inch Covebase, Blue,	LAYER 1			None Detected			
	Homogeneous	100%	Calcium Carbonate Vinyl Binder/ Filler	30% 70%				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		
1625713-014	Webster Elementary School							
810-7B	Adhesive, Cream, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected			
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		
1625713-015	Webster Elementary School							
810-8A	4 inch Covebase, Blue,	LAYER 1			None Detected			
	Homogeneous	100%	Calcium Carbonate Vinyl Binder/ Filler	30% 70%				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		
1625713-016	Webster Elementary School							
810-8B	Adhesive, Cream, Homogeneous	LAYER 1			None Detected			
		100%	Adhesive Binders/Filler	100%				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		
1625713-017	Webster Elementary School							
810-9A	4 inch Covebase, Blue,	LAYER 1			None Detected			
	Homogeneous	100%	Vinyl Binder/ Filler	100%				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		
1625713-018	Webster Elementary School							
810-9B	Adhesive, Cream, Homogeneous	LAYER 1 100%	Adhesive Binders/Filler	100%	None Detected			
		100 /0	Addiosive Diliders/1 lile					
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tot	al %Asbestos:	No Asbestos Detected		

PAGE: 3 of 5



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625713

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/10/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 Total Samples 30

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)			
1625713-019 810-10A	Webster Elementary School 9x9 FT, Beige, Homogeneous		Calcium Carbonate Vinyl Binder	35% 45%	Chrysotile	20%			
	Asbestos Present: Yes	Total	% Non-Asbestos:	80.0% To	tal %Asbestos:	20.0%			
1625713-020 810-10B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix/Filler	100%	None Detected				
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected			
1625713-021 810-11A	Webster Elementary School 9x9 FT, Beige, Homogeneous		Calcium Carbonate Vinyl Binder	35% 45%	Chrysotile	20%			
	Asbestos Present: Yes	Total	% Non-Asbestos:	80.0% To	tal %Asbestos:	20.0%			
1625713-022 810-11B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix/Filler	100%	None Detected				
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected			
1625713-023 810-12A	Webster Elementary School 9x9 FT, Beige, Homogeneous		Calcium Carbonate Vinyl Binder	35% 45%	Chrysotile	20%			
	Asbestos Present: Yes	Total	% Non-Asbestos:	80.0% To	tal %Asbestos:	20.0%			
1625713-024 810-12B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	95%	Chrysotile	5%			
	Asbestos Present: Yes	Total	% Non-Asbestos:	95.0% To	tal %Asbestos:	5.0%			
1625713-025 810-13A	Webster Elementary School Mastic, Yellow		Cellulose Fiber Adhesive Binders/Filler	2% 98%	None Detected				
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected			

PAGE: 4 of 5



3777 Long Beach Blvd.

Long Beach CA 90807

Report Number 1625713

Attn.: Cesar Ruvalcaba

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

09/30/2016 09/27/2016 **Date Received Date Sampled**

10/10/2016 **Date Analyzed** Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/10/2016 **Total Samples**

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

		Test R	eport			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625713-026 810-13B	Webster Elementary School Carpet, Gray/Black/White/Yellow, Non-homogeneous		Synthetic Fiber Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625713-027 810-14A	Webster Elementary School Mastic, Yellow, Non-homogeneous		Cellulose Fiber Adhesive Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625713-028 810-14B	Webster Elementary School Carpet, Gray/Black/White/Yellow, Non-homogeneous		Synthetic Fiber Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Total % Non-Asbestos:		100.0% Total %Asbestos:		No Asbestos Detected
1625713-029 810-15A	Webster Elementary School Mastic, Yellow, Non-homogeneous		Cellulose Fiber Adhesive Binders/Filler	<1% 100%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625713-030 810-15B	Webster Elementary School Carpet, Gray/Black/White/Yellow, Non-homogeneous		Synthetic Fiber Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Fred Thappelear

Approved Signatory Cristina E. Tabatt

PAGE: 5 of



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625709

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

	Test Report								
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)			
1625709-001 C-1A	Webster Elementary School 12 inch Speckles FT, White w/ Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 43%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%			
1625709-002 C-1B	Webster Elementary School Mastic, Black/Yellow/Grey, Non- homogeneous Asbestos Present: No	LAYER 1 100%	Organic Binders/Filler	100% 100.0% T	None Detected	No Ashestos			
	76333133 Trademi No	. 010	21 70 11011 7 lob coloc.	•	ota: 707 tobootoo:	Detected			
1625709-003 C-2A	Webster Elementary School 12 inch Speckles FT, White w/ Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 43%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%			
1625709-004 C-2B	Webster Elementary School Mastic, Black/ Brown, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	40% 60%	None Detected				
	Asbestos Present: No	Total % Non-Asbestos:		100.0% T	otal %Asbestos:	No Asbestos Detected			
1625709-005 C-3A	Webster Elementary School 12 inch Speckles FT, White w/ Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	55% 43%	Chrysotile	2%			
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	98.0% T	otal %Asbestos:	2.0%			
1625709-006 C-3B	Webster Elementary School Mastic, Black/ Brown, Non- homogeneous	LAYER 1 100%	Bituminous Matrix Organic Binders/Filler	40% 60%	None Detected				
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected			

PAGE: 1 of 6



3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625709

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test R	eport			
Laboratory ID	Sample Location	Layer No.	Non-Asbestos		Asbestos	
Sample No.	Description	Layer %	Components	(%)	Туре	(%)
1625709-007	Webster Elementary School					
C-4A	12 inch Speckles FT, Brown w/	LAYER 1			None Detected	
0 47 (White, Homogeneous		Calcium Carbonate	60%	Ttorio Botottoa	
	ville, riemegeneeus		Vinyl Binder	40%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-008	Webster Elementary School					
C-4B	Mastic, Black/Gray, Non-	LAYER 1			None Detected	
	homogeneous		Bituminous Matrix Organic Binders/Filler	20% 80%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-009	Webster Elementary School					
C-5A	12 inch Speckles FT, Brown w/	LAYER 1			None Detected	
	White, Homogeneous	100%	Calcium Carbonate	60%		
	-	`	Vermiculite	40%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-010	Webster Elementary School					
C-5B	Mastic, Black/Gray, Non-	LAYER 1			None Detected	
	homogeneous	100% I	Bituminous Matrix	70%		
		(Organic Binders/Filler	30%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-011	Webster Elementary School					
C-6A	12 inch Speckles FT, Brown w/	LAYER 1			None Detected	
	White, Homogeneous		Calcium Carbonate	60%		
		,	Vinyl Binder	40%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-012	Webster Elementary School					
C-6B	Mastic, Black/Gray, Non-	LAYER 1			None Detected	
	homogeneous	100%	Bituminous Matrix	70%		
		(Organic Binders/Filler	30%		
	Asbestos Present: No	Total	% Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 2 of 6



09/30/2016

10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625709

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %		(%)	Asbestos Type	(%)
1625709-013 C-7A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Vinyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Tota	Il % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected
1625709-014 C-7B	Webster Elementary School Adhesive, Brown, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected
1625709-015 C-8A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Vinyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected
1625709-016 C-8B	Webster Elementary School Adhesive, Brown, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected
1625709-017 C-9A	Webster Elementary School 4 inch Covebase, Black, Homogeneous	LAYER 1 100%	Vinyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected
1625709-018 C-9B	Webster Elementary School Adhesive, Brown, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected

PAGE: 3 of 6



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625709

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %		(%)	Asbestos Type	(%)
1625709-019 C-10A	Webster Elementary School 12 inch Speckles FT, Beige w/ Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected
1625709-020	Webster Elementary School					
C-10B	Adhesive, Yellow/Clear, Homogeneous	LAYER 1 100%	Cellulose Fiber Organic Binders	<1% 100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected
1625709-021 C-11A	Webster Elementary School 12 inch Speckles FT, Beige w/ Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	No Asbestos Detected
1625709-022 C-11B	Webster Elementary School Adhesive, Yellow/Clear, Homogeneous	LAYER 1 100%	Cellulose Fiber Organic Binders	<1% 100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	No Asbestos Detected
1625709-023 C-12A	Webster Elementary School 12 inch Speckles FT, Beige w/ Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	No Asbestos Detected
1625709-024	Webster Elementary School					
C-12B	Adhesive, Yellow/Clear, Homogeneous	LAYER 1 100%	Organic Binders	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	No Asbestos Detected

PAGE: 4 of 6



09/30/2016

10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625709

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Sampled 09/26/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625709-025 C-13A	Webster Elementary School 9 inch FT, Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 58%	Chrysotile	7%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	93.0% To	otal %Asbestos:	7.0%
1625709-026 C-13B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	<1%
1625709-027 C-14A	Webster Elementary School 9 inch FT, Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 58%	Chrysotile	7%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	93.0% To	otal %Asbestos:	7.0%
1625709-028 C-14B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	<1%
1625709-029 C-15A	Webster Elementary School 9 inch FT, Brown, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	35% 57%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% To	otal %Asbestos:	8.0%
1625709-030 C-15B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	<1%
1625709-031 C-16	Webster Elementary School Sheet Vinyl, Beige, Non- homogeneous	LAYER 1 100%	Jute Fiber Vinyl Binder/ Filler	15% 85%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	otal %Asbestos:	No Asbestos Detected

PAGE: 5 of 6



Alta Environmental

3777 Long Beach Blvd.

Long Beach CA 90807

Report Number 1625709

Attn.: Cesar Ruvalcaba

Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

1508 East 33rd Street

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/26/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 34

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test I	Report			
Laboratory ID	Sample Location	Layer No	. Non-Asbestos		Asbestos	
Sample No.	Description	Layer %	Components	(%)	Туре	(%)
1625709-032	Webster Elementary School					
C-17	Sheet Vinyl, Beige, Non-	LAYER 1	Jute Fiber	15%	None Detected	
	homogeneous	100%	Vinyl Binder/ Filler	85%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T o	otal %Asbestos:	No Asbestos Detected
1625709-033	Webster Elementary School					
C-18	Sheet Vinyl, Beige, Non-	LAYER 1	Jute Fiber	15%	None Detected	
	homogeneous	100%	Vinyl Binder/ Filler	85%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625709-034	Webster Elementary School					
C-19	12x12 FT, Dk. Gray, Homogeneous	LAYER 1			None Detected	
		100%	Calcium Carbonate Vinyl Binder	65% 35%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt

Lab Code 500044-0

PAGE: 6 of 6



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625712

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 36

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625712-001	Webster Elementary School					
234-1A	12 inch FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625712-002	Webster Elementary School					
234-1B	Leveling Compound, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625712-003	Webster Elementary School					
234-2A	12 inch FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	Il % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625712-004	Webster Elementary School					
234-2B	Leveling Compound, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625712-005	Webster Elementary School					
234-3A	12 inch FT, Lt. Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	65% 35%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected
1625712-006	Webster Elementary School					
234-3B	Leveling Compound, bw, Homogeneous	LAYER 1 100%	Calcium Carbonate Binder/Filler	75% 25%	None Detected	
	Asbestos Present: No	Tota	ıl % Non-Asbestos:	100.0% T	otal %Asbestos:	No Asbestos Detected

PAGE: 1 of 6



09/30/2016

10/07/2016

10/07/2016

Alta Environmental

Date Received

Date Analyzed

Date Reported

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625712

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

3602 Winter Canyon Rd, Malibu, CA Location

PO Number WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625712-007 234-4A	Webster Elementary School 9x9 FT, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T c	otal %Asbestos:	8.0%
1625712-008 234-4B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0% T c	otal %Asbestos:	<1%
1625712-009 234-5A	Webster Elementary School 9x9 FT, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% Tc	otal %Asbestos:	8.0%
1625712-010 234-5B	Webster Elementary School Mastic, Black, Homogeneous	LAYER 1 100%	Bituminous Matrix	100%	Chrysotile	<1%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	100.0% Tc	otal %Asbestos:	<1%
1625712-011 234-6A	Webster Elementary School 9x9 FT, Beige, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	40% 52%	Chrysotile	8%
	Asbestos Present: Yes	Tota	al % Non-Asbestos:	92.0% T c	otal %Asbestos:	8.0%
1625712-012 234-6B	Webster Elementary School Mastic, Note: No Mastic Present	LAYER 1 100%				
1625712-013 234-7A	Webster Elementary School 12x12 FT Patchwork, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% T c	otal %Asbestos:	No Asbestos Detected

PAGE: 2 of



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625712

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 36

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625712-014	Webster Elementary School	1.43/55.4				
234-7B	Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% 7	Total %Asbestos:	No Asbestos Detected
1625712-015 234-8A	Webster Elementary School 12x12 FT Patchwork, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	ן 100.0%	Total %Asbestos:	No Asbestos Detected
1625712-016 234-8B	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	ן 100.0%	Total %Asbestos:	No Asbestos Detected
1625712-017 234-9A	Webster Elementary School 12x12 FT Patchwork, Lt. Blue, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	ן 100.0%	Total %Asbestos:	No Asbestos Detected
1625712-018 234-9B	Webster Elementary School Mastic, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0%	Total %Asbestos:	No Asbestos Detected
1625712-019 234-10A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous	LAYER 1 100%	Calcium Carbonate Vinyl Binder	30% 70%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	ן 100.0%	Total %Asbestos:	No Asbestos Detected

PAGE: 3 of 6



09/30/2016

10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625712

Date Received

Date Analyzed

Date Reported

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

205

3602 Winter Canyon Rd, Malibu, CA

Project Number SMSD-16-6285

Project Name Webster Elementary

PO Number

Location

WO Number

Date Sampled 09/27/2016

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples 36

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
1625712-020	Webster Elementary School					
234-10B	Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-021 234-11A	Webster Elementary School 4 inch Covebase, Gray, Homogeneous		Calcium Carbonate Vinyl Binder	30% 70%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-022 234-11B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-023	Webster Elementary School					
234-12A	4 inch Covebase, Gray, Homogeneous		Calcium Carbonate Vinyl Binder	30% 70%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-024 234-12B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-025	Webster Elementary School					
234-13A	4 inch Covebase, Blue, Homogeneous	LAYER 1 100%	Vinyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Tota	I % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected

PAGE: 4 of 6



Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Report Number 1625712

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770 Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

Date Received 09/30/2016 **Date Sampled** 09/27/2016

Date Analyzed 10/07/2016 Sampled By Fabian Ruvalcaba, Anthony Vice

Date Reported 10/07/2016 Total Samples 36

Method of Analysis 40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID Sample No.	Sample Location Description	Layer No Layer %	. Non-Asbestos Components	(%)	Asbestos Type	(%)
1625712-026 234-13B	Webster Elementary School Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	l %Asbestos:	No Asbestos Detected
1625712-027 234-14A	Webster Elementary School 4 inch Covebase, Blue,	LAYER 1			None Detected	
	Homogeneous	100%	Vinyl Binder/ Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected
1625712-028	Webster Elementary School	1 AVE 2 (N 8	
234-14B	Adhesive, Cream, Homogeneous	100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected
1625712-029	Webster Elementary School					
234-15A	4 inch Covebase, Blue, Homogeneous	LAYER 1 100%	Vinyl Binder/ Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected
1625712-030	Webster Elementary School					
234-15B	Adhesive, Cream, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected
1625712-031	Webster Elementary School					
234-16A	Adhesive, Yellow, Homogeneous	LAYER 1 100%	Organic Binders/Filler	100%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected
1625712-032	Webster Elementary School					
234-16B	Carpet, Dk. Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	70% 30%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% Tota	I %Asbestos:	No Asbestos Detected

PAGE: 5 of 6



09/30/2016

10/07/2016

10/07/2016

Alta Environmental

3777 Long Beach Blvd. Long Beach CA 90807

Attn.: Cesar Ruvalcaba

Date Received

Date Analyzed

Date Reported

Report Number 1625712

1508 East 33rd Street Signal Hill, CA 90755 Toll: 888-207-2022 Tel: 562-206-2770

Fax: 562-206-2773

Project Number SMSD-16-6285

Project Name Webster Elementary

Location 3602 Winter Canyon Rd, Malibu, CA

PO Number WO Number

09/27/2016 **Date Sampled**

Sampled By Fabian Ruvalcaba, Anthony Vice

Total Samples

40 CFR Part 763 Appendix E to Subpart E, EPA Method 600/M4-82-020; updated method 600 R-93/116 **Method of Analysis**

Determination of Asbestos in Bulk Building Materials.

		Test F	Report			
Laboratory ID	Sample Location	Layer No		(0/)	Asbestos	(0/)
Sample No.	Description	Layer %	Components	(%)	Туре	(%)
1625712-033	Webster Elementary School					
234-17A	Adhesive, Tan, Homogeneous	LAYER 1			None Detected	
	-	100%	Organic Binders/Filler	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-034	Webster Elementary School					
234-17B	Carpet, Dk. Gray, Non-homogeneous		Synthetic Fiber	60%	None Detected	
		100%	Binder/Filler	40%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-035	Webster Elementary School					
234-18A	Adhesive, Dk. Gray, Non-	LAYER 1			None Detected	
	homogeneous	100%	Adhesive Binders	100%		
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected
1625712-036	Webster Elementary School					
234-18B	Carpet, Dk. Gray, Non-homogeneous	LAYER 1 100%	Synthetic Fiber Binder/Filler	60% 40%	None Detected	
	Asbestos Present: No	Tota	al % Non-Asbestos:	100.0% To	tal %Asbestos:	No Asbestos Detected

Method Detection Limit: Less than one percent (<1%). Asbestos content has been determined using calibrated visual estimation (CVES). Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. Due to PLM limitations, results on samples with None Detected or samples with low asbestos concentrations may not be reliable and further analysis such as TEM is recommended to confirm PLM results. This report shall not be reproduced except in full without the written approval of this laboratory. This report may not be used by the customer to claim product certification, endorsement, or approval by NIST/NVLAP or any agency of the government. Samples shall be disposed according to local, state and federal laws, 30 days after results are reported.

Analyst - Cristina Tabatt

Approved Signatory Cristina E. Tabatt

PAGE: 6 of



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

(Lab) Order No. 1625708 thru 1625715

	CUSTOMER INF	FORMATIO	N	Turnaround Time	Shipp	ed By	Ren	ort Send Vi	0.
Company	Alta Environmen	ital		Same Day □	Fedex	led by	Web		a:
Address	3777 Long beach	h Blvd	1	1 Day	UPS		100		
City/State/Zip	Long beach			2 Day	USPS		Emai		
Contact	Cesar Ruvalcaba	a		3 Day	Drop Off		Verba		
Office Phone	5624955777			5 Day	Drop Box		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Cell	3109519485			Weekend □	Other	× =	Mai Pick un		
Fax	5624955877			Special Instruction			Pick up) []	
Email	bscresults@altae	environ.com		- Shearen Francisco	nə.				
			PROJECT	INFORMATION					
Project Name:	Webster Elementa			PO Number:					
Project Number:	SMSD-16-6285			Work Order No.:					
Location:	3602 Winter Canyo	on Rd, Malibu	ı, CA	Sampled By:		Fabian I	Ruvalcaba	, Anthony	/ Vicente
PL	_M	PC	M	MOLD					
PLM EPA 600/M4	4-82-020	NIOSH 740	3.57 M	Spore Trap		Air	LEAD	(Pb)	
PLM 400 Pt. Cour		NIOSH 740	00B 🗆	Tape Lift		Paint		1120	_
PLM 1000 Pt. Cou	unt (<0.1%)	w/ TWA		Bulk Sample	- CE-1	Wipe			
SAMPLE ID	CAMPLET			Swab		Soil			
SAMPLE	SAMPLE TY	YPE		LOCATION		Date	Start Time	-	Volume
	12x12 LT grey speckled	ET with vollow	N.5 -			Sampled	Stop Time	Flow Rate	(L)
MA-1 *	mastic with black resi		Webster Elementary School			9.26.16			
MA-2	12x12 LT grey speckled mastic with black resi		Web	bster Elementary Sch	hool	9.26.16			
MA-3	12x12 LT grey speckled mastic with black residual	FT with yellow idual mastic	Wet	oster Elementary Sch	nool	9.26.16			
MA-4	9x9 Dark brow black mas		Wet	oster Elementary Sch	nool	9.26.16			- 44
MA-5	9x9 Dark brow	n FT w/	Web	oster Elementary Sch	nool	9.26.16			
MA-6 -	9x9 Dark brow	n FT w/		lead of the same					
IVIA-U	black mas		Web	oster Elementary Sch	100	9.26.16			
MA-7	4 inch dark grey o w/ adhesi	ive	Web	oster Elementary Sch	nool	9.26.16	,		
MA-8 .	4 inch dark grey o w/ adhesi		Web	oster Elementary Sch	nool	9.26.16			
MA-9	4 inch dark grey o w/ adhesiv		Webster Elementary School			9.26.16			
MA-10	Yellow adhesive with residual black n	carpet with	Webster Elementary School			9.26.16			
Relinquished By:	1	conte		Received By:	D	v-(c	1		
Date/Time: 9/3	30/16 6500	Am		Date/Time: 5/3	0/15	54.	-		
Relinquished By:	assar Porale	csba		Received By: Ker	Wilmila	ala			
Date/Time: 93	114 22	15 pin		Date/Time: 9/30/	14. 11	1415			
			_	1/0-1	.0 / .	1/14			

Page _ of _ g



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 thru

1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg	Volun
MA-11 1	Yellow adhesive with carpet with residual black mastic	Webster Elementary School	9.26.16	Stop Time	Flow Rate	(L)
MA-12	Yellow adhesive with carpet with residual black mastic	Webster Elementary School	9.26.16			
C-1 -	12 inch white w/ LT grey speckles FT w/ Mastic	Webster Elementary School	9.26.16			
C-2	12 inch white w/ LT grey speckles FT w/ Mastic	Webster Elementary School	9.26.16			
C-3 -	12 inch white w/ LT grey speckles FT w/ Mastic	Webster Elementary School	9.26.16			
C-4	12 inch brown w/ white speckles FT w/ mastic	Webster Elementary School	9.26.16			
C-5 4	12 inch brown w/ white speckles FT w/ mastic	Webster Elementary School	9.26.16			
C-6 .	12 inch brown w/ white speckles FT w/ mastic	Webster Elementary School	9.26.16			
C-7 4	4 inch black covebase w/ brown adhesive	Webster Elementary School	9.26.16			Э
C-8 -	4 inch black covebase w/ brown adhesive	Webster Elementary School	9.26.16			
C-9	4 inch black covebase w/ brown adhesive	Webster Elementary School	9.26.16			
C-10	12 inch beige with blue speckles FT w/ yellow adhesive	Webster Elementary School	9.26.16			E
C-11	12 inch beige with blue speckles FT w/ yellow adhesive	Webster Elementary School	9.26.16			
C-12	12 inch beige with blue speckles FT w/ yellow adhesive	Webster Elementary School	9.26.16			
C-13	9 inch brown FT with black mastic	Webster Elementary School	9.26.16			
C-14	9 inch brown FT with black mastic	Webster Elementary School	9.26.16			
C-15	9 inch brown FT with black mastic	Webster Elementary School	9.26.16			
C-16 ,	Beige Sheet Vinyl	Webster Elementary School	9.26.16			
C-17	Beige Sheet Vinyl	Webster Elementary School	9.26.16			
C-18	Beige Sheet Vinyl	Webster Elementary School	9.26.16			
inquished By:	Anthony Vocanto	Received By: Corr	Ruston			
e/Time: 5/3		Date/Time: 9/3/15/	MEAN			
inquished By: (Cogne Provolator	Received By: Kullu	Mussel			
e/Time: 9	30/16 218/1	Date/Time: 9/30/1/	11415		Lab For	ns

Page Zof 8

Ver. 2016-06-27



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 thm 1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volur (L)
C-19	12x12 Dark grey FT	Webster Elementary School	9.26.16			(-/
L7-1 ,	yellow mastic with dark blue carpet	Webster Elementary School	9.26.16		7=-	
L7-2	yellow mastic with dark blue carpet	Webster Elementary School	9.26.16			
L7-3	yellow mastic with dark blue carpet	Webster Elementary School	9.26.16		v = 1	
L7-4	Black mastic with dark grey carpet	Webster Elementary School	9,26.16			
L7-5 ·	Black mastic with dark grey carpet	Webster Elementary School	9.26.16			
L7-6 +	Black mastic with dark grey carpet	Webster Elementary School	9.26.16			
L7-7	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16			
L7-8 `	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16			ī
L7-9 `	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16			Т
L7-10 ·	12 inch LT grey speckled FT	Webster Elementary School	9.26.16			
L7-11 ,	12 inch LT grey speckled FT	Webster Elementary School	9.26.16			
L7-12 `	12 inch LT grey speckled FT	Webster Elementary School	9.26.16			
L7-13	4 inch Black covebase w/ adhesive	Webster Elementary School	9.26.16			
L7-14	4 inch Black covebase w/ adhesive	Webster Elementary School	9.26.16			
L7-15 ·	4 inch Black covebase w/ adhesive	Webster Elementary School	9.26.16			
L7-16 *	12 inch LT blue FT with yellow adhesive	Webster Elementary School	9.26.16			
L7-17 ·	12 inch LT blue FT with yellow adhesive	Webster Elementary School	9.26.16			
L7-18 ,	12 inch LT blue FT with yellow adhesive	Webster Elementary School	9.26.16			
L7-19	12 inch LT blue FT with black mastic	Webster Elementary School	9.26.16			
nquished By:	Anthony Vicanto	Received By:	releate			
/Time: 9/3/	Ulib Jsan	Date/Time: 5/30/16	5A-			_
nquished By: (Cigena Romalcato	Received By: Hallelle	1			
	20/16 21157.2	Date/Time: 9/30/16 //	1415		_	

Page 3 of 8



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company: Alta Environmental
Project Number: SMSD-16-6285
Project Name: Webster Elementary School

(Lab) Order No. 1625708 thry

1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volum (L)
L7-20 '	12 inch LT blue FT with black mastic	Webster Elementary School	9.26.16		, low Nate	(L.
L7-21 *	12 inch LT blue FT with black mastic	Webster Elementary School	9.26.16		1	
L7-22 1	black mastic w/ dark blue carpet	Webster Elementary School	9.26.16			
L7-23 *	black mastic w/ dark blue carpet	Webster Elementary School	9.26.16		/ [
L7-24	black mastic w/ dark blue carpet	Webster Elementary School	9.26.16			
111	9 inch dark greay FT w/ black mastic	Webster Elementary School	9.26.16			
112	9 inch dark greay FT w/ black mastic	Webster Elementary School	9.26.16		1	
113 、	9 inch dark greay FT w/ black mastic	Webster Elementary School	9.26.16			
114	12 inch LT blue speckled FT w/ black adhesive	Webster Elementary School	9.26,16			
115	12 inch LT blue speckled FT w/ black adhesive	Webster Elementary School	9.26.16			
116	12 inch LT blue speckled FT w/ black adhesive	Webster Elementary School	9.26.16			
117	yellow adhesive w carpet with residual black mastic	Webster Elementary School	9.26.16			
118	yellow adhesive w carpet with residual black mastic	Webster Elementary School	9.26.16			
119 +	yellow adhesive w carpet with residual black mastic	Webster Elementary School	9.26.16			
1110	4 inch grey covebase w/ adhesive	Webster Elementary School	9.26.16			
1111	4 inch grey covebase w/ adhesive	Webster Elementary School	9.26.16			
1112 '	4 inch grey covebase w/ adhesive	Webster Elementary School	9.26.16			
1113	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16			
1114 +	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16			
1115	4 inch dark blue covebase w/ adhesive	Webster Elementary School	9.26.16	المستند		
nquished By:	Antrony Vicanta	Received By:	200-lo-f			
	ulia dan	Date/Time: 9/30/16	54-1	1		
nquished By:		Received By: Fusikall	mink			
e/Time: /	116 20117.0	Date/Time: /9/30/16	11/11/1	-		_

Page 4 of 8



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 thru

1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volum (L)
234-1	12 inch LT grey FT with white leveling compound on 9x9 beige FT	Webster Elementary School	9.27.16			\-/
234-2	12 inch LT grey FT with white leveling compound on 9x9 beige FT	Webster Elementary School	9.27.16			
234-3 .	12 inch LT grey FT with white leveling compound on 9x9 beige FT	Webster Elementary School	9.27.16			
234-4	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
234-5	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
234-6	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
234-7	12x12 LT blue FT patchwork w/ yellow mastic	Webster Elementary School	9.27.16			
234-8	12x12 LT blue FT patchwork w/ yellow mastic	Webster Elementary School	9.27.16			
234-9	12x12 LT blue FT patchwork w/ yellow mastic	Webster Elementary School	9.27.16			
234-10	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
234-11 ,	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
234-12	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
234-13	4 inch Dark blue covebase w/ adhesive	Webster Elementary School	9.27.16			T
234-14	4 inch Dark blue covebase w/ adhesive	Webster Elementary School	9.27.16			
234-15 ,	4 inch Dark blue covebase w/ adhesive	Webster Elementary School	9.27.16			
234-16 ,	yellow adhesive w/ dark grey carpet over 9x9 beige FT underneath	Webster Elementary School	9.27.16			
234-17	yellow adhesive w/ dark grey carpet over 9x9 beige FT underneath	Webster Elementary School	9.27.16			
234-18	yellow adhesive w/ dark grey carpet over 9x9 beige FT underneath	Webster Elementary School	9.27.16			
810-1	12x12 LT grey speckled FT with yellow adhesive on 9x9 beige FT	Webster Elementary School	9.27.16			
810-2	12x12 LT grey speckled FT with yellow adhesive on 9x9 beige FT	Webster Elementary School	9.27.16			
inquished By:	Anythong Vicanto	Received By:	Lwalcafu			
e/Time: G	30/16 J 5 72,	Date/Time: 9 30/10	SA-1			
inquished By:	year Karelack	Received By: Kallula	Vers a 1			
e/Time: 9/30		Date/Time: 9/30/16	1415			_

Page 5 of 8



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 +hru

1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volur (L)
810-3	12x12 LT grey speckled FT with yellow adhesive on 9x9 beige FT	Webster Elementary School				1-
810-4	4 inch grey covebase with adhesive	Webster Elementary School	9,27.16			
810-5	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
810-6	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
810-7	4 inch of blue covebase with ashesive	Webster Elementary School	9.27.16			
810-8	4 inch of blue covebase with ashesive	Webster Elementary School	9.27.16			
810-9	4 inch of blue covebase with ashesive	Webster Elementary School	9.27.16			
810-10	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
810-11	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
810-12	9x9 beige FT w/ black mastic	Webster Elementary School	9.27.16			
810-13	yellow mastic w dark green carpet over 9x9 beige FT	Webster Elementary School	9.27.16			
810-14	yellow mastic w dark green carpet over 9x9 beige FT	Webster Elementary School	9.27.16			
810-15	yellow mastic w dark green carpet over 9x9 beige FT	Webster Elementary School	9.27.16		11	
13A-1	12s12 LT grey speckled FT with yellow adhesive and black residual mastic	Webster Elementary School	9.27.16			
13A-2 ⁺	12s12 LT grey speckled FT with yellow adhesive and black residual mastic	Webster Elementary School	9.27.16			
13A-3	12s12 LT grey speckled FT with yellow adhesive and black residual mastic	Webster Elementary School	9.27.16			
13A-4	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
13A-5	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
13A-6	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
13A-7	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16			
inquished By:	Aythong Viconto	Received By:	ZwJa-h			
e/Time: 9/3	2016 25,4-,	Date/Time: 9/30/4	no SAP			
inquished By;		Received By:	Menry 1-			
e/Time: 9/3	016 2:18 120	Date/Time: 9/50/14	1415			_

Page 6 of 8



1508 E, 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 thru

1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volum (L)
13A-8 *	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16	************	. Tott Hate	(2
13A-9	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16			
13A-10	yellow mastic w/ dark carpet on 9x9 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-11	yellow mastic w/ dark carpet on 9x9 beige FT with black mastic	Webster Elementary School	9.27.16	-		
13A-12	yellow mastic w/ dark carpet on 9x9 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-13	9x9 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-14	9x9 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-15	9x9 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-16 *	yellow mastic w/ dark carpet on 12x12 beige FT with black mastics	Webster Elementary School	9.27.16			
13A-17 ·	yellow mastic w/ dark carpet on 12x12 beige FT with black mastics	Webster Elementary School	9.27.16			
13A-18	yellow mastic w/ dark carpet on 12x12 beige FT with black mastics	Webster Elementary School	9.27.16			
13A-19 ¹	12x12 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-20 '	12x12 beige FT with black mastic	Webster Elementary School	9.27.16			
13A-21	12x12 beige FT with black mastic	Webster Elementary School	9.27.16			
170-1	4 inch black covebase w/ adhesive	Webster Elementary School	9.27.16			
170-2	4 inch black covebase w/ adhesive	Webster Elementary School	9.27.16			
170-3	4 inch black covebase w/ adhesive	Webster Elementary School	9.27.16			
170-4	yellow adhesive w/ carpet	Webster Elementary School	9.27.16			
170-5	yellow adhesive w/ carpet	Webster Elementary School	9.27.16			
170-6	yellow adhesive w/ carpet	Webster Elementary School	9.27.16			
nquished By:	Anthony Viconto	Received By: Carry R	mu al calm			
e/Time: 9/34/	16 5 - 1	Date/Time: 6/30/16	Fin/			
nquished By		Received By: Andexid	were 1			
e/Time: 9/3/	0/16 5-4 2:13-P-1	Date/Time: 4/30/14	1415			_

Page $\frac{9}{2}$ of $\frac{8}{2}$



1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

Company:	Alta Environmental	
Project Number:	SMSD-16-6285	
Project Name:	Webster Elementary School	

(Lab) Order No. 1625708 thru


1625715

SAMPLE ID	SAMPLE TYPE	LOCATION	Date Sampled	Start Time Stop Time	Avg Flow Rate	Volui (L)
170-7	12x12 LT grey FT with yellow adhesive	Webster Elementary School	9.27.16		, iow reace	(L
170-8	12x12 LT grey FT with yellow adhesive	Webster Elementary School	9.27.16			
170-9	12x12 LT grey FT with yellow adhesive	Webster Elementary School	9.27.16			
170-10 .	12x12 Dark brown FT with black mastic	Webster Elementary School	9.27.16			
170-11 -	12x12 Dark brown FT with black mastic	Webster Elementary School	9.27.16			
170-12	12x12 Dark brown FT with black mastic	Webster Elementary School	9.27.16			
170-13	9x9 Beige FT with black mastic	Webster Elementary School	9.27.16			
170-14	9x9 Beige FT with black mastic	Webster Elementary School	9.27.16			
170-15	9x9 Beige FT with black mastic	Webster Elementary School	9.27.16			
170-16	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
170-17 -	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
170-18	4 inch grey covebase with adhesive	Webster Elementary School	9.27.16			
170-19	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16			
170-20 -	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16			
170-21	4 inch blue covebase with adhesive	Webster Elementary School	9.27.16			
nquished By;	A-thony Vicont-		retenta			
e/Time: 6/2	0116 519-	Date/Time: 9/30/16	TA-1			
nquished By:		Received By:	mela			
11me: 9/3	0/16 2:15 /2~	Date/Time: 9/30/16 //	1415			

Page g of 8


Appendix C

Sample Location Map: Asbestos



8C9 55 ft due Brown green orgh 192 ft of Noury Ble corport co linth grey cove Put 18 Hault cove


640 54ct of Bah and 90 lia. Us of each Pag 17



wabster Er.


NA

Wobsty cos.



* you true that I'm gray could book with a dashing the your wood (00 25 ft of 9Kg

Asbestos Somple (occulton



Webster Br.


L'bour C 28×66

42 Hours 6t of 4" Down 8te consoluse 3705yet of 12"x12" CT 8148 spectfed F. (

* Cibray 8


80 how Hot 4" double Bleck conclused

32K 32 = 1000 SAH




Rug 1,024 syft 12x12
96 librar ft of each courbase
RM 9-10 6to syft of Oay guy carpet
80 tillea ft of each courbase





Webstar Es capetaine Bllg



Websla prof. 12x12

2005/14 Bout 5/10x Coupet
65 \$10 Five 6+ Dout 8 loc cove
65 \$1007 cove

Appendix D

Paint Chip Sample List: Lead

MATERIAL INVENTORY LEAD PAINT CHIP SAMPLES

CLIENT: SMMUSD PROJECT NO: SMSD-16-6285 PROJECT NAME: Webster ES

Page 1 of 3

		0111	D : 40 I			D 14 (DD14)		Approx.
Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Damage Qty.
Wall	PC-1	plaster	white	building 17-20- room 17 northwest corner	Building- library, 11,12,1,2,3,4,8,9,10,13,1 4,15,16,16A,19,20, cafeteria	78	no	N/A
post	PC-2	metal	white	library north center	interaval at window frames- buildings 8-10, library	1,200	no	N/A
window case	PC-3	metal	white	building 11,12- room 12 north center	interior- building: library, administration, cafeteria 11,12, 8-10, 13-16A,17- 20	2,400	no	N/A
door	PC-4	wood	brown	Library Northwest	interior of library	<49	no	N/A
door case	PC-5	metal	white	Library Southwest	interior all buildings	1,100	no	N/A
door	PC-6	wood	white	Library Southwest	interior all buildings	260	no	N/A
doorcase	PC-7	metal	green	Library building C East center	interior all buildings	4,400	no	N/A
door	PC-8	wood	red	Library Building, room 7 southwest	interior buildings at room 7	<46	no	N/A
baseboard	PC-9	wood	white	Library buildings, room 7 south center	interior buildings all buildings baseboard and wall trims	1,900	no	N/A
cabinet	PC-10	wood	white	buildings 1-4 room 3 west center	interior buildings 11,12, library, administration, cafeteria, 1-4,8-10, 13- 16A, 17-20	2,000	no	N/A
window case	positive by xrf	metal	green	#24	exterior builldings; library, administration, cafetieria, 1-4,8-10	Pos	no	N/A

MATERIAL INVENTORY LEAD PAINT CHIP SAMPLES

CLIENT: SMMUSD PROJECT NO: SMSD-16-6285 PROJECT NAME: Webster ES

Page 2 of 3

Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Approx. Damage Qty.
door case	positive by xrf	metal	green	#28	exterior builldings; library, administration, cafetieria, 1-4,8-11	Pos	no	N/A
flashing	positive by xrf	metal	green	#29	exterior builldings; library, administration, cafetieria, 1-4,8-12	Pos	no	N/A
Window case	10A	wood	green	building 17-20 exterior south center	building 17-20 exterior	3,100	no	N/A
wall	PC-11	stucco	white	cafeteria north center	exterior all buildings	520	no	N/A
wall	PC-12	concrete	white	library south center	exterior/interior library, rooms 1-4, 8-10	600	no	N/A
door	PC-13	wood	green	library southwest	exterior all buildings	<59	no	N/A
case	PC-14	metal	green	library southwest	exterior all buildings	3,700	no	N/A
window case	PC-15	wood	white	administration builldings- copy room west center	exterior all buildings except at buildings 1-4	630	no	N/A
Wall	PC-16	drywall	white	administration buildings- main office south center	interior buildings all buildings	<50	no	N/A
window case	PC-17	metal	green	buildings 17-20 northwest	exterior buildings 11- 12,13-16A, 17-20	18,000	no	N/A
door case	PC-18	wood	green	guildings 17-20- northwest	exterior all buildings	<46	no	N/A
flashing	PC-19	metal	green	buildings 13-16A North center	exterior buildings 11- 12,13-16A, 17-20	6,900		N/A
wall	positive by xrf	wood	white	buildings 17-20 northwest	exterior administration buildings	Pos		N/A

MATERIAL INVENTORY LEAD PAINT CHIP SAMPLES

CLIENT: SMMUSD PROJECT NO: SMSD-16-6285 PROJECT NAME: Webster ES

Page 3 of 3

Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Approx. Damage Qty.
door case	PC- 20	metal	grey	Buildings administration-	Interior administration	<47	no	N/A
door case	1 0- 20	metai	grey	copy room Southwest	buildings	747	110	IN/A
				loopy room countries.	Januarigo			
pipe	PC- 21	metal	white	cafeteria- storage room	interior all buildings	620	no	N/A
				northwest				
ceiling	PC- 22	metal	green	exterior stage center	cafeteria at stage	61	no	N/A
door	PC- 23	metal	green	exterior stage center	cafeteria at stage	2,500	no	N/A
floor	PC- 24	wood	brown	exterior stage southwest	cafeteria at stage	<71	no	N/A
handrail	PC- 25	metal	red	exterior stage southeast	cafeteria at stage	<340	no	N/A
wall	PC- 26	plaster	blue	buildings administration copy room southwest	administration building copy room	300	no	N/A
door case	PC- 27	wood	white	administration bilding copy room north east	interior all buildings	<48	no	N/A
coat rack	PC- 28	wood	white	building 1-4, south center	exterior buildings 1-4, administration, cafeteria, library, rooms 11-12, 13- 16, 17-20	<47	no	N/A
post	positive by xrf	metal	white	#13 9-27-16	interior builidngs 1-4	Pos	no	N/A
Window case	positive by xrf	metal	white	#16 9-27-16	interior builidngs 1-5	Pos	no	N/A
Post	positive by xrf	metal	green	#95/101	walkways	Pos	no	N/A
ceiling	PC- 29	wood	white	walkway by 17-20 south	walkway ceilings and	2,100	no	N/A
ceiling	PC- 30	stucco	white	center walkway by administration buildings south east	walkway ceiligs	<50	no	N/A



Client:	SMUSO	Technician:	F. Ruvalcaba
Project No.:	SM 50-16-6285	Date:	9-26-16
Project Name:	Webster E.S.	Page:	1 of 4

Homogeneous #	Photo #	Component	Sample #	Substrate	Paint Color	Sample Location	Material Location	Damaged Yes/No	Est. Damaged Qty.
	78	Wall	PC-1	plaste	white	81d, 17-720-R-17	Oldg - Diavay, 11-12,	7	
	10					' N/W	1-84,8-010,13-1716A	17-120	, Cateter,
	1200	Post	2	Metal	white	Ribray - Bet	Juter at budous	N	
	1200					,	france - Blog 5: Lilevary	,	
			(TV.)				(9-7(0),		
	V	wade	3	metal	Wlit	Bldg 11-012-	Inter - Bldg: Library	N	
	2400	Coie				f-12-N/ctr	Admy Catatory 11-012,		
	PE,						Admin, Catatorn, 11-012, 8-010, 13-016A, 17-020		
	249	0.00	4	mas f	Всои	Library - P/V	Inter-Library	P	
	1100	Cese	5	met.	Cyl:k	hibray - Sw	Inter - All Bldgs	~	***************************************
	260	Pour	6	wood	wh.te	Bldy 17-820-8-18	Intern-All Blogs	~	
1	440	Case	7	Metel	leveen	Ext	Inter - Ar Blog	N	
	(46	020	8	was d	Red	Bto Libay 81d, -	Juteer - Bldy at Pu 7	Ν	
	1900	Baserno	9	له موس	whit	Library Bldg - Ra7	Inter-Bldg-Acl Bldgs: Buechard	N	



Client:	SMU	r 0	 		Technician:	F-1	luve (ed	/
Project No.:					Date:	9.	26-16	
Project Name:	webste	€.(.			Page:	۶	of	4

Homogeneous #	Photo #	Component	Sample #	Substrate	Paint Color	Sample Location	Material Location	Damaged Yes/No	Est. Damaged Qty.
	2000	Cabinet	PC-10	ward	wh.te	Bldy 1-14-12-3	Intar - Bldg 1/12,	بر	
						V /CV	Library, Admir, Coteler	n,	
							1-04, 8-010, 13-016A, 1-	7,-1720	
		wasu	Pas	metal	buccu	# 24	Exter - Bld: Library	ىر	
		Cosa	XXF		O-CEU		Admin, Caretera, 1-00	1,8-010	
		Doa	1		1	# 28	Exter - Alg: Library	' ~	
		Case					Admin: Cafetera, 1-00	1,8-010	
	1	fluster	1	-		# 29	Exter - Bld: Library.	· ~	
					0		Admir, Catatora, 1-04		
	3100	Case	10A	wood	Green	6/dg - 17-P26	R/4 17-820 Exte	<i>r P</i>	
	2100		'			Extu-Sct.			
	520	wall	(t	Stucco	white	Catetra - Plat	Extern - All Blds s	N	
	1.00		12	Conwele	white	Library - S/ct	Externey deaning I	uten:	N
	600	4	()				Library 2. 1-174, P.	P-P10	
	150	Doder	13	Wood	Green	Library - Sw	Exter - All Bless	N	
	20	1	14	wetel	Eveen		Exter - All Bldgs	2	
	3700	Case							
	630	morren	15	Wood	white	Admir Bldg -	Jaten - All Bldgs	W	
	0 00	cuse				Copy Pa- Wat	except at (Blk 1-04)		



Client:	Smu	· D	Technician:	F. Ru	-lc-b	
Project No.:			Date:	9-	26-16	
Project Name:	webste	6.5	Page:	3	of	#

Homogeneous #	Photo #	Component	Sample #	Substrate	Paint Color	Sample Location	Material Location	Damaged Yes/No	Est. Damaged Qty.
	(50	ひょり	PC-16	Digwall	white	Admir Bldg - Mun aftre - Set	Juker · Blog All ,	~	
1	18600	wordens	17	metal	Green	18/4 17-120-	Exten-Blog - Met 11-012, 13-016A, 17-0	20	
	<46	Don	18	wood	1	18/2/17-1720-	Extens - All Blogs		
4	6900	pholory	19	Medd	Green	Blog 13-17/6A	Exter Bldg: 11-P12,	~	
9		wall	for by xee	wood	culate	# 62	Exten Adunside	Ν	
	<47	Dow	26	metal	Evay	Bldy - Admin	Inter-Admobby	<i>/</i> \/	
	620	Pipe	2(redd	White	Cateters - Stever	Indean - All Blogs	<u></u>	
	61	Césley	27	fish	Green	Catedra -	Catetra - at	7	
	2500	Beac	23	metal	bocev	Stage - Ctr.	July 2	~	
	(71	How	24	word	Gran	Stage-S/w		~	***************************************
	1340	Hondral	25	Metal	Ped	stage-		N	



Client:	_ Suceo	Paint Chip Sample List		
Project No.:			Technician:	f. Rusalea
Project Name:	wegete (C		Data	0 7-40-126

Project Name: 9-26-16 Date: Page:

Homogeneous	Photo		Sample				Page: 4	of	4
20 min 32	0.40	Component سدر(Substrate	Color	Sample Location	Material Location	Damaged Yes/No	Est. Damage
	300		PC- 26	Plete	Blue	Bldg - Admin Bldg	Adm Bldg		Qty.
<	(48)	Osu Cest	27	wood	white	Admi Bldg-	Inter All Bldgs	*	
<	47	Coat Rock	28	400 J	white	BIZ 1-04-5/2	Exter - Rily (1-4), A.	1	22
			_			•		P-11-812]	
		Pos t	Pocitu XRF	Mehl	white	#15 9-27-16	Inter - 614/1-4)	. ,;;	-
	4	C-ce	+1	Me fol	whole	H16 9-87-16		<i>N</i> .	
	R	ost		Meti	tueen	# 95/101	walkways		
		futte eus a t	1	1		16 .			
210	1	7	-29	ا لے م دس	ph.to b	17/102 salkuny-by 17-20	Welkway - Coilugs		
10		1	30 5	tucco -		salkury-by Adum	and Beauc	~	
	رينا	Cale XR	of w	ood 6			Adum Blds -	~	
locuments\fleld forms\	lwhslpala						Extern -		

Appendix E

Laboratory Analytical Report: Lead



Alta Environmental 3777 Long Beach Boulevard Long Beach, CA 90807

Attention: Cesar Ruvalcaba

Report Number: 1625695

Date Received: 9/29/2016
Date Analyzed: 10/4/2016

Date Reported: 10/4/2016

Analytical Method: EPA 7420/3050

Reporting Limit: 5.0 µg

Project Number:

Project Name: Webster E.S. Location: Malibu

Date Sampled: 9/27/2016

Sampled By: Fabian Ruvalcaba

Total Samples: 31

	Lead (Pb) in	Paint by Flame AAS	
Lab ID Client ID	Location/Description	Sample Weight (g)	Lead Concentration ppm (mg/kg)
1625695-001 PC-1	Wall Plaster White	0.1032	78
1625695-002 PC-2	Post Metal White	0.0404	1,200
1625695-003 PC-3	Windowcase Metal White	0.0717	2,400
1625695-004 PC-4	Door Wood Brown	0.1012	< 49
1625695-005 PC-5	Doorcase Metal White	0.1014	1,100
1625695-006 PC-6	Door Wood White	0.1055	260
1625695-007 PC-7	Doorcase Metal Green	0.0741	440
1625695-008 PC-8	Door Wood Red	0.1083	< 46
1625695-009 PC-9	Baseboard Wood White	0.1079	1,900
1625695-010 PC-10	Cabinet Wood White	0.1055	2,000
1625695-011 PC-10A	Windowcase Wood Green	0.1041	3,100
1625695-012 PC-11	Wall Stucco White	0.1038	520
1625695-013 PC-12	Wall Concrete White	0.1034	600
1625695-014 PC-13	Door Wood Green	0.1007	< 50



Report Number: 1625695

Alta Environmental
3777 Long Beach Boulevard
Long Beach, CA 90807
Attention: Cesar Ruvalcaba

Project Number:

Project Name: Webster E.S. **Location:** Malibu

	Lead in Pain	t by Flame AAS	
Lab ID Client ID	Location/Description	Sample Weight (g)	Lead Concentration ppm (mg/kg)
1625695-015 PC-14	Door Metal Green	0.1025	3,700
1625695-016 PC-15	Windowcase Wood White	0.1007	630
1625695-017 PC-16	Wall Drywall White	0.1001	< 50
1625695-018 PC-17	Windowcase Metal Green	0.1022	18,000
1625695-019 PC-18	Doorcase Wood Green	0.1096	< 46
1625695-020 PC-19	Flashing Metal Green	0.1042	6,900
1625695-021 PC-20	Doorcase Metal Gray	0.1065	< 47
1625695-022 PC-21	Pipe Metal White	0.1033	620
1625695-023 PC-22	Ceiling Plaster Green	0.1098	61
1625695-024 PC-23	Beam Metal Green	0.1025	2,500
1625695-025 PC-24	Floor Wood Brown	0.0705	< 71
1625695-026 PC-25	Handrail Metal Red	0.0148	< 340
1625695-027 PC-26	Wall Plaster Blue	0.0502	300
1625695-028 PC-27	Doorcase Wood White	0.1037	< 48
1625695-029 PC-28	Coat Rack Wood White	0.1058	< 47
1625695-030 PC-29	Ceiling Wood White	0.1009	2,100
1625695-031 PC-30	Ceiling Stucco White	0.1003	< 50

Samples tested were received in acceptable condition unless otherwise stated. Test report relates only to items tested. This report shall not be reproduced without the written approval of this laboratory. The client shall be solely responsible for interpreting analytical results. Samples have not been blank corrected. Samples shall be disposed according to local, state and federal laws, 30 days after reporting results.

CA ELAP Cert #2823

Approved Signatory- Cristina E. Tabatt

detabatt



CHAIN OF CUSTODY

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com

		(Lab) Orde	er No.	16256	,95					
	CUSTOMER INFO	RMATION		Turnaround Ti	me	Shipped	Ву	Report	Send Via:	
Company Address City/State/Zip Contact Office Phone Cell Fax Email	BSC RESULT	Ca Ca La Sa Alla cu	wran*Coa	Same Day 1 Day 2 Day 3 Day 5 Day Weekend Special Ins	□ □ □ ctructions	Fedex UPS USPS Drop Off Drop Box Other	By	Web Email Fax		
Project Number: Location:	Malibu			_Work Order Sampled By		0.	Fabi	us Rus	lech	
PLM EPA 600/M ² PLM 400 Pt. Cou PLM 1000 Pt. Co	int (<0.25%)	PC NIOSH 740 NIOSH 740 W/ TWA	00A 🗆	Sp Ta Bu	MOLD fore Trap pe Lift llk Sample wab	0000	1	LEAD	(Pb) TTLC	
SAMPLE ID	SAMPLE TY	PE		LOCATI	ON		Date Sampled	Start Time Stop Time	Avg Flow Rate	Volume (L)
Pc-1	and Plaste	while					8-27-16			
2	Post Medl www. Corp M	white					1			
3	window Corp M	etel W	i.te							
4	Dow W.	od Bio	میں							
5	dease M.									
6		. d whi	Y .				Mag			
1	tease me								1	
1 8	Pose wood								-	
9	Brebad		16.1							
10	Cabriet 0					-	te			
Relinquished By	1	200		Received I	Ву:	2746	alt		1	
Date/Time:	4			Date/Time		1/29/16		1:00		
Relinquished By	y:			Received I	Ву:					
Date/Time:				Date/Time	:					

ENVIRONMENTAL LABORATORIES

CHAIN OF CUSTODY

1508 E. 33rd Street Signal Hill, CA 90755 562-206-2770 Tel 562-206-2773 Fax services@AQenvlabs.com


Company:	Alta	EUN	-tel		(Lab) Order No.	1625695
Project Number:						
n to a Name	120 60	odes	fs.			

SAMPLE ID	SAMPL	ETYPE		LOCATION		Date Sampled	Start Time Stop Time	Avg Flow Rate	Volum (L)	
	window	Case,					Stop Time	. IOW TAKE	(-)	
PC -10A	0,0200	wood	Guera			9-27-16				
. ((Wall		shite							
12	Wall	Concrete	white							
13	Dow w	od Guces	4			7				
17	1 4	etal Green	1							
15		e wood				145				
16		wall while								
17		· Metal 6								
18		Wood 6						-		
19		yetel Evee								
70	T	Metal &								
21		etel who								
22		doste to		-						
23		Nexl Gar.								
24	100	ood Row						-		
5 2-	Herdral	Met (R	e 1							
26	wall Plas	the Blue								
27	Dow lose	wood 4	sh.Le					-		
28	Coat R		of white							
29	Reilug	wood L	white							
飞	1 5	facco 1	white					-		
Relinquished By:	7			Received By:	1	batt	1011			
Date/Time:				Date/Time:	09/29/1	6,1	1:00			
Relinquished By:				Received By:						
Date/Time:				Date/Time:						


Lab Forms Ver. 2016-06-27

Appendix F

Sample Location Map: Lead



Pantchp M.P Rusland 9.27-16



Pantchp Map 9-27-16 F. Raviloda

part day very RIG 82-78 RM 3-4024-


12 2 12x12

140 27: 12x12

670 54th Dave grey curret

65 450 fireu &t Donk Blue cove

65 4002 cover



fast chip by f. passleh 9-27-16


2



32X 52	
32428	- Par
32×32 Red 8 11024 59t4	

Rug 1,02455ft 12x12
96 library ft of early courbast

RM 9-10 6 to syste of Day gay campet go three 14 of even cour box e



B

NA

Port chy Mp Bldg 11-812 F. Luckohn

Ren 1684 PC-14 Jen 16 PCM 15 32732 Pr 14 3. X15X W RP 8 RR

faut clup My F. Baulch 7-27-16

5400

.

340 02 bord 11-20 दिल एव PC-10 A 21797 763 Pr118 32x37 82459 PC-29 81-26 1 5 my 32×32

pant chy buy p. Ruselceh 9-27-16

Rull8
128 111 A Black Cove
60 111 A gray core
814: 54 dat Brown gueen copt
814: 54 dat Brown gueen copt
192 H of Nowy Ble capot

640 54 ct of Bak rguk 90 lia. 45 of ecuen Pag 17

Appendix G

XRF Lead Inspection, Instrument Calibration, and DHS 8552

Location: Webster Elementary School

Inspector: Fabian Ruvalcaba

Inspection Date: 09/26/16
Report Date: 10/20/2016
Abatement Level: 0.8
Report No. S#01184 - 09/26/16 19:22
Total Readings: 100
Job Started: 09/26/16 19:22
Job Finished: 09/26/16 22:56

Read					Paint		Paint	Lead	
No.	Wall	Structure	Location	Member	Cond	Substrate	Color	(mg/cm^2)	Mode
Exte	rior Ro	oom 003 Librar							
029	А	Flashing	Ctr		I	Metal	Green	0.8	QM
024	С	Window	Lft	Lft casing	I	Metal	Green	0.8	QM
028	С	Door	Lft	Lft casing	I	Metal	Green	0.8	QM
027	С	Door	Lft	U Ctr	I	Wood	Green	-0.3	QM
023	С	Wall	Lft		I	Concrete	White	-0.5	QM
025	С	Wall	Lft		I	Stucco	White	-0.7	QM
026	С	Vent	Lft		I	Metal	White	0.2	QM
Exte	rior Ro	oom 005 Buildi	ing B						
043	A	Window	Rgt	Rgt casing	I	Metal	Green	-0.4	MQ
042	A	Wall	Rgt		I	Stucco	White	-0.1	MQ
044	A	Flashing	Rgt		I	Metal	Green	-0.4	QM
046	С	Door	Ctr	Lft casing	I	Wood	Green	-0.4	MQ
045	С	Door	Ctr	U Ctr	I	Wood	Green	-0.3	QM
		oom 009 Admini							
066	А	Window	Rgt	Rgt casing	I	Wood	Green	2.2	MQ
067	А	Window	Rgt	Rgt casing	I	Metal	Green	2.2	QM
064	А	Door	Lft	Lft casing	I	Metal	Green	-0.3	МQ
063	А	Door	Lft	U Ctr	I	Wood	Green	-0.1	MQ
065	А	Wall	Lft		I	Stucco	White	-0.3	QM
062	А	Wall	Ctr		I	Wood	White	1.5	MQ
068	А	Flashing	Rgt		I	Metal	Green	1.8	QM
069	С	Downspout	Lft		I	Metal	White	-0.7	QM
Exte	rior Ro	oom 013 Cafete	eria (G)						
096	С	Window	Ctr	Lft casing	I	Metal	Green	0.8	QM
095	С	Door	Ctr	U Ctr	I	Wood	Green	-0.1	MQ
094	С	Wall	Ctr		I	Stucco	White	0.1	MQ
097	С	Flashing	Ctr		I	Metal	Green	0.2	QM
Inte	rior Ro	oom 001 Librar	ry area						
006	A	Window	Ctr	Lft casing	I	Metal	White	-0.5	MQ
011	A	Window	Ctr	Lft casing	I	Wood	White	-0.5	MQ
010	A	Door	Ctr	L Ctr	I	Wood	White	-0.4	MQ
005	A	Post	Ctr		I	Metal	White	-0.5	MQ
007	С	Wall	L Ctr		I	Concrete	White	-0.6	MQ
009	С	Door	Ctr	Lft casing	I	Metal	White	-0.4	QM
008	С	Door	Ctr	L Ctr	I	Wood	brown	-0.2	MQ

Location: Webster Elementary School

Inspector: Fabian Ruvalcaba

Inspection Date: 09/26/16
Report Date: 10/20/2016
Abatement Level: 0.8
Report No. S#01184 - 09/26/16 19:22
Total Readings: 100
Job Started: 09/26/16 19:22
Job Finished: 09/26/16 22:56

004	D	Wall	L Ctr		I	Plaster	White	0.0	QM
		000 711							
		Room 002 Libra	_		_				
012	A	Wall	L Ctr		I	Plaster	White	-0.5	QM
014	В	Door	Rgt	Rgt casing	Ι	Metal	White	-0.8	МQ
013	В	Door	Rgt	U Ctr	Ι	Metal	White	-0.6	MQ
Inter	ior E	Room 003 Libra	 cy Rm 7						
017	A	Door	Lft	Lft casing	I	Metal	White	-0.3	QM
016	А	Door	Lft	L Lft	I	Wood	Red	-0.5	QM
021	А	Baseboard	Lft		I	Wood	White	-0.5	QM
015	В	Wall	L Ctr		I	Plaster	White	-0.2	QM
018	В	Post	Ctr		I	Metal	White	-0.6	QM
019	С	Wall	L Ctr		I	Concrete	White	-0.2	QM
020	С	Window	Ctr	Lft casing	I	Metal	White	-0.1	QM
022	D	Cabinet	Ctr	3	I	Wood	White	-0.2	QM
 Tnter	ior F	Room 004 Buildi	ing B Rm	12					
031	. 101 1 A	Wall	L Rgt	12	I	Drywall	White	-0.2	QM
032	A	Window	Ctr	Lft casing	I	Wood	White	-0.3	QM
033	A	Window	Ctr	Lft casing	I	Metal	White	0.3	QM
030	В	Cabinet	Ctr	Hic casing	I	Wood	White	-0.2	QM
035	С	Door	Rgt	Rgt casing	I	Wood	White	-0.6	QM
034	C	Door	Rgt	U Ctr	I	Wood	White	-0.6	QM
			11.90	0 001		wood	WIIICC		211
	cior E	Room 005 Buildi	_	11					
039	A	Window	Lft	Lft casing	I	Wood	White	-0.6	QM
040	A	Window	Lft	Lft casing	I	Metal	White	-0.3	QM
036	В	Wall	L Lft		I	Drywall	White	-0.3	QM
038	В	Door	Lft	Lft casing	I	Metal	White	-0.8	QM
037	В	Door	Lft	L Lft	I	Wood	White	-0.3	QM
041	D	Cabinet	Ctr		I	Wood	White	-0.7	MQ
 Inter	ior E	Room 006 Admini	istration,	Main Office					
051	А	Wall	L Lft		I	Drywall	White	-0.6	QM
047	В	Door	Lft	Lft casing	I	Metal	Grey	-0.1	QM
048	В	Door	Lft	U Ctr	I	Wood	Brown	-0.3	QM
049	D	Window	Ctr	Lft casing	I	Wood	White	-0.2	QM
050	D	Window	Ctr	Lft casing	I	Metal	White	-0.3	QM
	cior E	Room 007 Admini		Main Office					
052	A	Wall	L Lft		I	Drywall	White	-0.4	QM
054	В	Door	Rgt	Rgt casing	I	Wood	Green	-0.5	QM
053	В	Door	Rgt	U Ctr	I	Wood	Green	-0.7	MQ

Location: Webster Elementary School

Inspector: Fabian Ruvalcaba

Inspection Date: 09/26/16

Report Date: 09/26/16
Report Date: 10/20/2016
Abatement Level: 0.8
Report No. S#01184 - 09/26/16 19:22
Total Readings: 100
Job Started: 09/26/16 19:22
Job Finished: 09/26/16 22:56

Inte	rior F	Room, Adminis	tration, pri	ncipal's offi						
055	D	Door	Rgt	U Ctr	I	Wood	White	-0.8	MQ	
			3							
Inte	rior F	Room Administ	ration Build	ling, Copy Rm						
058	A	Wall	L Ctr		I	Drywall	Blue	-0.5	MQ	
061	A	Cabinet	Ctr		I	Wood	White	-0.4	MQ	
056	В	Door	Rgt	Rgt casing	I	Metal	Gray	-0.4	MQ	
057	В	Door	Rgt	L Rgt	I	Wood	Brown	-0.3	QM	
059	D	Window	Rgt	Rgt casing	I	Wood	White	-0.5	MQ	
060	D	Window	Rgt	Rgt casing	I	Metal	White	-0.5	QM	
Interior Room 010, Cafeteria Building, Stage										
				ling, Stage		_				
070	А	Wall	L Lft		I	Plaster	White	-0.5	MQ	
073	А	Wall	L Ctr		I	Plaster	White	-0.3	MQ	
078	A	Floor			I	Wood	Brown	-0.2	MQ	
076	A	Ceiling			I	Plaster	Green	-0.4	MQ	
075	А	Window	Ctr	Lft casing	I	Metal	White	0.0	МQ	
077	А	Beam	Ctr		I	Metal	Green	-0.4	MQ	
079	С	Railing	Lft	Railing	I	Metal	Red	-0.2	MQ	
072	D	Door	Rgt	Rgt casing	I	Metal	White	-0.5	MQ	
071	D	Door	Rgt	U Rgt	I	Metal	White	-0.4	MQ	
074	D	Pipe	Lft		I	Metal	White	-0.8	MQ	
	ni on T	Room 011 Cafe	+ 0 20 1 0 0 20 0 0							
083	C C	Wall	L Ctr		I	Plaster	White	-0.2	QM	
085		-		Ift cocina						
	С	Door	Lft	Lft casing	I	Metal	Black	-0.6	MQ	
084	С	Door	Lft	U Ctr	I	Metal	Beige	-0.5	MQ	
080	D	Wall	L Ctr		I	Plaster	White	-0.2	MQ	
081	D	Wall	L Ctr		I	Plaster	Red	-0.2	QM	
082	D	Wall	L Ctr		I	Plaster	Blue	-0.3	QM	
Inte	rior F	Room 012 Cafe	teria, Kitch	 nen						
086	A	Wall	L Rgt		I	Plaster	White	-0.2	MQ	
087	С	Window	Ctr	Lft casing	I	Metal	White	-0.3	QM	
089	C	Door	Lft	Lft casing	I	Metal	White	-0.5	OM	
088	C	Door	Lft	U Ctr	I	Wood	White	-0.4	OM	
	rior F	Room 013 Cafe	teria Buildi	ng, Lounge						
090	A	Wall	L Lft		I	Plaster	White	-0.2	MQ	
092	A	Door	Ctr	Lft casing	I	Metal	White	-0.4	MQ	
091	A	Door	Ctr	U Ctr	I	Wood	White	-0.3	MQ	
093	С	Window	Ctr	Lft casing	I	Metal	White	-0.3	QM	

Location: Webster Elementary School

Inspector: Fabian Ruvalcaba

Inspection Date: 09/26/16
Report Date: 10/20/2016
Abatement Level: 0.8
Report No. S#01184 - 09/26/16 19:22
Total Readings: 100
Job Started: 09/26/16 19:22
Job Finished: 09/26/16 22:56

Calibration Readings

001	0.8	TC
002	0.9	TC
003	0.9	TC
098	0.9	TC
099	1.0	TC
100	0.9	TC

---- End of Readings ----

Location: Webster Elementary School

Inspector: Fabian Ruvalcaba

Inspection Date: 09/27/16
Report Date: 10/25/2016
Abatement Level: 0.8
Report No. S#01184 - 09/27/16 19:13
Total Readings: 107
Job Started: 09/27/16 19:13
Job Finished: 09/27/16 22:10

Read					Paint		Paint	Lead	
No.	Wall	Structure	Location	Member	Cond	Substrate	Color	(mg/cm^2)	Mode
		oom 001 Buildi	.ng H						
023	A	Window	Ctr	Lft casing	I	Metal	Green	1.8	QM
024	А	Flashing	Ctr		I	Metal	Green	2.0	QM
019	С	Wall	L Ctr		I	Stucco	White	-0.2	QM
021	С	Door	Ctr	Lft casing	I	Metal	Green	-0.2	QM
020	С	Door	Ctr	U Ctr	I	Wood	Green	-0.2	QM
022	С	Rack	Ctr		I	Wood	White	0.0	QM
Exte	rior R	oom 002 Buildi	 .ng F						
040	А	Wall	L Ctr		I	Concrete	White	0.0	QM
041	А	Window	Ctr	Lft casing	I	Metal	Green	0.8	QM
042	А	Door	Ctr	Lft casing	I	Metal	Green	-0.1	QM
044	A	Door	Ctr	L Ctr	I	Wood	Green	-0.2	QM
043	А	Flashing	Ctr		I	Metal	Green	0.8	QM
045	А	Vent	Ctr		I	Metal	White	-0.5	QM
046	С	Rack	Ctr		I	Wood	White	-0.4	QM
 Exte	rior R	 .oom 003 Buildi	.ng C						
066	A	Window	Ctr	Lft casing	I	Metal	Green	-0.2	QM
067	A	Window	Ctr	Lft casing	I	Metal	Green	-0.2	QM
065	A	Door	Ctr	Lft casing	I	Metal	Green	-0.2	QM
064	A	Door	Ctr	L Ctr	I	Wood	Green	-0.2	QM
068	В	Flashing	Ctr		I	Metal	Green	-0.3	QΜ
069	С	Wall	L Ctr		I	Stucco	White	-0.2	QM
070	С	Rack	Ctr		I	Wood	White	-0.2	QM
 Exte	rior R	oom 004 Buildi	 .ng A						
092	A	Wall	L Ctr		I	Stucco	White	0.0	QM
087	A	Window	Ctr	Lft casing	I	Wood	Green	-0.3	QM
088	A	Window	Ctr	Lft casing	I	Metal	Green	0.0	QM
093	С	Wall	L Ctr		I	Stucco	White	0.1	QM
090	С	Door	Ctr	Lft casing	I	Wood	Green	0.2	QM
094	С	Door	Ctr	Lft casing	I	Wood	Green	0.2	QΜ
089	С	Door	Ctr	L Ctr	I	Wood	Green	0.0	QM
091	С	Flashing	Ctr		I	Metal	Green	0.2	QM
Exte	rior R	oom 005 Walkwa	ys by 17-20	O					
098	А	Bench	Ctr		I	Wood	White	0.0	QM
099	А	Ceiling	Ctr		I	Wood	White	-0.4	QM
100	A	Ceiling	Ctr		I	Stucco	White	0.0	QM
096	С	Gutter			I	Metal	Green	1.5	QM
095	C	Post	Ctr		I	Metal	Green	1.6	QM
097	C	Downspout	Ctr		I	Metal	Green	1.7	QM
		-							

Exterior Room 006 Walkways by Administration 101 C Post Ctr I Metal Green 0.8 102 C Downspout Ctr I Metal Green 0.8 103 C Flashing Ctr I Metal Green 0.8 104 C Ceiling Ctr I Stucco White -0.4 Interior Room 001 H-2 005 A Window Ctr Lft casing I Metal White 2.3 004 A Post Ctr I Metal White 0.8 006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1 008 D Door Ctr Lft casing I Wood White -0.5	
103 C Flashing Ctr I Metal Green 0.8 104 C Ceiling Ctr I Stucco White -0.4 Interior Room 001 H-2 005 A Window Ctr Lft casing I Metal White 2.3 004 A Post Ctr I Metal White 0.8 006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1	QM
Interior Room 001 H-2 005 A Window Ctr Lft casing I Metal White 0.8 004 A Post Ctr I Metal White 0.8 006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White 0.1	QM
Interior Room 001 H-2 005 A Window Ctr Lft casing I Metal White 2.3 004 A Post Ctr I Metal White 0.8 006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1	QM
005AWindowCtrLft casingIMetalWhite2.3004APostCtrIMetalWhite0.8006BWallLCtrIPlasterWhite-0.3009CDoorCtrLft casingIMetalWhite-0.4010DWallLCtrIDrywallWhite0.1	
005AWindowCtrLft casingIMetalWhite2.3004APostCtrIMetalWhite0.8006BWallLCtrIPlasterWhite-0.3009CDoorCtrLft casingIMetalWhite-0.4010DWallLCtrIDrywallWhite0.1	
004 A Post Ctr I Metal White 0.8 006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1	
006 B Wall L Ctr I Plaster White -0.3 009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1	QM
009 C Door Ctr Lft casing I Metal White -0.4 010 D Wall L Ctr I Drywall White 0.1	QM
010 D Wall L Ctr I Drywall White 0.1	QM
2	MQ
008 D Door Ctr Lft casing I Wood White -0.5	
	MQ
007 D Door Ctr L Ctr I Wood White -0.1	
011 D Cabinet Ctr I Wood White -0.2	MQ
Interior Room 002 H-4	63.5
016 A Window Ctr Lft casing I Metal White 2.4	
O15 A Post Ctr I Metal White 3.7	
012 B Wall L Ctr I Plaster White -0.4	
017 C Wall L Ctr I Drywall White -0.5	_
014 C Door Ctr Lft casing I Metal White -0.5	_
013 C Door Ctr L Ctr I Wood White -0.4	~
018 D Cabinet Ctr I Wood White -0.7	QM
Interior Room 003 F-8	
026 A Window Ctr Lft casing I Metal White -0.2	QM
025 A Post Ctr I Metal White -0.1	
028 C Door Ctr Lft casing I Metal White -0.2	
027 C Door Ctr U Lft I Wood White -0.4	
029 D Wall L Ctr I Plaster White -0.2	
030 D W-trim Ctr I Wood White -0.3	
031 D Cabinet Ctr I Wood White -0.1	
Interior Room 004 F-10	
036 A Wall L Ctr I Concrete White -0.3	QM
032 A Window Ctr Lft casing I Metal White -0.4	QM
035 A Door Ctr Lft casing I Metal White -0.2	QM
034 A Door Ctr L Ctr I Wood White -0.3	MQ
033 A Post Ctr I Metal White -0.6	MQ
039 A Vent Ctr I Metal White -0.5	
037 B Wall L Ctr I Plaster White -0.3	MQ
038 D W-trim Ctr I Wood White -0.4	QM
Tatonion Doom OOF C 160	
Interior Room 005 C-16A	○1 4
047 A Wall L Ctr I Drywall White -0.2	_
050 B Window Ctr Lft casing I Wood White -0.2	
049 D Door Ctr Lft casing I Wood White -0.2 048 D Door Ctr L Ctr I Wood White -0.1	
048 D Door Ctr L Ctr I Wood White -0.1	MQ
Interior Room 006 C-15	
051 A Window Ctr Lft casing I Wood White -0.2	QM
052 A Window Ctr Lft casing I Metal White -0.2	
054 A Door Ctr Lft casing I Wood White 0.0	
053 A Door Ctr L Rgt I Wood Blue -0.3	
055 A Cabinet Ctr I Wood White -0.3	
056 D Wall L Ctr I Plaster White -0.3	

Inter	ior R	Room 007 C-13							
062	A	Window	Ctr	Lft casing	I	Wood	White	-0.3	QM
063	A	Window	Ctr	Lft casing	I	Metal	White	-0.2	QM
057	В	Wall	L Ctr		I	Drywall	White	-0.5	QM
060	С	Wall	L Ctr		I	Drywall	White	-0.2	QM
059	С	Door	Ctr	Lft casing	I	Wood	White	-0.3	QM
058	С	Door	Ctr	L Ctr	I	Wood	White	-0.2	QM
061	D	Cabinet	Ctr		I	Wood	White	-0.3	QM
 Tnter	ior R	Room 008 A-17							
071	A	Wall	L Ctr		I	Plaster	White	-0.2	QM
074	A	Window	Ctr	Lft casing	I	Wood	White	-0.4	QM
075	А	Window	Ctr	Lft casing	I	Metal	White	-0.3	QM
073	А	Door	Ctr	Lft casing	I	Wood	White	-0.3	QM
072	А	Door	Ctr	L Ctr	I	Wood	White	-0.2	QM
076	С	Wall	L Ctr		I	Drywall	White	-0.5	QM
077	D	Cabinet	Ctr		I	Wood	Brown	-0.4	QM
	ior R	toom 009 A-18							
078	В	Wall	L Ctr		I	Drywall	Beige	-0.2	QM
080	С	Door	Ctr	Lft casing	I	Wood	Beige	-0.5	QM
079	С	Door	Ctr	L Ctr	I	Wood	Beige	-0.7	QM
081	D	Cabinet	Ctr		I	Wood	White	-0.4	QM
Inter	ior R	Noom 010 A-20							
082	A	Window	Ctr	Lft casing	I	Wood	White	-0.5	QM
083	A	Window	Ctr	Lft casing	I	Metal	White	-0.5	QM
085	A	Door	Ctr	Lft casing	I	Wood	White	-0.3	QM
084	A	Door	Ctr	L Ctr	I	Wood	Green	-0.4	QM
086	В	Wall	L Ctr		I	Drywall	White	-0.3	МQ
Calib	ratio	n Readings							
001	14010	ii itaaaiiigo						1.0	TC
002								0.7	TC
003								0.9	TC
105								1.2	TC
106								1.0	TC
107								0.7	TC
			_					- • •	_ ~

---- End of Readings ----

We bster

DW P M C B S CE

9-26-16

P. F. I

Site: Library Bloc Unit: Project # **ROOM EQUIVALENT:** INSPECTOR: Number Component Wall Location Substrate Condition Color **Æ**B C **Ø**) **∕**A) B C D 4 Wall R 6 W DW PM C B S CE F X white Wall Post R C W DW P/M)C B S CE FW 6 AB CD words lose ₩all $R \otimes$ W DW PATC B S CE FO Wall ABOD R (0) WDWPMOBS CE F 4 Doa ABQD RO C L DW P M C B S F 42 Ρ Brow Œ Baseboard Luce ABED OR) C DW POWCBS F CE Р 10 Door A)BCD 12) R С ODW PMCBSCE P FO wh. 11 Door casing ADB C D R / OOV DW P M C B S CE P FO Door jamb ABCD W DW P M C B S CE R C Р FI Geiling Wh ((ADB C D 12 R O W DW (P)M C B S F (C) CE 13 A 60 C D Window casing Daw B С W DW POMP C B S CE Р FCB Window sash Α B/C D B C W DW P DW C B S CE F4 Cablnets Α BCD R DW P M C B S CE Р FI ABCD W DW P M C B S CE R С ABCD R C

W

2 m

C

Notes:

Number	Component	Wall	Location	Substrate	Condition	Color
15	Wall	A/B/C D	L R	W DW PM C B S CE		white
16	Walt Dov	A)BCD	OR C	W DW P M C B S CE	PFO	Red
17	Wall LCCE	(A) B C D	D R C	W DW PM & B S CE	PF	WWI
18	Wall Post	A B OD	L R @	WDWPMCBSCE	PFB	
19	Wall	ABOD	L R O	W DW P M C B S CE	PFW	-
20	Basebeard Pa Ca	A B CO D	L R (Q)	W DW PAR C B S CE	PFCD	4
21	Door Basely-d	BBCD	K) R C	OD DW P M C B S CE	PF	7
22	Door casing casual	A B C(D)	L R (C)	O DW P M C B S CE	PFOS	
<u> </u>	Door jamb	ABCD	LRC	WDWPMCBSCE	PFI	
	Ceiling	ABCD	LRC	WDWPMCBSCE	PFI	
	Window casing	ABCD	LRC	WDWPMCBSCE	PFI	
	Window sash '	ABCD	LRC	WDWPMCBSCE	PFI	
	Cabinets	ABCD	LRC	WDWPMCBSCE	PFI	
		ABCD	LRC.	WDWPMCBSCE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	

Cineris ROOM FOLIVALENT:

Number	Component	Wall	Location	Substrate	Condition	Color
23	Wall	_ A B & D	Ø R C	W DW P M B S CE	P F (D)	WWA
24	Wall Wall	A B 🗗 D	k R C	W DW P W C B EE	PFV	\$ Gve
25	Wall Wall	A B (C>D	(L) R (5)	W DW P C B S CE	PFC	GOTTON L
26	Wall Vert	A B CD	O R C	W DW P CAP C B S CE	PFD	WLIG
27	Don	A B O D	Ø R C	OW PMCBSCE	PFD	treey
28	Baseboard Cock	ABCD	ی R C یار	W DW PAN C B S CE	PFL	2
29	Door flashing	A & C D	LRÓ	W DW P & C B S CE	PF4	
	Door casing	ABCD	LRC	W DW P M C B S CE	PFI	
	Door jamb -	ABCD	L R C	WDWPMCBSCE	PFI	
	Ceiling	ABCD	L R C	W DW P M C B S CE	PFI	
	Window casing	ABCD	L R C	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	LRC	WDWPMCBSCE	PFI	
	,	ABCD	LRC	WDWPMCBSCE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	

W = Wood

DW = Drywall

P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side Address side

Entrance to unit

ALTA ENVIRONMENTAL - XRF DATA FORM Webster 9-26-16

Site: Gla (P-11-12) (Dunit: 7 Project #

ROOM EC	QUIVALENT: /-	12.4		INSPECTOR:		
Number	Component	Wall	Location	Substrate	Condition	Color
30	Wall Cobinet	ABCD	L R 😂	DW P M C B S CE	PFO	who
7(Wall	ADB C D	L de C	WPWPMCBSCE	P FO	h
37	Wall W. C.	Ø B C D	L R Ø	(W)DW P M C B S CE	PF	1
37	Wall _	ABCD	L R CO	W DW P MDC B S CE	PF	
34	Dow	A B & D	LRC	MODW PM CBSCE	PFAD	
35	Baseboard 2 ase	A B O D	L GC	MY DW P M C B S CE	PF4	4
	Door	ABCD	LRC	W DW P M C B S CE	P. F. I	
	Door casing	ABCD	L R C	WDWPMCBSCE	P F I	
	Door jamb	ABCD	LRC	WDWPMCBSCE	P. F. I	
	Celling	ABCD	L R C	W DW P M C B S CE	PFI	
	Window casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	LRC	WDWPMCBSCE	PFI	
		ABCD	LRC	WDWPMCBSCE	P F I	
		ABCD	L R C	WDWPMCBSCE	P#F I	
Votes:						

	NUIVALENT:					
Number	Component	Wall	Location	Substrate	Condition	Color
136	Wall	A 8020 D	E)RC	W DWDP M C B S CE	P FCD	Whit
37	Wall Dow	A B C D	d⊃ R C	DOW PMCBSCE	PFD	
38	Wall Last	ABCD	€ R C	W DW P M) C B S CE	PFW	
34	Wall winds Corpo	A)B C D	ØR C	APDW P M C B S CE	PFD	-1
40	a	ABCD	& R C	W DW PATOC B S CE	PF	
	Baseboard	ABCD	L R C	W DW P M C B S CE	PFI	
	Door	ABCD	LRC	W DW P M C B S CE	PFI	
	Door casing /	ABCD	LRC	W DW P M C B S CE	PFI	
	Door jamb	ABCD	LRC	W DW P M C B S CE	PFI	
	Ceiling	ABCD	L R C	W DW P M C B S CE	PFI	
	Window casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash '	ABCD	L R C	W DW P M C B S CE	PFI	
91	Cabinets	A B C Ø	L R (C)	DW P M C B S CE	P F @	white
		ABCD	L R C	W DW P M C B S CE	PFI	CO CARC
-24		ABCD	L R C	W DW P M C B S CE	PFI	

6,201,1-9 ROOM EQUIVALENT:

		XTENO - 3				
Number	Component	Wall	Location	Substrate	Condition	Color
72	Wall	ADB C D	L BC	W DW P M C B S CE		white
43	Wall W. C.	B B C D	L BC	W DW P MOC B S CE	PFC	Guer
44	Wall Hashing	A)BCD	L & C	W DW P AP C B S CE	PFŁ	10400
45	Watt Pour	A B Ø D	L R (C)	DW P M C B S CE	P F 🗗	EUCKY
46	duse	A B & D	LRG	WDW P M C B S CE	PFW	-1
	Baseboard	ABCD	L R C	W DW P M C B S CE	PFI	
	Door	ABCD	L R C	W DW P M C B S CE	PFI	
	Door casing	ABCD	L R C	W DW P M C B S CE	PFI	
	Door jamb	ABCD	L R C	W DW P M C B S CE	PFI	
	Celling	ABCD	LRC	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	LRC	W DW P M C B S CE	PFI	
		ABCD	L R C	W DW P M C B S CE	PFI	
Notes:					1. 1. 1.	

W = Wood

DW = Drywall P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

ALTA ENVIRONMENTAL - XRF DATA FORM

Webster

9-26-(6

Site: Adun Unit: Project # ROOM EQUIVALENT: Nusz. offer- 6 INSPECTOR: Number Component Wall Location Substrate Condition Color 45 BC D Wall W DW PMCBSCE R C Р FD -4 47 Wall Dow Luce A B C D R W DW P AT C B S CE С FO Wall Dag A. BOC D ODD DW P M C B S CE D R С P F b Wall was Lus ABC(\$) L R MOW PMCB <u>~</u>5 CE FOP 50 Α B C 6 L R MC B S CE W DW P Р F 42 Baseboard Way 5 BBCD R C WDWPMCBS Ρ FW CE Door Α BCD R C W DW P M C B S CE Р FI 52 Door easing wall 75) B C D R С W DW PMCBSCE Ρ F 20 ibha A OF C D Door Jamb C OD DW PMCBS B F CE 42 54 Colling a Cast B) ALB C D C DW P M C B S CE Ρ F 0 Window casing BCD R DW P M C B S CE C W Р F 1 Window sash ABCD R C W DW P M C B S CE Ρ FI Cabinets Oou A B CO R) C DW P M C B S CE Ρ FD ABCD L R C DW P M C B S Ρ F ABCD R W DW P M C B S CE C P. F Notes:

8m.9 ROOM EQUIVALENT: Number Wall Component Location **Substrate** Condition Color 56 Wall-Don Car A BOC D B) C W DW P MDC B S CE P F 💬 (vay Wall Dow L (R) C B)C D WDW PMCBSCE Р F 1 1000 58 Wall val A)B C D R & W PWDP M C В S CE P F wind A B C 6 BO C ØDW P MCBS CE P F (1) 60 DW P MOC B C W S CE P F K Baseboard ABCD R С W DW P M C B S CE Ρ F - 1 Door ABCD R С W DW P M C B S CE Р F 1 Door casing ABCD R С W DW P M C B S Р F CE Door jamb ABCD R C DW P С M В P F I Celling ABCD R C W DW Ρ MCBS CE Ρ F 1 Window casing BCD R С DW P W M_C B S F CE Ρ Window sash Α BCD I. R C W DW P M C B S CE F 6 Cabinets ADB C D MODW PMCBSCE R Ρ FB ABCD L R c WDWPMCBS P CE F ABCD R С W DW P M C B S CE F Р

ROOM	EQUIVALENT:	Exteer-9
LACOIM	LOUIVALLIAI.	7.4000

	Number	Component	Wall	Location	Substrate	Condition	Color
X([62	Wall	ABCD	L R Ĉ	NO DW P M C B S CE	PFP	White
	63	Wall Pour	OR B C D	(B) R C	DW PMCBSCE	PFC	Ever-
-	64	Wall of Cas	(A) B C D	URC	W DW P MC B S CE	PFŁ	2
. 4	65	Wall	(A) B C D	₩R C	W DW P M C B SO DE	PFD	white
才		Who Cose	Ø B C D	L R)C	WODW PMCBSCE	PFD	Lucey
C#	67	Baseboard d	& B C D	L & C	WDWPDCBSCE	P F 49	1
*4	68	Boor flacky	_ABCD	L BC	WDWPWCBSCE	PF4	0
-	68	Door casing Po Sport	A B C>D	Ø R C	WDWPOPCBSCE	P F Ø	White
-		Door jamb /	ABCD	LRC	WDWPMCBSCE	PFI	
-		Ceiling	ABCD	LRC	W DW P M C B S CE	PFI	
-		Window casing	ABCD	L R C	W DW P M C B S CE	PFI	
-		Window sash	ABCD	L R C	W DW P M C B S CE	PFI	
-		Cabinets	ABCD	L R C	W DW P M C B S CE	PFI	
-			ABCD	L R C	WDWPMCBSCE	PFI	
-			A B C D	LRC	WDWPMCBSCE	PFI	
L	Notes:				***************************************		

W = Wood

Notes:

lade

-8

DW = Drywall

P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

Webs les

9-26-16

Cateterion Unit: Project # **ROOM EQUIVALENT:** Stage - 10 **INSPECTOR:** Number Component Wall Location Color Substrate Condition 70 Wall B C D W DW M C B S CE R C PFO WILL 71 Wall ABCOS 85 DW P O C B S CE C F 72 Wall deces-D A B C 49 C DW P W C B S FD CE Wall BCD R С W DW P M C B S CE Р F - 1 BCD R C W DW P M C B S Ρ FI CE Baseboard well A) B C D **6** R DW PM C B S CE Р FOU Door / F A B C O c W DW P MD C B S CE R C Boor casing SCADB C D R DW P (DV C B S CE F @ Door jamb ABCD R C W DW P M C B S CE Р F - } Ceiling ABCD R C DW P M C B S CE F Ρ Window casing A B C D R 0 DW BM CBS CE Р F Window sash AB C D R 6 WDWPOACBS FC CE Cabinets A)B C D F R (C) DW PMC B S CE Р B OD R C DW P M C B S CE Ρ F @ ABCD R C W DW P M C B S CE P. F Notes:

ROOM EQUIVALENT: Cafefural-11

Number	Component	Wall	Location	Substrate	Condition	Color
80	Wall	A B C D	L R B	W DW OM C B S CE	PFB	white
81	Wall	ABCA	L R Q	W DW PM C B S CE	PFU	Red
28	Wall	A B C	L R Ø	W DW PM C B S CE	P F 4	Sluce
8.3	Wall	A B COD	L R (Q)	W DW B M C B S CE	PF4	Colote
84	000	A B ODD	/D'R C	W DW P (N) C B S CE	PFA	Blace
85	Baseboard & Carr	A B C/D	D) R C	W DW P W C B S CE	PFO	Bluck
	Door	ABCD	LRC	W DW P M C B S CE	PFI	
F6	Poor-easing Vac1	_ ⊕ B C D	L RンC	W DW DM C B S CE	PFO	WIIL
8./	Boorjamb W. C.	A B C2D	L R C	WDWPWCBSCE	PFO.	1
884	Calling Pow	A B O D	AS R C	DW PM CB S CE	PFB	1
,84	Window casing &	CABED	DR C	W DW POPC B S CE	PFD	4
	Window sash '	ABCD	L R C	W DW P M C B S CE	PFI	
	Cabinets	ABCD	L R C	W DW P M C B S CE	PFI	
	//	ABCD	LRC,	WDWPMCBSCE	PFI	
100	<i>(</i> /)	ABCD	L R C	WDWPMCBSCE	PFI	
Notes:				19		

ROOM EQUIVALENT: Laure -13

Number	Component	Wall	Location	Substrate	Condition	Color
90	Wall	ØBCD	Q R C	W DW OM C B S CE	PF-CD	-whit
91	Wall Orac	A B C D	L R Ø	OP DW P M C B S CE	P F CG	1
97	Wall Case	A∕B C D	LRE	W DW P A C B S CE	PFE	*
93	Wall W.C.	A B C D	L R (C)	W DW PADC B S CE	PFO	
		ABCD	L R C	W DW P M C B S CE	PFI	
1 94	Baseboard way	ABOD	LRC	W DW P M C SCE	PFΦ	white
95	Door	A B C D	LRC	(NO DW P M C B S CE	PF	Kreey
46	Door casing W.L	A B Ø D	LRE	W DW P DP C B S CE	PFO	1
al	Door jamb. W. C. Acst		LR(S	W DW P (N) C B S CE	P F 🗗	1
	Ceiling	ABCD	LRC	W DW P M C B S CE	PFI	
	Window casing	ABCD	LRC	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	W DW P M C B S CE	PFI	
	Cabinets	ABCD	LRC	W DW P M C B S CE	P F I	
		ABCD	LRC	W DW P M C B S CE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	
Notes:						

W = Wood

DW = Drywall

P = Plaster N

M = Metal C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are Identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

18 - 0.7

99.1.0

loo 0-9 f:\alta documents\field forms\whs\xrf data form.doc 2 2,7 ALTA ENVIRONMENTAL - XRF DATA FORM Webs le

Unit:

Websler

Project #

 \mathscr{S}

9=27-16

-14 ROOM EQUIVALENT: 2 **INSPECTOR:** Number Component Wall Location Substrate Condition Color 13 THE Post ₩all A B C D d R W DW PATE B S CE Р F Wall-W. ADB C D (5) W DW POO C B S CE R C F (C) Wall A B C D $R \bigcirc$ W DW/P) M C B S CE F 🔘 Watt Dow B CC RD C DW PM CBS CE F 1000 ABCO B/C DW P M C B S CE Р F F Baseboard 4 BCD R С W. DW P M C B S CE Р F Door BCD Α L R C W DW P M C B S Р FI CE Door casing A B 00 D L R DW PADC B S CE F_(1) 10 Doorjamb Wwll W DW P M C B S CE ABCO ムン R С FO Ocilling Cub we ABCDI R 00 P M C B S CE WOOW FO Window casing BCD Α R C W. DW P M C B S CE Р F Window sash ABCD R C W DW P M C B S CE Р F Cabinets ABCD R C DW P M C B S CE Р F ABCD R C W DW P M C F B S CE ABCD R C DW P M C B S CE P. F Notes:

ROOM EQUIVALENT: PLY-5

3 .7 Site:

	Number	Component	Wall	Location	Substrate	Condition Color
_	12	Wall	A BCD	L R C	W DW PM C B S CE	PFD WLite
	13	Wall Pour	A B Ø D	LORC	DW P M C B S CE	PF® 1
	14	Wall + Cese	A B & D	L & C	W DW P ODC B S CE	PFO
	15	Wall Post	Ø B C D	LRCD	W DW POW C B S CE	P FOD
*		mmd,-6-50	ABCD	LRO	W DW P W C B S CE	PFI
_		Baseboard	ABCD	LRC	WDWPMCBSCE	PFI
_	17	Door Wall	A B 🖒 D	L EDC	WOMPMCBSCE	PFD White
_	18	Door casing - Cabre.	ABCO	L R C	OW PMCBSCE	P FOD 1
_		Door jamb	ABCD	LRC	WDWPMCBSCE	PF
<u></u>	4	Celling	ABCD	LRC	W DW P M C B S CE	PFI
_		Window casing	ABCD	L R C	WDWPMCBSCE	PFI
_		Window sash '	ABCD	L R C	W DW P M C B S CE	PFI
_		Cabinets	ABCD	L R C	W DW P M C B S CE	PFI
			ABCD	LRC.	W DW P M C B S CE	PFI
	130		ABCD	L R C	W DW P M C B S CE	PFI

ROOM EQUIVALENT: Exter -18

	XOTT TELITIT	Alce				
Number	Component	Wall	Location	Substrate	Condition (olor
19	Wall	ABCZD	L RZC	W DW P M C B CE	PFO WL	
70	Wall Down	A B CD	L R C	(V) DW P M C B S CE	PFC Gre	
21	Watt 2 CCS	ABCD	LRE	W DW P W C B S CE	PFU	-1
22	Wall Rack	A B CD	LR(C)	OD DW P M C B S CE	PFC CUC	:/-
73	Mrg-Cely	A B C D	LRKO	W DW P MC C B S CE	PFB Gere	
24	Basebeard Hacks	& B C D	L R/C	W DW P CH C B S CE	Al	
	Door	ABCD	L R C	W DW P M C B S CE	PFI D	
	Door casing	ABCD	LRC	W DW P M C B S CE	PFI	
	Door jamb	ABCD	L R C	W DW P M C B S CE	PFI	
	Ceiling	ABCD	L R C	W DW P M C B S CE	PFI	
	Window casing	ABCD	LRC	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	W DW P M C B S CE	PFI	
	Cabinets	ABCD	L R C	W DW P M C B S CE	PFI	
		ABCD	L R C	W DW P M C B S CE	PFI	
		ABCD	L R C	W DW P M C B S CE	PFI	
Notes:					FFI	

W = Wood DW

DW = Drywall

P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

003/1913

WODS Ley

Site: Bldy Rm 8-PIO Unit: 8 Project #

	UIVALENT: Q	1 -16		INSPECTOR:		
Number	Component	Wall	Location	Substrate	Condition	Color
	Walt Post	A B C D	C) R C	W DW P KOC B S CE	PFD	White
	Wall W. C.	A)BCD	LOR C	W DW PMC B S CE	P F d	44
	Wall Doo	ABOD	L B C	W DW P M C B S CE	PFC	7
28	Watt decre	A B 🖒 D	L&C	W DW P M C B S CE	PF Ł)	d
2a	Wall	A B C (D)	L R (C)	W DW P M C B S CE	PFO	celu/
30	Beseboard - Trus	A BCD	LRO)	OW PMCBSCE	P F Q	1
	Door	ABCD	LRC	W DW P M C B S CE	PFI	
,	Door casing	ABCD	L'RC	WDWPMCBSCE	PFI	
	Door jamb	ABCD	L R C	W DW P M C B S CE	PFI	
	Ceiling	ABCD	L R C	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	······································
3.(Cabinets	ABCO	T 89	AV DW P M C B S CE	PFO	wwife
		ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	L R C	WDWPMCBSCE	P. F	

Number	Component	Wall	Location	Substrate	Condition	Color
32	₩ell 60, C.	₽ B C D	L R 63	W DW P AC B S CE	PFØ	White
33	Wall Post	<u> </u>	LRC	WDWPARCBSCE	PFW	
34	Wall Dow	BBCD	R C	DW P M C B S CE	PFO	
35	Wall a cuse	₽ BCD	₩ R C	WDWPADCBSCE	PF	
36	Wall	BBCD	WR C	W DW P M COB S CE	PFO	1
37	Baseboard-WCU	A BC D	L R O	WDWPMCBSCE	P F (D)	1
38	Book of me	ABÇ(O)	L BOC	WDW P M C B S CE	P FO	-
39	Boor easing Vent	(A) B C D	(L) R C	W DW P OD C B S CE	PFQ	4
(3)	Door jamb	ABCD	L R C	WDWPMCBSCE	PFI	
0.0	Ceiling	ABCD	L R C	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash '	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	LRC.	WDWPMCBSCE	PFI	
-		ABCD	L R C	WDWPMCBSCE	PFI	

KOOW E	JUIVALENT:	Krew -17				
Number	Component	Wall	Location	Substrate	Condition	Color
40	Wall	BBCD	L R C	W DW P M CB S CE	PF	While
4 41	Wall W. C.	ØB C D	L R	W DW P M C B S CE	PFP	Green
42	Wall D. C.	A)B C D	L AR C	W DW P (M) C B S CE	P FO	1
43	Wall Flechus	ØB C D	LRE)	W DW PM C B S CE	P F(T)	
74	Dow	(A) B C D	(L) R C	OW PMCBSCE	P FCT	Green
45	Baseboard Jent	Q B C D	LR)C	W DW P NOC B S CE	P F(T)	white
46	Door Fack	ABCTD	L R C	DW P M C B S CE	PFO	White
	Door casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Door jamb	ABCD	LRC	W DW P M C B S CE	PFI	
	Ceiling	ABCD	LRC	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	W DW P M C B STCE	PFL	
	Window sash	ABCD	LRC	W DW P M C B S CE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	
Notes:						

W = Wood

DW = Drywall P = Plaster M = Metal C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

Webs 104

9-27-16

13 -016 A Unit: __ Project # ROOM FOLIVALENT. // A

	JUIVALENT: 16 A	-10.		INSPECTOR:		
Number	Component	Wall	Location	Substrate	Condition	Color
47	Wall	B BCD	L R C	WEAPMCBSCE	PFQ	White
48	Well Dow	A B C Ø	⊕ R C	M DW P M C B S CE	PFB	1
49	Wall I Cary	A B C O		W DW P M C B S CE	PF	
80	Wall W.C.	A Æ CD	L R) C	DW P M C B S CE	PFC	
		ABCD	LRC	WDWPMCBSCE	PFI	
51	Baseboard W.C.	BBCD.	L R 🐑	WDDW P M C B S CE	P F Ø	white
52	DOOR W.C.	(A) B C D	L R O	W DW P MO B S CE	PFK	1
53	Door casing Door	A)BCD	J⊋ R C	@ DW P M C B S CE	PFO	Blue
54	Doorjamb, Lare	A) B C D	(L) R C	DW P M C B S CE	PFP	wh.to
55	Ooiling Casart	A B CO	LRO	W PW PM CB S CE	P F 🗘	While
56	Window easing pall	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash	ABCD	LRC	WDWPMCBSCE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	L R C	WDWPMCBSCE	P. F I	
Notes:						

Ru 13 -20 ROOM EQUIVALENT: Number Component Wall Location Substrate Condition Color 57 Wall A BC D R C W DV PMCBSCE PFU 38 A B Ø D Wall-B DW P M C B S CE P F P 59 & care Walt A B D D B/ C AW DW P M C B S CE P F 4 bwallA BC)D 60 L B) C WODPPMCBS CE Р F do ABCO R 0 DW P M C B S CE Р F 62 -Baseboard W. B C D DW P M C B S CE R Р FO Door (0), (ABCD R W DW P NADC B S CE FW Door casing ABCD R W DW P M C B S CE C FI Door jamb ABCD W DW P M C B S CE R С Р F Celling ABCD W DW P M C B S R C F Window casing ABCD R С DW P M C B S CE Р F 1 Window sash ABCD R С W DW P M C B S CE Р F Cabinets ABCD R C W DW P M C B S CE Р FI ABCD R C W DW P M C B S CE Р FI ABCD R С W DW P M C B S CE Р F Notes:

Number	Component	Wall	Location	Substrate	Condition	Color
64	Wall Our	⊕ B C D	L R 🖒	WDW P M C B S CE	PFP	Gueen
65	Watt dese	(A) B C D	L R 🖒	W DW P TALL C B S CE	PF	00 - 9
66	Wall W~d-(-51	@BCD	L R 🖒	W DW P (ND C B S CE	PFG	
67	Wall- 4	A B C>D	L R Ø	W DW P DC B S CE	PFK	7
68	terbe	A BOCD	L R ©	W DW P MOC B S CE	P FU	5 4. √e
69	Baseboard Wall	А В О Д D	L R O	W DW P M C B S CE	P FC	white
70	Door Rack	A B 6 D	L R C	(A) DW P M C B S CE	PFØ	4
	Door casing	ABCD	L-R C	WDWPMCBSCE	PFI	
	_Door jamb	ABCD	L R C	WDWPMCBSCE	PFI	
	Ceiling	ABCD	L R C	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	
oles:		ABCD	LRC	WDWPMCBSCE	PFI	

M = Metal C = Concrete B = Brick S = Stucco SIDE IDENTIFICATION: Sides B, C & D are Identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit

CE = Ceramic

Site: Ru 17-120 Unit: Project # 7. -21 ROOM EQUIVALENT: **INSPECTOR:** Number Component Wall Location Substrate Condition Color 71 Wall ADB C D W PM C B S CE PFD R С 72 Wall Vo w AB C D 0 NO DW P M C B S CE R F (LILLE 73 Watt (A) B C D R С W DW P M C B S CE Ρ FW W.C. A B C D Wall L R (C) OW DW P M C B S CE Р F /b 75 1 (A) B C D PFB R W DW P DO C B S CE 76 Basebeard Wull A B (0) D B/C WADAPMCBS CE 7700 -Door Cabint ABCO R WDW PMCBSCE 15100 Р F Door casing ABCD R W DW P M C B S CE C Р F I Door jamb ABCD L R C W DW P M C B S CE Ρ F | Gelling Wall ABCD (R) C WOOPMCBSCE Ρ FO Berse Window casing Po ABCD B C W DW P M C B S CE Ρ F O Window sash & Cas BED Α æ C NO DW P M C B S CE Р F (1) Cabinets ABC(B) R 0 W DW P M C B S CE F Р ABCD R С W DW P M C B S CE Р FI ABCD R С W DW P M C B S CE P. FI Notes: 2. 217-13

18

-72

Number	Component	Wall	Location	Substrate	Condition	Color
81	Wall W. C.	ABCD	LRCO	DW PM CB S CE	PFC	white
23	Wall	ØB C D	L R 🐼	W DW P OC B S CE	PFW	7
24	Watt Dow	₿ BCD	Ĉ R C	ON DW P M C B S CE	PFCP	Wery
85	Wall dece	_ ∠ B C D	4 R C	(W) DW P M C B S CE	PF4	white
86	Whil	A & C D	L R O	WEAPPMCBSCE	P F 🗘	White
	Baseboard	ABCD	LRC	W DW P M C B S CE	PFI	
	Door	ABCD	LRC	W DW P M C B S CE	PFI	
	Door casing	ABCD	L R C	W DW P M C B S CE	PFI	
100	Door jamb	ABCD	L R C	W DW P M C B S CE	PFI	
	Ceiling	ABCD	LRC	W DW P M C B S CE	PFI	
	Window casing	ABCD	LRC	W DW P M C B S CE	PFI	
	Window sash '	ABCD	L R C	W DW P M C B S CE	PFI	
	Cabinets	ABCD	LRC	W DW P M C B S CE	PFI	
		ABCD	LRC,	W DW P M C B S CE	PFI	
00		ABCD	L R C	WDWPMCBSCE	PFI	

Exter -13 ROOM EQUIVALENT:

Number	Component	Wall	Location	Substrate	Condition	Color
67	Wall W. 4	₿ BCD	L R (C)	W DW P M C B S CE	PFO	Gere
88	Wall W. C	(ABCD	L B C	W DW P M C B S CE	PFW	4
89	Wall Doa	A B 🗘 D	€ R C	ADW PMCBSCE	PFO	
90	Wall 2 Cose	A B 🖒 D	₩ R C	DW P M C B S CE	PF4	P.
41	Plotloras	A B G D	L R (C)	W DW P C B S CE	PFD	
92	Baseboard Wall	A)B C	L R	W DW P M C B S CE	PFO	whit.
93	Door Wall	A B COD	LRO	W DW P M C B SOCE	PFQ	4
94	Door casing	A B COD	B) R C	DW P M C B S CE	P F (1)	Guera
	Door jamb	ABCD	LRC	W DW P M C B S CE	PFI	
	Celling	ABCD	LRC	W DW P M C B S CE	PFI	
	Window casing	ABCD	LRC	W DW P M C B S-CE	PFI	
	Window sash	ABCD	L R C	WDWPMCBSCE	PFI	
	Cabinets	ABCD	LRC	WDWPMCBSCE	PFI	
		ABCD	L R C	W DW P M C B S CE	PFI	
		ABCD	LRC	W DW P M C B S CE	PFI	

W = Wood

DW = Drywall

P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

Address side Entrance to unit ALTA ENVIRONMENTAL - XRF DATA FORM Websiler

9-21-16

walk ways Unit: Project # **ROOM EQUIVALENT:** 17-020-24 INSPECTOR: Number Component Wall Location Substrate Condition Color 95 Post A B R) D R 🖉 W DW POOC B S CE P F 13 Every Well Gutte ABØD R 62 W DW P MP C B S CE Р FB 97 W DW P AP C B S CE WALL DOWNSOLT A B e D d R Р FK 98 Wall Rean Q BBCD R C ON DW P M C B S CE Р Fa 99 cerlne AB C D ي R W DW P M C B S CE C F4 100 Baseboard BB CD R C W DW P M C B S CE FO Door ABCD R С W DW P M C B S CE Р FI Door casing ABCD L R С W DW P M C B S CE Ρ F I Door jamb A B C D R C DW P M C B S CE Р FI Ceiling ABCD R С DW P M C B S CE FI Window casing ABCD L R C DW P M C B S CE -F Window sash ABCD R C W DW P M C B S CE Ρ F - 1 Cabinets ABCD R C W DW P M C B S CE Р F ABCD R C W DW P M C B S CE Ρ FI ABCD R С W DW P M C B S CE P. F | Notes:

ROOM EQUIVALENT: by Away -23

Number	Component	/ Wall	Location	Substrate	Condition	Color
Pest		A B Ø D	BR C	W DW P OL C B S CE	PFG	Gerand 4
102	Wall Parcet	A B C D	R C	W DW P M C B S CE	PFW	- 4
103	Wall fluctily	A B & D	COR C	W DW P AM C B S CE	PF	
104	Wall Celling	A B & D	R C رجار	W DW P M C B & CE	PF	White
		ABCD	L R C	W DW P M C B S CE	PFI	
	Baseboard	ABCD	LRC	W DW P M C B S CE	PFI	
	Door	ABCD	L R C	W DW P M C B S CE	PFI	
	Door casing	ABCD	LRC	W DW P M C B S CE	PFI	
<u></u> :	Door jamb	ABCD	L R C	W DW P M C B S CE	PFI	
	Celling	ABCD	L R C	W DW P M C B S CE	PFI	
	Window casing	ABCD	L R C	WDWPMCBSCE	PFI	
	Window sash '	ABCD	L R C	W DW P M C B S CE	PFI	
	Cabinets	ABCD	L R C	WDWPMCBSCE	PFI	
		ABCD	LRC.	W DW P M C B S CE	PFI	
94		ABCD	L R C	W DW P M C B S CE	PFI	

ROOM EQUIVALENT:

Number	Component	Wall	Location	Substrate	Condition	Color
	Wall	ABCD	L R C	W DW P M C B S CE	PFI	
	Wall	ABCD	L R C	W DW P M C B S CE	PFI	
	Wall	ABCD	L R C	W DW P M C B S CE	PFI	
	Wall	ABCD	LRC	W DW P M C B S CE	PFI	
		ABCD	L R C	W DW P M C B S CE	PFI	
	Baseboard	ABCD	L R C	WDWPMCBSCE	PFI	
	Door	ABCD	LRC	WDWPMCBSCE	PFI	
	Door casing	ABCD	LRC	WDWPMCBSCE	PFI	
	Door jamb	ABCD	LRC	WDWPMCBSCE	PFI	
	Ceiling	ABCD	LRC	WDWPMCBSCE	PFI	
	Window casing	ABCD	L R C	W DW P M C B S CE	PFI	
	Window sash	ABCD	L R C	W DW P M C B S CE	PFI	-
	Cabinets	ABCD	LRC	W DW P M C B S CE	PFI	
		ABCD	LRC	WDWPMCBSCE	PFI	
	<u></u>	ABCD	LRC	W DW P M C B S CE	PFI	

W = Wood

DW = Drywall

P = Plaster

M = Metal

C = Concrete B = Brick

S = Stucco

CE = Ceramic

SIDE IDENTIFICATION: Sides B, C & D are identified clockwise from Side A; where Side A corresponds to: North side

North side Address side Entrance to unit

105-1.2

1 - 6. 1 f:\alta documents\field forms\whs\xrf data form.doc

LEAD HAZARD EVALUATION REPORT

Section 1 — Date of Lead Hazard Evaluation 9-/26/16,	9/27/16		
Section 2 — Type of Lead Hazard Evaluation (Check o	ne box only)		
✓ Lead Inspection Risk assessment Cle	arance Inspection	Other (specify) Limited fo	r construction purpose
Section 3 — Structure Where Lead Hazard Evaluation	Was Conducted		
Address [number, street, apartment (if applicable)]	City	County	Zip Code
3601 Winter Canyon Road	Malibu	Los Angeles	90265
Construction date (year) of structure Multi-unit building Single family dwelling	School or daycare Other	Children living in structu Yes V N Don't Know	
Section 4 — Owner of Structure (if business/agency, li	st contact person)		
Name		Telephone number	
Santa Monica Malibu USD			
Address [number, street, apartment (if applicable)]	City	State	Zip Code
1651 Sixteenth Street	Santa Monica	California	90405
Section 5 — Results of Lead Hazard Evaluation (check	all that apply)		
No lead hazards detected Lead-contaminated dust Section 6 — Individual Conducting Lead Hazard Evalue Name Fabian Ruvalcaba		Telephone number	hther
Address [number, street, apartment (if applicable)]	City	State	Zip Code
3777 Long Beach Blvd., Annex Building	Long Beach	California	90807
22130	ature A		Date 9/22/16
Name and CDPH certification number of any other individuals cor Section 7 — Attachments	ducting sampling or testing	(if applicable)	
A. A foundation diagram or sketch of the structure indicating lead-based paint; B. Each testing method, device, and sampling procedure u.C. All data collected, including quality control data, laborate.	ised;		
First copy and attachments retained by inspector	Third copy only (no a	ttachments) mailed or faxed	to:
Second copy and attachments retained by owner		oning Prevention Branch Re way, Building P, Third Floor	ports

A al al a a a a /I I = 14 B I =		on Check		Page 1 of
Address/Unit No.	Webster ES			
Device	LPA-1			
Date	9/26/2016		XRF Sei	rial No. 1184
Contractor	Alta Environmenta	al		
Inspector Name	Fabian Ruvalcaba		Signatur	e
NIST SRM i lead	1.04	ma/cm2		
Calibration Check			ma/cm2	
First Calibration C				
	NIST SRM		First Average	Difference Between Average and NIST SI
	Second reading			
0.8	0.8	0.9	0.83	0.207
	Second reading		-	
0.9	1	0.9	0.93	0.107
Third Calibration (Check (if required))		
	NIST SRM Second reading	Third reading	First Average	Difference Between f Average and NIST SI
	Second reading		First Average	Average and NIST Si
First Reading Fourth Calibration	Second reading Check (not requ	ired)		Average and NIST SI
First Reading Fourth Calibration	Second reading Check (not requ	ired)		Average and NIST Si

	Calibratio	on Check 7	est Result	S		Page 1 of 1	
Address/Unit No.	Webster ES						
Device	LPA-1						
	9/27/2016			XRF Serial	No.	1184	
Contractor	Alta Environmenta	1				·	
Inspector Name	Fabian Ruvalcaba			Signature	The		
NICT COM Local	4.04				1		
NIST SKIVI Used	1.04	mg/cm2	, 0				
Calibration Check	l olerance Used _	0.3	mg/cm2				
First Calibration C	heck						
	NIST SRM		First Average			Between first nd NIST SRM*	
First Reading	Second reading	Third reading					
1	0.7	0.9	0.87		0.174		
	-						
Second Calibration	n Check						
	NIST SRM		First Average	-		Between first nd NIST SRM*	
	Second reading						
1.2	1	0.7	0.97		0.07		
Third Calibration C	Check (if required)						
	NIST SRM		First Average			Between first nd NIST SRM*	
First Reading	Second reading	Third reading					
Fourth Calibration	Check <i>(not requi</i>	red)					
	NIST SRM		First Average			Between first nd NIST SRM*	
First Reading	Second reading	Third reading		-			
the specified Calib recommendations	if the difference of the Calibration Check Average from the NIST SRM film value is greater than he specified Calibration Check Tolerance for this device, consult the manufacturer's ecommendations to bring the instrument back into control. Retest all testing combinations ested since the last successful Calibration Check test.						

Appendix H

Alta Environmental Employee Certifications

State of California Division of Occupational Safety and Health **Certified Asbestos Consultant**

Cesar Ruvalcaba of

Certification No. 95-1799

Expires on 10/27/17

This certification was issued by the Division of Occupational Service and Health as authorized by Sections 7180 at 50 m file Business and Professions Code.



State of California Division of Occupational Safety and Health **Certified Asbestos Consultant**

Certification No. 15-5633

Expires on 1977/17

This certification was Issued to the Division of Occupational Service and Bealth as authorized by Sections 7 to be serviced by Business and Professions Code.



State of California Division of Occupational Safety and Health **Certified Asbestos Consultant**

David R Schack

Certification No. 92-0219

Expires on 07/09/17

This certification was issued by the Division of Occupational Sefety and Health as authorized by Sections 7180 et sed of the Business and Professions Code.

Certificate Of Completion

Asbestos Building Inspector Initial Course

DOSH #:CA-015-05

Anthony Vincente

ABII0613160001N9487

Alan Dages

Principal Instructor

6/13/2016

Course Start Date

6/15/2016

Course End Date

Michael W. Horne

Michael W. Horner

Training Director

6/15/2016

Exam Date

6/15/2017

Expiration Date

This course satisfies the education requirements for Asbestos accreditation under the Toxic Substances Control Act, Title II. This course has been approved by the Department of Industrial Relations, Division of Occupational Safety and Health of the State of California

NATEC International, Inc.

National Association of Training and Environmental Consulting

1100 Technology Circle- Suite A, Anaheim, CA 92805 • www.natecintl.com • 800-969-3228

Important Industry Contacts

CAL-OSHA: Ph# (916) 574-2993

(916) 483-0572 Fax Notification

web: www.dir.ca.gov or calosha.com

CDPH/CLPPB:Ph# (510) 620-5600

Web: www.cdph.ca.gov/programs/CLPPB

SCAQMD:

Ph# (909) 396-3739 Fax#(909) 396-3342

BAAQMD: Ph# (415) 749-4762 NATEC International, Inc.

National Association of Training and Environmental Consulting

Anaheim, CA . Oakland, CA . Fresno, CA . Sacramento, CA

Asbestos · Lead · Mold · HAZWOPER

P.O. Box 25205 Anaheim, CA 92825-5205 (714) 678-2750, (800) 969-3228, Fax (714) 678-2757 www.natecintl.com

NATEC International, Inc.

National Association of Training and Environmental Consulting
*Note: Card is not suitable substitute for certificate and is not accepted by SCAQMD as proof of

This Card Acknowledges That Anthony Vincente

Asbestos Building Inspector Initial Course

(Valid for 12 months)

6/13/2016

Michael W. Horner

Training Director

Appendix I

Summary of Lead-Containing Paints

Summary of Lead-Containing Paint

Page 1 of 2

CLIENT: SMMUSD SMSD-16-6285 PROJECT NAME: Webster ES

								Approx.
Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Damage Qty.
Wall	PC-1	plaster	white	building 17-20- room 17 northwest corner	Building- library, 11,12,1,2,3,4,8,9,10,13,1 4,15,16,16A,19,20, cafeteria	78	no	N/A
post	PC-2	metal	white	library north center	interaval at window frames- buildings 8-10, library	1,200	no	N/A
window case	PC-3	metal	white	building 11,12- room 12 north center	interior- building: library, administration, cafeteria 11,12, 8-10, 13-16A,17- 20	2,400	no	N/A
door case	PC-5	metal	white	Library Southwest	interior all buildings	1,100	no	N/A
door	PC-6	wood	white	Library Southwest	interior all buildings	260	no	N/A
doorcase	PC-7	metal	green	Library building C East center	interior all buildings	4,400	no	N/A
baseboard	PC-9	wood	white	Library buildings, room 7 south center	interior buildings all buildings baseboard and wall trims	1,900	no	N/A
cabinet	PC-10	wood	white	buildings 1-4 room 3 west center	interior buildings 11,12, library, administration, cafeteria, 1-4,8-10, 13- 16A, 17-20	2,000	no	N/A
Window case	10A	wood	green	building 17-20 exterior south center	building 17-20 exterior	3,100	no	N/A
wall	PC-11	stucco	white	cafeteria north center	exterior all buildings	520	no	N/A
wall	PC-12	concrete	white	library south center	exterior/interior library, rooms 1-4, 8-10	600	no	N/A
case	PC-14	metal	green	library southwest	exterior all buildings	3,700	no	N/A

Summary of Lead-Containing Paint

CLIENT: SMMUSD PROJECT NO: SMSD-16-6285 PROJECT NAME: Webster ES

Component	Sample No.	Substrate	Paint Color	Sample Location	Material Location	Results (PPM)	Damage	Approx. Damage Qty.
window case	PC-15	wood	white	administration builldings- copy room west center	exterior all buildings except at buildings 1-4	630	no	N/A
pipe	PC- 21	metal	white	cafeteria- storage room northwest	interior all buildings	620	no	N/A
ceiling	PC- 22	metal	green	exterior stage center	cafeteria at stage	61	no	N/A
door	PC- 23	metal	green	exterior stage center	cafeteria at stage	2,500	no	N/A
wall	PC- 26	plaster	blue	buildings administration copy room southwest	administration building copy room	300	no	N/A
ceiling	PC- 29	wood	white	walkway by 17-20 south center	walkway ceilings and beams	2,100	no	N/A

Page 2 of 2