CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD

LOS ANGELES REGION 101 CENTRE PLAZA DRIVE

MONTEREY PARK, CA 91754-2156
1) 266-7500
1: (213) 266-7600



September 11, 1996

Mr. Robert Cornell Santa Monica-Malibu Unified School District 1651 16th Street Santa Monica, CA 90404

UNDERGROUND STORAGE TANK CASE CLOSURE MALIBU PARK SCHOOL 30215 MORNING VIEW DRIVE, MALIBU (I-13216)

Dear Mr. Cornell:

This letter confirms the completion of the site investigation and remedial action for the underground storage tank(s) formerly located at the above-described location.

Based on the available information and with the provision that the information provided to this agency was accurate and representative of site conditions, no further action related to the underground storage tank release is required.

This notice is issued pursuant to a regulation contained in Title 23, California Code of Regulations, Division 3, Chapter 16, Section 2721(e).

If you have groundwater monitoring wells or vapor extraction wells at the subject property, you must comply with the following:

- All wells must be located and properly abandoned
- 2. Well abandonment permits must be obtained from the Los Angeles County Department of Health Services, and all other necessary permits must be obtained from the appropriate agencies prior to the start of work.
- 3. You must submit a report on the abandonment of the wells to this office by September 30, 1996. This report must include at a minimum, a site map, a description of the well abandonment process, and copies of all signed permits.

CHANGED LOD FAMOLICAN OUT CADE DOMERACT 03/12/36				
Site Name MALIBU HIGH SCHOOL Case Number: I-13216 Address 30215 MORNING VIEW DR Staff FileLoc @ MALIBU 90265 Status 9 @ 09/11/96 Cross Street PACIFIC COAST HWY Priority MTBE: Operator Watershed: 5 Phone: () - Groundwater basin:				
Resp. Party SANTA MONICA-MALIBU USD Phone: (310)452-5058 RP Contact CORNELL, ROBERT USTCF 0 0 0 RP Address 1651 16TH ST., SANTA MONICA CA 90404 L Const. Firm Phone: () - Const. Contact Date of Last Rpt/Ltr was 11/06/96				
Lead Agency = R Date Reported: 02/18/93 Date Discovered: 08/26/92 Date Stopped: / How Discovered: Date Stopped: / How Stopped: Close Tank Source of Leak: Substances: HYDROCARBONS Interim Remediation: Abatement Methods: Tank System Upgrade: Tank Local Agency = 19000 COUNTY OF LOS ANGELES Referral Date(s):09/14/95 / / / How Discovered: How Stopped: Close Tank Cause of Leak: NOT REPORTED Amts Leaked: Gals Abatement Methods: Pipeline Active Site Tanks in place				
Case Type: Other Groundwater (O)Status: Case Closed (9) Leak Being Confirmed // (1) Suspension of Work // (6) Pre. Assess. Workplan Sub. 02/18/93 (3A) Letter of Commitment // () Pre. Site Assess. Underway // (3B) Remedial Action // (7) Pollution Characterization // (5C) Post Action Monitoring // (8) Remediation Plan // (5R) Case Closed 09/11/96 (9)				
MTBE first detected on / / Well No. Depth to groundwater (ft): 0.00 Report Date: / / MTBE Benzene TPH (Gas) Highest groundwater concen. (ppb): Highest soil concentration (ppm): Soil type: Current MTBE concen. (ppb): on / /				
Enforcement Type: (0,1,2,3) Enforcement Date (1): / / Enforcement Date (2): / / Enforcement Date (3): / /				
Tracking Dates & Comments follow: 08/29/96 CASE ASSIGNED TO HP BY GK 09/11/96 CASE CLOSED BY RB 11/06/96 DESTRUCTION OF 4 GROUNDWATER				
Dates and Comments by Staff for the following Actions: Staff Review Date: / / Workplan Approved: / / Work Directive: / / Others-Countable: / / Others-Uncountable: / /				
Tickler / / _ Dates & / / _ Comment / / _				
Plume/Site Status: Summary: SITE FILE RWB ASSESSMENT BY JDP ON 5/31/96				

HBC 08 (11/00)

UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT				
	RIGENCY HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED ? YES NO ORT DATE CASE #	FOR LOCAL AGENCY USE ONLY I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNM REPORTED THIS INFORMATION TO LOCAL OFFICIALS PL THE HEALTH AND SAFTY CODE	JRSUANT TO SECTION 25180.7 OF	
	1 1 0 1 7 9 3 v	SIONED	JAN 2 8 1993	
	NAME OF INDIVIDUAL FILING REPORT PHONE	SIGNATURE	4	
¥		1458 -3516 Patent Con	1-	
EPORTED BY	REPRESENTING OWNER/OPERATOR REGIONAL BOARD	COMPANY OR AGENCY NAME	Warte	
EPO PO		LA. CO Dept. of Public Al hambia CA	91803	
	TILE PROPERTY.	1/C Now Bloc	riate ze	
"	NAME Santa Monka Malibu	CONTACT PERSON	PHONE B10,450-8338	
BEACH THE	School District unknown		0101430 030	
PARTY	1651 Sixteenth Street, San			
NOL	Malibu High School	OPERATOR	PHONE	
SITELOCATION	30215 Morining View Driv	re, Malibu, CA	90026	
	CROSS STREET			
9	LOCAL AGENCY AGENCY NAME	CONTACT PERSON	PHONE	
MENT	L.A. County Dept of Public Wosters	Carl Sjobergy	(8/8) 458-3539 PHONE	
MPLEMENTING AGENCIES	REGIONAL BOARD' CR WQCB	Hubot Kang	(213) 266-7619	
	ALABAP		QUANTITY LOST (GALLONS)	
#2 _				
TANCES	TPH 5800	mag _	UNKNOWN	
BUBSTANCES	TPH 5800 BTXE ND/10,000/130,0		✓ UNKNOWN	
MENT BUBSTANCES	TPH 5800 BTXE ND/10,000/130, 6 DATE DISCOVERED HOW DISCOVERED INV	ENTORY CONTROL USUBSURFACE MONITORING		
BATEMENT BUBSTANCES RYOLVED	TPH 5800 BTXE ND/10,000/130,0 DATE DISCOVERED HOW DISCOVERED INV	000 / 15,000 PPB	UNKNOWN NUISANCE CONDITIONS	
ERY/ABATEMENT BUBSTANCES	TPH 5800 BTXE $ND/10,000/130,0$ DATE DISCOVERED HOW DISCOVERED INV $ A = 2 \ln A = 3 \ln A = 3 \ln A $ TANK TEST INV TANK TEST INV	ENTORY CONTROL SUBSURFACE MONITORING OTHER	UNKNOWN NUISANCE CONDITIONS	
VERYABATEMENT	TPH 5800 BTXE ND/10,000/130,0 DATE DISCOVERED HOW DISCOVERED INV / wi Z wi / pi S pi 9 yi Z yi I TANK TEST I TANK DATE DISCHARGE BEGAN	ENTORY CONTROL SUBSURFACE MONITORING BK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT A) REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING	UNKNOWN NUISANCE CONDITIONS PPLY)	
DISCOVERY/ABATEMENT	TPH 5800 BTXE ND/10,000/130,0 DATE DISCOVERED HOW DISCOVERED INV / M Z M / D S D 9 y Z Y TANK TEST TAN DATE DISCHARGE BEGAN M D D D Y Y ENROWN HAS DISCHARGE BEEN STOPPED? YES NO FYES, DATE M M D D Y	ENTORY CONTROL SUBSURFACE MONITORING IK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT A	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK	
DISCOVERY/ABATEMENT	TPH 5800 BTXE ND/10,000/130,0 DATE DISCOVERED HOW DISCOVERED INV / M Z M / D S D 9 y Z Y TANK TEST TAN DATE DISCHARGE BEGAN M D D D Y Y ENROWN HAS DISCHARGE BEEN STOPPED? YES NO FYES, DATE M M D D Y	ENTORY CONTROL SUBSURFACE MONITORING BK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT A) REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK	
VERYABATEMENT	TPH 5800 BTXE ND/10,000/130,0 DATE DISCOVERED HOW DISCOVERED INV / M Z M / D S D 9 y Z Y TANK TEST TAN DATE DISCHARGE BEGAN M D D D Y Y ENROWN HAS DISCHARGE BEEN STOPPED? YES NO FYES, DATE M M D D Y	ENTORY CONTROL USUBSURFACE MONITORING IK REMOVAL UTHER METHOD USED TO STOP DISCHARGE CHECK ALL THAT A REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR CL	PPLY) CLOSE TANK CHANGE PROCEDURE	
SOURCE DISCOVERYABATEMENT	BTXE ND 10,000 130,000 130,000 130,000 130,000 130,000 130,000 130,000 130,000 130,000 130,000 130,0000 130,00	ENTORY CONTROL SUBSURFACE MONITORING IK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT A) REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR PIPING VERFILL RUPTURE/FAILURE ORROSION UNKNOWN	PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER	
DISCOVERY/ABATEMENT	BTXE ND 10,000 130,000 BTXE ND 10,000 130,000 DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL BUBSURFACE MONITORING BK REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT AN REPLACE TANK REPLACE TANK REPAIR PIPING OTHER TANK REPAIR PIPING STAFF REPLACE TANK REPLACE TANK REPLACE TANK REPAIR PIPING STAFF REPLACE TANK REPLACE	PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER	
CASE SOURCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000 130,000 BTXE ND 10,000 130,000 DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL SUBSURFACE MONITORING ENTORY CONTROL SUBSURFACE MONITORING IN REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL PREMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PPING OTHER TANK REPAIR PPING OTHER TANK REPAIR PPING OTHER TANK REPAIR PPING OTHER TANK PROVINCE ORROSION UNKNOWN TWORKPLAN SUBMITTED POLLLITION CHAR	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED)	
SOURCE DISCOVERYABATEMENT	BTXE ND 10,000 130,000 BTXE ND 10,000 130,000 DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL SUBSURFACE MONITORING K REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR PIPING VERFILL SUPTURE/FAILURE ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IT T WORKPLAN SUBMITTED POST CLEANUP IN	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION AGNITORING IN PROGRESS	
CASE SOURCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000 130, 0 DATE DISCOVERED HOW DISCOVERED INV. M	ENTORY CONTROL SUBSURFACE MONITORING ENTORY CONTROL SUBSURFACE MONITORING IN REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL PREMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK PROVINCE ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IF WORKPLAN SUBMITTED POLLLITION CHAP I UNDERWAY POST CLEANUP IN LETED OR UNINECESSARY) CLEANUP UNDER	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION AGNITORING IN PROGRESS	
CURPENT CASE SOUNCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000/130, C BTXE ND 10,000/130, C DATE DISCOVERED HOW DISCOVERED INV / M 7 M / D S D 9 Y Y I TANK TEST TAN DATE DISCOVERED HOW DISCOVERED INV / M 7 M / D S D 9 Y Y I TANK TEST TAN DATE DISCOVERED ON TANK TEST TANK DATE DISCOVERED INV LINKNOWN CAUSE(S) TANK LEAK UNKNOWN ON	ENTORY CONTROL SUBSURFACE MONITORING ENTORY CONTROL SUBSURFACE MONITORING IN REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL PREMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK PROVINCE ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IF WORKPLAN SUBMITTED POLLLITION CHAP I UNDERWAY POST CLEANUP IN LETED OR UNINECESSARY) CLEANUP UNDER	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION HONITORING IN PROGRESS	
CURPENT CASE SOUNCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000/130, C DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL SUBSURFACE MONITORING K REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL REMOVE CONTENTS REPLACE TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IN THE CORROSION POST CLEANUP WELLS IN THE CORROSION CLEANUP UNDERWAY POST CLEANUP UNDERWAY	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION AONITORING IN PROGRESS WAY ENHANCED BIO DEGRADATION (IT)	
CASE SOURCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000/130, C BTXE ND 10,000/130, C DATE DISCOVERED HOW DISCOVERED INV / M 7 M / D S D 9 Y Y I TANK TEST TAN DATE DISCOVERED HOW DISCOVERED INV / M 7 M / D S D 9 Y Y I TANK TEST TAN DATE DISCOVERED ON TANK TEST TANK DATE DISCOVERED INV LINKNOWN CAUSE(S) TANK LEAK UNKNOWN ON	ENTORY CONTROL SUBSURFACE MONITORING K REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT AL REMOVE CONTENTS REPLACE TANK REPAIR TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING ORROSION UNKNOWN TWORKPLAN SUBMITTED POLLUTION CHAP I UNDERWAY POST CLEANUP IN LETED OR UNNECESSARY) CLEANUP UNDER ORROSION REMOVE FREE PRODUCT (FP) PUMP & TREAT GROUNDWATER (GT)	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION MONITORING IN PROGRESS WAY ENHANCED BIO DEGRADATION (IT) REPLACE SUPPLY (RS)	
REMEDIAL CURPENT CASE SOUNCE DISCOVERY/ABATEMENT	BTXE ND 10,000/130, 0 BTXE ND 10,000/130, 0 DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL SUBSURFACE MONITORING K REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL REMOVE CONTENTS REPLACE TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IN THE CORROSION POST CLEANUP WELLS IN THE CORROSION CLEANUP UNDERWAY POST CLEANUP UNDERWAY	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION MONITORING IN PROGRESS WAY ENHANCED BIO DEGRADATION (IT) REPLACE SUPPLY (RS)	
CURPENT CASE SOUNCE/ DISCOVERY/ABATEMENT	BTXE ND 10,000/130, 0 BTXE ND 10,000/130, 0 DATE DISCOVERED HOW DISCOVERED INV M	ENTORY CONTROL SUBSURFACE MONITORING K REMOVAL OTHER METHOD USED TO STOP DISCHARGE (CHECK ALL THAT ALL REMOVE CONTENTS REPLACE TANK REPAIR PIPING OTHER TANK REPAIR PIPING OTHER TANK REPAIR PIPING ORROSION UNKNOWN DRINKING WATER - (CHECK ONLY IF WATER WELLS IN THE CORROSION POST CLEANUP WELLS IN THE CORROSION CLEANUP UNDERWAY POST CLEANUP UNDERWAY	UNKNOWN NUISANCE CONDITIONS PPLY) CLOSE TANK CHANGE PROCEDURE SPILL OTHER HAVE ACTUALLY BEEN AFFECTED) RACTERIZATION MONITORING IN PROGRESS WAY ENHANCED BIO DEGRADATION (IT) REPLACE SUPPLY (RS)	