NV5
ALTA ENVIRONMENTAL

Client: SMMUSD

Page 1 of 1

Project Name: SAMOHI

Alta Job No.: SMSD-21-10154

TIME OF OBSERVATION	COMMENTS
	Final clearance letter for H127
	Miller Environmental have completed all abatement of asbestos containing materials at H127. Miller Environmental removed Mirror mastic and Transite pipe. Exterior paint has been stabilized. All work areas have been cleared by ALTA. No asbestos containing materials remain at Bldg H127.

For Bag-Out Shift Only

# of Bags	Manifest #

Alta Rep. Signature: [signature]
Cert. Number: 17-6028
Date: 6/17/21