



Division of the
State Architect

CALIFORNIA DEPARTMENT OF GENERAL SERVICES


FORM

DSA-293

rev. 01/12

Geotechnical Verified Report (GVR)

Note: This form must be submitted by the Responsible Geotechnical Engineer within 14 days of the conclusion of the soil related testing / inspection program, or when work has stopped for more than one month, or if the services of the Geotechnical Engineer have been terminated for any reason.

A.	Re: Elev. Tower Bldg. and Ramps/Stairs <small>Project Name</small> Franklin Elementary School <small>School Name</small> To: Santa Monica-Malibu Unified School District <small>School Dist.</small> 1651 Sixteenth Street, Santa Monica, CA90404 <small>Address</small> <small>Attention</small>	19-96 <small>DSA File #</small> 03-059179 <small>DSA App. #</small> <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
B.	<input checked="" type="checkbox"/> Engineered Fill <input type="checkbox"/> Footing Excavations <input type="checkbox"/> Driven Deep Foundations <input type="checkbox"/> Retaining Walls / Cantilevered Freestanding Walls <input type="checkbox"/> Composite Piles <input type="checkbox"/> Cast-In-Place Deep Foundations <input type="checkbox"/> Pre-stressed Rock/Soil Foundation Anchors It is my professional opinion that all of the geotechnical related tests and inspections (as indicated above) required by the Division of the State Architect (DSA) approved documents for the project identified in Section A were performed. Any tests of which I am aware that were not performed are listed on an attachment to this report. I am of the professional opinion that the tests and inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	All reports were sent to all entities as required by Section 4-335 of Title 24, Part 1.	
D.	Qualified personnel under my direct supervision conducted all geotechnical related testing and inspection services.	
E.	The results of all tests and inspections indicate that the materials tested comply with the requirements of the DSA approved documents.	
F.	I declare under penalty of perjury that this report was prepared under my direct supervision, I know the contents thereof, and that all of the statements are true and correct.	
	Signed <u>Artedi B. Cortez</u> <u>6-20-12</u> <small>GEOTECHNICAL ENGINEER * Date</small>	
	Print Name: ARTEDI B. CORTEZ Lab Name: Smith-Emery Laboratories Address: 781 E. Washington Blvd. City: Los Angeles State: CA Zip: 90021	
	DSA / LEA # 25	

cc: Project Architect _____ Project Inspector _____
 Structural Engineer _____ DSA Regional office _____

***For Lutz Kunze, RGE 493 (1993 project completion)**